## Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





Report Date: July 22, 2020

<u>Project</u>: Metzenbaum Center

3343 Community College Ave

Cleveland, Ohio 44115

<u>Inspector(s)</u>: Julie Gue, Certified Technician

## <u>Inspection and Test Date(s)</u>:

June 18, 2020

• June 19, 2020

June 22, 2020

Duct Fabricators, Inc. "Fire Safety Division" inspected the sixteen (16) fire dampers as noted on the following sheets for proper installation. The dampers were then tested and photographed in the "open" and "closed" positions to confirm that they were functioning as designed.

All dampers passed the inspection and functional testing.

NOTES: NFPA 80, NFPA101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.

Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

the dampers were functional at the time of testing Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

## Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





## <u>Fire / Smoke / Fire & Smoke Damper</u> <u>Composite Inspection Report</u>

	FD/SD/FSD	<u>I.D.#</u>	<u>Size</u>	Manufacturer	Model	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1	FD	AHU1-R1	36×12	Unknown	Unknown	Pass	Pass	Replaced missing bolt
2	FD	AHU1-R2	24×10	Unknown	Unknown	Pass	Pass	None
3	FD	AHU1-R3	10×10	Unknown	Unknown	Pass	Pass	Replaced missing bolt
4	FD	AHU1-R4	32×12	Unknown	Unknown	Pass	Pass	Replaced missing bolt
5	FD	AHU1-R5	10×10	Unknown	Unknown	Pass	Pass	Replaced missing bolt
6	FD	AHU1-R6	36×36	Unknown	Unknown	Pass	Pass	None
7	FD	AHU1-R7	36×36	Unknown	Unknown	Pass	Pass	Damper blade repaired.
8	FD	AHU2-R1	24X10	Unknown	Unknown	Pass	Pass	None
9	FD	AHU2-R2	24X10	Unknown	Unknown	Pass	Pass	None
10	FD	AHU2-R3	36X12	Unknown	Unknown	Pass	Pass	None
11	FD	AHU2-R4	24X10	Unknown	Unknown	Pass	Pass	None
12	FD	AHU2-R5	24X10	Unknown	Unknown	Pass	Pass	None
13	FD	AHU2-R6	36X36	Unknown	Unknown	Pass	Pass	None
14	FD	AHU2-R7	36X36	Unknown	Unknown	Pass	Pass	None
15	FD	AHU2-R8	36X36	Unknown	Unknown	Pass	Pass	None
16	FD	AHU2-R9	36X36	Unknown	Unknown	Pass	Pass	None
17								
18								
19								
20								

Inspector:Julie GueSA = Supply AirFD = Fire DamperInspection Dates:RA = Return AirSD = Smoke Damper

Facility: Metzenbaum Center EA = Exhaust Air FSD = Fire Smoke Damper