883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection** 

2022-11-01

**Facility Location** 

Jane Edna Hunter Building

**Damper Location** 

2nd floor West

**Inspector Name** 

Dan Tulcewicz

Damper I.D. #

AHU-1 Supply

**Damper Type** 

Horizontal Fire Damper

**Damper Size** 

64x36

**Damper Manufacturer** 

Safe Air

**Damper Model #** 

Unknown

**Fusible Link Temperature** 

165 Degrees

**Access Door Size** 

20x14

Pass / Fail / Abandoned

Pass

**Comments / Corrections** 

None


**Exterior Picture of Damper** 



**Interior Picture of Damper** 



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

#### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

2nd floor West mechanical room

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU1- Return

#### **Damper Type**

Horizontal Fire Damper

#### **Damper Size**

64x40

#### **Damper Manufacturer**

Safe Air

### Damper Model #

Unknown

#### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

16x16

#### Pass / Fail / Abandoned

Pass

## **Comments / Corrections**

None

## **Exterior Picture of Damper**



**Interior Picture of Damper** 





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

2nd floor Mechanical room east

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU2-Return

### **Damper Type**

Horizontal Fire Damper

#### **Damper Size**

64x40

#### **Damper Manufacturer**

Safe Air

### Damper Model #

Unknown

### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

16x16

#### Pass / Fail / Abandoned

Pass

## **Comments / Corrections**

None

## **Exterior Picture of Damper**



### **Interior Picture of Damper**





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

#### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

2nd floor Mechanical room east

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU2- Supply

### **Damper Type**

Horizontal Fire Damper

#### **Damper Size**

64x36

#### **Damper Manufacturer**

Ruskin

#### Damper Model #

IBD2

### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

16x16

#### Pass / Fail / Abandoned

Pass

## **Comments / Corrections**


None

## **Exterior Picture of Damper**



### **Interior Picture of Damper**





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

2nd floor West Mechanical Room

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU3- Return

## **Damper Type**

Vertical Fire Damper

#### **Damper Size**

109x33

## **Damper Manufacturer**

Ruskin

## Damper Model #

IBD2

### **Fusible Link Temperature**

165 Degrees

## **Access Door Size**

20x14

#### Pass / Fail / Abandoned

Pass

#### **Comments / Corrections**


None

## **Exterior Picture of Damper**



### **Interior Picture of Damper**





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

2nd floor West Mechanical Room

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU3- Supply

### **Damper Type**

Vertical Fire Damper

#### **Damper Size**

72x32

## **Damper Manufacturer**

Safe Air

### Damper Model #

Unknown

#### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

20x14

#### Pass / Fail / Abandoned

Pass

## **Comments / Corrections**

None

## **Exterior Picture of Damper**



**Interior Picture of Damper** 





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### **Date of Inspection**

2022-11-01

## **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

2nd floor Mechanical Room East

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU4-Return

### **Damper Type**

Vertical Fire Damper

#### **Damper Size**

110x30

#### **Damper Manufacturer**

Safe Air

## **Damper Model #**

Unknown

### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

20x14

#### Pass / Fail / Abandoned

Pass

## **Comments / Corrections**

None

## **Exterior Picture of Damper**



### **Interior Picture of Damper**





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

#### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

2nd Floor East Mechanical room

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU4-Supply

### **Damper Type**

Vertical Fire Damper

#### **Damper Size**

76x32

## **Damper Manufacturer**

Safe Air

### Damper Model #

Unknown

#### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

20x14

#### Pass / Fail / Abandoned

Pass

## **Comments / Corrections**


None

## **Exterior Picture of Damper**



**Interior Picture of Damper** 





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

3<sup>rd</sup> Floor West Mechanical Room

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU5- Supply

### **Damper Type**

Vertical Fire Damper

#### **Damper Size**

90x36

#### **Damper Manufacturer**

Safe Air

### Damper Model #

Unknown

### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

20x14

#### Pass / Fail / Abandoned

Pass

## **Comments / Corrections**

None

## **Exterior Picture of Damper**



**Interior Picture of Damper** 





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

3rd floor West Mechanical Room

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU5-Return

#### **Damper Type**

Vertical Fire Damper

#### **Damper Size**

114x36

#### **Damper Manufacturer**

Safe Air

## **Damper Model #**

Unknown

#### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

20x14

#### Pass / Fail / Abandoned

Pass

#### **Comments / Corrections**


None

## **Exterior Picture of Damper**



**Interior Picture of Damper** 





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

3rd Floor Mechanical Room

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU6-Return

### **Damper Type**

Vertical Fire Damper

#### **Damper Size**

112x36

## **Damper Manufacturer**

Safe Air

## **Damper Model #**

Unknown

### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

20x14

#### Pass / Fail / Abandoned

Pass

## **Comments / Corrections**


None

## **Exterior Picture of Damper**



**Interior Picture of Damper** 





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





#### VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### **Date of Inspection**

2022-11-01

#### **Facility Location**

Jane Edna Hunter Building

#### **Damper Location**

3rd floor East Mechanical room

#### **Inspector Name**

Dan Tulcewicz

#### Damper I.D. #

AHU6-Supply

## **Damper Type**

Vertical Fire Damper

## **Damper Size**

92x36

## **Damper Manufacturer**

Safe Air

### Damper Model #

Unknown

### **Fusible Link Temperature**

165 Degrees

#### **Access Door Size**

20x14

#### Pass / Fail / Abandoned

Pass

## **Comments / Corrections**


None

## **Exterior Picture of Damper**



**Interior Picture of Damper** 





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





# <u>Fire / Smoke / Fire & Smoke Damper</u> <u>Composite Inspection Report</u>

	FD/SD/FSD	<u>I.D.#</u>	<u>Size</u>	Manufacturer	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1	FD	AHU1-R	64×40	Safe Air	Unknown	Pass	N/A	None
2	FD	AHU1-S	64×36	Safe Air	Unknown	Pass	N/A	None
3	FD	AHU2-R	64×40	Safe Air	Unknown	Pass	N/A	None
4	FD	AHU2-S	64×40	Ruskin	IBD20	Pass	N/A	None
5	FD	AHU3-R	110×33	Ruskin	IBD20	Pass	N/A	None
6	FD	AHU3-S	72×32	Safe Air	Unknown	Pass	N/A	None
7	FD	AHU4-R	110×30	Safe Air	Unknown	Pass	N/A	None
8	FD	AHU4-S	76×32	Safe Air	Unknown	Pass	N/A	None
9	FD	AHU5-R	110×30	Safe Air	Unknown	Pass	N/A	None
10	FD	AHU5-S	90×30	Safe Air	Unknown	Pass	N/A	None
11	FD	AHU6-R	114×36	Safe Air	Unknown	Pass	N/A	None
12	FD	AHU6-S	92×36	Safe Air	Unknown	Pass	N/A	None

<u>Inspector:</u> Julie Gue, Dan Tulcewicz and Larry Coreno

SA = Supply Air

FD = Fire Damper

<u>Inspection Dates:</u> November 1 2022

RA = Return Air

Facility: Jane Edna Hunter