Cuyahoga County
Animal Shelter

9500 Sweet Valley Drive
Valley View, Ohio 44125

Physical Inspections

Fire Damper Inspection Report

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER
NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 3, 2025

Project: Cuyahoga County
Animal Shelter

Inspector(s):

- Dan Tulcewicz, Certified Technician

Inspection and Test Date(s):

- July 31, 2024

Duct Fabricators, Inc. “Fire Safety Division” inspected (4) dampers as noted on the following sheets for proper installation. The dampers were then tested and photographed in the “open” and “closed” positions to confirm that they were functioning as designed.

All dampers have passed physical inspection.

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I.D. #	Damper Type	Damper Size	Damper Manufacturer	Damper Model #	Fusible Link Temperature	Access Door Size	Pass / Fail / Abandoned	Comments / Corrections
2024-07-31	County Animal Shelter	Corridor 059 between rooms 03/04 supply diffuser	Dan Tulcewicz	Fire Damper #1	Ceiling Radiation Damper	8"Round	Ruskin	CFDR5	165 Degrees	Remove the air diverter	Pass	None
2024-07-31	County Animal Shelter	Corridor 059 between files (011)med super(010)	Dan Tulcewicz	Fire Damper #2	Ceiling Radiation Damper	6"Round	Ruskin	CFD5	165 Degrees	Remove the deflector	Pass	None
2024-07-31	County Animal Shelter	Files (011)	Dan Tulcewicz	Fire Damper #3	Ceiling Radiation Damper	6"Round	Ruskin	CFDR5	165 Degrees	Remove the deflector.	Pass	None
2024-07-31	County Animal Shelter	Corridor 059 outside of R.R(014)	Dan Tulcewicz	Fire Damper #4	Ceiling Radiation Damper	8"Round	Ruskin	CFDR5	165 Degrees	Remove the deflector	Pass	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-31

Facility Location
County Animal Shelter

Damper Location
Corridor 059 between rooms 03/04 supply diffuser

Inspector Name
Dan Tulcewicz

Damper I.D. #
Fire Damper 1

Damper Type
Ceiling Radiation Damper

Damper Size
8"Round

Damper Manufacturer
Ruskin

Damper Model #
CFDR5

Fusible Link Temperature
165 Degrees

Access Door Size
Remove the air diverter

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-31

Facility Location
County Animal Shelter

Damper Location
Corridor 059 between files (011)med super(010)

Inspector Name
Dan Tulcewicz

Damper I.D. #
Fire Damper 2

Damper Type
Ceiling Radiation Damper

Damper Size
6"Round

Damper Manufacturer
Ruskin

Damper Model #
CFD5

Fusible Link Temperature
165 Degrees

Access Door Size
Remove the deflector

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-31

Facility Location
County Animal Shelter

Damper Location
Files (011)

Inspector Name
Dan Tulcewicz

Damper I.D. #
Fire Damper #3

Damper Type
Ceiling Radiation Damper

Damper Size
6"Round

Damper Manufacturer
Ruskin

Damper Model #
CFDR5

Fusible Link Temperature
165 Degrees

Access Door Size
Remove the deflector.

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-31

Facility Location
County Animal Shelter

Damper Location
Corridor 059 outside of R.R(014)

Inspector Name
Dan Tulcewicz

Damper I.D. #
Fire Damper 4

Damper Type
Ceiling Radiation Damper

Damper Size
8"Round

Damper Manufacturer
Ruskin

Damper Model #
CFDR5

Fusible Link Temperature
165 Degrees

Access Door Size
Remove the deflector

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Cuyahoga County

County Board of Elections
2925 Euclid Ave
Cleveland, Ohio 44115

Fire/Smoke Damper Inspection Report

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: August 2024

Project: Cuyahoga County
Board of Elections

Inspector(s):

- Dan Tulcewicz, Certified Technician
- Tristan May, Certified Technician

Inspection and Test Date(s):

- July 2024

Duct Fabricators, Inc. “Fire Safety Division” inspected the Thirteen (13) fire dampers noted on the following sheets for proper installation. The dampers were then tested and photographed in the “open” and “closed” positions to confirm that they were functioning as designed.

All the dampers passed the inspection and functional testing.

NOTES: NFPA 80 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers located in patient care facilities are to be inspected and tested every six years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Fire / Smoke / Fire & Smoke Damper Composite Inspection Report

	FD/SD/FSD	I.D.#	Size	Manufacturer	Model	Visual	Functional	Comments
1	FD	AHU1-1-R	52X15	Safe Air	Unknown	Pass	Pass	None
2	FD	AHU1-1-S	52x14 Oval	Safe Air	Unknown	Pass	Pass	None
3	FD	AHU1-2-R1	70x14	Safe Air	Unknown	Pass	Pass	None
4	FD	AHU1-2-R2	70x14	Safe Air	Unknown	Pass	Pass	None
5	FD	AHU1-2-S	64x14 Oval	Safe Air	Unknown	Pass	Pass	None
6	FD	AHU1-3-R1	68x14	Safe Air	Unknown	Pass	Pass	None
7	FD	AHU1-3-R1	69x14	Safe Air	Unknown	Pass	Pass	None
8	FD	AHU1-3-S	32 Round	Safe Air	Unknown	Pass	Pass	None
9	FD	AHU1-4-R1	75x14	Safe Air	Unknown	Pass	Pass	None
10	FD	AHU1-4-R2	30x14	Safe Air	Unknown	Pass	Pass	None
11	FD	AHU1-4-S	32 Round	Safe Air	Unknown	Pass	Pass	None
12	FD	AHU1-B-R	36x24	Safe Air	Unknown	Pass	Pass	None
13	FD	AHU1-B-S	20x7 Oval	Safe Air	Unknown	Pass	Pass	None
14								
15								
16								
17								
18								
19								
20								

Inspector: Dan Tulcewicz & Tristan May
Inspection Dates: July, 2024
Facility: Board of Elections

S= Supply Air
R = Return Air
EA = Exhaust Air

FD = Fire Damper
SD = Smoke Damper
FSD = Fire Smoke Damper

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-30

Facility Location
County Board of Elections

Damper Location
First floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-1-R

Damper Type
Vertical Fire Damper

Damper Size
52"x15"

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-30

Facility Location
County Board of Elections

Damper Location
First floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-1-S

Damper Type
Vertical Fire Damper

Damper Size
52"x14" Oval

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18"Round

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-25

Facility Location
County Board of Elections

Damper Location
Second floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-2-R1

Damper Type
Vertical Fire Damper

Damper Size
70"x14"

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-25

Facility Location
County Board of Elections

Damper Location
Second floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-2-R2

Damper Type
Vertical Fire Damper

Damper Size
70"x14"

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-25

Facility Location
County Board of Elections

Damper Location
Second floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-2-S

Damper Type
Vertical Fire Damper

Damper Size
64"x14" Oval

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18"Round

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-25

Facility Location
County Board of Elections

Damper Location
Third floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-3-R1

Damper Type
Vertical Fire Damper

Damper Size
68"x14"

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-25

Facility Location
County Board of Elections

Damper Location
Third floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-3-R2

Damper Type
Vertical Fire Damper

Damper Size
69"x14"

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-25

Facility Location
County Board of Elections

Damper Location
Third floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-3-S

Damper Type
Vertical Fire Damper

Damper Size
32"Round

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18"Round

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-25

Facility Location
County Board of Elections

Damper Location
Fourth floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-4-R1

Damper Type
Vertical Fire Damper

Damper Size
75"x14"

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-25

Facility Location
County Board of Elections

Damper Location
Fourth floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-4-R2

Damper Type
Vertical Fire Damper

Damper Size
30"x14"

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-25

Facility Location
County Board of Elections

Damper Location
Fourth floor

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-4-S

Damper Type
Vertical Fire Damper

Damper Size
32"Round

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20"x18" Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-30

Facility Location
County Board of Elections

Damper Location
Basement

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-B-R

Damper Type
Vertical Fire Damper

Damper Size
36"x24"

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-30

Facility Location
County Board of Elections

Damper Location
Basement

Inspector Name
Dan Tulcewicz

Damper I.D. #
AHU1-B-S

Damper Type
Vertical Fire Damper

Damper Size
20"x7" Oval

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14"x14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Cuyahoga County Airport

26300 Curtiss Wright Pkwy
Richmond Heights, Ohio 44143

Fire Damper Inspection Report

Physical Inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 24, 2025

Project: Cuyahoga County
County Airport

Inspector(s):

- Tristan May, Certified Technician

Inspection and Test Date(s):

- November 18, 2025

Duct Fabricators, Inc. “Fire Safety Division” inspected two (2) dampers as noted on the following sheets for proper installation. The dampers were then tested and photographed in the “open” and “closed” positions to confirm that they were functioning as designed.

(2) dampers passed physical and functional testing.

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-18

Facility Location
SC/1916 Building

Damper Location
Mezzanine

Inspector Name
Tristan May

Damper I.D. #
FD-1

Damper Type
Horizontal Fire Damper (floor)

Damper Size
36*30

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-18

Facility Location
SC/1916 Building

Damper Location
Mezzanine

Inspector Name
Tristan May

Damper I.D. #
FD-2

Damper Type
Horizontal Fire Damper (floor)

Damper Size
49*13

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Courthouse Square

310 West Lakeside Ave
Cleveland Ohio 44114

Physical Inspections

Fire/Smoke Damper Inspection Report

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 3, 2025

Project: Cuyahoga County
Courthouse Square

Inspector(s):

- Dan Tulcewicz, Certified Technician

Inspection and Test Date(s):

- July 18, 2024 – July 22, 2024

Duct Fabricators, Inc. “Fire Safety Division” inspected (24) dampers as noted on the following sheets for proper installation. The dampers were then tested and photographed in the “open” and “closed” positions to confirm that they were functioning as designed.

All dampers have passed physical inspection.

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I.D. #	Damper Type	Damper Size	Damper Manufacturer	Damper Model #	Fusible Link Temperature	Access Door Size	Pass / Fail / Abandoned	Comments / Corrections
2024-07-18	Courthouse Square	7FL Storage Area	Dan Tulcewicz	CHS-Gen Ex-7	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	14"x14"	Pass	None
2024-07-18	Courthouse Square	7FL Storage Area	Dan Tulcewicz	CHS-OA-7	Vertical Fire Damper	24"x10"	Prefco Products	Unknown	165 Degrees	10"x10"	Pass	None
2024-07-18	Courthouse Square	Penthouse	Dan Tulcewicz	CHS-OA-PH	Horizontal Fire Damper	36"x30"	Prefco Products	Unknown	165 Degrees	14"x14"	Pass	None
2024-07-18	Courthouse Square	Penthouse	Dan Tulcewicz	CHS-P Gen. Ex.	Horizontal Fire Damper	30"x20"	Prefco Products	Unknown	165 Degrees	12"x12"	Pass	None
2024-07-18	Courthouse Square	Penthouse	Dan Tulcewicz	CHS-P Toilet Ex.	Horizontal Fire Damper	30"x20"	Prefco Products	Unknown	165 Degrees	12"x12"	Pass	None
2024-07-22	Courthouse Square	7FL Men's Restroom	Dan Tulcewicz	CHS-7 Toilet Ex	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	14"x14"	Pass	None
2024-07-22	Courthouse Square	Outside of Office #238	Dan Tulcewicz	CHS-Gen Ex-2	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	8"x18"	Pass	None
2024-07-22	Courthouse Square	3FL Room 315	Dan Tulcewicz	CHS-Gen Ex-3	Vertical Fire Damper	10"x14"	Prefco Products	Unknown	165 Degrees	Patch	Pass	Added angle
2024-07-22	Courthouse Square	Coffee Area Fish Tank	Dan Tulcewicz	CHS-Gen Ex-4	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	8"x8"	Pass	None
2024-07-22	Courthouse Square	Storage Closet	Dan Tulcewicz	CHS-Gen Ex-5	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	8"x8"	Pass	None
2024-07-22	Courthouse Square	Kitchen #614	Dan Tulcewicz	CHS-Gen Ex-6	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	8"x8"	Pass	None
2024-07-22	Courthouse Square	Oriana House Office	Dan Tulcewicz	CHS-Gen Ex-B	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	6"x6"	Pass	None
2024-07-22	Courthouse Square	Outside of Office #234	Dan Tulcewicz	CHS-OA-2	Vertical Fire Damper	24"x10"	Prefco Products	Unknown	165 Degrees	12"x12"	Pass	None
2024-07-22	Courthouse Square	3FL Kitchen	Dan Tulcewicz	CHS-OA-3	Vertical Fire Damper	10x24	Prefco Products	Unknown	165 Degrees	12"x12"	Pass	Added angle
2024-07-22	Courthouse Square	Conference Room Closet	Dan Tulcewicz	CHS-OA-4	Vertical Fire Damper	24"x10"	Prefco Products	Unknown	165 Degrees	20"x8"	Pass	None
2024-07-22	Courthouse Square	Office Outside of Storage Area	Dan Tulcewicz	CHS-OA-5	Vertical Fire Damper	24"x10"	Prefco Products	Unknown	165 Degrees	12"x12"	Pass	None
2024-07-22	Courthouse Square	6FL Storage Closet	Dan Tulcewicz	CHS-OA-6	Vertical Fire Damper	24"x10"	Prefco Products	Unknown	165 Degrees	18"x18"	Pass	None
2024-07-22	Courthouse Square	Oriana House Office	Dan Tulcewicz	CHS-OA-B	Horizontal Fire Damper	24"x14"	Prefco Products	Unknown	165 Degrees	18"x8"	Pass	None

2024-07-22	Courthouse Square	Men's Restroom	Dan Tulcewicz	CHS-Toilet Ex-2	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	12"x6"	Pass	None
2024-07-22	Courthouse Square	Men's Restroom	Dan Tulcewicz	CHS-Toilet Ex-3	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	14"x14"	Pass	None
2024-07-22	Courthouse Square	Men's Restroom	Dan Tulcewicz	CHS-Toilet Ex-4	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	14"x14"	Pass	None
2024-07-22	Courthouse Square	Men's Restroom	Dan Tulcewicz	CHS-Toilet Ex-5	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	14"x14"	Pass	None
2024-07-22	Courthouse Square	6FL Men's Restroom	Dan Tulcewicz	CHS-Toilet Ex-6	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	12"x12"	Pass	None
2024-07-22	Courthouse Square	Oriana House Office	Dan Tulcewicz	CHS-Toilet Ex-B	Vertical Fire Damper	14"x10"	Prefco Products	Unknown	165 Degrees	8"x8"	Pass	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Men's Restroom

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Toilet Ex-3

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14"x14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Oriana House Office

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Toilet Ex-B

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"x8"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Men's Restroom

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Toilet Ex-4

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14"x14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Men's Restroom

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Toilet Ex-5

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14"x14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Men's Restroom

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Toilet Ex-2

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Oriana house office.

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-OA-B

Damper Type
Horizontal Fire Damper

Damper Size
24"x14"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18"x8"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-18

Facility Location
Courthouse Square

Damper Location
Penthouse

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-P Gen. Ex

Damper Type
Horizontal Fire Damper

Damper Size
30"x20"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-18

Facility Location
Courthouse Square

Damper Location
Penthouse

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-OA-PH

Damper Type
Horizontal Fire Damper

Damper Size
36"x30"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14"x14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-18

Facility Location
Courthouse Square

Damper Location
Penthouse

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-P Toilet Ex.

Damper Type
Horizontal Fire Damper

Damper Size
30"x20"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Office Outside of Storage Area

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-OA-5

Damper Type
Vertical Fire Damper

Damper Size
24"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-18

Facility Location
Courthouse Square

Damper Location
7FL Storage Area

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-OA-7

Damper Type
Vertical Fire Damper

Damper Size
24"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10"x10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
3rd Floor Kitchen

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-OA-3

Damper Type
Vertical Fire Damper

Damper Size
10x24

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Conference Room Closet

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-OA-4

Damper Type
Vertical Fire Damper

Damper Size
24"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20"x8"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
6FL Storage Closet

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-OA-6

Damper Type
Vertical Fire Damper

Damper Size
24"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18"x18"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Storage Closet

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Gen Ex-5

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"x8"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Kitchen #614

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-GEN Ex-6

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"x8"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Outside of Office #234

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-OA-2

Damper Type
Vertical Fire Damper

Damper Size
24"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-18

Facility Location
Justice Center Court Towers

Damper Location
7FL Storage Area

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Gen Ex-7

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14"x14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Oriana House Office

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Gen Ex-B

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6"x6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-18

Facility Location
Justice Center Court Towers

Damper Location
7FL Men's Restroom

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-7 Toilet EX

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14"x14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
6FL Men's Restroom

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Toilet Ex-6

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Outside of Office #238

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Gen Ex-2

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"x18"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
Coffee Area Fish Tank

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Gen Ex-4

Damper Type
Vertical Fire Damper

Damper Size
14"x10"

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"x8"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-07-22

Facility Location
Courthouse Square

Damper Location
3FL Rm 315

Inspector Name
Dan Tulcewicz

Damper I.D. #
CHS-Gen Ex-3

Damper Type
Vertical Fire Damper

Damper Size
10x14

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Jail 1

West 3rd Street
Cleveland, Ohio 44113

Fire/Smoke Damper Inspection Report

Visual inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 3, 2025

Project: Cuyahoga County
Jail 1

Inspector(s):

- Larry Coreno, Certified Technician
- Tristan May, Certified Technician
- Kaitlyn McElroy, Certified Technician

Inspection and Test Date(s):

- May 20, 2025 – *In progress*

As of October 31, 2025, Duct Fabricators, Inc. "Fire Safety Division" inspected (327) dampers as noted on the following sheets. The dampers were visually inspected and photographed in the "exterior" and "interior" positions to confirm that they have not been altered and are free of any obstructions. Preventative maintenance was performed, and any deficiencies addressed.

(216) Dampers passed visual inspection
(111) Dampers failed due to reasons indicated on the report

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I.D. #	Damper Type	Damper Size	Damper Manufacturer	Damper Model #	Fusible Link Temperature	Access Door Size	Pass / Fail / Abandoned	Comments / Corrections
2025-05-20	Jail 1	5th Floor Mechanical Room.	Tristan May	AC12-S4	Vertical Fire Damper	28" Round	Unknown	Unknown	165 Degrees	18" Round	Pass	None
2025-05-20	Jail 1	5th Floor Mechanical Room.	Tristan May	AC8-S1	Vertical Fire Damper	22" Round	Unknown	Unknown	N/A	18" Round	Fail	No Angle,dampe r not secured in sleeve
2025-05-20	Jail 1	5th Floor Mechanical Room.	Tristan May	AC7-S1	Vertical Fire Damper	24" Round	Air Balance	Unknown	165 Degrees	18 Round	Fail	Damper not in wall, no angle
2025-05-20	Jail 1	5th Floor Mechanical Room.	Tristan May	AC7-S2	Vertical Fire Damper	31" Round	Unknown	Unknown	165 Degrees	18" Round	Fail	Damper not in wall, no angle
2025-05-20	Jail 1	5th Floor Mechanical Room.	Tristan May	AC12-S2	Vertical Fire Damper	22" Round	Air Balance	Unknown	165 Degrees	18" Round	Fail	Damper not secured in sleeve. Damper not in wall. No access to back of damper.
2025-05-20	Jail 1	5th Floor Mechanical Room.	Tristan May	3EF-2	Vertical Fire Damper	22*34	Unknown	Unknown	165 Degrees	20*20	Fail	No Angle, no sleeve. No access bottom of duct.
2025-05-20	Jail 1	5th Floor Mechanical.	Tristan May	AC12-S3	Vertical Fire Damper	28" Round	Unknown	Unknown	165 Degrees	18" Round	Fail	Damper not secured in sleeve. No access to back of damper
2025-05-20	Jail 1	5th Floor Mechanical Room.	Tristan May	AC7-S3	Vertical Fire Damper	28"rnd	Unknown	Unknown	165 Degrees	18" rnd	Fail	Damper not secured in wall, no angle

2025-05-20	Jail 1	5th Floor Mechanical Room	Tristan May	AC12-S1	Vertical Fire Damper	28" Round	Air Balance	Unknown	165 Degrees	18" Round	Fail	Damper not attached to sleeve. No angle. No access to back of damper
2025-05-21	Jail 1	5th Floor Mechanical Room.	Kaitlyn McElroy	AC29-Supply	Horizontal Fire Damper	32*14	Prefco Products	E6-BC	165 Degrees	14*14	Pass	None
2025-05-21	Jail 1	5th Floor Mechanical Room	Tristan May	3EF-3	Vertical Fire Damper	20*24	Unknown	Unknown	165 Degrees	10*8	Fail	Wall not complete, no access to back, no room for external damper, not secured in wall, incomplete angle, no room for more angle
2025-05-21	Jail 1	5th Floor Mechanical Room.	Kaitlyn McElroy	AC29 Return	Horizontal Fire Damper	23*14	Prefco Products	E6-BC	165 Degrees	12*12	Pass	None
2025-05-21	Jail 1	5th Floor Mechanical Room.	Tristan May	AC7A-R	Horizontal Fire Damper	32*34	Unknown	Unknown	165 Degrees	17*29	Pass	None

2025-05-21	Jail 1	5th Floor Mechanical Room.	Tristan May	AC11-S4	Vertical Fire Damper	24" Round	Unknown	Unknown	165 Degrees	18" Round	Fail	Not in wall, damper not secured to sleeve. Access to both sides of wall. Damper can be replaced with in-wall damper. 26.25 x 28 max exterior damper size
2025-05-21	Jail 1	5th Floor Mechanical Room.	Tristan May	AC7-S4	Vertical Fire Damper	20" Round	Unknown	Unknown	165 Degrees	18" Round	Fail	No angle, no access to back, not secured in wall. No room for external damper unless offset away from existing ductwork. East access from ground
2025-05-21	Jail 1	5th Floor Mechanical Room.	Kaitlyn McElroy	AC10-Return 1	Horizontal Fire Damper	44*24	Ruskin	IBD2	165 Degrees	18*18	Fail	Welded angle
2025-05-21	Jail 1	5th Floor Mechanical Room.	Tristan May	AC7A-S1	Horizontal Fire Damper	14*14	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-21	Jail 1	5th Floor Mechanical Room.	Tristan May	AC7A-S2	Horizontal Fire Damper	18" Round	Air Balance	Unknown	165 Degrees	18*16	Pass	None

2025-05-21	Jail 1	5th Floor Mechanical Room	Kaitlyn McElroy	AC11-S3	Vertical Fire Damper	24" Round	Air Balance	Unknown	165 Degrees	18" Round	Fail	No angle, damper not secured to sleeve, can replace with external or in stream damper, access to back. Wall sleeve dimensions 26.25 x 28 max exterior damper size
2025-05-21	Jail 1	5th Floor Mechanical Room.	Tristan May	AC7A-S3	Horizontal Fire Damper	16" Round	Air Balance	Unknown	165 Degrees	17*16	Pass	None
2025-05-22	Jail 1	5th Floor Mechanical Room.	Tristan May	AC11-S2	Vertical Fire Damper	26" Round	Unknown	Unknown	165 Degrees	20" Round	Fail	No sleeve or angle. Access to back, can be replaced with in or out of wall damper. Max exterior damper size for in wall 28wide X 30tall.
2025-05-22	Jail 1	5th Floor Mechanical Room.	Tristan May	3EF-5	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	10	Fail	No angle, damper not secured in wall. Incomplete wall, no access to back

2025-05-22	Jail 1	5th Floor Inmate Elevator Room.	Tristan May	INM-ELV-RM-S	Vertical Fire Damper	20*18	Ruskin	IBD40	165 Degrees	Patch	Pass	None
2025-05-22	Jail 1	5th Floor G Elevator Room.	Tristan May	G-ELV-RM S	Vertical Fire Damper	30*16	Ruskin	IBD40	165 Degrees	Grille	Pass	None
2025-05-22	Jail 1	5th Floor Mechanical Room.	Tristan May	AC10-S4	Vertical Fire Damper	30" Round	Unknown	Unknown	165 Degrees	18" Round	Pass	None
2025-05-22	Jail 1	5th Floor Mechanical Room.	Tristan May	AC10-S1	Vertical Fire Damper	18" Round	Air Balance	Unknown	165 Degrees	12" Round	Fail	No sleeve or angle, damper not secured in wall.
2025-05-22	Jail 1	5th Floor Inmate Elevator Room	Tristan May	INM-ELV-RM-R	Vertical Fire Damper	32*32	Ruskin	IBD40	165 Degrees	Grille	Pass	None
2025-05-22	Jail 1	5th Floor G Elevator Room.	Tristan May	G-ELV-RM R	Vertical Fire Damper	36*20	Ruskin	IBD40	165 Degrees	Grille	Pass	None
2025-05-22	Jail 1	5th Floor Mechanical Room.	Tristan May	3EF-4	Vertical Fire Damper	58*40	Air Balance	Unknown	165 Degrees	20	Fail	No angle, no access to back
2025-05-22	Jail 1	5th Floor Mechanical Room	Tristan May	AC10-S2	Vertical Fire Damper	25	Unknown	Unknown	165 Degrees	18	Fail	Damper not secured in wall. No angle. No access to rear

2025-05-22	Jail 1	5th Floor Mechanical Room.	Tristan May	AC11-S1	Vertical Fire Damper	28" Round	Unknown	Unknown	165 Degrees	18" Round	Fail	Sleeve not secured in wall, no angle. Access to back, can be replaced with in or out of wall damper. Exterior damper max 30 wide X 32 7/8 tall.
2025-05-22	Jail 1	5th Floor Mechanical Room.	Tristan May	AC10-Return	Vertical Fire Damper	60*54	Air Balance	Unknown	165 Degrees	20*20	Fail	No angle. No access to back, top or left side of damper.
2025-05-27	Jail 1	Penthouse.	Tristan May	PH-FD5	Vertical Fire Damper	12*12	Prefco Products	Unknown	165 Degrees	12	Pass	None
2025-05-27	Jail 1	Trade Office Dock Doors.	Tristan May	P1-FD3	Vertical Fire Damper	30*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-05-27	Jail 1	P2 Garage.	Tristan May	PS-FD S1	Vertical Fire Damper	30*12	Unknown	Unknown	165 Degrees	10*10	Pass	None
2025-05-27	Jail 1	P1 Elevator Lobby.	Tristan May	P1-FD EX1	Horizontal Fire Damper	14*6	Unknown	Unknown	165 Degrees	12*12	Pass	Angle on back side
2025-05-27	Jail 1	Penthouse Elevator Room.	Tristan May	PH-FD1	Vertical Fire Damper	12*12	Unknown	Unknown	165 Degrees	10	Pass	None
2025-05-27	Jail 1	P1 Garage.	Tristan May	P1-FD EX7	Vertical Fire Damper	70*14	Unknown	Unknown	165 Degrees	10*10	Fail	Damper not secured to sleeve. Can fix with screws
2025-05-27	Jail 1	Trade Office Dock Doors.	Tristan May	P1-SD3	Vertical Fire Damper	14*10	Unknown	Unknown	N/A	Patch	Fail	Damper not in wall

2025-05-27	Jail 1	Trade Office Dock Doors.	Tristan May	P1-SD4	Vertical Smoke Damper	26*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-05-27	Jail 1	Penthouse.	Tristan May	PH-FD4	Horizontal Fire Damper	12*12	Prefco Products	Unknown	165 Degrees	12*12	Pass	None
2025-05-27	Jail 1	Penthouse Elevator Room.	Tristan May	PH-FD2	Vertical Fire Damper	12*12	Unknown	Unknown	165 Degrees	10	Pass	None
2025-05-27	Jail 1	Penthouse.	Tristan May	PH-FD3	Vertical Fire Damper	12*12	Unknown	Unknown	165 Degrees	10	Pass	None
2025-05-27	Jail 1	P1 Garage.	Tristan May	P1-FD EX5	Vertical Fire Damper	96*30	Ruskin	Unknown	165 Degrees	10*10	Fail	Not secured to sleeve. No angle
2025-07-22	Jail 1	Trades Corridor Dock 1.	Tristan May	P1-FD2	Vertical Fire Damper	10" R	Air Balance	Unknown	165 Degrees	6" R	Fail	No Angle, sleeve in wall
2025-07-22	Jail 1	Trades Corridor Dock 1.	Tristan May	P1-SD2	Vertical Smoke Damper	10" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-07-22	Jail 1	Trades Corridor Dock 1.	Tristan May	P1-FD1.	Vertical Fire Damper	12" R	Air Balance	Unknown	165 Degrees	9" R	Fail	No Angle, sleeve in wall.
2025-07-22	Jail 1	Trades Corridor Dock 1.	Tristan May	P1-SD1	Vertical Smoke Damper	12" R	Air Balance	Unknown	N/A	9" R	Pass	None
2025-07-23	Jail 1	Sally Port Bathroom.	Tristan May	P1-SD6	Vertical Smoke Damper	24*10	Unknown	Unknown	N/A	Open	Pass	None
2025-07-23	Jail 1	Sally Port Bathroom.	Tristan May	P1-FD5	Vertical Fire Damper	24*10	Air Balance	Unknown	165 Degrees	12*12	Fail	No Angle. No sleeve.
2025-07-23	Jail 1	4FL Bridge to Jail 2.	Tristan May	4FL-SD1 S	Vertical Smoke Damper	12" R	Unknown	Unknown	N/A	Patch	Pass	None
2025-07-23	Jail 1	4FL NW Hallway Women's Bathroom.	Tristan May	4FL-FD5 N	Vertical Fire Damper	18" R	Air Balance	Unknown	165 Degrees	12x R	Fail	No Angle. Sleeve in wall.
2025-07-23	Jail 1	4FL Bridge to Jail 2.	Tristan May	4FL-FD2 S	Vertical Fire Damper	20*10	Air Balance	Unknown	165 Degrees	12*12	Fail	No Sleeve.

2025-07-23	Jail 1	4FL Bridge to Jail 2.	Tristan May	4FL-FD1 S	Vertical Fire Damper	12" R	Air Balance	Unknown	165 Degrees	Patch	Fail	No Angle. No Sleeve.
2025-07-23	Jail 1	4FL NW Hallway Women's Restroom.	Tristan May	4FL-SD5 N	Vertical Smoke Damper	18" R	Air Balance	Unknown	N/A	12" R	Pass	None
2025-07-23	Jail 1	4FL NW Hallway.	Tristan May	4FL-FD4 N	Vertical Fire Damper	14*6	Air Balance	Unknown	165 Degrees	8*8	Fail	No Sleeve.
2025-07-23	Jail 1	NW Hallway, Outside Employee Bathroom.	Tristan May	4FL-SD1 N	Vertical Smoke Damper	42*12	Air Balance	Unknown	N/A	Open	Pass	None
2025-07-23	Jail 1	4FL NW Hallway.	Tristan May	4FL-SD4 N	Vertical Smoke Damper	14*6	Air Balance	Unknown	N/A	8*8	Pass	None
2025-07-23	Jail 1	4FL NW Corridor.	Tristan May	4FL-FD3 N	Vertical Fire Damper	14*6	Air Balance	Unknown	165 Degrees	8*8	Fail	No Sleeve.
2025-07-23	Jail 1	NW Corridor.	Tristan May	4FL-SD2 N	Vertical Smoke Damper	9" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-07-23	Jail 1	Sally Port Dock 2 Hallway.	Tristan May	P1-SD8	Vertical Smoke Damper	24*12	Unknown	Unknown	N/A	Open	Pass	None
2025-07-23	Jail 1	4FL NW Corridor.	Tristan May	4FL-FD2 N	Vertical Fire Damper	9" R	Air Balance	Unknown	165 Degrees	6" R	Fail	No Angle. No Sleeve
2025-07-23	Jail 1	Sally Port Bathroom.	Tristan May	P1-FD6	Vertical Fire Damper	8*6	Air Balance	Unknown	165 Degrees	Patch	Fail	No Angle. No sleeve.
2025-07-23	Jail 1	4 FL NW Hallway.	Tristan May	4FL-SD3 N	Vertical Smoke Damper	14*6	Air Balance	Unknown	N/A	8*8	Pass	None
2025-07-23	Jail 1	Sally Port Hallway.	Tristan May	P1-FSD1	Vertical Fire / Smoke Damper	12" R	Ruskin	FSD60	165 Degrees	Patch	Pass	None
2025-07-23	Jail 1	Sally Port.	Tristan May	P1-FD4	Vertical Fire Damper	10" R	Air Balance	Unknown	165 Degrees	6" R	Fail	No Angle. No sleeve.
2025-07-23	Jail 1	Sally Port Hallway.	Tristan May	P1-FSD2	Vertical Fire / Smoke Damper	10" R	Ruskin	FSD60	165 Degrees	Patch	Pass	None

2025-07-24	Jail 1	4FL Bridge to Jail 2.	Tristan May	4FL-FD4 S	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Open	Fail	No Sleeve.
2025-07-24	Jail 1	4FL Bridge to Jail 2.	Tristan May	4FL-FD3 S	Vertical Fire Damper	15*10	Air Balance	Unknown	165 Degrees	8*6	Fail	No Sleeve.
2025-07-24	Jail 1	4FL Bridge to Jail 2.	Tristan May	4FL-SD4 S	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Open	Pass	None
2025-07-24	Jail 1	4FL Bridge to Jail 2.	Tristan May	4FL-SD3 S	Vertical Smoke Damper	15*10	Air Balance	Unknown	N/A	8*6	Pass	None
2025-08-19	Jail 1	SW Corridor by Release Desk.	Tristan May	4FL-SD12 S	Vertical Smoke Damper	14*6	Air Balance	Unknown	N/A	Patch	Pass	Abandoned per jci. Passed visual inspection
2025-08-19	Jail 1	SW Corridor by Release Desk.	Tristan May	4FL-FD11 S	Vertical Fire Damper	14" R	Air Balance	Unknown	165 Degrees	12" R	Fail	No Angle.
2025-08-19	Jail 1	SW Corridor by Release Desk.	Tristan May	4FL-SD9 S	Vertical Smoke Damper	34*12	Air Balance	Unknown	N/A	Open	Pass	None
2025-08-19	Jail 1	Old Commissary Storage Closet	Tristan May	4FL-SD6 N	Vertical Smoke Damper	42*12	Air Balance	Unknown	N/A	Open	Pass	None
2025-08-19	Jail 1	SW Corridor by Release Desk.	Tristan May	4FL-FD9 S	Vertical Fire Damper	34*12	Air Balance	Unknown	165 Degrees	Open	Fail	No Angle.
2025-08-19	Jail 1	SW Corridor by Release Desk.	Tristan May	4FL-SD10 S	Vertical Smoke Damper	32*10	Air Balance	Unknown	N/A	Patch	Pass	Abandoned per jci. Passes visual inspection
2025-08-19	Jail 1	SW Corridor by Release Desk.	Tristan May	4FL-FD7 s	Vertical Fire Damper	38*10	Air Balance	Unknown	165 Degrees	13*9	Fail	No breakaway connection.
2025-08-19	Jail 1	SW Corridor by Release Desk.	Tristan May	4FL-FD8 S	Vertical Fire Damper	12" R	Air Balance	Unknown	165 Degrees	9" R	Fail	Damper not in wall.

2025-08-19	Jail 1	Commissary Storage Closet.	Tristan May	4FL-SD9 N	Vertical Smoke Damper	40*12	Air Balance	Unknown	N/A	Open	Pass	None
2025-08-19	Jail 1	Commissary Storage Closet.	Tristan May	4FL-FD6 N	Vertical Fire Damper	42*12	Air Balance	Unknown	165 Degrees	Open	Fail	No Angle
2025-08-19	Jail 1	Bridge to Jail 2.	Tristan May	4FL-FD5 S	Vertical Fire Damper	17" R	Air Balance	Unknown	165 Degrees	12" R	Fail	Inaccessible. Conduit in way, would need to crawl on top of ductwork
2025-08-19	Jail 1	SW Corridor by Release Desk.	Tristan May	4FL-FD15 S	Vertical Smoke Damper	12" R	Air Balance	Unknown	N/A	4*4	Fail	More than 2' from fire rated barrier
2025-08-20	Jail 1	Storage Closet in F/G Vestibule.	Tristan May	3FL-FD3 N	Vertical Fire Damper	10*4	Air Balance	Unknown	165 Degrees	Patch	Fail	No wall between dampers.
2025-08-20	Jail 1	Storage Closet in F/G Vestibule.	Tristan May	3FL-FD2 N	Vertical Fire Damper	9*5	Air Balance	Unknown	165 Degrees	Open	Pass	None
2025-08-20	Jail 1	Storage Closet in F/G Vestibule.	Tristan May	3FL-FD1 N	Vertical Fire Damper	14" R	Air Balance	Unknown	165 Degrees	Patch	Fail	No wall between dampers
2025-08-20	Jail 1	Storage Closet in F/G Vestibule.	Tristan May	3FL-SD4 N	Vertical Smoke Damper	48*15	Air Balance	Unknown	N/A	Open	Pass	None
2025-08-20	Jail 1	Storage Closet in F/G Vestibule.	Tristan May	3FL-FD4 N	Vertical Fire Damper	48*15	Air Balance	Unknown	165 Degrees	Open	Fail	No Angle.
2025-08-20	Jail 1	Storage Closet in F/G Vestibule.	Tristan May	3FL-FD5 N	Vertical Fire Damper	16*8	Air Balance	Unknown	165 Degrees	Patch	Fail	No Angle.
2025-08-20	Jail 1	F/G Vestibule.	Tristan May	3FL-FD9 N	Vertical Fire Damper	14" R	Air Balance	Unknown	165 Degrees	Patch	Fail	No Angle. No Sleeve
2025-08-20	Jail 1	F/G Vestibule.	Tristan May	3FL-SD6 N	Vertical Smoke Damper	9" R	Air Balance	Unknown	N/A	Patch	Pass	None

2025-08-20	Jail 1	F/G Vestibule.	Tristan May	3FL-FD6 N	Vertical Fire Damper	9" R	Air Balance	Unknown	165 Degrees	Patch	Fail	No Angle.
2025-08-20	Jail 1	F/G Vestibule.	Tristan May	3FL-FSD1 N	Vertical Fire / Smoke Damper	16*12	Ruskin	FSD36	165 Degrees	6*6	Fail	No angle
2025-08-20	Jail 1	F/G Vestibule.	Tristan May	3FL-FSD2 N	Vertical Fire / Smoke Damper	16" R	Ruskin	FSDR26	165 Degrees	6*6	Fail	No Angle
2025-08-20	Jail 1	NE Corridor 120 Holding.	Tristan May	3FL-SD13 N	Vertical Smoke Damper	48*12	Air Balance	Unknown	N/A	Open	Pass	None
2025-08-20	Jail 1	NE Corridor 120 Holding.	Tristan May	3FL-SD11 N	Vertical Smoke Damper	14" R	Air Balance	Unknown	N/A	12" R	Pass	None
2025-08-20	Jail 1	NE Corridor 120 Holding.	Tristan May	3FL-FD11 N	Vertical Fire Damper	14" R	Air Balance	Unknown	165 Degrees	12" R	Fail	Damper out of wall
2025-08-20	Jail 1	NE Corridor 120 Holding.	Tristan May	3FL-FD10 N	Vertical Fire Damper	26*10	Air Balance	Unknown	165 Degrees	5*7	Pass	None
2025-08-20	Jail 1	NE Corridor 120 Holding.	Tristan May	3FL-SD8 N	Vertical Smoke Damper	36*15	Air Balance	Unknown	N/A	Open	Pass	None
2025-08-20	Jail 1	NE Corridor 120 Holding.	Tristan May	3FL-FD8 N	Vertical Fire Damper	36*15	Air Balance	Unknown	165 Degrees	Open	Pass	None
2025-08-21	Jail 1	NW Corridor Z1.	Tristan May	6FL-SD8 N	Vertical Smoke Damper	6" R	Prefco Products	Unknown	N/A	Patch	Pass	None
2025-08-21	Jail 1	NW Corridor Z1.	Tristan May	6FL-SD9 N	Vertical Smoke Damper	14" R	Prefco Products	Unknown	N/A	Patch	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-FD1 N	Vertical Fire Damper	6" R	Air Balance	Unknown	165 Degrees	Flex	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-FD2 N	Vertical Fire Damper	20*16	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-FD3 N	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	12*12	Fail	No Angle. No breakaway connection.
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD3 N	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	12*12	Pass	None

2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-FD6 N	Vertical Fire Damper	32*10	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD5 N	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	9" R	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-FD5 N	Vertical Fire Damper	16" R	Air Balance	Unknown	165 Degrees	9" R	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD4 N	Vertical Smoke Damper	9" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-FD7 N	Vertical Fire Damper	10*6	Air Balance	Unknown	165 Degrees	Patch	Fail	No breakaway connection, sleeve in wall
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD18 N	Vertical Smoke Damper	48*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD11 N	Vertical Smoke Damper	30*10	Air Balance	Unknown	N/A	Patch	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD12 N	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD17 N	Vertical Smoke Damper	12" R	Prefco Products	Unknown	N/A	Unknown	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD16 N	Vertical Smoke Damper	8*8	Prefco Products	Unknown	N/A	Patch	Pass	None
2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD15 N	Vertical Smoke Damper	24*10	Prefco Products	Unknown	N/A	Open	Pass	None
2025-08-21	Jail 1	Vestibule E/F.	Tristan May	6FL-SD14 N	Vertical Smoke Damper	24*12	Air Balance	Unknown	N/A	Open	Pass	None

2025-08-21	Jail 1	NW Corridor.	Tristan May	6FL-SD10 N	Vertical Smoke Damper	18*8	Air Balance	Unknown	N/A	Patch	Fail	Not within 2 feet of fire rated partition
2025-08-25	Jail 1	Southeast Corridor	Tristan May	6FL-FD5 S	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Fail	Angle is attached to duct work not damper.
2025-08-25	Jail 1	Southeast Corridor	Tristan May	6FL-FD7 S	Vertical Fire Damper	26*12	Air Balance	Unknown	165 Degrees	Patch	Fail	No breakaway connection. Not enough space between dampers. Improper installation of angle.
2025-08-25	Jail 1	Southeast Corridor.	Tristan May	6FL-SD11 S	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	6" R	Pass	None.
2025-08-25	Jail 1	Outside of 6-A-1	Tristan May	6FL-SD2 S	Vertical Smoke Damper	14*8	Air Balance	Unknown	N/A	Open	Pass	None
2025-08-25	Jail 1	Inside 6-A-1	Tristan May	6FL-SD10 S	Vertical Smoke Damper	18*8	Air Balance	Unknown	N/A	Open	Pass	None
2025-08-25	Jail 1	Room 6A1.	Tristan May	6FL-SD8 S	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	8*6 OV	Pass	None
2025-08-25	Jail 1	Southeast Corridor.	Tristan May	6FL-FD6 S	Vertical Fire Damper	16*6	Air Balance	Unknown	165 Degrees	Patch	Fail	No annular space, improper installation of angle, no space between dampers

2025-08-25	Jail 1	Room 6A1-5.	Tristan May	6FL-SD9 S	Vertical Smoke Damper	18*8	Prefco Products	Unknown	N/A	6" R	Pass	None
2025-08-25	Jail 1	Southeast Corridor.	Tristan May	6FL-SD5 S	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-08-25	Jail 1	Southeast Corridor.	Tristan May	6FL-SD3 S	Vertical Smoke Damper	18*8	Air Balance	Unknown	N/A	Patch	Fail	More than 2' away from fire rated barrier. Found in closed position.
2025-08-25	Jail 1	Outside of Office 6-A-1.	Tristan May	6FL-SD1 S	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-08-26	Jail 1	Southeast Corridor	Tristan May	6FL-FD4 S	Vertical Fire Damper	16" R	Air Balance	Unknown	165 Degrees	10" R	Fail	Damper out of wall
2025-08-26	Jail 1	Southeast Corridor	Tristan May	6FL-FD12 S	Vertical Fire Damper	14" R	Air Balance	Unknown	165 Degrees	12" R	Fail	No Angle. Damper out of wall.
2025-08-26	Jail 1	South Corridor.	Tristan May	6FL-FD21 S	Vertical Fire Damper	12" R	Prefco Products	Unknown	165 Degrees	Patch	Pass	None
2025-08-26	Jail 1	Outside of 6C1 Pod.	Tristan May	6FL-FSD1 S	Vertical Fire / Smoke Damper	8*8	Prefco Products	Unknown	165 Degrees	Open	Fail	Need access door. No Angle
2025-08-26	Jail 1	Southwest Corridor.	Tristan May	6FL-SD18 S	Vertical Smoke Damper	38*8	Air Balance	Unknown	N/A	7*7	Pass	None
2025-08-26	Jail 1	Southwest Corridor.	Tristan May	6FL-FD17 S	Vertical Fire Damper	54*12	Air Balance	Unknown	165 Degrees	10*10	Pass	None
2025-08-26	Jail 1	Southwest Corridor.	Tristan May	6FL-SD16 S	Vertical Smoke Damper	20*10	Air Balance	Unknown	N/A	5*6	Pass	None
2025-08-26	Jail 1	Southwest Corridor.	Tristan May	6FL-FD14 S	Vertical Fire Damper	20" R	Unknown	Unknown	165 Degrees	Patch	Fail	Inaccessible. Conduit and light in the way.

2025-08-26	Jail 1	Southwest Corridor.	Tristan May	6FL-SD13 S	Vertical Smoke Damper	28*10	Air Balance	Unknown	N/A	14*10	Pass	None
2025-08-26	Jail 1	Northwest Room 616.	Tristan May	6FL-FSD1 N	Vertical Fire / Smoke Damper	20*16	Ruskin	Unknown	165 Degrees	Patch	Pass	None
2025-08-26	Jail 1	Southwest Corridor.	Tristan May	6FL-SD14 S	Vertical Smoke Damper	18" R	Prefco Products	Unknown	N/A	3*4	Pass	Pass
2025-08-26	Jail 1	Southwest Corridor.	Tristan May	6FL-SD15 S	Vertical Smoke Damper	28*8	Air Balance	Unknown	N/A	4*4 patch	Pass	None
2025-08-26	Jail 1	Southwest Corridor.	Tristan May	6FL-SD17 S	Vertical Smoke Damper	54*12	Air Balance	Unknown	N/A	10*10	Pass	None
2025-08-26	Jail 1	Southwest Corridor.	Tristan May	6FL-SD19 S	Vertical Smoke Damper	14*6	Air Balance	Unknown	N/A	3*3	Pass	None
2025-08-26	Jail 1	South Corridor.	Tristan May	6FL-SD20 S	Vertical Smoke Damper	34*10	Air Balance	Unknown	N/A	Patch	Pass	Damper found closed.
2025-08-26	Jail 1	Southeast Corridor.	Tristan May	6FL-SD12 S	Vertical Smoke Damper	14" R	Air Balance	Unknown	N/A	12" R	Pass	None
2025-08-26	Jail 1	Southeast Corridor	Tristan May	6FL-FD11 S	Vertical Fire Damper	8" R	Air Balance	Unknown	165 Degrees	6" R	Fail	No annular space. No Angle.
2025-08-27	Jail 1	Pod C.	Tristan May	6FL-SD22 S	Vertical Smoke Damper	20*8	Air Balance	Unknown	N/A	Patch	Pass	None
2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-FD2 S	Vertical Fire Damper	28*8	Unknown	Unknown	165 Degrees	7*5	Fail	No sleeve.
2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-FD1 S	Vertical Fire Damper	16" R	Air Balance	Unknown	165 Degrees	7*5	Pass	None
2025-08-27	Jail 1	Pod C.	Tristan May	6FL-SD24 S	Vertical Smoke Damper	20*8	Air Balance	Unknown	N/A	4*4	Pass	None

2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-SD7 S	Vertical Smoke Damper	16*6	Air Balance	Unknown	N/A	Open	Pass	None
2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-SD3 S	Vertical Smoke Damper	55*12	Air Balance	Unknown	N/A	10*12	Pass	None
2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-FD4 S	Vertical Fire Damper	13*6	Air Balance	Unknown	165 Degrees	7*5	Pass	No breakaway connection
2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-SD6 S	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	4*4	Pass	None
2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-SD5 S	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	6*4	Pass	None
2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-FD6 S	Vertical Fire Damper	8" R	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-SD1 S	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	7*5	Pass	None
2025-08-27	Jail 1	Room 6A1.	Tristan May	6FL-FSD2 S	Vertical Fire / Smoke Damper	14*8	Prefco Products	Unknown	165 Degrees	Open	Fail	No annular space. No Angle
2025-08-27	Jail 1	Southwest Corridor.	Tristan May	7FL-FD3 S	Vertical Fire Damper	55*12	Air Balance	Unknown	165 Degrees	10*12	Fail	No angle. No annular apace
2025-08-27	Jail 1	Pod C.	Tristan May	6FL-SD23 S	Vertical Smoke Damper	34*10	Air Balance	Unknown	N/A	Open	Pass	None
2025-09-02	Jail 1	Door 7A-B	Tristan May	7FL-SD9	Vertical Smoke Damper	6" R	Air Balance	Unknown	N/A	Remove elbow	Pass	None
2025-09-02	Jail 1	Door 7A2	Tristan May	7FL-SD17 S	Vertical Smoke Damper	28*8	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-02	Jail 1	Door 7A2	Tristan May	7FL-SD16 S	Vertical Smoke Damper	12R	Air Balance	Unknown	N/A	Patch	Pass	None

2025-09-02	Jail 1	Door 7A2	Tristan May	7FL-FD14 S	Vertical Fire Damper	28*8	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-09-02	Jail 1	Door 7A2	Tristan May	7FL-FD15 S	Vertical Fire Damper	14" R	Air Balance	Unknown	165 Degrees	12" R	Fail	Damper not in wall.
2025-09-02	Jail 1	Door 7A2	Tristan May	7FL- FD13 S	Vertical Fire Damper	48*11	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-09-02	Jail 1	Door 7A2	Tristan May	7FL- SD13 S	Vertical Smoke Damper	48*11	Air Balance	Unknown	N/A	12*12	Pass	None
2025-09-02	Jail 1	Door 7A2	Tristan May	7FL-SD12 S	Vertical Smoke Damper	6" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-02	Jail 1	Door 7J1	Tristan May	7FL-FD8 S	Vertical Fire Damper	14" R	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-09-02	Jail 1	Pod A Corridor	Tristan May	7FL-SD11 S	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	12" R	Pass	None.
2025-09-02	Jail 1	Pod A Corridor.	Tristan May	7FL-FD11 S	Vertical Fire Damper	16" R	Air Balance	Unknown	165 Degrees	12" R	Fail	Damper out of wall.
2025-09-03	Jail 1	Pod A Corridor.	Tristan May	7FL-SD15 S	Vertical Smoke Damper	14" R	Air Balance	Unknown	N/A	12" R	Pass	None
2025-09-03	Jail 1	NW Corridor.	Tristan May	7FL-FD1 N	Vertical Fire Damper	6" R	Air Balance	Unknown	165 Degrees	Flex	Pass	None
2025-09-03	Jail 1	NW Corridor.	Tristan May	7FL-SD3 N	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-03	Jail 1	NW Corridor.	Tristan May	7FL-SD2 N	Vertical Smoke Damper	12*8	Air Balance	Unknown	N/A	Open	Fail	Wall has been removed.
2025-09-03	Jail 1	A/B Psych Office.	Tristan May	7FL-SD21 S	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-03	Jail 1	Room 7J1.	Tristan May	7FL-FD12 S	Vertical Fire Damper	6" R	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-09-03	Jail 1	Pod C/D.	Tristan May	7FL-SD18 S	Vertical Smoke Damper	48*8	Air Balance	Unknown	N/A	Open	Pass	None

2025-09-03	Jail 1	NW Corridor.	Tristan May	7FL-SD4 N	Vertical Smoke Damper	54*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-04	Jail 1	In H Pod	Tristan May	7FL-SD20 N	Vertical Smoke Damper	14" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-04	Jail 1	In H Pod	Tristan May	7FL-SD19 N	Vertical Smoke Damper	6" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-04	Jail 1	NW Corridor	Tristan May	7FL-FD5 N	Vertical Fire Damper	16" R	Air Balance	Unknown	165 Degrees	12" R	Pass	None
2025-09-04	Jail 1	NW Corridor	Tristan May	7FL-SD9 N	Vertical Smoke Damper	22*8	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-04	Jail 1	NW Corridor	Tristan May	7FL-SD16 N	Vertical Smoke Damper	22*8	Air Balance	Unknown	N/A	9*6	Pass	None
2025-09-04	Jail 1	NW Corridor	Tristan May	7FL-FD8 N	Vertical Fire Damper	22*6	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-09-04	Jail 1	NW Corridor	Tristan May	7FL-FD14 N	Vertical Fire Damper	6*4	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-09-04	Jail 1	NW Corridor	Tristan May	7FL-SD12 N	Vertical Smoke Damper	6" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-04	Jail 1	In H Pod.	Tristan May	7FL-FD20 N	Vertical Fire Damper	14" R	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-09-04	Jail 1	In H Pod.	Tristan May	7FL-FD19 N	Vertical Fire Damper	6" R	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-09-04	Jail 1	NW Corridor.	Tristan May	7FL-SD5 N	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	12" R	Abandoned	Abandoned per jci
2025-09-04	Jail 1	NW Corridor.	Tristan May	7FL-SD6 N	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-04	Jail 1	NW Corridor.	Tristan May	7FL-FD7 N	Vertical Fire Damper	22*8	Air Balance	Unknown	165 Degrees	Patch	Fail	No breakaway connection

2025-09-04	Jail 1	NW Corridor.	Tristan May	7FL-SD13 N	Vertical Smoke Damper	24*10	Air Balance	Unknown	N/A	Open	Pass	None
2025-09-04	Jail 1	NW Corridor.	Tristan May	7FL-SD11 N	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-04	Jail 1	NW Corridor.	Tristan May	7FL-SD10 S	Vertical Smoke Damper	28*12	Air Balance	Unknown	N/A	Patch	Fail	Damper found closed.
2025-09-16	Jail 1	SW Corridor	Kaitlyn McElroy	8FL-SD1 S	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	12" R	Pass	None
2025-09-16	Jail 1	SW Corridor	Kaitlyn McElroy	8FL-FD2 S	Vertical Fire Damper	26*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-09-16	Jail 1	SW Corridor	Kaitlyn McElroy	8FL-FD4 S	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-09-16	Jail 1	SW Corridor	Kaitlyn McElroy	8FL-SD5 S	Vertical Smoke Damper	17" R	Air Balance	Unknown	N/A	12" R	Pass	None
2025-09-16	Jail 1	SW Corridor	Kaitlyn McElroy	8FL-FD3 S	Vertical Fire Damper	16*6	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-09-16	Jail 1	SW Corridor.	Kaitlyn McElroy	8FL-SD4 S	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-16	Jail 1	SW Corridor.	Kaitlyn McElroy	8FL-FD1 S	Vertical Fire Damper	16" R	Air Balance	Unknown	165 Degrees	12" R	Pass	None
2025-09-16	Jail 1	SW Corridor	Kaitlyn McElroy	8FL-FD5 S	Vertical Fire Damper	17" R	Air Balance	Unknown	165 Degrees	12" R	Fail	Damper out of wall
2025-09-17	Jail 1	SW Corridor	Kaitlyn McElroy	8FL-SD8 S	Vertical Smoke Damper	8" R	Ruskin	Unknown	N/A	Patch	Pass	None
2025-09-17	Jail 1	NW Corridor	Kaitlyn McElroy	8FL-SD3 N	Vertical Smoke Damper	9" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-09-17	Jail 1	NW Corridor	Kaitlyn McElroy	8FL-FD4 N	Vertical Fire Damper	26*11	Air Balance	Unknown	165 Degrees	7*5	Pass	None
2025-09-17	Jail 1	NW Corridor.	Kaitlyn McElroy	8FL-FD5 N	Vertical Fire Damper	12*6	Ruskin	ADC24	165 Degrees	8*8	Abandoned	None

2025-09-17	Jail 1	NW Corridor	Kaitlyn McElroy	8FL-FSD1 N	Vertical Fire / Smoke Damper	12*8	Prefco Products	Unknown	165 Degrees	8*8	Fail	Actuator needs replaced. Damper found closed
2025-09-17	Jail 1	NW Corridor.	Kaitlyn McElroy	8FL-SD2 N	Vertical Smoke Damper	54*12	Air Balance	Unknown	N/A	Unknown	Pass	None
2025-09-17	Jail 1	NW Corridor.	Kaitlyn McElroy	8FL-SD6 N	Vertical Smoke Damper	14*14	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-17	Jail 1	SW Corridor.	Kaitlyn McElroy	8FL-FD7 S	Vertical Fire Damper	18*12	Prefco Products	Unknown	165 Degrees	Open	Pass	None
2025-09-17	Jail 1	NW Corridor	Kaitlyn McElroy	8FL-FD1 N	Vertical Fire Damper	5" R	Unknown	Unknown	165 Degrees	Flex	Pass	None
2025-09-23	Jail 1	Outside Commissary Window	Tristan May	1FL-FD6	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	9" R	Pass	None
2025-09-23	Jail 1	Outside Commissary Window	Tristan May	1FL-SD5	Vertical Smoke Damper	12*6	Air Balance	Unknown	N/A	7*5	Pass	None
2025-09-23	Jail 1	Outside Commissary Window	Tristan May	1FL-SD7	Vertical Smoke Damper	60*15	Air Balance	Unknown	N/A	Open	Pass	None
2025-09-23	Jail 1	Offenders Hallway	Tristan May	1FL-FD8	Vertical Fire Damper	11" R	Air Balance	Unknown	165 Degrees	9" R	Pass	None
2025-09-23	Jail 1	Offenders Hallway	Tristan May	1FL-FD9	Vertical Fire Damper	10" R	Unknown	Unknown	165 Degrees	6" R	Pass	None
2025-09-23	Jail 1	Offenders Hallway	Tristan May	1FL-SD10	Vertical Smoke Damper	7" R	Air Balance	Unknown	N/A	Patch	Fail	More than 2' away from the wall
2025-09-23	Jail 1	Outside Commissary Window	Tristan May	1FL-FD7	Vertical Fire Damper	60*15	Air Balance	Unknown	165 Degrees	Open	Pass	None
2025-09-23	Jail 1	Offenders Hallway.	Tristan May	1FL-SD1	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	Patch	Fail	More than 2' away from wall

2025-09-23	Jail 1	Offenders Hallway.	Tristan May	1FL-SD8	Vertical Smoke Damper	11" R	Air Balance	Unknown	N/A	9" R	Pass	None
2025-09-23	Jail 1	Outside Commissary Window.	Tristan May	1FL-FD5	Vertical Fire Damper	12*6	Air Balance	Unknown	165 Degrees	7*5	Fail	No sleeve
2025-09-23	Jail 1	Outside Commissary Window.	Tristan May	1FL-SD6	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	9" R	Pass	None
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-SD8 S	Vertical Smoke Damper	12*8	Prefco Products	Unknown	N/A	Open	Pass	None
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-SD1 S	Vertical Smoke Damper	14" R	Air Balance	Unknown	N/A	9" R	Pass	None
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-FD19 S	Vertical Fire Damper	15" R	Unknown	Unknown	165 Degrees	Patch	Fail	Needs drywall access door. Inaccessible
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-FD7 S	Vertical Fire Damper	48*12	Air Balance	Unknown	165 Degrees	22*22	Fail	Sleeve in wall. Need drywall access door for physical inspection
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-SD3 S	Vertical Smoke Damper	28*12	Air Balance	Unknown	N/A	Open	Pass	None
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-FD20 S	Vertical Fire Damper	10" R	Unknown	Unknown	165 Degrees	10" R	Fail	Inaccessible. Need drywall AD.
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-SD7 S	Vertical Smoke Damper	48*12	Air Balance	Unknown	N/A	22*22	Pass	None
2025-10-14	Jail 1	Inside Vestibule C.	Tristan May	9FL-SD15 S	Vertical Smoke Damper	26*12	Air Balance	Unknown	N/A	Open	Pass	None

2025-10-14	Jail 1	9A Arraignment Hallway.	Tristan May	9FL-FD13 S	Vertical Fire Damper	44*12	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-10-14	Jail 1	9 South Gym.	Tristan May	9FL-FD18 S	Vertical Fire Damper	24*22	Unknown	Unknown	165 Degrees	Grille	Pass	None
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-SD9 S	Vertical Smoke Damper	12*8	Air Balance	Unknown	N/A	Open.	Pass	None
2025-10-14	Jail 1	Vestibule B	Tristan May	9FL-SD16 S	Vertical Smoke Damper	22*8	Unknown	Unknown	N/A	Patch	Fail	Damper found closed. Need JCI
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-FD2 S	Vertical Fire Damper	22*8	Air Balance	Unknwon	165 Degrees	Patch	Fail	No sleeve, no breakaway connection
2025-10-14	Jail 1	Vestibule B	Tristan May	9FL-SD17 S	Vertical Smoke Damper	22*8	Air Balance	Unknown	N/A	Patch	Fail	Damper found closed.
2025-10-14	Jail 1	Vestibule 9A.	Tristan May	9FL-SD12 S	Vertical Smoke Damper	12*8	Air Balance	Unknown	N/A	Open	Pass	None
2025-10-14	Jail 1	9A Arraignment Hallway.	Tristan May	9FL-SD13 S	Vertical Smoke Damper	44*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-SD19 S	Vertical Smoke Damper	15" R	Unknown	Unknown	N/A	Patch	Fail	Needs drywall access door. Inaccessible
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-FD1 S	Vertical Fire Damper	14" R	Air Balance	Unknown	165 Degrees	9" R	Fail	No angle no where to attach
2025-10-14	Jail 1	Southwest Corridor	Tristan May	9FL-SD20 S	Vertical Smoke Damper	10" R	Unknown	Unknown	165 Degrees	8" R	Fail	Inaccessible need drywall A/D
2025-10-15	Jail 1	North Utility Closet	Tristan May	9FL-FD3 N	Vertical Fire Damper	48*14	Air Balance	Unknown	165 Degrees	18*12	Fail	No sleeve no angle no breakaway

2025-10-15	Jail 1	Inside 9E Pod	Tristan May	9FL-SD22 N	Vertical Smoke Damper	24*12	Unknown	Unknown	N/A	Open	Pass	None
2025-10-15	Jail 1	Outside 9E	Tristan May	9FL-FD9 N	Vertical Fire Damper	12*8	Air Balance	Unknown	165 Degrees	6*9	Fail	Sleeve in wall, angle on duct not damper
2025-10-15	Jail 1	Outside 9E	Tristan May	9FL-SD21 N	Vertical Smoke Damper	14*8	Unknown	Unknown	165 Degrees	Open	Pass	None
2025-10-15	Jail 1	Outside 9E	Tristan May	9FL-FD6 N	Vertical Fire Damper	17" R	Air Balance	Unknown	165 Degrees	15" R	Pass	None
2025-10-15	Jail 1	Outside 9E	Tristan May	9FL-SD2 N	Vertical Smoke Damper	12"R	Unknown	Unknown	N/A	Patch	Pass	None
2025-10-15	Jail 1	9FL outside 9e.	Tristan May	9FL- FD1 N	Vertical Fire Damper	6" R	Air Balance	Unknown	165 Degrees	Flex	Fail	Sleeve in wall, no angle
2025-10-15	Jail 1	Northwest Restroom.	Tristan May	9FL-FD2 N	Vertical Fire Damper	12" R	Air Balance	Unknown	165 Degrees	9" R	Fail	Sleeve in wall no angle, no where to attach
2025-10-15	Jail 1	Vestibule F.	Tristan May	9FL-SD15 N	Vertical Fire Damper	22*8	Air Balance	Unknown	N/A	Patch	Pass	None
2025-10-15	Jail 1	9Fl outside 9e.	Tristan May	9FL-FD7 N	Vertical Fire Damper	22*8	Air Balance	Unknown	165 Degrees	8*8	Fail	No sleeve no breakaway
2025-10-15	Jail 1	9H Chapel Hallway.	Tristan May	9FL-SD21A N	Vertical Smoke Damper	14*8	Unknown	Unknown	N/A	Open	Pass	Next to open volume damer?
2025-10-15	Jail 1	9th floor outside 9e.	Tristan May	9FL-SD3 N	Vertical Smoke Damper	48*14	Unknown	Unknown	N/A	Patch	Pass	Actuator behind wall
2025-10-16	Jail 1	Northwest Corridor.	Tristan May	10FL-SD18 N	Vertical Smoke Damper	18*12	Unknown	Unknown	N/A	Open	Pass	None
2025-10-16	Jail 1	Northwest Corridor.	Tristan May	10FL-FD2 N	Vertical Fire Damper	5" R	Air Balance	Unknown	165 Degrees	Flex	Fail	No angle

2025-10-16	Jail 1	C/D Vestibule	Tristan May	10FL-SD13 S	Vertical Smoke Damper	8"R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-10-16	Jail 1	South Corridor	Tristan May	10FL-FD17 S	Vertical Fire Damper	18*13	Prefco Products	Unknown	165 Degrees	Open	Fail	No angle, pipes too close to install.
2025-10-16	Jail 1	Southwest Corridor	Tristan May	10FL-FD3 S	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Fail	No breakaway, no sleeve, no angle
2025-10-16	Jail 1	Southwest Corridor	Tristan May	10FL-FD4 S	Vertical Fire Damper	17"R	Air Balance	Unknown	165 Degrees	7*6	Fail	Damper out of wall
2025-10-16	Jail 1	Southwest Corridor	Tristan May	10FL-FD2 S	Vertical Fire Damper	26*12	Air Balance	Unknown	165 Degrees	8*6	Pass	None
2025-10-16	Jail 1	Southwest Corridor	Tristan May	10FL-FD1 S	Vertical Fire Damper	15"R	Air Balance	Unknown	165 Degrees	12"R	Fail	Damper out of wall
2025-10-16	Jail 1	Northwest Corridor	Tristan May	10FL-SD8 N	Vertical Smoke Damper	10*8	Prefco Products	Unknown	N/A	Patch	Pass	None
2025-10-16	Jail 1	North Utility Closet	Tristan May	10FL-FD5 N	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	6" R	Fail	No Angle. No annular space. Damper out of wall
2025-10-16	Jail 1	Southwest Corridor.	Tristan May	10FL-SD1 S	Vertical Smoke Damper	15" R	Air Balance	Unknown	N/A	12" R	Pass	None
2025-10-16	Jail 1	SW Corridor	Tristan May	10FL-FSD1 S	Vertical Fire / Smoke Damper	10*8	Prefco Products	Unknown	165 Degrees	10*8	Pass	None
2025-10-16	Jail 1	Sw Corridor	Tristan May	10FL-SD3 S	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	16*4	Pass	None
2025-10-16	Jail 1	C/D Vestibule	Tristan May	10FL-SD14 S	Vertical Smoke Damper	22*8	Air Balance	Unknown	N/A	Patch	Pass	None

2025-10-16	Jail 1	NW Corridor	Tristan May	10FL-SD1 N	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	8*8	Pass	None
2025-10-16	Jail 1	NW Corridor	Tristan May	10FL-SD3 N	Vertical Smoke Damper	54*12	Air Balance	Unknown	N/A	17*11	Pass	None
2025-10-16	Jail 1	NW Corridor	Tristan May	10FL-FD7 N	Vertical Fire Damper	26*11	Air Balance	Unknown	165 Degrees	12*12	Fail	No breakaway connection.
2025-10-16	Jail 1	North Utility Closet	Tristan May	10FL-FD6 N	Vertical Fire Damper	54*12	Air Balance	Unknown	165 Degrees	12*12	Fail	No angle. No sleeve. No breakaway connection
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 8FL SD1	Vertical Smoke Damper	15"R	Air Balance	Unknown	N/A	12"R	Fail	Labeled as fail from prior inspection
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 8FL FD2	Vertical Fire Damper	30*10	Air Balance	Unknown	165 Degrees	12*12	Pass	No breakaway connection, no sleeve
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 8FL FD3	Vertical Fire Damper	48*12	Air Balance	Unknown	165 Degrees	Open	Pass	None
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 8FL FD4	Vertical Fire Damper	9"R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 8FL SD3	Vertical Smoke Damper	9"R	Air Balance	Unknown	N/A	6"R	Pass	None
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 8FL FD5	Vertical Fire Damper	15" R	Air Balance	Unknown	165 Degrees	9*6	Fail	No sleeve, angle in duct.
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 8FL FD1	Vertical Fire Damper	15"R	Air Balance	Unknown	165 Degrees	12"R	Pass	None
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 6FL FD3	Vertical Fire Damper	60*14	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 6FL SD3	Vertical Fire Damper	60*14	Air Balance	Unknown	N/A	12*12	Pass	None

2025-10-20	Jail 1	North Stairwell	Tristan May	NS 6FL FSD2	Vertical Fire / Smoke Damper	36*10	Prefco Products	Unknown	165 Degrees	10*10	Pass	None
2025-10-20	Jail 1	North Stairwell	Tristan May	NS 6FL SD4	Vertical Smoke Damper	15" R	Air Balance	Unknown	N/A	12" R	Pass	None
2025-10-20	Jail 1	E Vestibule	Tristan May	10FL-SD14 N	Vertical Smoke Damper	8*8	Prefco Products	Unknown	N/A	Patch	Pass	Damper found closed
2025-10-20	Jail 1	E Vestibule	Tristan May	10F-SD9 N	Vertical Smoke Damper	22*8	Air Balance	Unknown	N/A	10*10	Pass	None
2025-10-21	Jail 1	South Stairwell	Tristan May	SS 8FL SD3	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	6"R	Pass	None
2025-10-21	Jail 1	South Stairwell	Tristan May	SS 8FL FD3	Vertical Fire Damper	8"R	Air Balance	Unknown	165 Degrees	6R	Fail	No angle no sleeve
2025-10-21	Jail 1	South Stairwell	Tristan May	SS 8FL FD2	Vertical Fire Damper	30*10	Unknown	Unknown	165 Degrees	12*12	Fail	No breakaway
2025-10-21	Jail 1	South Stairwell	Tristan May	SS 8FL FD1	Vertical Fire Damper	14"R	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-10-21	Jail 1	South stairwell	Tristan May	SS 8FL SD1	Vertical Smoke Damper	14" R	Air Balance	Unknown	N/A	12*12	Pass	None
2025-10-21	Jail 1	South Stairwell	Tristan May	SS 8FL SD4	Vertical Smoke Damper	48*12	Air Balance	Unknown	N/A	20*10	Pass	None
2025-10-21	Jail 1	South Stairwell	Tristan May	SS 8FL FD5	Vertical Fire Damper	15" R	Air Balance	Unknown	165 Degrees	12" R	Fail	No angle, no access
2025-10-21	Jail 1	South Stairwell	Tristan May	SS 8FL FD4	Vertical Fire Damper	48*12	Air Balance	Unknown	165 Degrees	20*10	Pass	None
2025-10-21	Jail 1	South Stairwell	Tristan May	SS 8FL SD5	Vertical Smoke Damper	15" R	Air Balance	Unknown	165 Degrees	12" R	Pass	None
2025-10-22	Jail 1	South stairwell	Tristan May	SS 10FL SD3	Vertical Smoke Damper	48*12	Air Balance	Unknown	N/A	20*10	Pass	None

2025-10-22	Jail 1	South stairwell	Tristan May	SS 10Fl FD4	Vertical Fire Damper	15R	Air Balance	Unknown	165 Degrees	6*6	Fail	Damper not in wall, no access
2025-10-22	Jail 1	Vending.	Tristan May	4FL-SD16 S	Vertical Smoke Damper	44*12	Air Balance	Unknown	N/A	Open	Abandoned	Abandoned per JCI, prior report. Actuator on the other side of wall.
2025-10-22	Jail 1	ID unit	Tristan May	3FL-SD2 S	Vertical Fire Damper	16*8	Air Balance	Unknown	N/A	7*5	Pass	None
2025-10-22	Jail 1	Sherrif records hallway.	Tristan May	3FL-FD1	Vertical Smoke Damper	10R	Air Balance	Unknown	N/A	9R	Pass	None
2025-10-22	Jail 1	South Stairwell	Tristan May	SS 10FL SD1	Vertical Smoke Damper	14" R	Air Balance	Unknown	N/A	12" R	Pass	None
2025-10-22	Jail 1	South Stairwell	Tristan May	SS 10FL FD2	Vertical Fire Damper	30*10	Unknown	Unknown	165 Degrees	12*12	Fail	No annular space
2025-10-22	Jail 1	South Stairwell	Tristan May	SS 10FL FD3	Vertical Fire Damper	48*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-10-30	Jail 1	Southwest Corridor	Tristan May	8FL-SD16 S	Vertical Smoke Damper	48*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-10-30	Jail 1	In H Pod.	Tristan May	7FL-FD21 N	Vertical Fire Damper	48*12	Air Balance	Unknown	165 Degrees	12*12	Fail	No angle, no annular space, no breakaway connection, no sleeve
2025-10-30	Jail 1	In H Pod.	Tristan May	7FL-FD24 N	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	9" R	Fail	No sleeve
2025-10-30	Jail 1	In H Pod.	Tristan May	7FL-FD23 N	Vertical Fire Damper	30*8	Air Balance	Unknown	165 Degrees	Patch	Fail	No angle, no annular space, no breakaway, no sleeve

2025-10-30	Jail 1	NW Corridor.	Tristan May	7FL-SD15 N	Vertical Smoke Damper	22*12	Air Balance	Unknown	N/A	10*10	Pass	None
2025-10-30	Jail 1	In H Pod.	Tristan May	7FL-SD22 N	Vertical Smoke Damper	26*12	Air Balance	Unknown	N/A	Open	Pass	None
2025-10-30	Jail 1	Northeast Corridor.	Tristan May	8FL-SD10 N	Vertical Smoke Damper	54*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-10-30	Jail 1	SW Corridor.	Tristan May	8FL-SD6 S	Vertical Smoke Damper	18*18	Air Balance	Unknown	N/A	Patch	Pass	None
2025-10-30	Jail 1	Northeast Corridor.	Tristan May	8FL-SD17 N	Vertical Smoke Damper	15" R	Prefco Products	Unknown	N/A	Patch	Pass	None
2025-10-30	Jail 1	Northeast Corridor.	Tristan May	8FL-SD16 N	Vertical Smoke Damper	10*10	Air Balance	Unknown	N/A	8*6	Pass	None
2025-10-30	Jail 1	Room 8K1.	Tristan May	8FL-FD7 N	Vertical Fire Damper	18*12	Ruskin	IBD20	165 Degrees	Open	Pass	None
2025-10-30	Jail 1	Room 811.	Tristan May	8FL-SD21 N	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-10-30	Jail 1	Room 811.	Kaitlyn McElroy	8FL-FD22 N	Vertical Fire Damper	54*12	Air Balance	12*10	165 Degrees	12*10	Pass	None
2025-10-30	Jail 1	Vestibule E/F.	Kaitlyn McElroy	8FL-SD8 N	Vertical Smoke Damper	22*8	Air Balance	Unknown	N/A	Patch	Pass	Damper found closed
2025-10-30	Jail 1	Vestibule E/F.	Kaitlyn McElroy	8FL-SD11 N	Vertical Smoke Damper	24*12	Air Balance	Unknown	N/A	Open	Pass	None
2025-10-30	Jail 1	Vestibule E/F.	Kaitlyn McElroy	8FL-SD12 N	Vertical Smoke Damper	22*8	Air Balance	Unknown	N/A	10*10	Pass	None
2025-10-30	Jail 1	Vestibule E/F.	Kaitlyn McElroy	8FL-SD13 N	Vertical Smoke Damper	10" R	Air Balance	Unknown	N/A	Patch	Fail	Damper more than 2' away from fire rated wall

2025-10-30	Jail 1	Vestibule E/F.	Kaitlyn McElroy	8FL-SD9 N	Vertical Smoke Damper	24*12	Air Balance	Unknown	N/A	Open	Pass	Damper found closed
2025-10-30	Jail 1	Room 7J7	Tristan May	7FL-FD23 S	Vertical Fire Damper	24*21	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-10-30	Jail 1	Southwest Corridor	Tristan May	7FL-SD23 S	Vertical Smoke Damper	28*8	Air Balance	Unknown	N/A	Open	Pass	None
2025-10-30	Jail 1	In H Pod	Tristan May	7FL-SD24 N	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	9" R	Pass	None
2025-10-30	Jail 1	In H Pod	Tristan May	7FL-SD23 N	Vertical Smoke Damper	30*8	Air Balance	Unknown	N/A	Patch	Pass	None
2025-10-30	Jail 1	In H Pod	Tristan May	7FL-SD21 N	Vertical Smoke Damper	48*12	Air Balance	Unknown	N/A	12*12	Pass	None
2025-10-30	Jail 1	F Pod	Tristan May	7FL-SD29 N	Vertical Smoke Damper	28*12	Unknown	Unknown	N/A	Open	Pass	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Outside Commissary Window

Inspector Name
Tristan May

Damper I.D. #
1FL-FD5

Damper Type
Vertical Fire Damper

Damper Size
12*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*5

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Outside Commissary Window

Inspector Name
Tristan May

Damper I.D. #
1FL-FD6

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Outside Commissary Window

Inspector Name
Tristan May

Damper I.D. #
1FL-FD7

Damper Type
Vertical Fire Damper

Damper Size
60*15

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Offenders Hallway

Inspector Name
Tristan May

Damper I.D. #
1FL-FD8

Damper Type
Vertical Fire Damper

Damper Size
11" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Offenders Hallway

Inspector Name
Tristan May

Damper I.D. #
1FL-FD9

Damper Type
Vertical Fire Damper

Damper Size
10" R

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Outside Commissary Window

Inspector Name
Tristan May

Damper I.D.
1FL-SD5

Damper Type
Vertical Smoke Damper

Damper Size
12*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
7*5

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Outside Commissary Window

Inspector Name
Tristan May

Damper I.D. #
1FL-SD6

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Outside Commissary Window

Inspector Name
Tristan May

Damper I.D. #
1FL-SD7

Damper Type
Vertical Smoke Damper

Damper Size
60*15

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Offenders Hallway

Inspector Name
Tristan May

Damper I.D. #
1FL-SD8

Damper Type
Vertical Smoke Damper

Damper Size
11" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Offenders Hallway

Inspector Name
Tristan May

Damper I.D.
1FL-SD10

Damper Type
Vertical Smoke Damper

Damper Size
7" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
More than 2' away from the wall

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Jail 1

Damper Location
Offenders Hallway

Inspector Name
Tristan May

Damper I.D. #
1FL-SD11

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
More than 2' away from wall

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-20

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
3EF-2

Damper Type
Vertical Fire Damper

Damper Size
22*34

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle, no sleeve. No access bottom of duct, 1.25" angle left side, 2*2 rest.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room

Inspector Name
Tristan May

Damper I.D.
3EF-3

Damper Type
Vertical Fire Damper

Damper Size
20*24

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wall not complete, no access to back, no room for external damper, not secured in wall, incomplete angle, no room for more angle

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D. #
3EF-4

Damper Type
Vertical Fire Damper

Damper Size
58*40

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no access to back

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
3EF-5

Damper Type
Vertical Fire Damper

Damper Size
24*24

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, damper not secured in wall.
Incomplete wall, no access to back

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
Storage Closet in F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-FD1 N

Damper Type
Vertical Fire Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No wall between dampers

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Jail 1

Damper Location
Sherrif Records Hallway

Inspector Name
Tristan May

Damper I.D. #
3FL-FD1 S

Damper Type
Vertical Smoke Damper

Damper Size
10” R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
9” R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
Storage Closet in F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-FD2 N

Damper Type
Vertical Fire Damper

Damper Size
9*5

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
Storage Closet in F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-FD3 N

Damper Type
Vertical Fire Damper

Damper Size
10*4

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No wall between dampers

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
Storage Closet in F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-FD4 N

Damper Type
Vertical Fire Damper

Damper Size
48*15

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
Storage Closet in F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-FD5 N

Damper Type
Vertical Fire Damper

Damper Size
16*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-FD6 N

Damper Type
Vertical Fire Damper

Damper Size
9" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
NE Corridor 120 Holding.

Inspector Name
Tristan May

Damper I.D.
3FL-FD8 N

Damper Type
Vertical Fire Damper

Damper Size
36*15

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-FD9 N

Damper Type
Vertical Fire Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle. No Sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
NE Corridor 120 Holding

Inspector Name
Tristan May

Damper I.D. #
3FL-FD10 N

Damper Type
Vertical Fire Damper

Damper Size
26*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
5*7

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
NE Corridor 120 Holding

Inspector Name
Tristan May

Damper I.D. #
3FL-FD11 N

Damper Type
Vertical Fire Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper out of wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-FSD1 N

Damper Type
Vertical Fire / Smoke Damper

Damper Size
16*12

Damper Manufacturer
Ruskin

Damper Model #
FSD36

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-FSD2 N

Damper Type
Vertical Fire / Smoke Damper

Damper Size
16" R

Damper Manufacturer
Ruskin

Damper Model #
FSDR26

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Jail 1

Damper Location
ID Unit

Inspector Name
Tristan May

Damper I.D.
3FL-SD2 S

Damper Type
Vertical Fire Damper

Damper Size
16*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
7*5

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
Storage Closet in F/G Vestibule

Inspector Name
Tristan May

Damper I.D. #
3FL-SD4 N

Damper Type
Vertical Smoke Damper

Damper Size
48*15

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
F/G Vestibule

Inspector Name
Tristan May

Damper I.D.
3FL-SD6 N

Damper Type
Vertical Smoke Damper

Damper Size
9" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
NE Corridor 120 Holding

Inspector Name
Tristan May

Damper I.D. #
3FL-SD8 N

Damper Type
Vertical Smoke Damper

Damper Size
36*15

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
NE Corridor 120 Holding

Inspector Name
Tristan May

Damper I.D. #
3FL-SD11 N

Damper Type
Vertical Smoke Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-20

Facility Location
Jail 1

Damper Location
NE Corridor 120 Holding

Inspector Name
Tristan May

Damper I.D. #
3FL-SD13 N

Damper Type
Vertical Smoke Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4FL Bridge to Jail 2.

Inspector Name
Tristan May

Damper I.D. #
4FL-FD1 S

Damper Type
Vertical Fire Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle. No Sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4FL NW Corridor.

Inspector Name
Tristan May

Damper I.D.
4FL-FD2 N

Damper Type
Vertical Fire Damper

Damper Size
9" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle. No Sleeve

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4FL Bridge to Jail 2.

Inspector Name
Tristan May

Damper I.D. #
4FL-FD2 S

Damper Type
Vertical Fire Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4FL NW Corridor.

Inspector Name
Tristan May

Damper I.D. #
4FL-FD3 N

Damper Type
Vertical Fire Damper

Damper Size
14*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-24

Facility Location
Jail 1

Damper Location
4FL Bridge to Jail 2.

Inspector Name
Tristan May

Damper I.D.
4FL-FD3 S

Damper Type
Vertical Fire Damper

Damper Size
15*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*6

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Sleeve.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4FL NW Hallway.

Inspector Name
Tristan May

Damper I.D.
4FL-FD4 N

Damper Type
Vertical Fire Damper

Damper Size
14*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Sleeve.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-24

Facility Location
Jail 1

Damper Location
4FL Bridge to Jail 2.

Inspector Name
Tristan May

Damper I.D.
4FL-FD4 S

Damper Type
Vertical Fire Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Sleeve.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4FL NW Hallway Women's Bathroom.

Inspector Name
Tristan May

Damper I.D.
4FL-FD5 N

Damper Type
Vertical Fire Damper

Damper Size
18" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12x R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle. Sleeve in wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
Bridge to Jail 2

Inspector Name
Tristan May

Damper I.D.
4FL-FD5 S

Damper Type
Vertical Fire Damper

Damper Size
17" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Inaccessible. Conduit in way, would need to crawl on top of ductwork

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
Commissary Storage Closet

Inspector Name
Tristan May

Damper I.D. #
4FL-FD6 N

Damper Type
Vertical Fire Damper

Damper Size
42*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
SW Corridor by Release Desk

Inspector Name
Tristan May

Damper I.D. #
4FL-FD7 S

Damper Type
Vertical Fire Damper

Damper Size
38*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
13*9

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
SW Corridor by Release Desk

Inspector Name
Tristan May

Damper I.D.
4FL-FD8 S

Damper Type
Vertical Fire Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
SW Corridor by Release Desk

Inspector Name
Tristan May

Damper I.D.
4FL-FD9 S

Damper Type
Vertical Fire Damper

Damper Size
34*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
SW Corridor by Release Desk

Inspector Name
Tristan May

Damper I.D.
4FL-FD11 S

Damper Type
Vertical Fire Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Jail 1

Damper Location
SW Corridor by Release Desk

Inspector Name
Tristan May

Damper I.D.
4FL-SD15 S

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
4*4

Pass / Fail / Abandoned
Fail

Comments / Corrections
More than 2' from fire rated wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
NW Hallway, Outside Employee Bathroom.

Inspector Name
Tristan May

Damper I.D.
4FL-SD1 N

Damper Type
Vertical Smoke Damper

Damper Size
42*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4FL Bridge to Jail 2.

Inspector Name
Tristan May

Damper I.D.
4FL-SD1 S

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
NW Corridor.

Inspector Name
Tristan May

Damper I.D. #
4FL-SD2 N

Damper Type
Vertical Smoke Damper

Damper Size
9" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4 FL NW Hallway.

Inspector Name
Tristan May

Damper I.D.
4FL-SD3 N

Damper Type
Vertical Smoke Damper

Damper Size
14*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-24

Facility Location
Jail 1

Damper Location
4FL Bridge to Jail 2.

Inspector Name
Tristan May

Damper I.D. #
4FL-SD3 S

Damper Type
Vertical Smoke Damper

Damper Size
15*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4FL NW Hallway.

Inspector Name
Tristan May

Damper I.D.
4FL-SD4 N

Damper Type
Vertical Smoke Damper

Damper Size
14*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-24

Facility Location
Jail 1

Damper Location
4FL Bridge to Jail 2.

Inspector Name
Tristan May

Damper I.D.
4FL-SD4 S

Damper Type
Vertical Smoke Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
4FL NW Hallway Women's Restroom.

Inspector Name
Tristan May

Damper I.D.
4FL-SD5 N

Damper Type
Vertical Smoke Damper

Damper Size
18" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
Old Commissary Storage Closet

Inspector Name
Tristan May

Damper I.D. #
4FL-SD6 N

Damper Type
Vertical Smoke Damper

Damper Size
42*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
Commissary Storage Closet.

Inspector Name
Tristan May

Damper I.D. #
4FL-SD9 N

Damper Type
Vertical Smoke Damper

Damper Size
40*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
SW Corridor by Release Desk

Inspector Name
Tristan May

Damper I.D.
4FL-SD9 S

Damper Type
Vertical Smoke Damper

Damper Size
34*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 1

Damper Location
SW Corridor by Release Desk

Inspector Name
Tristan May

Damper I.D.
4FL-SD10 S

Damper Type
Vertical Smoke Damper

Damper Size
32*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Abandoned per JCI. Passes visual inspection.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Jail 1

Damper Location
SW Corridor by Release Desk.

Inspector Name
Tristan May

Damper I.D.
4FL-SD12 S

Damper Type
Vertical Smoke Damper

Damper Size
14*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Abandoned per JCI. Passed visual inspection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Jail 1

Damper Location
Vending

Inspector Name
Tristan May

Damper I.D. #
4FL-SD16 S

Damper Type
Vertical Smoke Damper

Damper Size
44*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Abandoned

Comments / Corrections
Abandoned per JCI on prior report.
Actuator on the other side of wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor.

Inspector Name
Tristan May

Damper I.D.
6FL-FD1 N

Damper Type
Vertical Fire Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Flex

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-FD2 N

Damper Type
Vertical Fire Damper

Damper Size
20*16

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor.

Inspector Name
Tristan May

Damper I.D.
6FL-FD3 N

Damper Type
Vertical Fire Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle. No breakaway connection.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-FD4 S

Damper Type
Vertical Fire Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper out of wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-FD5 N

Damper Type
Vertical Fire Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-FD5 S

Damper Type
Vertical Fire Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Angle is attached to duct work not damper sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-FD6 N

Damper Type
Vertical Fire Damper

Damper Size
32*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-FD6 S

Damper Type
Vertical Fire Damper

Damper Size
16*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space. Improper installation of angle. No space between dampers.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-FD7 N

Damper Type
Vertical Fire Damper

Damper Size
10*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection. Sleeve in wall

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-FD7 S

Damper Type
Vertical Fire Damper

Damper Size
26*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection. Not enough space between dampers. Improper installation of angle.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-FD11 S

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space. No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-FD12 S

Damper Type
Vertical Fire Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle. Damper out of wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-FD14 S

Damper Type
Vertical Fire Damper

Damper Size
20" R

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Inaccessible. Conduit and light block access.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-FD17 S

Damper Type
Vertical Fire Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
South Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-FD21 S

Damper Type
Vertical Fire Damper

Damper Size
12" R

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
NW Room 616

Inspector Name
Tristan May

Damper I.D. #
6FL-FSD1 N

Damper Type
Vertical Fire / Smoke Damper

Damper Size
20*16

Damper Manufacturer
Ruskin

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Outside of 6C1 Pod

Inspector Name
Tristan May

Damper I.D.
6FL-FSD1 S

Damper Type
Vertical Fire / Smoke Damper

Damper Size
8*8

Damper Manufacturer
Prefco Products

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
Need access door. No angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
Room 6A1

Inspector Name
Tristan May

Damper I.D. #
6FL-FSD2 S

Damper Type
Vertical Fire / Smoke Damper

Damper Size
14*8

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space. No angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Outside of Office 6A1

Inspector Name
Tristan May

Damper I.D. #
6FL-SD1 S

Damper Type
Vertical Smoke Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Outside of 6A1

Inspector Name
Tristan May

Damper I.D. #
6FL-SD2 S

Damper Type
Vertical Smoke Damper

Damper Size
14*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD3 N

Damper Type
Vertical Smoke Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-SD3 S

Damper Type
Vertical Smoke Damper

Damper Size
18*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
More than 2' away from fire rated wall.
Found in closed position.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD4 N

Damper Type
Vertical Smoke Damper

Damper Size
9" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD5 N

Damper Type
Vertical Smoke Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD5 S

Damper Type
Vertical Smoke Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-SD8 N

Damper Type
Vertical Smoke Damper

Damper Size
6" R

Damper Manufacturer
Prefco Products

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Room 6A1

Inspector Name
Tristan May

Damper I.D. #
6FL-SD8 S

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD9 N

Damper Type
Vertical Smoke Damper

Damper Size
14" R

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Room 6A1-5

Inspector Name
Tristan May

Damper I.D. #
6FL-SD9 S

Damper Type
Vertical Smoke Damper

Damper Size
18*8

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD10 N

Damper Type
Vertical Smoke Damper

Damper Size
18*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
More than 2' from fire rated wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-25

Facility Location
Jail 1

Damper Location
Inside 6A1

Inspector Name
Tristan May

Damper I.D. #
6FL-SD10 S

Damper Type
Vertical Smoke Damper

Damper Size
18*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD11 N

Damper Type
Vertical Smoke Damper

Damper Size
30*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-SD11 S

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-SD12 N

Damper Type
Vertical Smoke Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southeast Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD12 S

Damper Type
Vertical Smoke Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD13 S

Damper Type
Vertical Smoke Damper

Damper Size
28*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
14*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
Vestibule E/F

Inspector Name
Tristan May

Damper I.D. #
6FL-SD14 N

Damper Type
Vertical Smoke Damper

Damper Size
24*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD14 S

Damper Type
Vertical Smoke Damper

Damper Size
18" R

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
3*4

Pass / Fail / Abandoned
Pass

Comments / Corrections
Pass

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD15 N

Damper Type
Vertical Smoke Damper

Damper Size
24*10

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southwest Corridor.

Inspector Name
Tristan May

Damper I.D.
6FL-SD15 S

Damper Type
Vertical Smoke Damper

Damper Size
28*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
4*4 patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD16 N

Damper Type
Vertical Smoke Damper

Damper Size
8*8

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD16 S

Damper Type
Vertical Smoke Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD17 N

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Unknown

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-SD17 S

Damper Type
Vertical Smoke Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-21

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD18 N

Damper Type
Vertical Smoke Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD18 S

Damper Type
Vertical Smoke Damper

Damper Size
38*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
7*7

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D.
6FL-SD19 S

Damper Type
Vertical Smoke Damper

Damper Size
14*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-26

Facility Location
Jail 1

Damper Location
South Corridor

Inspector Name
Tristan May

Damper I.D. #
6FL-SD20 S

Damper Type
Vertical Smoke Damper

Damper Size
34*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Damper found closed.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
Pod C

Inspector Name
Tristan May

Damper I.D. #
6FL-SD22 S

Damper Type
Vertical Smoke Damper

Damper Size
20*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
Pod C

Inspector Name
Tristan May

Damper I.D. #
6FL-SD23 S

Damper Type
Vertical Smoke Damper

Damper Size
34*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
Pod C

Inspector Name
Tristan May

Damper I.D. #
6FL-SD24 S

Damper Type
Vertical Smoke Damper

Damper Size
20*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
4*4

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7A2

Inspector Name
Tristan May

Damper I.D.
7FL-FD13 S

Damper Type
Vertical Fire Damper

Damper Size
48*11

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7A2

Inspector Name
Tristan May

Damper I.D. #
7FL- SD13 S

Damper Type
Vertical Smoke Damper

Damper Size
48*11

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD1 N

Damper Type
Vertical Fire Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Flex

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD1 S

Damper Type
Vertical Fire Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*5

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D.
7FL-FD2 S

Damper Type
Vertical Fire Damper

Damper Size
28*8

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*5

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD3 S

Damper Type
Vertical Fire Damper

Damper Size
55*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle. No annular space.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD4 S

Damper Type
Vertical Fire Damper

Damper Size
13*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*5

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD5 N

Damper Type
Vertical Fire Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD6 S

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD7 N

Damper Type
Vertical Fire Damper

Damper Size
22*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD8 N

Damper Type
Vertical Fire Damper

Damper Size
22*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7J1

Inspector Name
Tristan May

Damper I.D.
7FL-FD8 S

Damper Type
Vertical Fire Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Pod A Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD11 S

Damper Type
Vertical Fire Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper out of wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Room 7J1

Inspector Name
Tristan May

Damper I.D.
7FL-FD12 S

Damper Type
Vertical Fire Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-FD14 N

Damper Type
Vertical Fire Damper

Damper Size
6*4

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7A2

Inspector Name
Tristan May

Damper I.D. #
7FL-FD14 S

Damper Type
Vertical Fire Damper

Damper Size
28*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7A2

Inspector Name
Tristan May

Damper I.D.
7FL-FD15 S

Damper Type
Vertical Fire Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
Inside H Pod

Inspector Name
Tristan May

Damper I.D. #
7FL-FD19 N

Damper Type
Vertical Fire Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
Inside H Pod

Inspector Name
Tristan May

Damper I.D. #
7FL-FD20 N

Damper Type
Vertical Fire Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
In H Pod

Inspector Name
Tristan May

Damper I.D.
7FL-FD21 N

Damper Type
Vertical Fire Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no annular space, no breakaway connection, no sleeve.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
In H Pod

Inspector Name
Tristan May

Damper I.D. #
7FL-FD23 N

Damper Type
Vertical Fire Damper

Damper Size
30*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no annular space, no breakaway, no sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Room 7J7

Inspector Name
Tristan May

Damper I.D.
7FL-FD23 S

Damper Type
Vertical Fire Damper

Damper Size
24*21

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
In H Pod

Inspector Name
Tristan May

Damper I.D. #
7FL-FD24 N

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD1 S

Damper Type
Vertical Smoke Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD2 N

Damper Type
Vertical Smoke Damper

Damper Size
12*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wall has been removed.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D.
7FL-SD3 N

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD3 S

Damper Type
Vertical Smoke Damper

Damper Size
55*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
10*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD4 N

Damper Type
Vertical Smoke Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD5 N

Damper Type
Vertical Smoke Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Abandoned

Comments / Corrections
Abandoned per JCI.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D.
7FL-SD5 S

Damper Type
Vertical Smoke Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6*4

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D.
7FL-SD6 N

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D.
7FL-SD6 S

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
4*4

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-27

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD7 S

Damper Type
Vertical Smoke Damper

Damper Size
16*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D.
7FL-SD9 N

Damper Type
Vertical Smoke Damper

Damper Size
22*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7A-B

Inspector Name
Tristan May

Damper I.D.
7FL-SD9 S

Damper Type
Vertical Smoke Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Remove elbow

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD10 N

Damper Type
Vertical Smoke Damper

Damper Size
28*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper found closed.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD11 N

Damper Type
Vertical Smoke Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Pod A Corridor

Inspector Name
Tristan May

Damper I.D.
7FL-SD11 S

Damper Type
Vertical Smoke Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD12 N

Damper Type
Vertical Smoke Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7A2

Inspector Name
Tristan May

Damper I.D.
7FL-SD12 S

Damper Type
Vertical Smoke Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D.
7FL-SD13 N

Damper Type
Vertical Smoke Damper

Damper Size
24*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7A2

Inspector Name
Tristan May

Damper I.D. #
7FL-SD13 S

Damper Type
Vertical Smoke Damper

Damper Size
48*11

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD15 N

Damper Type
Vertical Smoke Damper

Damper Size
22*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Jail 1

Damper Location
Pod A Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD15 S

Damper Type
Vertical Smoke Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
7FL-SD16 N

Damper Type
Vertical Smoke Damper

Damper Size
22*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
9*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7A2

Inspector Name
Tristan May

Damper I.D. #
7FL-SD16 S

Damper Type
Vertical Smoke Damper

Damper Size
12R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-02

Facility Location
Jail 1

Damper Location
Door 7A2

Inspector Name
Tristan May

Damper I.D.
7FL-SD17 S

Damper Type
Vertical Smoke Damper

Damper Size
28*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Jail 1

Damper Location
Pod C/D

Inspector Name
Tristan May

Damper I.D. #
7FL-SD18 S

Damper Type
Vertical Smoke Damper

Damper Size
48*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
In H Pod

Inspector Name
Tristan May

Damper I.D.
7FL-SD19 N

Damper Type
Vertical Smoke Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-04

Facility Location
Jail 1

Damper Location
In H Pod

Inspector Name
Tristan May

Damper I.D.
7FL-SD20 N

Damper Type
Vertical Smoke Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
In H Pod

Inspector Name
Tristan May

Damper I.D. #
7FL-SD21 N

Damper Type
Vertical Smoke Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Jail 1

Damper Location
A/B Psych Office

Inspector Name
Tristan May

Damper I.D.
7FL-SD21 S

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
In H Pod

Inspector Name
Tristan May

Damper I.D. #
7FL-SD22 N

Damper Type
Vertical Smoke Damper

Damper Size
26*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
In H Pod

Inspector Name
Tristan May

Damper I.D.
7FL-SD23 N

Damper Type
Vertical Smoke Damper

Damper Size
30*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D.
7FL-SD23 S

Damper Type
Vertical Smoke Damper

Damper Size
28*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
In H Pod

Inspector Name
Tristan May

Damper I.D.
7FL-SD24 N

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
F Pod

Inspector Name
Tristan May

Damper I.D. #
7FL-SD29 N

Damper Type
Vertical Smoke Damper

Damper Size
28*12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-FD1 S

Damper Type
Vertical Fire Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-FD2 S

Damper Type
Vertical Fire Damper

Damper Size
26*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D.
8FL-FD3 S

Damper Type
Vertical Fire Damper

Damper Size
16*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-17

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D.
8FL-FD4 N

Damper Type
Vertical Fire Damper

Damper Size
26*11

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*5

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-FD4 S

Damper Type
Vertical Fire Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-17

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-FD5 N

Damper Type
Vertical Fire Damper

Damper Size
12*6

Damper Manufacturer
Ruskin

Damper Model #
ADC24

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Abandoned

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-FD5 S

Damper Type
Vertical Fire Damper

Damper Size
17" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper out of wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Room 8K1

Inspector Name
Tristan May

Damper I.D.
8FL-FD7 N

Damper Type
Vertical Fire Damper

Damper Size
18*12

Damper Manufacturer
Ruskin

Damper Model
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Room 811

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-FD21 N

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Room 811

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-FD22 N

Damper Type
Vertical Fire Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model #
12*10

Fusible Link Temperature
165 Degrees

Access Door Size
12*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-17

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D.
8FL-FSD1 N

Damper Type
Vertical Fire / Smoke Damper

Damper Size
12*8

Damper Manufacturer
Prefco Products

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper found closed, actuator needs replaced.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D.
8FL-SD1 S

Damper Type
Vertical Smoke Damper

Damper Size
16" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-17

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-SD2 N

Damper Type
Vertical Smoke Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Unknown

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-17

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-SD3 N

Damper Type
Vertical Smoke Damper

Damper Size
9" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-SD4 S

Damper Type
Vertical Smoke Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-SD5 S

Damper Type
Vertical Smoke Damper

Damper Size
17" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-17

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D.
8FL-SD6 N

Damper Type
Vertical Smoke Damper

Damper Size
14*14

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D.
8FL-SD6 S

Damper Type
Vertical Smoke Damper

Damper Size
18*18

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Vestibule E/F

Inspector Name
Kaitlyn McElroy

Damper I.D.
8FL-SD8 N

Damper Type
Vertical Smoke Damper

Damper Size
22*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Damper found closed.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-17

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-SD8 S

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Ruskin

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Vestibule E/F

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-SD9 N

Damper Type
Vertical Smoke Damper

Damper Size
24*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Damper found closed

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
NE Corridor

Inspector Name
Tristan May

Damper I.D.
8FL-SD10 N

Damper Type
Vertical Smoke Damper

Damper Size
54*12

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Vestibule E/F

Inspector Name
Kaitlyn McElroy

Damper I.D.
8FL-SD11 N

Damper Type
Vertical Smoke Damper

Damper Size
24*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Vestibule E/F

Inspector Name
Kaitlyn McElroy

Damper I.D. #
8FL-SD12 N

Damper Type
Vertical Smoke Damper

Damper Size
22*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Vestibule E/F

Inspector Name
Kaitlyn McElroy

Damper I.D.
8FL-SD13 N

Damper Type
Vertical Smoke Damper

Damper Size
10" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper more than 2' away from fire rated wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
NE Corridor

Inspector Name
Tristan May

Damper I.D.
8FL-SD16 N

Damper Type
Vertical Smoke Damper

Damper Size
10*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
8FL-SD16 S

Damper Type
Vertical Smoke Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
NE Corridor

Inspector Name
Tristan May

Damper I.D. #
8FL-SD17 N

Damper Type
Vertical Smoke Damper

Damper Size
15" R

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-30

Facility Location
Jail 1

Damper Location
Room 811

Inspector Name
Tristan May

Damper I.D. #
8FL-SD21 N

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
Outside 9E

Inspector Name
Tristan May

Damper I.D.
9FL-FD1 N

Damper Type
Vertical Fire Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Flex

Pass / Fail / Abandoned
Fail

Comments / Corrections
Sleeve in wall, no angle.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Justice Center Court Towers

Damper Location
Outside 9E

Inspector Name
Tristan May

Damper I.D.
9FL-SD6 N

Damper Type
Vertical Fire Damper

Damper Size
17" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
15" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper out of wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Justice Center Court Towers

Damper Location
Outside 9E

Inspector Name
Tristan May

Damper I.D.
9FL-SD9 N

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
North Utility Closet

Inspector Name
Tristan May

Damper I.D. #
9FL-FD3 N

Damper Type
Vertical Fire Damper

Damper Size
48*14

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve, no angle, no breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
Outside 9E

Inspector Name
Tristan May

Damper I.D. #
9FL-FD6 N

Damper Type
Vertical Fire Damper

Damper Size
17" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
15" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
Outside 9E

Inspector Name
Tristan May

Damper I.D.
9FL-FD9 N

Damper Type
Vertical Fire Damper

Damper Size
12*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*9

Pass / Fail / Abandoned
Fail

Comments / Corrections
Sleeve in wall, angle attached to duct not damper.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
9A Arraignment Hallway

Inspector Name
Tristan May

Damper I.D. #
9FL-FD13 S

Damper Type
Vertical Fire Damper

Damper Size
44*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
9FL South Gym

Inspector Name
Tristan May

Damper I.D. #
9FL-FD18 S

Damper Type
Vertical Fire Damper

Damper Size
24*22

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
9FL-FD19 S

Damper Type
Vertical Fire Damper

Damper Size
15" R

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Inaccessible. Needs drywall access door.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
9FL-FD20 S

Damper Type
Vertical Fire Damper

Damper Size
10" R

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Inaccessible. Need drywall access door.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
9FL-SD1 S

Damper Type
Vertical Smoke Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
Outside 9E

Inspector Name
Tristan May

Damper I.D. #
9FL-SD2 N

Damper Type
Vertical Smoke Damper

Damper Size
12"R

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
Outside 9E

Inspector Name
Tristan May

Damper I.D. #
9FL-SD3 N

Damper Type
Vertical Smoke Damper

Damper Size
48*14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Actuator behind wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
9FL-SD3 S

Damper Type
Vertical Smoke Damper

Damper Size
28*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
9FL-SD7 S

Damper Type
Vertical Smoke Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
22*22

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D.
9FL-SD8 S

Damper Type
Vertical Smoke Damper

Damper Size
12*8

Damper Manufacturer
Prefco Products

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
9FL-SD9 S

Damper Type
Vertical Smoke Damper

Damper Size
12*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Vestibule 9A

Inspector Name
Tristan May

Damper I.D.
9FL-SD12 S

Damper Type
Vertical Smoke Damper

Damper Size
12*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
9A Arraignment Hallway

Inspector Name
Tristan May

Damper I.D. #
9FL-SD13 S

Damper Type
Vertical Smoke Damper

Damper Size
44*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
Vestibule F

Inspector Name
Tristan May

Damper I.D.
9FL-SD15 N

Damper Type
Vertical Fire Damper

Damper Size
22*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Vestibule C

Inspector Name
Tristan May

Damper I.D.
9FL-SD15 S

Damper Type
Vertical Smoke Damper

Damper Size
26*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Vestibule B

Inspector Name
Tristan May

Damper I.D. #
9FL-SD16 S

Damper Type
Vertical Smoke Damper

Damper Size
22*8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper found closed.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Vestibule B

Inspector Name
Tristan May

Damper I.D. #
9FL-SD17 S

Damper Type
Vertical Smoke Damper

Damper Size
22*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper found closed.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D.
9FL-SD19 S

Damper Type
Vertical Smoke Damper

Damper Size
15" R

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Inaccessible. Needs drywall access door.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-14

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D.
9FL-SD20 S

Damper Type
Vertical Smoke Damper

Damper Size
10" R

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Inaccessible. Need drywall access door.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
Outside 9E

Inspector Name
Tristan May

Damper I.D.
9FL-SD21 N

Damper Type
Vertical Smoke Damper

Damper Size
14*8

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
9H Chapel Hallway

Inspector Name
Tristan May

Damper I.D.
9FL-SD21A N

Damper Type
Vertical Smoke Damper

Damper Size
14*8

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Next to open volume damper

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-15

Facility Location
Jail 1

Damper Location
Inside 9E Pod

Inspector Name
Tristan May

Damper I.D. #
9FL-SD22 N

Damper Type
Vertical Smoke Damper

Damper Size
24*12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D.
10FL-FD1 S

Damper Type
Vertical Fire Damper

Damper Size
15"R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper out of wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
Northwest Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-FD2 N

Damper Type
Vertical Fire Damper

Damper Size
5" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Flex

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-FD2 S

Damper Type
Vertical Fire Damper

Damper Size
26*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D.
10FL-FD3 S

Damper Type
Vertical Fire Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway, no sleeve, no angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-FD4 S

Damper Type
Vertical Fire Damper

Damper Size
17"R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*6

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper out of wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
North Utility Closet

Inspector Name
Tristan May

Damper I.D.
10FL-FD5 N

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no annular space. Damper out of wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
North Utility Closet

Inspector Name
Tristan May

Damper I.D.
10FL-FD6 N

Damper Type
Vertical Fire Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle. No sleeve. No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-FD7 N

Damper Type
Vertical Fire Damper

Damper Size
26*11

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
South Corridor

Inspector Name
Tristan May

Damper I.D.
10FL-FD17 S

Damper Type
Vertical Fire Damper

Damper Size
18*13

Damper Manufacturer
Prefco Products

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, pipes too close to install angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-FSD1 S

Damper Type
Vertical Fire / Smoke Damper

Damper Size
10*8

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-SD1 N

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
Southwest Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-SD1 S

Damper Type
Vertical Smoke Damper

Damper Size
15" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
NW Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-SD3 N

Damper Type
Vertical Smoke Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
17*11

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
SW Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-SD3 S

Damper Type
Vertical Smoke Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
16*4

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
Northwest Corridor

Inspector Name
Tristan May

Damper I.D.
10FL-SD8 N

Damper Type
Vertical Smoke Damper

Damper Size
10*8

Damper Manufacturer
Prefco Products

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
C/D Vestibule

Inspector Name
Tristan May

Damper I.D. #
10FL-SD13 S

Damper Type
Vertical Smoke Damper

Damper Size
8"R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
E Vestibule

Inspector Name
Tristan May

Damper I.D.
10FL-SD14 N

Damper Type
Vertical Smoke Damper

Damper Size
8*8

Damper Manufacturer
Prefco Products

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Damper found closed.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
C/D Vestibule

Inspector Name
Tristan May

Damper I.D. #
10FL-SD14 S

Damper Type
Vertical Smoke Damper

Damper Size
22*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-16

Facility Location
Jail 1

Damper Location
Northwest Corridor

Inspector Name
Tristan May

Damper I.D. #
10FL-SD18 N

Damper Type
Vertical Smoke Damper

Damper Size
18*12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
E Vestibule

Inspector Name
Tristan May

Damper I.D.
10F-SD9 N

Damper Type
Vertical Smoke Damper

Damper Size
22*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D. #
AC7A-R

Damper Type
Horizontal Fire Damper

Damper Size
32*34

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
17*29

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D. #
AC7A-S1

Damper Type
Horizontal Fire Damper

Damper Size
14*14

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D. #
AC7A-S2

Damper Type
Horizontal Fire Damper

Damper Size
18" Round

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18*16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D. #
AC7A-S3

Damper Type
Horizontal Fire Damper

Damper Size
16" Round

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
17*16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-20

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D. #
AC7-S1

Damper Type
Vertical Fire Damper

Damper Size
24" Round

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18 Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall, no angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-20

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC7-S2

Damper Type
Vertical Fire Damper

Damper Size
31" Round

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall, no angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-20

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC7-S3

Damper Type
Vertical Fire Damper

Damper Size
28"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" rnd

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not secured in wall, no angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC7-S4

Damper Type
Vertical Fire Damper

Damper Size
20" Round

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no access to back, not secured in wall. No room for external damper unless offset away from existing ductwork. East access from ground

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-20

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC8-S1

Damper Type
Vertical Fire Damper

Damper Size
22" Round

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle,damper not secured in sleeve

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Kaitlyn McElroy

Damper I.D. #
AC10-Return 1

Damper Type
Horizontal Fire Damper

Damper Size
44*24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18*18

Pass / Fail / Abandoned
Fail

Comments / Corrections
Welded angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC10-Return

Damper Type
Vertical Fire Damper

Damper Size
60*54

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle. No access to back, top or left side of damper.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC10-S1

Damper Type
Vertical Fire Damper

Damper Size
18" Round

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve or angle, damper not secured in wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room

Inspector Name
Tristan May

Damper I.D.
AC10-S2

Damper Type
Vertical Fire Damper

Damper Size
25

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not secured in wall. No angle. No access to rear

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D. #
AC10-S4

Damper Type
Vertical Fire Damper

Damper Size
30" Round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC11-S1

Damper Type
Vertical Fire Damper

Damper Size
28" Round

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
Sleeve not secured in wall, no angle.
Access to back, can be replaced with in or out of wall damper. Exterior damper max 30 wide X 32 7/8 tall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC11-S2

Damper Type
Vertical Fire Damper

Damper Size
26" Round

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve or angle. Access to back, can be replaced with in or out of wall damper.

Max exterior damper size for in wall 28wide X 30tall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room

Inspector Name
Kaitlyn McElroy

Damper I.D.
AC11-S3

Damper Type
Vertical Fire Damper

Damper Size
24" Round

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, damper not secured to sleeve, can replace with external or in stream damper, access to back. Wall sleeve dimensions 26.25 x 28 max exterior damper size

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC11-S4

Damper Type
Vertical Fire Damper

Damper Size
24" Round

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
Not in wall, damper not secured to sleeve. Access to both sides of wall. Damper can be replaced with in-wall damper. 26.25 x 28 max exterior damper size

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-20

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room

Inspector Name
Tristan May

Damper I.D.
AC12-S1

Damper Type
Vertical Fire Damper

Damper Size
28" Round

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not attached to sleeve. No angle.
No access to back of damper

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-20

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC12-S2

Damper Type
Vertical Fire Damper

Damper Size
22" Round

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not secured in sleeve. Damper not in wall. No access to back of damper.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-20

Facility Location
Jail 1

Damper Location
5th Floor Mechanical.

Inspector Name
Tristan May

Damper I.D.
AC12-S3

Damper Type
Vertical Fire Damper

Damper Size
28" Round

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not secured in sleeve. No access to back of damper

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-20

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Tristan May

Damper I.D.
AC12-S4

Damper Type
Vertical Fire Damper

Damper Size
28" Round

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18" Round

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Kaitlyn McElroy

Damper I.D.
AC29 Return

Damper Type
Horizontal Fire Damper

Damper Size
23*14

Damper Manufacturer
Prefco Products

Damper Model
E6-BC

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-21

Facility Location
Jail 1

Damper Location
5th Floor Mechanical Room.

Inspector Name
Kaitlyn McElroy

Damper I.D.
AC29-Supply

Damper Type
Horizontal Fire Damper

Damper Size
32*14

Damper Manufacturer
Prefco Products

Damper Model
E6-BC

Fusible Link Temperature
165 Degrees

Access Door Size
14*14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor G Elevator Room.

Inspector Name
Tristan May

Damper I.D.
G-ELV-RM R

Damper Type
Vertical Fire Damper

Damper Size
36*20

Damper Manufacturer
Ruskin

Damper Model
IBD40

Fusible Link Temperature
165 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor G Elevator Room.

Inspector Name
Tristan May

Damper I.D.
G-ELV-RM S

Damper Type
Vertical Fire Damper

Damper Size
30*16

Damper Manufacturer
Ruskin

Damper Model
IBD40

Fusible Link Temperature
165 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Inmate Elevator Room

Inspector Name
Tristan May

Damper I.D.
INM-ELV-RM-R

Damper Type
Vertical Fire Damper

Damper Size
32*32

Damper Manufacturer
Ruskin

Damper Model
IBD40

Fusible Link Temperature
165 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-22

Facility Location
Jail 1

Damper Location
5th Floor Inmate Elevator Room.

Inspector Name
Tristan May

Damper I.D.
INM-ELV-RM-S

Damper Type
Vertical Fire Damper

Damper Size
20*18

Damper Manufacturer
Ruskin

Damper Model
IBD40

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D. #
NS 6FL FD2

Damper Type
Vertical Fire Damper

Damper Size
26*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D. #
NS 6FL FD3

Damper Type
Vertical Fire Damper

Damper Size
60*14

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D. #
NS 6FL FD4

Damper Type
Vertical Fire Damper

Damper Size
15" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D.
NS 6FL FSD2

Damper Type
Vertical Fire / Smoke Damper

Damper Size
36*10

Damper Manufacturer
Prefco Products

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D. #
NS 6FL FSD3

Damper Type
Vertical Fire / Smoke Damper

Damper Size
6*12

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
4*4

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D. #
NS 6FL SD3

Damper Type
Vertical Fire Damper

Damper Size
60*14

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D.
NS 6FL SD4

Damper Type
Vertical Smoke Damper

Damper Size
15" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D.
NS 8FL FD1

Damper Type
Vertical Fire Damper

Damper Size
15"R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D.
NS 8FL FD2

Damper Type
Vertical Fire Damper

Damper Size
30*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection, no sleeve.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D. #
NS 8FL FD3

Damper Type
Vertical Fire Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D.
NS 8FL FD4

Damper Type
Vertical Fire Damper

Damper Size
9"R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D.
NS 8FL FD5

Damper Type
Vertical Fire Damper

Damper Size
15" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9*6

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve, angle in duct.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D.
NS 8FL SD1

Damper Type
Vertical Smoke Damper

Damper Size
15"R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12"R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Labeled as fail from prior inspection.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-20

Facility Location
Jail 1

Damper Location
North Stairwell

Inspector Name
Tristan May

Damper I.D.
NS 8FL SD4

Damper Type
Vertical Smoke Damper

Damper Size
9"R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6"R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
P1 Elevator Lobby.

Inspector Name
Tristan May

Damper I.D. #
P1-FD EX1

Damper Type
Horizontal Fire Damper

Damper Size
14*6

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Angle on back side

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
P1 Garage.

Inspector Name
Tristan May

Damper I.D.
P1-FD EX5

Damper Type
Vertical Fire Damper

Damper Size
96*30

Damper Manufacturer
Ruskin

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Fail

Comments / Corrections
Not secured to sleeve. No angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
P1 Garage.

Inspector Name
Tristan May

Damper I.D.
P1-FD EX7

Damper Type
Vertical Fire Damper

Damper Size
70*14

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not secured to sleeve. Can fix with screws

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-22

Facility Location
Jail 1

Damper Location
Trades Corridor Dock 1.

Inspector Name
Tristan May

Damper I.D.
P1-FD1.

Damper Type
Vertical Fire Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle, sleeve in wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-22

Facility Location
Jail 1

Damper Location
Trades Corridor Dock 1.

Inspector Name
Tristan May

Damper I.D. #
P1-FD2

Damper Type
Vertical Fire Damper

Damper Size
10" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle, sleeve in wall

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
Trade Office Dock Doors.

Inspector Name
Tristan May

Damper I.D.
P1-FD3

Damper Type
Vertical Fire Damper

Damper Size
30*12

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
Sally Port.

Inspector Name
Tristan May

Damper I.D. #
P1-FD4

Damper Type
Vertical Fire Damper

Damper Size
10" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle. No sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
Sally Port Bathroom.

Inspector Name
Tristan May

Damper I.D.
P1-FD5

Damper Type
Vertical Fire Damper

Damper Size
24*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle. No sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
Sally Port Bathroom.

Inspector Name
Tristan May

Damper I.D. #
P1-FD6

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle. No sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
Sally Port Hallway.

Inspector Name
Tristan May

Damper I.D.
P1-FSD1

Damper Type
Vertical Fire / Smoke Damper

Damper Size
12" R

Damper Manufacturer
Ruskin

Damper Model
FSD60

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
Sally Port Hallway.

Inspector Name
Tristan May

Damper I.D. #
P1-FSD2

Damper Type
Vertical Fire / Smoke Damper

Damper Size
10" R

Damper Manufacturer
Ruskin

Damper Model #
FSD60

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-22

Facility Location
Jail 1

Damper Location
Trades Corridor Dock 1.

Inspector Name
Tristan May

Damper I.D.
P1-SD1

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-22

Facility Location
Jail 1

Damper Location
Trades Corridor Dock 1.

Inspector Name
Tristan May

Damper I.D. #
P1-SD2

Damper Type
Vertical Smoke Damper

Damper Size
10" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
Trade Office Dock Doors.

Inspector Name
Tristan May

Damper I.D.
P1-SD3

Damper Type
Vertical Fire Damper

Damper Size
14*10

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
Trade Office Dock Doors.

Inspector Name
Tristan May

Damper I.D. #
P1-SD4

Damper Type
Vertical Smoke Damper

Damper Size
26*12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
Sally Port Bathroom.

Inspector Name
Tristan May

Damper I.D.
P1-SD6

Damper Type
Vertical Smoke Damper

Damper Size
24*10

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-07-23

Facility Location
Jail 1

Damper Location
Sally Port Dock 2 Hallway.

Inspector Name
Tristan May

Damper I.D.
P1-SD8

Damper Type
Vertical Smoke Damper

Damper Size
24*12

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
Penthouse Elevator Room.

Inspector Name
Tristan May

Damper I.D.
PH-FD1

Damper Type
Vertical Fire Damper

Damper Size
12*12

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
Penthouse Elevator Room.

Inspector Name
Tristan May

Damper I.D. #
PH-FD2

Damper Type
Vertical Fire Damper

Damper Size
12*12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
Penthouse.

Inspector Name
Tristan May

Damper I.D. #
PH-FD3

Damper Type
Vertical Fire Damper

Damper Size
12*12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
Penthouse.

Inspector Name
Tristan May

Damper I.D. #
PH-FD4

Damper Type
Horizontal Fire Damper

Damper Size
12*12

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
Penthouse.

Inspector Name
Tristan May

Damper I.D. #
PH-FD5

Damper Type
Vertical Fire Damper

Damper Size
12*12

Damper Manufacturer
Prefco Products

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-27

Facility Location
Jail 1

Damper Location
P2 Garage.

Inspector Name
Tristan May

Damper I.D. #
PS-FD S1

Damper Type
Vertical Fire Damper

Damper Size
30*12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-21

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D.
SS 8FL FD1

Damper Type
Vertical Fire Damper

Damper Size
14"R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-21

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D.
SS 8FL FD2

Damper Type
Vertical Fire Damper

Damper Size
30*10

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-21

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D. #
SS 8FL FD3

Damper Type
Vertical Fire Damper

Damper Size
8"R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-21

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D.
SS 8FL FD4

Damper Type
Vertical Fire Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-21

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D.
SS 8FL FD5

Damper Type
Vertical Fire Damper

Damper Size
15" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no access.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-21

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D. #
SS 8FL SD1

Damper Type
Vertical Smoke Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-21

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D.
SS 8FL SD3

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6"R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-21

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D.
SS 8FL SD4

Damper Type
Vertical Smoke Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
20*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-21

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D.
SS 8FL SD5

Damper Type
Vertical Smoke Damper

Damper Size
15" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Justice Center Court Towers

Damper Location
South stairwell

Inspector Name
Tristan May

Damper I.D.
SS 10FL FD1

Damper Type
Vertical Fire Damper

Damper Size
14"R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D. #
SS 10FL FD2

Damper Type
Vertical Fire Damper

Damper Size
30*10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D.
SS 10FL FD3

Damper Type
Vertical Fire Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Jail 1

Damper Location
South stairwell

Inspector Name
Tristan May

Damper I.D. #
SS 10Fl FD4

Damper Type
Vertical Fire Damper

Damper Size
15R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall, no access.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D.
SS 10FL SD1

Damper Type
Vertical Smoke Damper

Damper Size
14" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Jail 1

Damper Location
South Stairwell

Inspector Name
Tristan May

Damper I.D. #
SS 10FL SD3

Damper Type
Vertical Smoke Damper

Damper Size
48*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
20*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Jail 2

Damper Location
South stairwell

Inspector Name
Tristan May

Damper I.D. #
SS 10FL SD4

Damper Type
Vertical Smoke Damper

Damper Size
15R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Jail 2

West 3rd Street
Cleveland, Ohio 44113

Fire/Smoke Damper Inspection Report

Visual inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 3, 2025

Project: Cuyahoga County
Jail 2

Inspector(s):

- Larry Coreno, Certified Technician
- Tristan May, Certified Technician
- Kaitlyn McElroy, Certified Technician

Inspection and Test Date(s):

- April 24, 2025 – *In progress*

As of October 31, 2025, Duct Fabricators, Inc. "Fire Safety Division" inspected (206) dampers as noted on the following sheets. The dampers were visually inspected and photographed in the "exterior" and "interior" positions to confirm that they have not been altered and are free of any obstructions. Preventative maintenance was performed, and any deficiencies addressed.

(176) Dampers passed visual inspection
(30) Dampers failed due to reasons indicated on the report

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I.D. #	Damper Type	Damper Size	Damper Manufacturer	Damper Model #	Fusible Link Temperature	Access Door Size	Pass / Fail / Abandoned	Comments / Corrections
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-S1	Vertical Fire Damper	14x12	Air Balance	119C	165 Degrees	10x10	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-R1	Vertical Fire Damper	12x16	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-R2	Vertical Fire Damper	16x12	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-S3	Vertical Fire Damper	16x12	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-S5	Vertical Fire Damper	16x12	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-S4	Horizontal Fire Damper	11.5x9.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-S6	Vertical Fire Damper	14x12	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-S7	Vertical Fire Damper	22x12	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-R4	Vertical Fire Damper	48x24	Air Balance	119C	165 Degrees	16x16	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm East	Larry Coreno	10FL-E-S8	Horizontal Fire Damper	10x8	Air Balance	119C	165 Degrees	8x8	Pass	None
2025-04-24	Jail 2	10FL between mechanical rooms	Larry Coreno	10FL-C-Relief	Horizontal Fire Damper	30x12	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-S1	Vertical Fire Damper	14x12	Air Balance	119C	165 Degrees	12x12	Pass	None

2025-04-24	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-R1	Vertical Fire Damper	12x16	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-R2	Vertical Fire Damper	16x12	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-24	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-R3	Vertical Fire Damper	48x24	Air Balance	119C	165 Degrees	12x12	Pass	None
2025-04-25	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-S8	Horizontal Fire Damper	10x6	Air Balance	119C	165 Degrees	8x8	Pass	Welded angle per manufactures instruction
2025-04-25	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-R4	Vertical Fire Damper	48x24	Air Balance	119C	165 Degrees	21x11	Pass	None
2025-04-25	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-S7	Vertical Fire Damper	22x12	Air Balance	119C	165 Degrees	12x12	Pass	Welded angle per manufactures instruction
2025-04-25	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-S6	Vertical Fire Damper	14x12	Air Balance	119C	165 Degrees	12x12	Pass	Welded angle per manufactures instruction
2025-04-25	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-S5	Vertical Fire Damper	16x12	Air Balance	119C	165 Degrees	12x12	Pass	Welded angle per manufactures instruction
2025-04-25	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-S2	Vertical Fire Damper	22x12	Air Balance	119C	165 Degrees	12x12	Pass	Welded angle per manufactures instruction
2025-04-25	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-S3	Vertical Fire Damper	16x12	Air Balance	119C	165 Degrees	12x12	Pass	Welded angle per manufactures instruction
2025-04-25	Jail 2	10FL Mechanical Rm West	Larry Coreno	10FL-W-S4	Horizontal Fire Damper	12x10	Air Balance	119C	165 Degrees	8x8	Pass	Welded angle per manufactures instruction

2025-04-28	Jail 2	8th FL mechanical training	Tristan May	8FL-C-Relief	Vertical Fire Damper	30*12	Air Balance	119C	165 Degrees	12*12	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	8th FL mechanical room West	Tristan May	8Fl-W-R4	Vertical Fire Damper	48*24	Air Balance	119C	165 Degrees	11*11 patch	Pass	None
2025-04-28	Jail 2	8th floor mechanical West	Tristan May	8F-W-S7	Vertical Fire Damper	22*12"	Air Balance	119C	165 Degrees	12*12"	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	8th FL mechanical room	Tristan May	8FL-W-S6	Vertical Fire Damper	14*16"	Air Balance	119C	165 Degrees	12*12"	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	8th FL mechanical room	Tristan May	8FL-W-R3	Vertical Fire Damper	48*24	Air Balance	119C	165 Degrees	11*11 Patch	Pass	None
2025-04-28	Jail 2	10th FL small mech room	Tristan May	10FL-AHU10-3-S3	Vertical Fire Damper	24*12	Air Balance	119C	165 Degrees	14*14"	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	10th FL small mech room	Tristan May	10FL-AHU10.3-S1	Horizontal Fire Damper	16*14"	Air Balance	119C	165 Degrees	12*12"	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	8th FL W mechanical room	Tristan May	8FL-W-S5	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12*12"	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	8th FL W mechanical room	Tristan May	8FL-W-S4	Vertical Fire Damper	12*10"	Air Balance	Unknown	165 Degrees	8*8"	Pass	None
2025-04-28	Jail 2	8th FL W mechanical room	Tristan May	8FL-W-R1	Vertical Fire Damper	12*16"	Air Balance	Unknown	165 Degrees	8*8"	Pass	None
2025-04-28	Jail 2	8th FL W mechanical room	Tristan May	8FL-W-S1	Vertical Fire Damper	14*12"	Air Balance	Unknown	165 Degrees	12*12"	Pass	None

2025-04-28	Jail 2	8th fl W mechanical	Tristan May	8FL-W-S2	Vertical Fire Damper	22*12"	Air Balance	Unknown	165 Degrees	12*12"	Pass	None
2025-04-28	Jail 2	8th FL W mechanical room	Tristan May	8FL-W-S3	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12*12"	Pass	None
2025-04-28	Jail 2	10FL small mech room	Tristan May	10FL-AHU10-3-S2	Vertical Fire Damper	16*10"	Air Balance	Unknown	165 Degrees	10*10"	Pass	None
2025-04-28	Jail 2	10th FL small mech room	Tristan May	10FL RF-R1	Horizontal Fire Damper	22*20"	Air Balance	Unknown	165 Degrees	14*14"	Pass	None
2025-04-28	Jail 2	8th FL East Mechanical Rm	Tristan May	8FL-E-S8	Vertical Fire Damper	10*6"	Air Balance	119C	165 Degrees	10*10	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E-S5	Vertical Fire Damper	16*12"	Air Balance	119C	165 Degrees	12*12"	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E-S6	Vertical Fire Damper	14*12"	Air Balance	119C	165 Degrees	12*12"	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E-S7	Vertical Fire Damper	22*12"	Air Balance	119C	165 Degrees	14*14"	Pass	Welded angle per manufactures instruction
2025-04-28	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E-R4	Vertical Fire Damper	48*24	Air Balance	119C	165 Degrees	11*16 patch	Pass	None
2025-04-29	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E- S1	Vertical Fire Damper	14*12"	Air Balance	119C	165 Degrees	12*12"	Pass	Welded angle per manufactures instruction
2025-04-29	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E-S2	Vertical Fire Damper	22*12	Air Balance	119C	165 Degrees	12*12"	Pass	Welded angle per manufactures instruction
2025-04-29	Jail 2	8 FL East Mechanical Rm	Tristan May	8FL-E-R2	Vertical Fire Damper	16*12"	Air Balance	119C	165 Degrees	12x12	Pass	Welded angle per manufactures instruction

2025-04-29	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E-S3	Vertical Fire Damper	16*12	Air Balance	119C	165 Degrees	12*12	Pass	Welded angle per manufactures instruction
2025-04-29	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E-R3	Vertical Fire Damper	12*10"	Air Balance	119C	165 Degrees	10*10"	Pass	Welded angle per manufactures instruction
2025-04-29	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E-R3	Vertical Fire Damper	48*24"	Air Balance	119C	165 Degrees	11*11 patch	Pass	None
2025-04-29	Jail 2	8FL East Mechanical Rm	Tristan May	8FL-E-R1	Vertical Fire Damper	12*16"	Air Balance	119C	165 Degrees	12*12"	Pass	Welded angle per manufactures instruction
2025-04-29	Jail 2	8FL SSD Rm	Tristan May	8FL-RF-R1	Horizontal Fire Damper	22x20	Air Balance	119C	165 Degrees	16x16	Pass	Welded angle per manufactures instruction
2025-04-29	Jail 2	8FL Small Mechanical Rm	Tristan May	8FL-AHU8.3-S1	Horizontal Fire Damper	16x14	Air Balance	119C	165 Degrees	12x12	Pass	Welded angle per manufacturer instructions
2025-04-29	Jail 2	8FL Small mechanical rm	Tristan May	8FL AHU8.3-S3	Vertical Fire Damper	24x12	Air Balance	119C	165 Degrees	12x12	Pass	Welded angle per manufactures instruction
2025-04-29	Jail 2	8FL SSD RM	Tristan May	8FL-AHU8.3-S2	Vertical Fire Damper	16x10	Air Balance	119C	165 Degrees	8x8	Pass	Welded angle per manufactures instruction
2025-04-30	Jail 2	8FL Small Mechanical Rm	Tristan May	8FL-AHU-6.3-S3	Vertical Fire Damper	24x12	Air Balance	119C	165 Degrees	12x12	Pass	Welded angle per manufactures instruction
2025-04-30	Jail 2	6fl E mechanical	Tristan May	6FL-E-R1	Vertical Fire Damper	12*16	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions

2025-04-30	Jail 2	6fl E mechanical	Tristan May	6Fl-E-S1	Vertical Fire Damper	14*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-04-30	Jail 2	6fl e mechanical	Tristan May	6fl-e-s2	Vertical Fire Damper	22*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-04-30	Jail 2	6fl e mechanical	Tristan May	6fl-e-s4	Horizontal Fire Damper	12*10	Air Balance	119c	165 Degrees	10*10	Pass	Welded angle per manufacturer instructions
2025-04-30	Jail 2	6fl E mechanical	Tristan May	6fl-E-s3	Vertical Fire Damper	16*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-04-30	Jail 2	6fl e mechanical	Tristan May	6fl-e-s6	Vertical Fire Damper	14*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-04-30	Jail 2	6fl E Mechanical	Tristan May	6Fl-E-R4	Vertical Fire Damper	48*24	Air Balance	119c	165 Degrees	12*12	Fail	Screws in track
2025-04-30	Jail 2	6Fl E mechanical	Tristan May	6Fl-E-R3	Vertical Fire Damper	48*24	Air Balance	119c	165 Degrees	12*12	Fail	Screws in track
2025-04-30	Jail 2	6fl E mech	Tristan May	6FL-E-R2	Vertical Fire Damper	16*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-04-30	Jail 2	6fl e mechanical	Tristan May	6fl-e-s5	Vertical Fire Damper	16*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-01	Jail 2	6fl W mechanical	Tristan May	6fl-w-r3	Vertical Fire Damper	48* 24	Air Balance	119c	165 Degrees	20*20	Fail	Screws in track, need new angle 24*48 2*3" angle
2025-05-01	Jail 2	6fl W r4	Tristan May	6fl-w-r4	Vertical Fire Damper	48*24	Air Balance	119c	165 Degrees	12*12	Fail	Screws in track

2025-05-01	Jail 2	6fl W mechanical	Tristan May	6fl-w-s4	Horizontal Fire Damper	12*10	Air Balance	119c	165 Degrees	8*8	Pass	None
2025-05-01	Jail 2	6fl W mechanical	Tristan May	6fl-w-s3	Vertical Fire Damper	16*12	Air Balance	119c	165 Degrees	12*12"	Pass	Welded angle per manufacturer instruction
2025-05-01	Jail 2	6fl w mechanical	Tristan May	6fl-w-s5	Vertical Fire Damper	16*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-01	Jail 2	6fl W mechanical	Tristan May	6fl-w-r2	Vertical Fire Damper	16*12	Air Balance	119c	250 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-01	Jail 2	6fl w mechanical	Tristan May	6fl-w-s6	Vertical Fire Damper	14*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-01	Jail 2	6fl w mechanical.	Tristan May	6fl-w-s7	Vertical Fire Damper	22*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded per manufacturer instructions
2025-05-01	Jail 2	6fl w mechanical	Tristan May	6fl-w-s8	Horizontal Fire Damper	10*6	Air Balance	119c	165 Degrees	8*8	Pass	None
2025-05-01	Jail 2	6fl w mechanical	Tristan May	6fl-w-r1	Vertical Fire Damper	12*16	Air Balance	119c	165 Degrees	10*10	Pass	Welded per manufacturer instructions
2025-05-01	Jail 2	6fl mechanical room hallway.	Tristan May	6fl-c-relief	Horizontal Fire Damper	30*12	Air Balance	119c	165 Degrees	12*12	Fail	Damper not in wall
2025-05-01	Jail 2	6fl e mechanical	Tristan May	6fl-e-s8	Horizontal Fire Damper	10*6	Air Balance	119c	165 Degrees	6*6	Pass	None
2025-05-01	Jail 2	6fl e mechanical	Tristan May	6fl-e-s7	Vertical Fire Damper	22*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-01	Jail 2	6fl W mechanical	Tristan May	6fl-w-s1	Vertical Fire Damper	14*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions

2025-05-01	Jail 2	6fl w mechanical	Tristan May	5fl-w-s2	Vertical Fire Damper	22*12	Air Balance	119c	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-02	Jail 2	4fl video conference	Tristan May	4fl-ahu-4.1-s6	Vertical Fire Damper	42*20	Air Balance	Presumed 119c	165 Degrees	14	Fail	Welded angle over 24"
2025-05-02	Jail 2	4fl mechanical room.	Tristan May	4fl-ahu-4.2-s1	Vertical Fire Damper	22*24	Air Balance	119c	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-02	Jail 2	4fl mechanical.	Tristan May	4fl-ahu-4.1-s5	Vertical Fire Damper	16*12	Air Balance	119c	165 Degrees	10	Pass	Welded angle per manufacturer instructions
2025-05-02	Jail 2	4fl mechanical	Tristan May	4fl-ahu-4.2-r1	Vertical Fire Damper	24*22	Air Balance	119c	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-02	Jail 2	Outside 45A.	Tristan May	4fl-ahu-4.1-s7	Vertical Fire Damper	16*12	Air Balance	Presumed 119c	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-02	Jail 2	4fl electrical room.	Tristan May	4flh-ahu-4.1-s1	Vertical Fire Damper	10*10	Air Balance	Presumed 119c	165 Degrees	8	Pass	Welded angle per manufacturer instructions
2025-05-02	Jail 2	4fl electrical room.	Tristan May	4fl-ahu-4.1-s2	Vertical Fire Damper	8*8	Air Balance	119c	165 Degrees	8*8	Pass	Welded angle per manufacturer instructions
2025-05-02	Jail 2	4fl mechanical.	Tristan May	4fl-ahu-4.1-s3	Vertical Fire Damper	60*20	Air Balance	119c	165 Degrees	12*12	Fail	Welded angle over 24"
2025-05-02	Jail 2	4 FL central control.	Tristan May	4fl-ahu-4.3-s1	Vertical Fire Damper	10*10	Air Balance	119c	165 Degrees	8*8	Fail	Damper not in wall. Wall not rated assembly
2025-05-02	Jail 2	4th outside warden complex mens room.	Tristan May	4fl-s-ex	Vertical Fire Damper	12*12	Air Balance	119c	165 Degrees	12"	Pass	Welded angle per manufacturer instructions

2025-05-02	Jail 2	4fl video conference.	Tristan May	4fl-ahu-4.1-s13	Vertical Fire Damper	26*14	Air Balance	Presumed 119c	165 Degrees	12	Pass	Welded angle over 24"
2025-05-02	Jail 2	4fl outside central control.	Tristan May	4fl-ahu-4.3-r1	Vertical Fire Damper	16*12	Air Balance	119c	165 Degrees	12	Fail	Damper not in wall. Wall not fire rates assembly
2025-05-05	Jail 2	4fl Outside woman's room.	Tristan May	4fl-ahu-4.1-r	Vertical Fire Damper	14*12	Air Balance	Presumed 119c	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-05	Jail 2	4fl elevator lobby.	Tristan May	4fl-ahu-4.1-s11	Vertical Fire Damper	8*8	Air Balance	Presumed 119c	165 Degrees	6	Pass	Welded angle per manufacturer instructions
2025-05-05	Jail 2	4fl inside pod a plumbing closet.	Tristan May	4fl-ahu-4.1-s9	Vertical Fire Damper	10*10	Air Balance	Presumed 119c	165 Degrees	8	Fail	Need angle 12*10 damper size. 3x3 angle
2025-05-06	Jail 2	3 FL mechanical	Tristan May	3fl-ahu3.1-s6	Vertical Fire Damper	24*14	Air Balance	Unknown	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-06	Jail 2	3fl mechanical	Tristan May	3fl-ahu3.1-s1	Vertical Fire Damper	10*10	Air Balance	Unknown	165 Degrees	8	Pass	Welded angle per manufacturer instructions
2025-05-06	Jail 2	3fl mechanical.	Tristan May	3fl-ahu3.2-s1	Vertical Fire Damper	10*10	Air Balance	Unknown	165 Degrees	8	Pass	Welded angle per manufacturer instructions
2025-05-06	Jail 2	3fl mechanical.	Tristan May	3fl-ahu3.1-s3	Vertical Fire Damper	18*12	Air Balance	Unknown	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-06	Jail 2	3fl mechanical.	Tristan May	3fl-ahu3.1-s5	Vertical Fire Damper	12*10	Air Balance	Unknown	165 Degrees	10	Pass	Welded angle per manufacturer instructions

2025-05-06	Jail 2	3fl mechanical.	Tristan May	3fl-ahu3.2-s2	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-06	Jail 2	3fl mechanical.	Tristan May	3fl-ahu3.2-s3	Vertical Fire Damper	18*12	Air Balance	Unknown	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-06	Jail 2	3fl mechanical.	Tristan May	3fl-ahu3.1-s2	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-06	Jail 2	3fl mechanical.	Tristan May	3fl-ahu3.2-s5	Vertical Fire Damper	12*12	Air Balance	Unknown	165 Degrees	10	Pass	Welded angle per manufacturer instructions
2025-05-06	Jail 2	3fl mechanical.	Tristan May	3fl-ahu3.2-4	Vertical Fire Damper	14*10	Air Balance	Unknown	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-06	Jail 2	3fl electrical closet mechanical.	Tristan May	3fl-ex1	Vertical Fire Damper	12*12	Air Balance	Unknown	165 Degrees	10	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical	Tristan May	2fl-ahu2.1-s3	Vertical Fire Damper	18*12	Air Balance	Unknown	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical	Tristan May	2fl-ahu-2.1-s2	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	10*10	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical	Tristan May	2fl-ahu2.1-s1	Vertical Fire Damper	10*10	Air Balance	Unknown	165 Degrees	8*8	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical	Tristan May	2fl-ahu2.1-s6	Vertical Fire Damper	24*14	Air Balance	Unknown	165 Degrees	12	Pass	Welded angle per manufacturer instructions

2025-05-07	Jail 2	2fl mechanical	Tristan May	2fl-ahu2.1-s5	Vertical Fire Damper	12*10	Air Balance	Unknown	165 Degrees	8*8	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical.	Tristan May	2fl-ahu2.2-s1	Vertical Fire Damper	10*10	Air Balance	Unknown	165 Degrees	8*8	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical	Tristan May	2dl-ahu2.2-s4	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical room	Tristan May	2fl-ahu2.2-s2	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	10*10	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical.	Tristan May	2fl-ahu2.2-s3	Vertical Fire Damper	18*12	Air Balance	Unknown	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions.
2025-05-07	Jail 2	2fl mechanical electrical room	Tristan May	2fl-ex-1	Vertical Fire Damper	12*12	Air Balance	Unknown	165 Degrees	8*8	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical	Tristan May	2fl-ahu2.2-s5	Vertical Fire Damper	12*10	Air Balance	Unknown	165 Degrees	8*8	Pass	Welded angle per manufacturer instructions
2025-05-07	Jail 2	2fl mechanical	Tristan May	2fl-ahu2.2-s1	Vertical Fire Damper	10*10	Air Balance	Unknown	165 Degrees	8*8	Pass	Welded angle per manufacturer instructions
2025-05-08	Jail 2	3fl mechanical electrical	Tristan May	3fl-ahu3.1-s7	Vertical Fire Damper	8*6	Air Balance	Unknown	165 Degrees	Patch	Pass	Welded angle per manufacturer instructions
2025-05-08	Jail 2	2fl mechanical electrical	Tristan May	2fl-ahu2.1-s7	Vertical Fire Damper	6*8	Air Balance	Unknown	165 Degrees	Patch	Pass	Welded angle per manufacturer instructions

2025-05-13	Jail 2	12fl mechanical hallway.	Tristan May	12fl-c-relief	Vertical Fire Damper	32*12	Air Balance	Unknown	165 Degrees	12*12	Fail	Damper not in wall
2025-05-13	Jail 2	12 w mechanical.	Tristan May	12fl-w-s4	Horizontal Fire Damper	12*10	Air Balance	Unknown	165 Degrees	8*8	Pass	None
2025-05-13	Jail 2	12fl w mechanical.	Tristan May	12fl-w-s4	Horizontal Fire Damper	12*10	Air Balance	Unknown	165 Degrees	8*8	Pass	None
2025-05-13	Jail 2	12fl w mechanical.	Tristan May	12fl-w-s3	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-13	Jail 2	12fl w mechanical.	Tristan May	12fl-w-s2	Vertical Fire Damper	22*12	Air Balance	Unknown	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-13	Jail 2	12 w mechanical.	Tristan May	12fl-w-r2	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	10	Pass	Welded angle per manufacturer instructions
2025-05-13	Jail 2	12w mechanical.	Tristan May	12fl-w-s1	Vertical Fire Damper	14*12	Air Balance	Unknown	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-13	Jail 2	12w mechanical.	Tristan May	12fl-w-r1	Vertical Fire Damper	12*16	Air Balance	Unknown	165 Degrees	10*10	Pass	Welded angle per manufacturer instructions
2025-05-13	Jail 2	12 w mechanical.	Tristan May	12fl-w-r3	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	10*10	Fail	Improper angle, screws in track. Need 3*3 and fire caulk
2025-05-13	Jail 2	12 w mechanical.	Tristan May	12fl-w-r4	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Patch	Pass	Screws in track, need 3*3 angle
2025-05-13	Jail 2	12w mechanical.	Tristan May	12fl-w-s6	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12	Pass	Welded angle per manufacturer instructions

2025-05-13	Jail 2	12fl w mechanical.	Tristan May	12fl-w-s5	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12	Pass	Welded angle per manufacturer instructions
2025-05-13	Jail 2	12 w mechanical	Tristan May	12fl-w-s7	Vertical Fire Damper	22*12	Air Balance	Unknown	165 Degrees	12*12	Pass	Welded angle per manufacturer instructions
2025-05-14	Jail 2	12fl e mechanical.	Tristan May	12fl-e-s5	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-14	Jail 2	12fl e mechanical	Tristan May	12l-e-r2	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-14	Jail 2	12 E Mechanical.	Tristan May	12fl-e-s3	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-14	Jail 2	Stairwell 4.	Tristan May	Str4-fl10	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Fail	No angle, need 2*2 1 side, tapcons and panhead Phillips screw
2025-05-14	Jail 2	12 e mechanical.	Tristan May	12fl-e-s4	Horizontal Fire Damper	12*10	Air Balance	Unknown	165 Degrees	8*8	Pass	None
2025-05-14	Jail 2	12fl e mechanical.	Tristan May	12fl-e-s2	Vertical Fire Damper	22*12	Unknown	Unknown	165 Degrees	12*12	Pass	None
2025-05-14	Jail 2	Stairwell 4.	Tristan May	Str4-fl12	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Fail	No angle, need 2*2 1 side, tapcons and panhead Phillips screw
2025-05-14	Jail 2	Stair 4 1st floor hallway.	Tristan May	Str4-ta1	Vertical Fire Damper	20*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-14	Jail 2	12fl e mechanical	Tristan May	12fl-e-r3	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	12*12	Fail	Screws in track.
2025-05-14	Jail 2	Stairwell 4.	Tristan May	Str4-fl2	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Fail	No angle, need 2*2 1 side, tapcons and panhead Phillips screw 24*24

2025-05-14	Jail 2	12fl e mechanical.	Tristan May	12fl-e-s7	Vertical Fire Damper	22*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-14	Jail 2	12 e mechanical.	Tristan May	12fl-e-s8	Horizontal Fire Damper	10*8	Air Balance	Unknown	165 Degrees	8*8	Pass	None
2025-05-14	Jail 2	12fl e mechanical.	Tristan May	12fl-e-s6	Vertical Fire Damper	14*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-14	Jail 2	Stairwell 4.	Tristan May	Str4-fl8	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Fail	No angle, need 2*2 1 side, tapcons and panhead Phillips screw
2025-05-14	Jail 2	12fl e mechanical.	Tristan May	12fl-e-r3	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	12*12	Fail	Screws in track.need 3*3 angle
2025-05-14	Jail 2	12fl e mechanical.	Tristan May	12fl-e-r1	Vertical Fire Damper	12*16	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-14	Jail 2	Stairwell 4.	Tristan May	Str4-fl4	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill.	Fail	No angle, need 2*2 1 side, tapcons and panhead Phillips screw
2025-05-14	Jail 2	Stairwell 4	Tristan May	Str4-fl3	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill.	Fail	No angle, need 2*2 1 side, tapcons and panhead Phillips screw
2025-05-14	Jail 2	Stairwell 4.	Tristan May	Str4-fl6	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Fail	No angle, need 2*2 1 side, tapcons and panhead Phillips screw
2025-05-15	Jail 2	Nw stairwell	Tristan May	Str-12fl	Vertical Fire Damper	24*24	Air Balance	119av	165 Degrees	Grill.	Pass	1.5 right
2025-05-15	Jail 2	Stairwell 2.	Tristan May	Str2-fl6	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Stairwell 2.	Tristan May	Str2-fl4	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	11fl Rm 1105	Tristan May	11fl-s3	Vertical Fire Damper	10*9	Air Balance	Unknown	165 Degrees	8*8	Pass	None

2025-05-15	Jail 2	Stairwell 2.	Tristan May	Str2-fl1	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Str2 fl10	Tristan May	Str2-fl10	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Nw stairs basement. Laundy chain gate	Tristan May	Str-flbl	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Fail	Damper not in wall
2025-05-15	Jail 2	11fl Rm 1102	Tristan May	11fl-s1	Vertical Fire Damper	10*4	Air Balance	Unknown	165 Degrees	8	Pass	None
2025-05-15	Jail 2	Stairwell 2.	Tristan May	Ste2-fl3	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Str2 fl12.	Tristan May	Str2-fl12	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grill	Pass	None.
2025-05-15	Jail 2	Nw stairs.	Tristan May	Str1-10fl	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	nw stairs.	Tristan May	Str1-fl1	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Str 2 basement	Tristan May	Str2-flbl	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grill	Fail	Damper not in wall. Need panhead Phillips screws
2025-05-15	Jail 2	Stairwell 2.	Tristan May	Str2-fl8	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Nw stairs.	Tristan May	Str1-fl2	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Stairwell 2.	Tristan May	Str2-fl2	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	24*24	Pass	None
2025-05-15	Jail 2	Nw Stairwell.	Tristan May	Str1-fl3	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Stair 1.	Tristan May	Str1-fl4	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Stairwell 1	Tristan May	Str1-fl6	Vertical Fire Damper	24*24	Air Balance	Unknown.	165 Degrees	Grill	Pass	None
2025-05-15	Jail 2	Nw stairs.	Tristan May	Str1-fl8	Vertical Fire Damper	24*24	Air Balance	Unknown	165 Degrees	Grill	Pass	None

2025-05-22	Jail 2	5fl mechanical	Tristan May	Ac10-s3	Vertical Fire Damper	28"rnd	Unknown	Unknown	165 Degrees	18" rnd	Fail	Damper not secured in wall, no angle, no access to rear. Hard to reach
2025-05-28	Jail 2	12FL Small Mechanical Room.	Tristan May	12FL-AHU 12.3 S3	Vertical Fire Damper	28*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-28	Jail 2	6th Floor Small Mechanical Room.	Tristan May	6FL-RF-R1	Horizontal Fire Damper	22*20	Air Balance	DIBD2	165 Degrees	14*14	Pass	None
2025-05-28	Jail 2	12th Floor Mechanical Room.	Tristan May	12FL-AHU12.3-S2	Vertical Fire Damper	16*12	Unknown	Unknown	165 Degrees	8*8	Pass	None
2025-05-28	Jail 2	6th Floor Small Mechanical Room.	Tristan May	6FL-AHU 6.3 - S1	Horizontal Fire Damper	16*14	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-05-28	Jail 2	12th Floor Mechanical Room.	Tristan May	12FL-AHU12.3-R1	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	20*20	Fail	Damper not in floor. ~16g sleeve
2025-05-28	Jail 2	12th Floor Mechanical Room.	Tristan May	12FL-AHU12.3-S1	Horizontal Fire Damper	16*14	Unknown	Unknown	165 Degrees	8*8	Fail	Damper not in floor
2025-05-28	Jail 2	6th Floor Small Mechanical Room.	Tristan May	6FL-AHU6.3 S2	Vertical Fire Damper	16*10	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-06-05	Jail 2	1st Floor Deputy Corridor.	Tristan May	1FL-S6	Vertical Fire Damper	36*14	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-06-05	Jail 2	1st Floor Deputy Corridor.	Dan Tulcewicz	1FL-S5	Vertical Fire Damper	36*14	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-06-05	Jail 2	1st Floor Mens Locker Room.	Tristan May	1FL-S1	Vertical Fire Damper	18*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None

2025-06-05	Jail 2	1st Floor Mens Locker Room.	Tristan May	1FL-S2	Vertical Fire Damper	24*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-06-05	Jail 2	1st Floor Mens Locker Room.	Tristan May	1FL-S3	Vertical Fire Damper	18*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-06-05	Jail 2	1st Floor Mens Locker Room.	Tristan May	1FL-TA-1	Vertical Fire Damper	24*24	Greenheck	Fd150a	165 Degrees	Open	Pass	None
2025-06-05	Jail 2	1st Floor Mens Locker Room.	Tristan May	1FL-S4	Vertical Fire Damper	8*8	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-06-05	Jail 2	1st Floor Mens Locker Room.	Tristan May	1FL-EX1	Vertical Fire Damper	10" Round	Greenheck	1FD150RV	165 Degrees	Elbow	Pass	None
2025-06-05	Jail 2	Basement Plumbing Equipment Room.	Tristan May	BL-TA-2	Vertical Fire Damper	24*56	Air Balance	Unknown	165 Degrees	Grille	Pass	None
2025-06-05	Jail 2	Basement Plumbing Equipment Room.	Tristan May	BL-TA-3	Vertical Fire Damper	20*40	Ruskin	IBD2	165 Degrees	Grille	Pass	None
2025-06-05	Jail 2	Basement Electrical Vault.	Tristan May	BL-S5	Vertical Fire Damper	18*12	Air Balance	Unknown	165 Degrees	10*10	Pass	None
2025-06-05	Jail 2	Basement Laundry Storage.	Tristan May	BL-S4	Vertical Fire Damper	10*15	Air Balance	Unknown	165 Degrees	10*10	Pass	None
2025-06-05	Jail 2	Basement Laundry Storage.	Tristan May	BL-TA-1	Vertical Fire Damper	24*56	Air Balance	Unknown	165 Degrees	Grille	Pass	None
2025-06-05	Jail 2	Basement Laundry Entrance.	Tristan May	BL-S3	Vertical Fire Damper	8*6	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-06-05	Jail 2	Basement Storage Room, B3 Hallway.	Tristan May	BL-S2	Vertical Fire Damper	10*6	Air Balance	Unknown	165 Degrees	4*4	Pass	None

2025-06-05	Jail 2	Basement Storage Room.	Tristan May	BL-S1	Vertical Fire Damper	9*12	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-08-04	Jail 2	12fl e Mechanical.	Tristan May	12FL-E-S1	Vertical Fire Damper	15*13	Unknown	Unknown	165 Degrees	12*12	Fail	Not secured in wall
2025-08-05	Jail 2	10FL East Mechanical Room.	Tristan May	10FL-E-S2	Vertical Fire Damper	22*12	Air Balance	Unknown	165 Degrees	12*12	Fail	Damper not secured in wall
2025-08-05	Jail 2	10FL West Mechanical Room.	Tristan May	10FL-W-R4	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Patch	Fail	Damper not in wall, unable to add angle, burglar bars need moved. Removed screws from track.
2025-08-05	Jail 2	8FL West Mechanical Room.	Tristan May	8FL-W-R2	Vertical Fire Damper	16*12	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-08-05	Jail 2	8FL West Mechanical Room	Tristan May	8FL-W-S8.	Horizontal Fire Damper	10*6	Air Balance	Unknown	165 Degrees	8*8	Pass	None
2025-08-05	Jail 2	10FL West Mechanical Room.	Tristan May	10FL-W-R3	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Patch	Fail	Damper not in wall, no way to attach angle. Burglar bars need moved.
2025-08-19	Jail 2	Female Inmate Property Room.	Tristan May	4FL-AHU4.1-S12	Vertical Fire Damper	8*8	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-08-19	Jail 2	45A Closet.	Tristan May	4FL-N-EX	Vertical Fire Damper	10*8	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-08-19	Jail 2	Outside of 45D.	Tristan May	4FL-AHU4.1-S10	Vertical Fire Damper	26*10	Air Balance	Unknown	165 Degrees	12*12	Pass	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical

Inspector Name
Tristan May

Damper I.D.
2fl-ahu2.1-s1

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical

Inspector Name
Tristan May

Damper I.D.
2fl-ahu-2.1-s2

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical

Inspector Name
Tristan May

Damper I.D.
2fl-ahu2.1-s3

Damper Type
Vertical Fire Damper

Damper Size
18*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical

Inspector Name
Tristan May

Damper I.D.
2fl-ahu2.1-s5

Damper Type
Vertical Fire Damper

Damper Size
12*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical

Inspector Name
Tristan May

Damper I.D. #
2fl-ahu2.1-s6

Damper Type
Vertical Fire Damper

Damper Size
24*14

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Jail 2

Damper Location
2fl mechanical electrical

Inspector Name
Tristan May

Damper I.D.
2fl-ahu2.1-s7

Damper Type
Vertical Fire Damper

Damper Size
6*8

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical

Inspector Name
Tristan May

Damper I.D.
2fl-ahu2.2-s1

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical.

Inspector Name
Tristan May

Damper I.D.
2fl-ahu2.2-s1

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical room

Inspector Name
Tristan May

Damper I.D.
2fl-ahu2.2-s2

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical.

Inspector Name
Tristan May

Damper I.D.
2fl-ahu2.2-s3

Damper Type
Vertical Fire Damper

Damper Size
18*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical

Inspector Name
Tristan May

Damper I.D. #
2fl-ahu2.2-s4

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical

Inspector Name
Tristan May

Damper I.D.
2fl-ahu2.2-s5

Damper Type
Vertical Fire Damper

Damper Size
12*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Jail 2

Damper Location
2fl mechanical electrical room

Inspector Name
Tristan May

Damper I.D.
2fl-ex-1

Damper Type
Vertical Fire Damper

Damper Size
12*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl mechanical

Inspector Name
Tristan May

Damper I.D.
3fl-ahu3.1-s1

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl mechanical.

Inspector Name
Tristan May

Damper I.D.
3fl-ahu3.1-s2

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl mechanical.

Inspector Name
Tristan May

Damper I.D.
3fl-ahu3.1-s3

Damper Type
Vertical Fire Damper

Damper Size
18*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl mechanical.

Inspector Name
Tristan May

Damper I.D.
3fl-ahu3.1-s5

Damper Type
Vertical Fire Damper

Damper Size
12*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3 FL mechanical

Inspector Name
Tristan May

Damper I.D.
3fl-ahu3.1-s6

Damper Type
Vertical Fire Damper

Damper Size
24*14

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Jail 2

Damper Location
3fl mechanical electrical

Inspector Name
Tristan May

Damper I.D. #
3fl-ahu3.1-s7

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl mechanical.

Inspector Name
Tristan May

Damper I.D.
3fl-ahu3.2-4

Damper Type
Vertical Fire Damper

Damper Size
14*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl mechanical.

Inspector Name
Tristan May

Damper I.D.
3fl-ahu3.2-s1

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl mechanical.

Inspector Name
Tristan May

Damper I.D.
3fl-ahu3.2-s2

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl mechanical.

Inspector Name
Tristan May

Damper I.D.
3fl-ahu3.2-s3

Damper Type
Vertical Fire Damper

Damper Size
18*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl mechanical.

Inspector Name
Tristan May

Damper I.D. #
3fl-ahu3.2-s5

Damper Type
Vertical Fire Damper

Damper Size
12*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Jail 2

Damper Location
3fl electrical closet mechanical.

Inspector Name
Tristan May

Damper I.D.
3fl-ex1

Damper Type
Vertical Fire Damper

Damper Size
12*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Jail 2

Damper Location
4fl Outside woman's room.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.1-r

Damper Type
Vertical Fire Damper

Damper Size
14*12

Damper Manufacturer
Air Balance

Damper Model
Presumed 119c

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4fl electrical room.

Inspector Name
Tristan May

Damper I.D. #
4fl-ahu-4.1-s1

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Air Balance

Damper Model #
Presumed 119c

Fusible Link Temperature
165 Degrees

Access Door Size
8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4fl electrical room.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.1-s2

Damper Type
Vertical Fire Damper

Damper Size
8*8

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4fl mechanical.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.1-s3

Damper Type
Vertical Fire Damper

Damper Size
60*20

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Welded angle over 24"

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4fl mechanical.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.1-s5

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4fl video conference

Inspector Name
Tristan May

Damper I.D. #
4fl-ahu-4.1-s6

Damper Type
Vertical Fire Damper

Damper Size
42*20

Damper Manufacturer
Air Balance

Damper Model #
Presumed 119c

Fusible Link Temperature
165 Degrees

Access Door Size
14

Pass / Fail / Abandoned
Fail

Comments / Corrections
Welded angle over 24"

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
Outside 45A.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.1-s7

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Presumed 119c

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 2

Damper Location
45A Closet.

Inspector Name
Tristan May

Damper I.D. #
4FL-AHU4.1-S8

Damper Type
Vertical Fire Damper

Damper Size
10*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Jail 2

Damper Location
4fl inside pod a plumbing closet.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.1-s9

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Air Balance

Damper Model
Presumed 119c

Fusible Link Temperature
165 Degrees

Access Door Size
8

Pass / Fail / Abandoned
Fail

Comments / Corrections
Need angle 12*10 damper size. 3x3 angle

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 2

Damper Location
Outside of 45D

Inspector Name
Tristan May

Damper I.D. #
4FL-AHU4.1-S10

Damper Type
Vertical Fire Damper

Damper Size
26*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Jail 2

Damper Location
4fl elevator lobby.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.1-s11

Damper Type
Vertical Fire Damper

Damper Size
8*8

Damper Manufacturer
Air Balance

Damper Model
Presumed 119c

Fusible Link Temperature
165 Degrees

Access Door Size
6

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 2

Damper Location
Female Inmate Property Room

Inspector Name
Tristan May

Damper I.D. #
4FL-AHU4.1-S12

Damper Type
Vertical Fire Damper

Damper Size
8*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4fl video conference.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.1-s13

Damper Type
Vertical Fire Damper

Damper Size
26*14

Damper Manufacturer
Air Balance

Damper Model
Presumed 119c

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle over 24"

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4fl mechanical

Inspector Name
Tristan May

Damper I.D. #
4fl-ahu-4.2-r1

Damper Type
Vertical Fire Damper

Damper Size
24*22

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4fl mechanical room.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.2-s1

Damper Type
Vertical Fire Damper

Damper Size
22*24

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4fl outside central control.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.3-r1

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall. Wall not fire rates assembly

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4 FL central control.

Inspector Name
Tristan May

Damper I.D.
4fl-ahu-4.3-s1

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall. Wall not rated assembly

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Jail 2

Damper Location
45A Closet

Inspector Name
Tristan May

Damper I.D. #
4FL-N-EX

Damper Type
Vertical Fire Damper

Damper Size
10*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-02

Facility Location
Jail 2

Damper Location
4th outside warden complex mens room.

Inspector Name
Tristan May

Damper I.D.
4fl-s-ex

Damper Type
Vertical Fire Damper

Damper Size
12*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl w mechanical

Inspector Name
Tristan May

Damper I.D.
5fl-w-s2

Damper Type
Vertical Fire Damper

Damper Size
22*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl mechanical room hallway.

Inspector Name
Tristan May

Damper I.D.
6fl-c-relief

Damper Type
Horizontal Fire Damper

Damper Size
30*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6fl E mechanical

Inspector Name
Tristan May

Damper I.D. #
6FL-E-R1

Damper Type
Vertical Fire Damper

Damper Size
12*16

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6fl E mech

Inspector Name
Tristan May

Damper I.D.
6FL-E-R2

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6Fl E mechanical

Inspector Name
Tristan May

Damper I.D. #
6Fl-E-R3

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Screws in track

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6fl E Mechanical

Inspector Name
Tristan May

Damper I.D. #
6Fl-E-R4

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Screws in track

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6fl E mechanical

Inspector Name
Tristan May

Damper I.D. #
6Fl-E-S1

Damper Type
Vertical Fire Damper

Damper Size
14*12

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6fl e mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-e-s2

Damper Type
Vertical Fire Damper

Damper Size
22*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6fl E mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-E-s3

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6fl e mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-e-s4

Damper Type
Horizontal Fire Damper

Damper Size
12*10

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6fl e mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-e-s5

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
6fl e mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-e-s6

Damper Type
Vertical Fire Damper

Damper Size
14*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl e mechanical

Inspector Name
Tristan May

Damper I.D. #
6fl-e-s7

Damper Type
Vertical Fire Damper

Damper Size
22*12

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl e mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-e-s8

Damper Type
Horizontal Fire Damper

Damper Size
10*6

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl w mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-w-r1

Damper Type
Vertical Fire Damper

Damper Size
12*16

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl W mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-w-r2

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
250 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl W mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-w-r3

Damper Type
Vertical Fire Damper

Damper Size
48* 24

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
20*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
Screws in track, need new angle 24*48
2*3" angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl W r4

Inspector Name
Tristan May

Damper I.D. #
6fl-w-r4

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Screws in track

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl W mechanical

Inspector Name
Tristan May

Damper I.D. #
6fl-w-s1

Damper Type
Vertical Fire Damper

Damper Size
14*12

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl W mechanical

Inspector Name
Tristan May

Damper I.D. #
6fl-w-s3

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl W mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-w-s4

Damper Type
Horizontal Fire Damper

Damper Size
12*10

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl w mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-w-s5

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl w mechanical

Inspector Name
Tristan May

Damper I.D.
6fl-w-s6

Damper Type
Vertical Fire Damper

Damper Size
14*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl w mechanical.

Inspector Name
Tristan May

Damper I.D.
6fl-w-s7

Damper Type
Vertical Fire Damper

Damper Size
22*12

Damper Manufacturer
Air Balance

Damper Model
119c

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-01

Facility Location
Jail 2

Damper Location
6fl w mechanical

Inspector Name
Tristan May

Damper I.D. #
6fl-w-s8

Damper Type
Horizontal Fire Damper

Damper Size
10*6

Damper Manufacturer
Air Balance

Damper Model #
119c

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL Small mechanical rm

Inspector Name
Tristan May

Damper I.D. #
8FL AHU8.3-S3

Damper Type
Vertical Fire Damper

Damper Size
24x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-30

Facility Location
Jail 2

Damper Location
8FL Small Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-AHU-6.3-S3

Damper Type
Vertical Fire Damper

Damper Size
24x12

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL Small Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-AHU8.3-S1

Damper Type
Horizontal Fire Damper

Damper Size
16x14

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL SSD RM

Inspector Name
Tristan May

Damper I.D.
8FL-AHU8.3-S2

Damper Type
Vertical Fire Damper

Damper Size
16x10

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL mechanical training

Inspector Name
Tristan May

Damper I.D.
8FL-C-Relief

Damper Type
Vertical Fire Damper

Damper Size
30*12

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-E- S1

Damper Type
Vertical Fire Damper

Damper Size
14*12"

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-E-R1

Damper Type
Vertical Fire Damper

Damper Size
12*16"

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8 FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D. #
8FL-E-R2

Damper Type
Vertical Fire Damper

Damper Size
16*12"

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-E-R3

Damper Type
Vertical Fire Damper

Damper Size
12*10"

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
10*10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D. #
8FL-E-R3

Damper Type
Vertical Fire Damper

Damper Size
48*24"

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
11*11 patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-E-R4

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
11*16 patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-E-S2

Damper Type
Vertical Fire Damper

Damper Size
22*12

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-E-S3

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-E-S5

Damper Type
Vertical Fire Damper

Damper Size
16*12"

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D. #
8FL-E-S6

Damper Type
Vertical Fire Damper

Damper Size
14*12"

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-E-S7

Damper Type
Vertical Fire Damper

Damper Size
22*12"

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
14*14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL East Mechanical Rm

Inspector Name
Tristan May

Damper I.D.
8FL-E-S8

Damper Type
Vertical Fire Damper

Damper Size
10*6"

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-29

Facility Location
Jail 2

Damper Location
8FL SSD Rm

Inspector Name
Tristan May

Damper I.D.
8FL-RF-R1

Damper Type
Horizontal Fire Damper

Damper Size
22x20

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL W mechanical room

Inspector Name
Tristan May

Damper I.D.
8FL-W-R1

Damper Type
Vertical Fire Damper

Damper Size
12*16"

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL mechanical room

Inspector Name
Tristan May

Damper I.D. #
8FL-W-R3

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
11*11 Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL mechanical room West

Inspector Name
Tristan May

Damper I.D. #
8Fl-W-R4

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
11*11 patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL W mechanical room

Inspector Name
Tristan May

Damper I.D. #
8FL-W-S1

Damper Type
Vertical Fire Damper

Damper Size
14*12"

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th fl W mechanical

Inspector Name
Tristan May

Damper I.D. #
8FL-W-S2

Damper Type
Vertical Fire Damper

Damper Size
22*12"

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL W mechanical room

Inspector Name
Tristan May

Damper I.D. #
8FL-W-S3

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL W mechanical room

Inspector Name
Tristan May

Damper I.D.
8FL-W-S4

Damper Type
Vertical Fire Damper

Damper Size
12*10"

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL W mechanical room

Inspector Name
Tristan May

Damper I.D.
8FL-W-S5

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th FL mechanical room

Inspector Name
Tristan May

Damper I.D.
8FL-W-S6

Damper Type
Vertical Fire Damper

Damper Size
14*16"

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
8th floor mechanical West

Inspector Name
Tristan May

Damper I.D.
8F-W-S7

Damper Type
Vertical Fire Damper

Damper Size
22*12"

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
10th FL small mech room

Inspector Name
Tristan May

Damper I.D. #
10FL RF-R1

Damper Type
Horizontal Fire Damper

Damper Size
22*20"

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14*14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
10th FL small mech room

Inspector Name
Tristan May

Damper I.D.
10FL-AHU10.3-S1

Damper Type
Horizontal Fire Damper

Damper Size
16*14"

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12*12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
10FL small mech room

Inspector Name
Tristan May

Damper I.D.
10FL-AHU10-3-S2

Damper Type
Vertical Fire Damper

Damper Size
16*10"

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-28

Facility Location
Jail 2

Damper Location
10th FL small mech room

Inspector Name
Tristan May

Damper I.D.
10FL-AHU10-3-S3

Damper Type
Vertical Fire Damper

Damper Size
24*12

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
14*14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL between mechanical rooms

Inspector Name
Larry Coreno

Damper I.D. #
10FL-C-Relief

Damper Type
Horizontal Fire Damper

Damper Size
30x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D. #
10FL-E-R1

Damper Type
Vertical Fire Damper

Damper Size
12x16

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D. #
10FL-E-R2

Damper Type
Vertical Fire Damper

Damper Size
16x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Juvenile Justice Center

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D. #
10FL-E-R3

Damper Type
Vertical Fire Damper

Damper Size
48x24

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D. #
10FL-E-R4

Damper Type
Vertical Fire Damper

Damper Size
48x24

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D. #
10FL-E-S1

Damper Type
Vertical Fire Damper

Damper Size
14x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D.
10FL-E-S3

Damper Type
Vertical Fire Damper

Damper Size
16x12

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D.
10FL-E-S4

Damper Type
Horizontal Fire Damper

Damper Size
11.5x9.5

Damper Manufacturer
Ruskin

Damper Model
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D. #
10FL-E-S5

Damper Type
Vertical Fire Damper

Damper Size
16x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D. #
10FL-E-S6

Damper Type
Vertical Fire Damper

Damper Size
14x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D. #
10FL-E-S7

Damper Type
Vertical Fire Damper

Damper Size
22x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm East

Inspector Name
Larry Coreno

Damper I.D. #
10FL-E-S8

Damper Type
Horizontal Fire Damper

Damper Size
10x8

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D. #
10FL-W-R1

Damper Type
Vertical Fire Damper

Damper Size
12x16

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D.
10FL-W-R2

Damper Type
Vertical Fire Damper

Damper Size
16x12

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D. #
10FL-W-R3

Damper Type
Vertical Fire Damper

Damper Size
48x24

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-25

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D. #
10FL-W-R4

Damper Type
Vertical Fire Damper

Damper Size
48x24

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
21x11

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-24

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D. #
10FL-W-S1

Damper Type
Vertical Fire Damper

Damper Size
14x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-25

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D. #
10FL-W-S2

Damper Type
Vertical Fire Damper

Damper Size
22x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-25

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D. #
10FL-W-S3

Damper Type
Vertical Fire Damper

Damper Size
16x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-25

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D. #
10FL-W-S4

Damper Type
Horizontal Fire Damper

Damper Size
12x10

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-25

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D.
10FL-W-S5

Damper Type
Vertical Fire Damper

Damper Size
16x12

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-25

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D. #
10FL-W-S6

Damper Type
Vertical Fire Damper

Damper Size
14x12

Damper Manufacturer
Air Balance

Damper Model #
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-25

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D.
10FL-W-S7

Damper Type
Vertical Fire Damper

Damper Size
22x12

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-25

Facility Location
Jail 2

Damper Location
10FL Mechanical Rm West

Inspector Name
Larry Coreno

Damper I.D.
10FL-W-S8

Damper Type
Horizontal Fire Damper

Damper Size
10x6

Damper Manufacturer
Air Balance

Damper Model
119C

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufactures instruction

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12fl mechanical hallway.

Inspector Name
Tristan May

Damper I.D.
12fl-c-relief

Damper Type
Vertical Fire Damper

Damper Size
32*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-14

Facility Location
Jail 2

Damper Location
12fl e mechanical

Inspector Name
Tristan May

Damper I.D.
12fl-e-r2

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-14

Facility Location
Jail 2

Damper Location
12fl e mechanical.

Inspector Name
Tristan May

Damper I.D. #
12fl-e-s5

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12w mechanical.

Inspector Name
Tristan May

Damper I.D.
12fl-w-r1

Damper Type
Vertical Fire Damper

Damper Size
12*16

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12 w mechanical.

Inspector Name
Tristan May

Damper I.D. #
12fl-w-r2

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12 w mechanical.

Inspector Name
Tristan May

Damper I.D.
12fl-w-r3

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Fail

Comments / Corrections
Improper angle, screws in track. Need 3*3 and fire caulk

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12 w mechanical.

Inspector Name
Tristan May

Damper I.D.
12fl-w-r4

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Screws in track, need 3*3 angle

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12w mechanical.

Inspector Name
Tristan May

Damper I.D.
12fl-w-s1

Damper Type
Vertical Fire Damper

Damper Size
14*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12fl w mechanical.

Inspector Name
Tristan May

Damper I.D. #
12fl-w-s2

Damper Type
Vertical Fire Damper

Damper Size
22*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12fl w mechanical.

Inspector Name
Tristan May

Damper I.D.
12fl-w-s3

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12 w mechanical.

Inspector Name
Tristan May

Damper I.D.
12fl-w-s4

Damper Type
Horizontal Fire Damper

Damper Size
12*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12fl w mechanical.

Inspector Name
Tristan May

Damper I.D.
12fl-w-s4

Damper Type
Horizontal Fire Damper

Damper Size
12*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12fl w mechanical.

Inspector Name
Tristan May

Damper I.D.
12fl-w-s5

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Jail 2

Damper Location
12w mechanical.

Inspector Name
Tristan May

Damper I.D.
12fl-w-s6

Damper Type
Vertical Fire Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Welded angle per manufacturer instructions

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Jane Edna Hunter Building

3955 Euclid Avenue #1
Cleveland, Ohio 44115

Fire/Smoke Damper Inspection Report

Visual Inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 3, 2025

Project: Cuyahoga County
Jane Edna Hunter Building

Inspector(s):

- Larry Coreno, Certified Technician

Inspection and Test Date(s):

- April 11, 2025

Duct Fabricators, Inc. “Fire Safety Division” inspected twelve (12) dampers as noted on the following sheets. The dampers were visually inspected and photographed in the “exterior” and “interior” positions to confirm that they have not been altered and are free of any obstructions. Preventative maintenance was performed, and any deficiencies addressed.

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Facility Location	Damper Location	Damper I.D. #	Damper Type	Damper Size	Damper Manufacturer	Damper Model #	Pass / Fail / Abandoned	Comments
Jane Edna Hunter Building	2nd FL West Mechanical Rm	AHU3- 2nd FL West Supply	Vertical Fire Damper	72x30	Safe Air	Unknown	Pass	None
Jane Edna Hunter Building	2nd FL West Mechanical Rm	AHU1-2ND FL West Return	Horizontal Fire Damper	64x44	Safe Air	Unknown	Pass	None
Jane Edna Hunter Building	2nd FL West Mechanical Rm	AHU3-2nd FL Return	Vertical Fire Damper	109x33	Ruskin	IBD2	Pass	None
Jane Edna Hunter Building	2nd FL East Mechanical Rm	AHU2-2ND FL East Supply	Horizontal Fire Damper	72x30	Safe Air	Unknown	Pass	None
Jane Edna Hunter Building	2nd FL East Mechanical Rm	AHU2-2ND FL East Return	Horizontal Fire Damper	64x44	Safe Air	Unknown	Pass	None
Jane Edna Hunter Building	2nd FL East Mechanical Rm	AHU4-2ND FL East Supply	Vertical Fire Damper	72x30	Ruskin	IBD2	Pass	None
Jane Edna Hunter Building	2nd FL East Mechanical Rm	AHU4-2nd FL East Return	Vertical Fire Damper	111x30	Safe Air	Unknown	Pass	None
Jane Edna Hunter Building	3rd FL East Mechanical Rm	AHU6- 3rd FL East Supply	Vertical Fire Damper	90x36	Safe Air	Unknown	Pass	None
Jane Edna Hunter Building	3rd FL East Mechanical Rm	AHU6- 3rd FL East Return	Vertical Fire Damper	114x36	Safe Air	Unknown	Pass	None
Jane Edna Hunter Building	3rd FL West Mechanical Rm	AHU5-3rd FL West Supply	Vertical Fire Damper	90x36	Safe Air	Unknown	Pass	None
Jane Edna Hunter Building	3rd FL West Mechanical Rm	AHU5-3rd FL West Return	Vertical Fire Damper	108x36	Safe Air	Unknown	Pass	None
Jane Edna Hunter Building	2nd FL West Mechanical Rm	AHU1-2nd FL Supply	Horizontal Fire Damper	64x36	Safe Air	Unknown	Pass	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Justice Center Court Towers

Damper Location
2nd floor west mechanical room

Inspector Name
Larry Coreno

Damper I.D.
AHU1-2nd FL Supply

Damper Type
Horizontal Fire Damper

Damper Size
64x36"

Damper Manufacturer
Safe Air

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
21x14"

Pass / Fail / Abandoned
Pass

Comments / Corrections
2nd FL West Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
2nd FL West Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D.
AHU1-2ND FL West Return

Damper Type
Horizontal Fire Damper

Damper Size
64x44

Damper Manufacturer
Safe Air

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
2nd FL West Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
2nd FL East Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-2ND FL East Return

Damper Type
Horizontal Fire Damper

Damper Size
64x44

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
21x14 & 18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
2ND FL East Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
2nd floor west mechanical room

Inspector Name
Larry Coreno

Damper I.D. #
AHU3- 2nd FL West Supply

Damper Type
Vertical Fire Damper

Damper Size
72x30

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
21x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
2nd FL West Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
2nd FL West Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU3-2nd FL Return

Damper Type
Vertical Fire Damper

Damper Size
109x33

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
21x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
2nd FL West Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
2nd FL East Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU4-2nd FL East Return

Damper Type
Vertical Fire Damper

Damper Size
111x30

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
21x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
2nd FL East Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
2ND FL East Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU4-2ND FL East Supply

Damper Type
Horizontal Fire Damper

Damper Size
72x30

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
21x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
2ND FL East Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
2ND FL East Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU4-2ND FL East Supply

Damper Type
Vertical Fire Damper

Damper Size
72x30

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
2nd FL East Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
3rd FL West Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5-3rd FL West Return

Damper Type
Vertical Fire Damper

Damper Size
108x36

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
3rd FL West Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
3rd FL West Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5-3rd FL West Supply

Damper Type
Vertical Fire Damper

Damper Size
90x36

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
21x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
3rd FL West Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
3rd FL East Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU6- 3rd FL East Return

Damper Type
Vertical Fire Damper

Damper Size
114x36

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
21x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
3rd FL East Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-11

Facility Location
Jane Edna Hunter Building

Damper Location
3rd FL East Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU6- 3rd FL East Supply

Damper Type
Vertical Fire Damper

Damper Size
90x36

Damper Manufacturer
Safe Air

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
21x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
3rd FL East Mechanical Rm

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Justice Center Court Towers

1200 Ontario Street
Cleveland, Ohio 44113

Fire/Smoke Damper Inspection Report

Visual Inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 3, 2025

Project: Cuyahoga County
Court Towers

Inspector(s):

- Tristan May, Certified Technician
- Kaitlyn McElroy, Certified Technician

Inspection and Test Date(s):

- May 5, 2025 – *In progress*

As of October 31, 2025, Duct Fabricators, Inc. "Fire Safety Division" inspected (296) dampers as noted on the following sheets. The dampers were visually inspected and photographed in the "exterior" and "interior" positions to confirm that they have not been altered and are free of any obstructions. Preventative maintenance was performed, and any deficiencies addressed.

(215) Dampers passed visual inspection
(81) Dampers failed due to reasons indicated on the report

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I.D. #	Damper Type	Damper Size	Damper Manufacturer	Damper Model #	Fusible Link Temperature	Access Door Size	Pass / Fail / Abandoned	Comments / Corrections
2025-05-05	Justice Center Court Towers	5fl mechanical	Tristan May	Ac2-s5	Horizontal Fire Damper	12 rnd	Unknown	Unknown	165 Degrees	12"rnd glass	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical	Tristan May	Ac6-s1	Horizontal Fire Damper	22"rnd	Unknown	Unknown	165 Degrees	22	Pass	Limited access between duct and wall
2025-05-05	Justice Center Court Towers	5fl mechanical	Tristan May	Ef4-5fl	Horizontal Fire Damper	24*24	Ruskin	Unknown	165 Degrees	18	Fail	Need 1" and 1.5" screws to secure damper in duct. Gap around damper
2025-05-05	Justice Center Court Towers	5fl mechanical	Tristan May	Ac2-s7	Horizontal Fire Damper	12" rnd	Ruskin	Dibd20	165 Degrees	12*20	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical	Tristan May	Ac2-fd ret1	Horizontal Fire Damper	60*30	Air Balance	Unknown	165 Degrees	24	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical	Tristan May	Ahu506-fd Supply	Horizontal Fire Damper	24*30	Unknown	Unknown	165 Degrees	12	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical	Tristan May	Ex1-fd2	Horizontal Fire Damper	18*10	Air Balance	Unknown	165 Degrees	12	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical.	Tristan May	Ef5-5fl	Horizontal Fire Damper	24*24	Air Balance	Unknown	165 Degrees	20	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical.	Tristan May	Ac2-s4	Horizontal Fire Damper	13rnd	Ruskin	Unknown	165 Degrees	14*20	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical	Tristan May	Ahu506-fd ret	Horizontal Fire Damper	22*30	Ruskin	Unknown	165 Degrees	14	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical room	Tristan May	Ac2-s8	Horizontal Fire Damper	12" rnd	Unknown	Unknown	165 Degrees	12*20	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical.	Tristan May	Ac2-s3	Horizontal Fire Damper	14"rnd	Ruskin	Ibd20	165 Degrees	14*20	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical.	Tristan May	Ac2-s6	Horizontal Fire Damper	18" rnd	Ruskin	Ibd20	165 Degrees	18*20	Pass	None
2025-05-05	Justice Center Court Towers	5fl mechanical	Tristan May	Ac1-s8	Horizontal Fire Damper	13"rnd.	Ruskin	Unknown	165 Degrees	13*20	Pass	None

2025-05-05	Justice Center Court Towers	5fl mechanical.	Tristan May	Ac1-s9	Horizontal Fire Damper	20" rnd	Unknown	Unknown	165 Degrees	12	Fail	Angle not attached to damper. Space around damper
2025-05-06	Justice Center Court Towers	5fl mechanical.	Tristan May	Ac1-s6	Horizontal Fire Damper	23" rnd	Ruskin	Ibd20	165 Degrees	23*20	Pass	None
2025-05-06	Justice Center Court Towers	5fl mechanical.	Tristan May	Ac3-s1	Horizontal Fire Damper	23" rnd	Ruskin	Ibd20	165 Degrees	23*20	Pass	None
2025-05-06	Justice Center Court Towers	5fl mechanical.	Tristan May	Ef3-5fl	Horizontal Fire Damper	20*20	Air Balance	Unknown	165 Degrees	12	Pass	None
2025-05-06	Justice Center Court Towers	5fl mechanical.	Tristan May	Kitchen supply fan 1	Vertical Fire Damper	30*15	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-05-06	Justice Center Court Towers	5fl mechanical.	Tristan May	Ac1-s11	Horizontal Fire Damper	15" rnd	Ruskin	Ibd20	165 Degrees	15*20	Pass	None
2025-05-06	Justice Center Court Towers	5fl mechanical.	Tristan May	Ac1-s12	Horizontal Fire Damper	14" rnd	Ruskin	Ibd20	165 Degrees	14*20	Pass	None
2025-05-06	Justice Center Court Towers	5fl mechanical	Tristan May	Mau2-west.	Horizontal Fire Damper	36*26	Unknown	Unknown	165 Degrees	16*14	Pass	None
2025-05-06	Justice Center Court Towers	5fl mechanical	Tristan May	Ac1-s7	Horizontal Fire Damper	16" rnd	Air Balance	Unknown	165 Degrees	12	Fail	No angle, damper in floor.
2025-05-06	Justice Center Court Towers	5fl mechanical	Tristan May	Mau2-east	Horizontal Fire Damper	30*24	Unknown	Unknown.	165 Degrees	16*14	Pass	Cut welded angle
2025-05-07	Justice Center Court Towers	5fl mechanical elevator lobby.	Tristan May	Ac2-r2	Vertical Fire Damper	54*36	Unknown	Unknown	165 Degrees	18*18	Fail	No Angle damper in the floor no sleeve.
2025-05-07	Justice Center Court Towers	5fl mechanical.	Tristan May	Ac1-r1	Horizontal Fire Damper	60*28	Unknown	Unknown	165 Degrees	18	Fail	No angle, damper in floor
2025-05-07	Justice Center Court Towers	5fl mechanical elevator lobby.	Tristan May	Ac1-s5	Vertical Fire Damper	24"rnd	Unknown	Unknown	165 Degrees	13*20	Fail	No angle damper in the floor, no sleeve
2025-05-07	Justice Center Court Towers	5fl mechanical elevator lobby.	Tristan May	Ac1-s2	Horizontal Fire Damper	10" rnd	Unknown	Unknown	165 Degrees	10*20	Fail	No angle, damper in floor no sleeve.

2025-05-07	Justice Center Court Towers	5fl mechanical elevator lobby	Tristan May	Ac1-s4	Horizontal Fire Damper	20"rnd	Unknown	Unknown	165 Degrees	13*20	Fail	No angle damper in the floor, no sleeve
2025-05-07	Justice Center Court Towers	5fl mechanical elevator lobby.	Tristan May	Ac2-s2	Horizontal Fire Damper	30"rnd	Unknown	Unknown	165 Degrees	13*20	Fail	No angle damper in the floor no sleeve
2025-05-07	Justice Center Court Towers	5fl mechanical elevator lobby.	Tristan May	Ac1-s1	Horizontal Fire Damper	16"rnd	Unknown	Unknown	165 Degrees	16*20	Fail	No angle, damper in floor, no sleeve
2025-05-07	Justice Center Court Towers	5fl mechanical.	Tristan May	Ef2-5fl	Horizontal Fire Damper	24*24	Unknown	Unknown	165 Degrees	20	Fail	No angle, damper in floor, no sleeve
2025-05-07	Justice Center Court Towers	5fl mechanical elevator lobby.	Tristan May	Ac1-s3	Horizontal Fire Damper	12"rnd	Unknown	Unknown	165 Degrees	12*20	Fail	No angle damper in the floor no sleeve
2025-05-07	Justice Center Court Towers	5fl mechanical elevator lobby.	Tristan May	Ac2-s1	Horizontal Fire Damper	36	Unknown	Unknown	165 Degrees	14*20	Fail	No Angle, damper in the floor,no sleeve
2025-05-08	Justice Center Court Towers	24fl mechanical.	Tristan May	Ac14-s2	Horizontal Fire Damper	26"rnd	Unknown	Unknown	165 Degrees	26*20	Fail	No angle, no sleeve, damper in floor
2025-05-08	Justice Center Court Towers	24fl mechanical.	Tristan May	Ac14-s1	Horizontal Fire Damper	26"rnd	Unknown	Unknown	165 Degrees	26*20	Fail	No Angle no sleeve, damper in floor
2025-05-08	Justice Center Court Towers	24fl mechanical	Tristan May	Ac14-s4	Horizontal Fire Damper	27"rnd	Unknown	Unknown	165 Degrees	27*20	Fail	No angle, no sleeve, damper in floor
2025-05-08	Justice Center Court Towers	24fl mechanical.	Tristan May	Ac13-s1	Horizontal Fire Damper	23"rnd	Unknown	Unknown	165 Degrees	23*20	Fail	No angle, damper in floor, no sleeve

2025-05-08	Justice Center Court Towers	24fl mechanical.	Tristan May	Ac14-s3	Horizontal Fire Damper	25"rnd	Unknown	Unknown	165 Degrees	25*20	Fail	No angle, no sleeve, damper in floor
2025-05-08	Justice Center Court Towers	24 mechanical.	Tristan May	Ef3-24fl	Horizontal Fire Damper	32*34	Unknown	Unknown	165 Degrees	24*24	Fail	No angle, no sleeve, damper in floor
2025-05-08	Justice Center Court Towers	24fl mechanical	Tristan May	Ac14-r1	Horizontal Fire Damper	66*66	Unknown	Unknown	165 Degrees	24*24	Fail	No angle, no sleeve, damper in floor
2025-05-08	Justice Center Court Towers	24fl mechanical.	Tristan May	Ef2-24fl	Horizontal Fire Damper	34*36	Unknown	Unknown	165 Degrees	24*24	Fail	No angle, no sleeve, damper in floor
2025-05-12	Justice Center Court Towers	24 high rise elevator room.	Tristan May	Ac24-s3	Vertical Fire Damper	36*18	Ruskin	Ibd40	165 Degrees	Grill	Pass	None
2025-05-12	Justice Center Court Towers	24fl mechanical.	Tristan May	Ef5-24fl	Horizontal Fire Damper	24*24	Unknown	Unknown	165 Degrees	24*24	Fail	No angle, damper not in floor, no sleeve
2025-05-12	Justice Center Court Towers	24fl mechanical.	Tristan May	Ef4-24fl	Horizontal Fire Damper	26*24	Unknown	Unknown	165 Degrees	18*18	Fail	No Angle, damper not in floor, no angle
2025-05-12	Justice Center Court Towers	24fl elevator room.	Tristan May	I1-s1	Vertical Fire Damper	22*10	Unknown	Unknown	165 Degrees	Open	Pass	None
2025-05-12	Justice Center Court Towers	24 high rise elevator room.	Tristan May	24 HR elev room relief 2	Vertical Fire Damper	48*48	Unknown	Unknown	165 Degrees	Grill	Fail	No angle. Need 48*48 2*2 one side + tapcon
2025-05-12	Justice Center Court Towers	24fl high rise elevator room	Tristan May	H.r. Elev room relief 1	Vertical Fire Damper	48*48	Unknown	Unknown	165 Degrees	Open	Fail	No angle. Need 48*48 2*2 angle. One side + tapcon

2025-05-12	Justice Center Court Towers	24 FL elevator room.	Tristan May	Ac24-s1	Vertical Fire Damper	18*18	Ruskin	Ibd40	212 Degrees	Grill	Pass	None
2025-05-12	Justice Center Court Towers	24 j elevator room.	Tristan May	Je-ex1	Vertical Fire Damper	38*38	Ruskin	Ibd2	212 Degrees	Grill	Pass	Angle on back
2025-05-12	Justice Center Court Towers	24 high rise elevator room.	Tristan May	Ac24-s2	Vertical Fire Damper	36*18	Ruskin	Ibd40	165 Degrees	Grill	Pass	Limited access
2025-05-12	Justice Center Court Towers	24fl j elevator room.	Tristan May	J elv-s2	Vertical Fire Damper	16*16	Ruskin	Ibd2	212 Degrees	Grill	Pass	Angle on back side
2025-05-12	Justice Center Court Towers	24fl elevator room.	Tristan May	Elv 1-2 1	Vertical Fire Damper	22*10	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-12	Justice Center Court Towers	24 j elevator room.	Tristan May	J elv-s1	Vertical Fire Damper	30*30	Ruskin	Ibd2	212 Degrees	Grill	Pass	Angle on back
2025-05-12	Justice Center Court Towers	24fl mechanical.	Tristan May	J elv-ta1	Vertical Fire Damper	48*30	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-12	Justice Center Court Towers	24fl high rise elevator room.	Tristan May	Ac24-r1	Vertical Fire Damper	38*38	Ruskin	Ibd40	165 Degrees	Grill	Pass	None
2025-05-12	Justice Center Court Towers	24 mechanical.	Tristan May	J elv-ta2	Vertical Fire Damper	48*30	Unknown	Unknown	165 Degrees	Grill	Pass	None
2025-05-12	Justice Center Court Towers	24fl i2 elevator room.	Tristan May	ELV i2-s1	Vertical Fire Damper	36*16	Ruskin	Ibd40	165 Degrees	Grill	Pass	Replace existing report
2025-05-13	Justice Center Court Towers	5fl nw stairs	Tristan May	5fl-nw str	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Grill	Fail	Damper not in wall No angle. Need 2*2 1 side +tapcon
2025-05-13	Justice Center Court Towers	5fl NE stair.	Tristan May	5fl-ne str	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Grill	Fail	No angle. Need 48*24. 2*2 one side plus tapcons. No sleeve?
2025-05-19	Justice Center Court Towers	24fl mechanical	Tristan May	Ac15-r1	Vertical Fire Damper	66*66	Unknown	Unknown	165 Degrees	24*24	Fail	No sleeve, no angle, damper in floor

2025-05-19	Justice Center Court Towers	5fl s.e. stairs	Tristan May	5fl- s.e str	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Grill	Fail	No angle, no access to back side. 2*2 one side + tapcon
2025-05-19	Justice Center Court Towers	23fl south	Tristan May	23fl-sd3	Vertical Smoke Damper	13" rnd	Unknown	Unknown	N/A	12"rnd	Pass	None
2025-05-19	Justice Center Court Towers	23fl south	Tristan May	23fl-fd1	Vertical Fire Damper	12*6	Unknown	Unknown	165 Degrees	10*10	Pass	None
2025-05-19	Justice Center Court Towers	23fl south	Tristan May	23fl-sd2	Vertical Smoke Damper	11" rnd	Unknown	Unknown	165 Degrees	10" rnd	Pass	None
2025-05-19	Justice Center Court Towers	23fl north	Tristan May	23fl-sd10	Vertical Smoke Damper	11" rnd	Unknown	Unknown	N/A	10"	Pass	None
2025-05-19	Justice Center Court Towers	23fl north	Tristan May	23fl-fd10	Vertical Fire Damper	11" rnd	Unknown	Unknown	165 Degrees	10" rnd	Pass	None
2025-05-19	Justice Center Court Towers	23fl north	Tristan May	23fl-fd5	Vertical Fire Damper	12*6	Unknown	Unknown	165 Degrees	10*10	Pass	None
2025-05-19	Justice Center Court Towers	23fl north	Tristan May	23fl-fd6	Vertical Fire Damper	9"rnd	Unknown	Unknown	165 Degrees	6"rnd	Pass	None
2025-05-19	Justice Center Court Towers	24fl nw stair.	Tristan May	24fl n.w. str	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Grill	Pass	None
2025-05-19	Justice Center Court Towers	24fl n.e stair.	Tristan May	24fl n.e. str	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Grill	Pass	None
2025-05-19	Justice Center Court Towers	23 south	Tristan May	23fl-fd3	Vertical Fire Damper	13" rnd	Unknown	Unknown	165 Degrees	12" rnd	Pass	None
2025-05-19	Justice Center Court Towers	23fl south	Tristan May	23fl-fd2	Vertical Fire Damper	12"rnd	Unknown	Unknown	165 Degrees	10" nd	Pass	None
2025-05-20	Justice Center Court Towers	23rd Floor North Shaft.	Tristan May	23FL-FD23	Vertical Fire Damper	8" rnd	Air Balance	Unknown	165 Degrees	6"rnd	Pass	None
2025-05-20	Justice Center Court Towers	23rd Floor South Shaft.	Tristan May	23FL- South Return	Vertical Fire Damper	61*23	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-05-20	Justice Center Court Towers	23 Floor South Shaft.	Tristan May	23FL-South Return	Vertical Smoke Damper	61*23	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-20	Justice Center Court Towers	23rd Floor North Shaft.	Tristan May	23FL-SD23	Vertical Smoke Damper	8" Round	Unknown	Unknown	N/A	6" Round	Pass	None

2025-05-20	Justice Center Court Towers	23rd Floor South Shaft.	Tristan May	23FL-SD22	Vertical Smoke Damper	8" Round	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-20	Justice Center Court Towers	23rd Floor South Shaft.	Tristan May	23FL-FD22	Vertical Fire Damper	61*23	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-05-20	Justice Center Court Towers	23rd Floor North Shaft.	Tristan May	23FL-fd n rtn	Vertical Fire Damper	61*23	Unknown	Unknown	165 Degrees	Patch	Fail	No angle
2025-05-20	Justice Center Court Towers	23rd Floor North Shaft.	Tristan May	23FL-SD N Rtn	Vertical Smoke Damper	61*23	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-21	Justice Center Court Towers	24FL Mechanical Room.	Tristan May	AC15-S3	Horizontal Fire Damper	23" Round	Unknown	Unknown	165 Degrees	23*24	Fail	No sleeve, damper in floor with no angle
2025-05-21	Justice Center Court Towers	24th floor mechanical room.	Tristan May	AC15-S2	Horizontal Fire Damper	25" Round	Unknown	Unknown	165 Degrees	25*24	Fail	No sleeve, damper in floor no angle
2025-05-21	Justice Center Court Towers	24th floor mechanical room.	Tristan May	AC16-S1	Horizontal Fire Damper	23" Round	Unknown	Unknown	165 Degrees	23*24	Fail	No sleeve, damper in floor with no angle
2025-05-21	Justice Center Court Towers	24FL Mechanical Room.	Tristan May	AC15-S4	Horizontal Fire Damper	13" Round	Unknown	Unknown	165 Degrees	9" Round	Fail	No sleeve, damper in floor no angle
2025-05-21	Justice Center Court Towers	24th floor southeast stairwell.	Tristan May	24FL SE STR	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Grille	Fail	No sleeve, damper is installed in duct without breakaway connection
2025-05-21	Justice Center Court Towers	5th FL Southwest Stairwell.	Kaitlyn McElroy	5FL-SW STR	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Grille	Pass	None
2025-05-21	Justice Center Court Towers	24th floor mechanical room.	Tristan May	AC15-S1	Horizontal Fire Damper	27" Round	Unknown	Unknown	165 Degrees	27*24	Fail	No sleeve, damper in floor no angle

2025-05-22	Justice Center Court Towers	22nd Floor North Shaft.	Tristan May	22FL-FD22	Vertical Fire Damper	8" Round	Unknown	Unknown	165 Degrees	6" Round	Pass	None
2025-05-22	Justice Center Court Towers	22nd Floor South Shaft.	Tristan May	22FL-South Return	Vertical Smoke Damper	60*13	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-22	Justice Center Court Towers	22 floor North shaft.	Tristan May	22FL-SD23	Vertical Smoke Damper	8" Round	Unknown	Unknown	N/A	6" Round	Pass	None
2025-05-22	Justice Center Court Towers	22nd Floor South Shaft	Tristan May	22FL-South Return	Vertical Fire Damper	60*13	Unknown	Unknown	165 Degrees	Patch	Pass	None.
2025-05-22	Justice Center Court Towers	22nd Floor South Shaft.	Tristan May	22FL-FD22	Vertical Fire Damper	8" Round	Unknown	Unknown	165 Degrees	8" Round	Pass	None
2025-05-22	Justice Center Court Towers	21st Floor North Shaft.	Tristan May	21FL-North Return	Vertical Fire Damper	60*13	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-05-22	Justice Center Court Towers	22nd Floor South Shaft.	Tristan May	22FL-SD22	Vertical Smoke Damper	8" Round	Unknown	Unknown	N/A	6" Round	Pass	None
2025-05-22	Justice Center Court Towers	21st Floor North Shaft.	Tristan May	21FL-North Return	Vertical Smoke Damper	60*13	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-22	Justice Center Court Towers	22d Floor North Shaft.	Tristan May	22FL-North Return	Vertical Fire Damper	60*13	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-05-22	Justice Center Court Towers	22nd Floor North Shaft.	Tristan May	22FL-North Return	Vertical Smoke Damper	60*13	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-27	Justice Center Court Towers	P1 Garage..	Tristan May	P1-FDEX2	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Grille	Fail	No angle, wall incomplete on top. Need 2*2 angle. Need lift
2025-05-27	Justice Center Court Towers	P1 Garage.	Tristan May	P1-FDEX3	Vertical Fire Damper	120*7	Unknown	Unknown	165 Degrees	Grille	Fail	Welded angle. Need lift
2025-05-27	Justice Center Court Towers	P1 Garage.	Tristan May	P1-FDEX4	Vertical Fire Damper	108*8	Unknown	Unknown	165 Degrees	Grille	Fail	Welded angle. Need lift
2025-05-27	Justice Center Court Towers	P2 Garage.	Tristan May	P2-FD1	Vertical Fire Damper	24*24	Unknown	Unknown	165 Degrees	Grille	Pass	None

2025-05-27	Justice Center Court Towers	P1 Garage.	Tristan May	P1-FD EX6	Vertical Fire Damper	70*14	Unknown	Unknown	165 Degrees	10*10	Fail	Damper not in wall. Not secured to sleeve. Need 2.5X2.5 x14 long 16 g.
2025-05-28	Justice Center Court Towers	19th Floor North Shaft.	Tristan May	19FL-SD N RTN	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-28	Justice Center Court Towers	20th Floor South Shaft.	Tristan May	20FL-FSD22 South	Vertical Fire / Smoke Damper	8" Round	Unknown	Unknown	165 Degrees	5*9	Pass	None
2025-05-28	Justice Center Court Towers	20th Floor South Shaft.	Tristan May	20FL-FD South Return	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-05-28	Justice Center Court Towers	20th Floor South Shaft.	Tristan May	20FL-SD South Return	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-28	Justice Center Court Towers	20th Floor North Shaft.	Tristan May	20FL-SD North Return	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-28	Justice Center Court Towers	20th Floor North Shaft.	Tristan May	20FL-FD North Return	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Parch	Pass	None
2025-05-28	Justice Center Court Towers	21st Floor South Shaft.	Tristan May	21FL-FSD22 South	Vertical Fire / Smoke Damper	10" Round	Unknown	Unknown	165 Degrees	5*9	Pass	None
2025-05-28	Justice Center Court Towers	21st Floor South Shaft.	Tristan May	21FL-SD South Return	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-05-28	Justice Center Court Towers	21st Floor South Shaft.	Tristan May	21FL-FD South Return	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-05-28	Justice Center Court Towers	24th Floor Mechanical Room.	Tristan May	ELV1-2 R1	Vertical Fire Damper	32*16	Ruskin	IBD40	165 Degrees	Grille	Pass	None
2025-05-28	Justice Center Court Towers	24th Floor Mechanical Room.	Tristan May	ELV1-2EX	Vertical Fire Damper	18*16	Ruskin	IBD40	165 Degrees	Grille	Pass	None
2025-05-28	Justice Center Court Towers	24th Floor Mechanical Room.	Tristan May	AC15-S2	Horizontal Fire Damper	25" Round	Unknown	Unknown	165 Degrees	25*24	Fail	Damper in floor, no sleeve or angle

2025-05-28	Justice Center Court Towers	24th Floor Mechanical Room	Tristan May	AC15-S1	Horizontal Fire Damper	27" Round	Unknown	Unknown	165 Degrees	27*24	Fail	No angle or sleeve
2025-05-28	Justice Center Court Towers	P2 Garage Employee Tunnel	Tristan May	P2-FD2	Vertical Fire Damper	27*35	Unknown	Unknown	165 Degrees	Grille	Pass	None
2025-05-29	Justice Center Court Towers	19th Floor North Shaft.	Tristan May	19FL-FD N RTN	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-06-02	Justice Center Court Towers	19th Floor South Shaft	Tristan May	19FL-FD S RTN	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-06-02	Justice Center Court Towers	18th Floor South Shaft	Tristan May	18FL-SD S RTN	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-06-02	Justice Center Court Towers	18th Floor South Shaft.	Tristan May	18FL-FSD22	Vertical Fire / Smoke Damper	8" Round	Unknown	Unknown	165 Degrees	4*8	Pass	None
2025-06-02	Justice Center Court Towers	19th Floor South Shaft.	Tristan May	19FL-FSD22	Vertical Fire / Smoke Damper	10" Round	Unknown	Unknown	165 Degrees	8*4	Pass	None
2025-06-02	Justice Center Court Towers	17th Floor North Shaft.	Tristan May	17FL-FD N RTN	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-06-02	Justice Center Court Towers	19th Floor South Shaft.	Tristan May	19FL-SD-S RTN	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-06-02	Justice Center Court Towers	18th Floor North Shaft	Tristan May	18FL-FD N RTN	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-06-02	Justice Center Court Towers	18th Floor North Shaft	Tristan May	18FL-SD N RTN	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-06-02	Justice Center Court Towers	17th Floor South Shaft.	Tristan May	17FL-FSD22	Vertical Fire / Smoke Damper	10" Round	Unknown	Unknown	165 Degrees	4*8	Pass	None
2025-06-02	Justice Center Court Towers	18th Floor South Shaft.	Tristan May	18FL-FD S RTN	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-06-02	Justice Center Court Towers	17th Floor South Shaft.	Tristan May	17FL-SD S RTN	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	60*12	Pass	None
2025-06-02	Justice Center Court Towers	17th Floor North Shaft	Tristan May	17FL-SD N RTN	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None

2025-06-02	Justice Center Court Towers	16th Floor North Shaft.	Tristan May	16FL-FD N RTN	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-06-02	Justice Center Court Towers	16th Floor North Shaft.	Tristan May	16FL-SD N RTN	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-06-02	Justice Center Court Towers	17th Floor South Shaft.	Tristan May	17FL-FD S RTN	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-06-03	Justice Center Court Towers	15th Floor North Shaft.	Tristan May	15FL-SD23	Vertical Smoke Damper	8" Round	Air Balance	Unknown	N/A	6" Round	Pass	None
2025-06-03	Justice Center Court Towers	14th Floor North Shaft.	Tristan May	14FL-SD N RTN	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-06-03	Justice Center Court Towers	16th Floor South Shaft.	Tristan May	16FL-FD-S RTN	Vertical Fire Damper	60*12	Unknown	Unknown	165 Degrees	Patch	Pass	None
2025-06-03	Justice Center Court Towers	15th Floor South Shaft.	Tristan May	15FL-FD S RTN	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-06-03	Justice Center Court Towers	15th Floor South Shaft.	Tristan May	15FL-SD S RTN	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-06-03	Justice Center Court Towers	15th Floor North Shaft.	Tristan May	15FL-FD23	Vertical Fire Damper	8" Round	Air Balance	Unknown	165 Degrees	6" Round	Pass	None
2025-06-03	Justice Center Court Towers	16th Floor South Shaft.	Tristan May	16FL-SD-S RTN	Vertical Smoke Damper	60*12	Unknown	Unknown	N/A	Patch	Pass	None
2025-06-03	Justice Center Court Towers	15th Floor South Shaft.	Tristan May	15FL-FD22	Vertical Fire Damper	8" Round	Air Balance	Unknown	165 Degrees	6" Round	Pass	None
2025-06-03	Justice Center Court Towers	15th Floor South Shaft.	Tristan May	15FL-SD22	Vertical Smoke Damper	8" Round	Air Balance	Unknown	N/A	6" Round	Pass	None
2025-06-03	Justice Center Court Towers	15th Floor North Shaft.	Tristan May	15FL-SD N RTN	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-06-03	Justice Center Court Towers	14th Floor North Shaft.	Tristan May	14FL-FD N RTN	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-06-03	Justice Center Court Towers	15th Floor North Shaft.	Tristan May	15FL-FD N RTN	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-06-03	Justice Center Court Towers	16th Floor South Shaft	Tristan May	16FL-FSD22	Vertical Fire / Smoke Damper	10" Round	Unknown	Unknown	165 Degrees	4*8	Pass	None

2025-06-04	Justice Center Court Towers	24th Floor Elevator Room.	Tristan May	ELV I1-S1	Vertical Fire Damper	22*10	Ruskin	IBD40	165 Degrees	10*10	Pass	None
2025-06-04	Justice Center Court Towers	14th Floor South Shaft.	Tristan May	14FL-SD S RTN	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-06-04	Justice Center Court Towers	24th Floor Southwest Stairwell.	Tristan May	24FL-SW STR	Vertical Fire Damper	48*24	Air Balance	Unknown	165 Degrees	Grille	Pass	None
2025-06-04	Justice Center Court Towers	13th Floor South Shaft.	Tristan May	13FL-FSD22	Vertical Fire / Smoke Damper	8" Round	Ruskin	Unknown	165 Degrees	8*4	Pass	None
2025-06-04	Justice Center Court Towers	13th Floor North Shaft.	Tristan May	13FL-SD N RTN	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-06-04	Justice Center Court Towers	14th Floor South Shaft.	Tristan May	14FL-FSD22	Vertical Fire / Smoke Damper	10" Round	Ruskin	Unknown	165 Degrees	4"r	Pass	None
2025-06-04	Justice Center Court Towers	14th Floor South Shaft.	Tristan May	14FL-FD S RTN	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-06-04	Justice Center Court Towers	13th Floor North Shaft.	Tristan May	13FL-FD N RTN	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-06-04	Justice Center Court Towers	24th Floor Elevator Room.	Tristan May	ELV I1-R1	Vertical Fire Damper	36*13	Ruskin	IBD40	165 Degrees	12*12	Pass	None
2025-06-04	Justice Center Court Towers	13th Floor South Shaft.	Tristan May	13FL-FD S RTN	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-06-04	Justice Center Court Towers	13th Floor South Shaft.	Tristan May	13FL-SD S RTN	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-06-05	Justice Center Court Towers	5A G Mechanical Room.	Kaitlyn McElroy	G ELV-R1	Horizontal Fire Damper	36*18	Ruskin	IBD40	165 Degrees	16*16	Pass	None
2025-06-05	Justice Center Court Towers	5A G Mechanical Room.	Tristan May	G ELV-S1	Horizontal Fire Damper	16*18	Unknown	Unknown	165 Degrees	10*10	Pass	None
2025-06-05	Justice Center Court Towers	24th Floor Elevator Room.	Tristan May	J ELV-S3	Vertical Fire Damper	30*22	Ruskin	IBD2	165 Degrees	Grille	Pass	None

2025-07-17	Justice Center Court Towers	12FL Mens Restroom.	Tristan May	12FL-SD3 S	Vertical Smoke Damper	13R	Air Balance	Unknown	N/A	10R	Pass	None
2025-07-17	Justice Center Court Towers	12FL Mens Restroom.	Tristan May	12FL-FD3 S	Vertical Fire Damper	13R	Air Balance	Unknown	165 Degrees	10R	Pass	None
2025-07-17	Justice Center Court Towers	12FL Womens Restroom.	Tristan May	12FL-SD2 S	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	10" R	Pass	None
2025-07-17	Justice Center Court Towers	12FL Computer Training Room.	Tristan May	12FL-SD2 N	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	8*4	Pass	None
2025-07-17	Justice Center Court Towers	12FL Computer Training Room.	Tristan May	12FL-FD2 N	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	8*4	Pass	None
2025-07-17	Justice Center Court Towers	12FL Computer Training Room.	Tristan May	12FL-FSD1 N	Vertical Fire / Smoke Damper	16" R	Ruskin	Unknown	165 Degrees	7*7	Pass	None
2025-07-17	Justice Center Court Towers	12FL Womens Restroom.	Tristan May	12FL-FD2 S	Vertical Fire Damper	13R	Air Balance	Unknown	165 Degrees	10R	Pass	None
2025-07-21	Justice Center Court Towers	5th Floor Mechanical Room	Tristan May	5FL-Bath Exhaust	Horizontal Fire Damper	10*11	Unknown	Unknown	165 Degrees	10*12	Pass	Next to mens bathroom
2025-07-22	Justice Center Court Towers	2FL Probation Office Hallway.	Tristan May	2FL-FD8 North	Vertical Fire Damper	8" R	Unknown	Unknown	165 Degrees	6" R	Fail	No Angle. Sleeve not through wall.
2025-07-23	Justice Center Court Towers	Sally Port Dock 2 Hallway.	Tristan May	P1-SD7	Vertical Smoke Damper	26*10	Air Balance	Unknown	165 Degrees	Open	Pass	None
2025-07-28	Justice Center Court Towers	4FL Galleria.	Tristan May	G-4FL SD3	Vertical Smoke Damper	16" R	Air Balance	Unknown	N/A	8*4	Pass	None
2025-07-28	Justice Center Court Towers	4FL Galleria.	Tristan May	G-4FL SD2	Vertical Smoke Damper	12" R	Air Balance	Unknown	N/A	8*4	Pass	None

2025-08-05	Justice Center Court Towers	7FL Classroom 731.	Tristan May	7FL-FD12 N	Vertical Fire Damper	20*8	Air Balance	Unknown	165 Degrees	8*6	Fail	No Angle.
2025-08-13	Justice Center Court Towers	3FL Galleria	Tristan May	G-3FL SD4	Vertical Smoke Damper	11*12	Air Balance	Unknown	N/A	7*7	Pass	None
2025-08-13	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD2	Vertical Smoke Damper	9" R	Air Balance	Unknown	N/A	9*6	Pass	None
2025-08-13	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 FD S R	Vertical Fire Damper	36*12	Air Balance	Unknown	165 Degrees	Patch	Pass	None
2025-08-13	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD5	Vertical Smoke Damper	12" R	Air Balance	Unknown	N/A	9*6	Pass	None
2025-08-13	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD S R	Vertical Smoke Damper	36*12	Air Balance	Unknown	N/A	36*12	Pass	None
2025-08-13	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD3	Vertical Smoke Damper	16*12	Air Balance	Unknown	N/A	12*12	Pass	None
2025-08-13	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD1	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	9*6	Pass	None
2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 FD1	Vertical Fire Damper	15" R	Air Balance	Unknown	165 Degrees	7*3	Pass	None
2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD6	Vertical Smoke Damper	14*12	Air Balance	Unknown	N/A	8*8	Fail	More than 2' away from fire barrier
2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD8	Vertical Smoke Damper	12" R	Air Balance	Unknown	N/A	8*4	Fail	More than 2' from fire rated barrier.
2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD7	Vertical Smoke Damper	12" R	Air Balance	Unknown	N/A	8*4	Fail	More than 2' away from fire rated barrier
2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 FD3	Vertical Fire Damper	24*14	Air Balance	Unknown	165 Degrees	7*7	Fail	No Angle.
2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 FD2	Vertical Fire Damper	44*10	Air Balance	Unknown	165 Degrees	10*8	Fail	No Angle. No wall.

2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 FD4	Vertical Fire Damper	10" R	Air Balance	Unknown	165 Degrees	Flex	Fail	No sleeve. No Angle
2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 FD N R	Vertical Fire Damper	54*12	Air Balance	Unknown	165 Degrees	12*8	Fail	No breakaway connection
2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD N R	Vertical Smoke Damper	54*12	Air Balance	Unknown	N/A	12*8	Pass	None
2025-08-18	Justice Center Court Towers	3FL Galleria.	Tristan May	G-FL3 SD9	Vertical Smoke Damper	10" R	Air Balance	Unknown	N/A	9*6	Pass	None
2025-08-18	Justice Center Court Towers	4FL Galleria.	Tristan May	G-4FL SD N R1	Vertical Smoke Damper	54*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-08-18	Justice Center Court Towers	4FL Galleria.	Tristan May	G-4FL FD N R1	Vertical Fire Damper	54*12	Air Balance	Unknown	165 Degrees	Patch	Pass	.
2025-08-18	Justice Center Court Towers	4FL Galleria.	Tristan May	G-4FL SD1	Vertical Smoke Damper	12" R	Air Balance	Unknown	N/A	8*4	Pass	None
2025-08-19	Justice Center Court Towers	45A Closet.	Tristan May	4FL-AHU4.1-S8	Vertical Fire Damper	10*8	Air Balance	Unknown	165 Degrees	8*8	Fail	No Angle.
2025-09-03	Justice Center Court Towers	Bailiff A	Tristan May	22FL-FD12	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-09-03	Justice Center Court Towers	Holding A	Tristan May	22FL-FD14	Vertical Fire Damper	8*6	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-09-03	Justice Center Court Towers	Holding C	Tristan May	22FL-SD13	Vertical Smoke Damper	16*10	Air Balance	Unknown	N/A	12*12	Pass	None
2025-09-03	Justice Center Court Towers	Bench C	Tristan May	22FL-FD15	Vertical Fire Damper	8" R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-09-03	Justice Center Court Towers	Bench C.	Tristan May	22FL-SD15	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-09-03	Justice Center Court Towers	Holding C.	Tristan May	22FL-FD13	Vertical Fire Damper	16*10	Air Balance	Unknown	165 Degrees	12*12	Fail	No breakaway connection.
2025-09-03	Justice Center Court Towers	Holding A.	Tristan May	22FL-SD14	Vertical Smoke Damper	8*6	Air Balance	Unknown	N/A	6*6	Pass	None

2025-09-03	Justice Center Court Towers	Bailiff A.	Tristan May	22FL-SD12	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-09-08	Justice Center Court Towers	Jury Room Hallway	Tristan May	4FL-SD4 N	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-09-08	Justice Center Court Towers	Kitchen	Tristan May	4FL-SD1 S	Vertical Smoke Damper	12" R	Air Balance	Unknown	N/A	10" R	Fail	Inaccessible, hard ceiling.
2025-09-08	Justice Center Court Towers	Kitchen Break Room	Tristan May	4FL-SD2 S	Vertical Smoke Damper	11" R	Air Balance	Unknown	N/A	10" R	Pass	None
2025-09-08	Justice Center Court Towers	Kitchen- Above Sinks	Tristan May	4FL-SD S RTN	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	20*20	Fail	Electrical piping blocks access to damper.
2025-09-08	Justice Center Court Towers	Jury Room Hallway	Tristan May	4FL-FD6 N	Vertical Fire Damper	11" R	Air Balance	Unknown	165 Degrees	9" R	Pass	None
2025-09-08	Justice Center Court Towers	Jury Room - Women's Restroom	Tristan May	4FL-FD9 N	Vertical Fire Damper	6" R	Air Balance	Unknown	165 Degrees	4*6	Abandoned	None
2025-09-08	Justice Center Court Towers	Jury Room	Tristan May	4FL-FD5 N	Vertical Fire Damper	11" R	Air Balance	Unknown	165 Degrees	9" R	Fail	Damper not secured in wall
2025-09-08	Justice Center Court Towers	Kitchen	Tristan May	4FL-FD1 S	Vertical Fire Damper	12" R	Air Balance	Unknown	165 Degrees	10" R	Fail	Inaccessible, hard ceiling
2025-09-08	Justice Center Court Towers	Kitchen Breakroom	Tristan May	4FL-FD3 S	Vertical Fire Damper	20x12	Air Balance	Unknown	165 Degrees	10*10	Pass	None
2025-09-08	Justice Center Court Towers	Kitchen Breakroom	Tristan May	4FL-FD2 S	Vertical Fire Damper	11* R	Air Balance	Unknown	165 Degrees	10" R	Pass	None
2025-09-08	Justice Center Court Towers	Kitchen	Tristan May	4FL-FD S RTN	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	20*20	Fail	Electrical piping is blocking access to damper
2025-09-08	Justice Center Court Towers	Jury Assembly Room	Tristan May	4FL-SD7 N	Vertical Smoke Damper	36*12	Unknown	Unknown	N/A	Open	Fail	Not in a fire rated wall. Abandoned?

2025-09-08	Justice Center Court Towers	Jury Assembly Room	Tristan May	4FL-SD8 N	Vertical Smoke Damper	54*12	Unknown	Unknown	N/A	Open	Fail	Damper not in a fire rated wall. Abandoned?
2025-09-08	Justice Center Court Towers	Jury Assembly Room	Tristan May	4FL-SD6 N	Vertical Smoke Damper	11" R	Air Balance	Unknown	N/A	9" R	Pass	None
2025-09-08	Justice Center Court Towers	Jury Assembly Room- Women's Restroom	Tristan May	4FL-SD9 N	Vertical Smoke Damper	6" R	Unknown	Unknown	N/A	4*6	Abandoned	None
2025-09-08	Justice Center Court Towers	Jury Assembly Room	Tristan May	4FL-SD5 N	Vertical Smoke Damper	11" R	Air Balance	Unknown	N/A	9" R	Pass	None
2025-09-08	Justice Center Court Towers	Jury Assembly Room	Tristan May	4FL-FD4 N	Vertical Fire Damper	8" R	Air Balance	Unknown	165 Degrees	6" R	Fail	Damper not in wall.
2025-09-08	Justice Center Court Towers	Jury Assembly Room- Office Hallway	Tristan May	4FL-FD10 N	Vertical Fire Damper	14*10	Unknown	Unknown	165 Degrees	10*10	Fail	Damper not secured in wall.
2025-09-09	Justice Center Court Towers	Jury - Training Room Hallway	Tristan May	4FL-FD1 N	Vertical Fire Damper	12" R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-09-09	Justice Center Court Towers	Jury Assembly Room	Tristan May	4FL-FD8 N	Vertical Fire Damper	24*15	Air Balance	Unknown	165 Degrees	10*10	Fail	Damper not secured in wall.
2025-09-09	Justice Center Court Towers	Jury - Training Room Hallway	Tristan May	4FL-FD N RTN	Vertical Fire Damper	60*12	Air Balance	Unknown	165 Degrees	Patch	Fail	Damper not secured in wall
2025-09-09	Justice Center Court Towers	Jury - Training Room Hallway	Tristan May	4FL-SD2 N	Vertical Smoke Damper	9" R	Air Balance	Unknown	N/A	6" R	Pass	None

2025-09-09	Justice Center Court Towers	Jury Assembly Room - Reception Office	Tristan May	4FL-SD12 N	Vertical Smoke Damper	48*14	Air Balance	Unknown	N/A	Open	Pass	None
2025-09-09	Justice Center Court Towers	Jury - Training Room Hallway	Tristan May	4FL-SD1 N	Vertical Smoke Damper	12" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-09-09	Justice Center Court Towers	Jury - Training Room Hallway	Tristan May	4FL-FD2 N	Vertical Fire Damper	9" R	Air Balance	Unknown	165 Degrees	6" R	Fail	Angle attached to ductwork not damper sleeve
2025-09-09	Justice Center Court Towers	Jury - Training Room Halway	Tristan May	4FL-SD N RTN	Vertical Smoke Damper	60*12	Air Balance	Unknown	N/A	Patch	Pass	None
2025-09-09	Justice Center Court Towers	Jury Assembly Room	Tristan May	4FL-SD11 N	Vertical Smoke Damper	20*10	Air Balance	Unknown	N/A	Grille	Fail	Damper more than 2' away from fire rated barrier
2025-09-11	Justice Center Court Towers	Holding C	Tristan May	21FL-FD14	Vertical Fire Damper	20*10	Air Balance	Unknown	165 Degrees	12*12	Fail	No breakaway connection.
2025-09-11	Justice Center Court Towers	Bench D	Tristan May	22FL-FD21	Vertical Fire Damper	8" R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-09-11	Justice Center Court Towers	Holding D	Tristan May	22FL-FD20	Vertical Fire Damper	10*6	Air Balance	Unknown	165 Degrees	8*8	Fail	Need angle, no breakaway connection
2025-09-11	Justice Center Court Towers	Bailiff B	Tristan May	22FL-FD17	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	6" R	Fail	Fire damper not in wall
2025-09-11	Justice Center Court Towers	Conference D	Tristan May	22FL-SD18	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	10" R	Pass	None
2025-09-11	Justice Center Court Towers	Conference C	Tristan May	22FL-FD16	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	10" R	Fail	No breakaway connection.

2025-09-11	Justice Center Court Towers	Bailiff A	Tristan May	21FL-FD12	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	6" R	Fail	No breakaway connection
2025-09-11	Justice Center Court Towers	Bailiff B	Tristan May	22FL-SD17	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-09-11	Justice Center Court Towers	Bench D	Tristan May	22FL-SD21	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-09-11	Justice Center Court Towers	Holding B	Tristan May	22FL-FD19	Vertical Fire Damper	16*10	Air Balance	Unknown	165 Degrees	7*7	Fail	No breakaway connection
2025-09-11	Justice Center Court Towers	Conference D	Tristan May	22FL-FD18	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	10" R	Fail	No breakaway connection
2025-09-11	Justice Center Court Towers	Conference D	Tristan May	22FL-SD24	Vertical Smoke Damper	Unknown	Unknown	Unknown	N/A	Open	Fail	Unable to access damper
2025-09-11	Justice Center Court Towers	Conference C	Tristan May	22FL-SD16	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	10" R	Pass	None
2025-09-11	Justice Center Court Towers	Bailiff A	Tristan May	21FL-SD12	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-09-11	Justice Center Court Towers	Holding A	Tristan May	21FL-FD13	Vertical Fire Damper	10*6	Air Balance	Unknown	165 Degrees	6*6	Fail	No breakaway connection
2025-09-11	Justice Center Court Towers	Holding C	Tristan May	21FL-SD14	Vertical Smoke Damper	20*10	Air Balance	Unknown	N/A	12*12	Pass	None
2025-09-11	Justice Center Court Towers	Bench A	Tristan May	21FL-FD21	Vertical Fire Damper	14*10	Air Balance	Unknown	165 Degrees	10*10	Fail	No breakaway connection
2025-09-23	Justice Center Court Towers	4FL South Corridor.	Tristan May	4FL-FD14 S	Vertical Fire Damper	48*24	Air Balance	119 C	165 Degrees	Grille	Pass	None
2025-10-15	Justice Center Court Towers	9Fl outside 9e	Tristan May	9FL- SD9 N	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	Patch	Pass	None
2025-10-15	Justice Center Court Towers	9FL outside 9e.	Tristan May	9FL- SD6 N	Vertical Fire Damper	17" R	Air Balance	Unknown	N/A	15" R	Fail	Damper out of wall

2025-10-20	Justice Center Court Towers	North Stairwell	Tristan May	NS 6FL FD2	Vertical Fire Damper	26*8	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-10-20	Justice Center Court Towers	North Stairwell	Tristan May	NS 6FL FD4	Vertical Fire Damper	15" R	Air Balance	Unknown	165 Degrees	12"	Pass	None
2025-10-20	Justice Center Court Towers	North Stairwell	Tristan May	NS 6FL FSD3	Vertical Fire / Smoke Damper	6*12	Prefco Products	Unknown	165 Degrees	4*4	Pass	None
2025-10-22	Justice Center Court Towers	South stairwell	Tristan May	SS 10FL FD1	Vertical Fire Damper	14"R	Air Balance	Unknown	165 Degrees	12"R	Pass	None
2025-10-22	Justice Center Court Towers	Sherrif records hallway.	Tristan May	3FL-FD1 S	Vertical Fire Damper	10"R	Air Balance	Unknown	165 Degrees	9"R	Pass	No angle no sleeve
2025-10-27	Justice Center Court Towers	Bailiff B.	Tristan May	18FL-FD18	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-10-27	Justice Center Court Towers	Holding D.	Tristan May	18FL-SD20	Vertical Smoke Damper	20*10	Air Balance	Unknown	N/A	12*12	Pass	None
2025-10-27	Justice Center Court Towers	Bench D.	Tristan May	18FL-FD21	Vertical Fire Damper	8" R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-10-27	Justice Center Court Towers	Conference D.	Tristan May	18FL-FD17	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	10" R	Pass	None
2025-10-27	Justice Center Court Towers	Bailiff B.	Tristan May	19FL-SD18	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-10-27	Justice Center Court Towers	Holding B.	Tristan May	19FL-FD19	Vertical Fire Damper	8*6	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-10-27	Justice Center Court Towers	Holding D.	Tristan May	19FL-FD20	Vertical Fire Damper	20*10	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-10-27	Justice Center Court Towers	Bench D.	Tristan May	19FL-SD21	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-10-27	Justice Center Court Towers	Conference D.	Tristan May	19FL-FD17	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	10" R	Pass	None
2025-10-27	Justice Center Court Towers	Holding B	Tristan May	19FL-SD19	Vertical Smoke Damper	8*6	Air Balance	Unknown	N/A	6*6	Pass	None
2025-10-27	Justice Center Court Towers	Holding D	Tristan May	19FL-SD20	Vertical Smoke Damper	20*10	Air Balance	Unknown	N/A	12*12	Pass	None

2025-10-27	Justice Center Court Towers	Bench D	Tristan May	19FL-FD21	Vertical Fire Damper	8" R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-10-27	Justice Center Court Towers	Conference D	Tristan May	19FL-SD17	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	10" R	Pass	None
2025-10-27	Justice Center Court Towers	Bench D	Tristan May	18FL-SD21	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-10-27	Justice Center Court Towers	Conference D	Tristan May	18FL-SD17	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	10" R	Pass	None
2025-10-27	Justice Center Court Towers	Holding D	Tristan May	18FL-FD20	Vertical Fire Damper	20*10	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-10-27	Justice Center Court Towers	Holding B	Tristan May	18FL-FD19	Vertical Fire Damper	8*6	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-10-27	Justice Center Court Towers	Bailiff B	Tristan May	18FL-SD18	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-10-27	Justice Center Court Towers	Bailiff B	Tristan May	19FL-FD18	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	6" R	Fail	Angle not properly installed.
2025-10-28	Justice Center Court Towers	Bailiff A.	Tristan May	19FL-FD12	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	6" R	Fail	Not properly secured in wall
2025-10-28	Justice Center Court Towers	Holding A.	Tristan May	19FL-FD13	Vertical Fire Damper	8*6	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-10-28	Justice Center Court Towers	Holding C.	Tristan May	19FL-FD14	Vertical Fire Damper	20*10	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-10-28	Justice Center Court Towers	Bench C.	Tristan May	19FL-FD15	Vertical Fire Damper	8" R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-10-28	Justice Center Court Towers	Conference C.	Tristan May	19FL-SD16	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	11" R	Pass	None
2025-10-28	Justice Center Court Towers	Bench A.	Tristan May	18FL-FD11	Vertical Fire Damper	14*10	Air Balance	Unknown	165 Degrees	10*10	Pass	None
2025-10-28	Justice Center Court Towers	Bailiff A.	Tristan May	18FL-SD12	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	6" R	Pass	None

2025-10-28	Justice Center Court Towers	Holding A.	Tristan May	18FL-SD13	Vertical Smoke Damper	10*6	Air Balance	Unknown	N/A	Patch	Pass	Added access door
2025-10-28	Justice Center Court Towers	Holding C.	Tristan May	18FL-SD14	Vertical Smoke Damper	20*14	Air Balance	Unknown	N/A	12*12	Pass	None
2025-10-28	Justice Center Court Towers	Bench C.	Tristan May	18FL-FD15	Vertical Fire Damper	8" R	Air Balance	Unknown	165 Degrees	6" R	Pass	None
2025-10-28	Justice Center Court Towers	Conference C.	Tristan May	18FL-SD16	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	10" R	Pass	None
2025-10-28	Justice Center Court Towers	Bench C	Tristan May	18FL-SD15	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-10-28	Justice Center Court Towers	Holding A	Tristan May	18FL-FD13	Vertical Fire Damper	10*6	Air Balance	Unknown	165 Degrees	6*6	Pass	None
2025-10-28	Justice Center Court Towers	Bailiff A	Tristan May	18FL-FD12	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	6" R	Fail	Damper not properly secured in wall
2025-10-28	Justice Center Court Towers	Holding C	Tristan May	18FL-FD14	Vertical Fire Damper	20*10	Air Balance	Unknown	165 Degrees	12*12	Pass	None
2025-10-28	Justice Center Court Towers	Conference C	Tristan May	19FL-FD16	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	10" R	Pass	None
2025-10-28	Justice Center Court Towers	Bench C	Tristan May	19FL-SD15	Vertical Smoke Damper	8" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-10-28	Justice Center Court Towers	Holding C	Tristan May	19FL-SD14	Vertical Smoke Damper	20*10	Air Balance	Unknown	N/A	12*12	Pass	None
2025-10-28	Justice Center Court Towers	Bailiff A	Tristan May	19FL-SD12	Vertical Smoke Damper	13" R	Air Balance	Unknown	N/A	6" R	Pass	None
2025-10-28	Justice Center Court Towers	Bench A	Tristan May	19FL-FD11	Vertical Fire Damper	14*10	Air Balance	Unknown	165 Degrees	10*10	Pass	None
2025-10-28	Justice Center Court Towers	Conference C	Tristan May	18FL-FD16	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	10" R	Pass	None
2025-10-28	Justice Center Court Towers	Holding A	Tristan May	19FL-SD13	Vertical Smoke Damper	10*6	Unknown	Unknown	N/A	Patch	Pass	Cut in access door

2025-10-30	Justice Center Court Towers	Room 811	Kaitlyn McElroy	8FL-FD21 N	Vertical Fire Damper	13" R	Air Balance	Unknown	165 Degrees	Patch	Fail	No angle, no breakaway connection

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-22

Facility Location
Justice Center Court Towers

Damper Location
Sherrif Records Hallway

Inspector Name
Tristan May

Damper I.D. #
3FL-FD1 S

Damper Type
Vertical Fire Damper

Damper Size
10"R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9"R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-19

Facility Location
Justice Center Court Towers

Damper Location
45A Closet

Inspector Name
Tristan May

Damper I.D. #
4FL-AHU4.1-S8

Damper Type
Vertical Fire Damper

Damper Size
10*8

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-09

Facility Location
Justice Center Court Towers

Damper Location
Jury - Training Room Hallway

Inspector Name
Tristan May

Damper I.D.
4FL-FD N RTN

Damper Type
Vertical Fire Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not secured in wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Kitchen

Inspector Name
Tristan May

Damper I.D. #
4FL-FD S RTN

Damper Type
Vertical Fire Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
Electrical piping is blocking access to damper.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-09

Facility Location
Justice Center Court Towers

Damper Location
Jury - Training Room Hallway

Inspector Name
Tristan May

Damper I.D. #
4FL-FD1 N

Damper Type
Vertical Fire Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Kitchen

Inspector Name
Tristan May

Damper I.D.
4FL-FD1 S

Damper Type
Vertical Fire Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Inaccessible, hard ceiling.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-09

Facility Location
Justice Center Court Towers

Damper Location
Jury - Training Room Hallway

Inspector Name
Tristan May

Damper I.D. #
4FL-FD2 N

Damper Type
Vertical Fire Damper

Damper Size
9" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Angle attached to ductwork not damper sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Kitchen Breakroom

Inspector Name
Tristan May

Damper I.D. #
4FL-FD2 S

Damper Type
Vertical Fire Damper

Damper Size
11* R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Kitchen Breakroom

Inspector Name
Tristan May

Damper I.D.
4FL-FD3 S

Damper Type
Vertical Fire Damper

Damper Size
20x12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Assembly Room

Inspector Name
Tristan May

Damper I.D. #
4FL-FD4 N

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Room

Inspector Name
Tristan May

Damper I.D.
4FL-FD5 N

Damper Type
Vertical Fire Damper

Damper Size
11" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not secured in wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Room Hallway

Inspector Name
Tristan May

Damper I.D. #
4FL-FD6 N

Damper Type
Vertical Fire Damper

Damper Size
11" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-09

Facility Location
Justice Center Court Towers

Damper Location
Jury Assembly Room

Inspector Name
Tristan May

Damper I.D. #
4FL-FD8 N

Damper Type
Vertical Fire Damper

Damper Size
24*15

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not secured in wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Room - Women's Restroom

Inspector Name
Tristan May

Damper I.D. #
4FL-FD9 N

Damper Type
Vertical Fire Damper

Damper Size
6" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
4*6

Pass / Fail / Abandoned
Abandoned

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Assembly Room- Office Hallway

Inspector Name
Tristan May

Damper I.D. #
4FL-FD10 N

Damper Type
Vertical Fire Damper

Damper Size
14*10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not secured in wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-23

Facility Location
Justice Center Court Towers

Damper Location
4FL South Corridor

Inspector Name
Tristan May

Damper I.D. #
4FL-FD14 S

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model #
119 C

Fusible Link Temperature
165 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-09

Facility Location
Justice Center Court Towers

Damper Location
Jury – North Training Room Hallway

Inspector Name
Tristan May

Damper I.D.
4FL-SD N RTN

Damper Type
Vertical Smoke Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Kitchen- Above Sinks

Inspector Name
Tristan May

Damper I.D.
4FL-SD S RTN

Damper Type
Vertical Smoke Damper

Damper Size
60*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
20*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
Electrical piping blocks access to damper.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-09

Facility Location
Justice Center Court Towers

Damper Location
Jury - Training Room Hallway

Inspector Name
Tristan May

Damper I.D. #
4FL-SD1 N

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Kitchen

Inspector Name
Tristan May

Damper I.D. #
4FL-SD1 S

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Inaccessible, hard ceiling.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-09

Facility Location
Justice Center Court Towers

Damper Location
Jury - Training Room Hallway

Inspector Name
Tristan May

Damper I.D. #
4FL-SD2 N

Damper Type
Vertical Smoke Damper

Damper Size
9" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Kitchen Break Room

Inspector Name
Tristan May

Damper I.D. #
4FL-SD2 S

Damper Type
Vertical Smoke Damper

Damper Size
11" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Room Hallway

Inspector Name
Tristan May

Damper I.D. #
4FL-SD4 N

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Assembly Room

Inspector Name
Tristan May

Damper I.D. #
4FL-SD5 N

Damper Type
Vertical Smoke Damper

Damper Size
11" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
9" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Assembly Room

Inspector Name
Tristan May

Damper I.D.
4FL-SD7 N

Damper Type
Vertical Smoke Damper

Damper Size
36*12

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
Not in a fire rated wall. Abandoned?

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Assembly Room

Inspector Name
Tristan May

Damper I.D.
4FL-SD8 N

Damper Type
Vertical Smoke Damper

Damper Size
54*12

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in a fire rated wall.
Abandoned?

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-08

Facility Location
Justice Center Court Towers

Damper Location
Jury Assembly Room- Women's Restroom

Inspector Name
Tristan May

Damper I.D.
4FL-SD9 N

Damper Type
Vertical Smoke Damper

Damper Size
6" R

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
4*6

Pass / Fail / Abandoned
Abandoned

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-09

Facility Location
Justice Center Court Towers

Damper Location
Jury Assembly Room

Inspector Name
Tristan May

Damper I.D.
4FL-SD11 N

Damper Type
Vertical Smoke Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Grille

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper more than 2' away from fire rated wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-09

Facility Location
Justice Center Court Towers

Damper Location
Jury Assembly Room - Reception Office

Inspector Name
Tristan May

Damper I.D.
4FL-SD12 N

Damper Type
Vertical Smoke Damper

Damper Size
48*14

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-19

Facility Location
Justice Center Court Towers

Damper Location
5fl s.e. stairs

Inspector Name
Tristan May

Damper I.D.
5fl- se str

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no access to back side. 2*2 one side + tapcon

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Justice Center Court Towers

Damper Location
5fl NE stair.

Inspector Name
Tristan May

Damper I.D.
5fl-ne str

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle. Need 48*24. 2*2 one side plus tapcons. No sleeve?

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-13

Facility Location
Justice Center Court Towers

Damper Location
5fl nw stairs

Inspector Name
Tristan May

Damper I.D.
5fl-nw str

Damper Type
Vertical Fire Damper

Damper Size
48*24

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not in wall No angle. Need 2*2 1 side +tapcon

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-25

Facility Location
Justice Center Court Towers

Damper Location
6FL Shaft 1 North

Inspector Name
Larry Coreno

Damper I.D. #
6FL-FD2 Shaft 1

Damper Type
Horizontal Fire Damper

Damper Size
23"

Damper Manufacturer
Ruskin

Damper Model #
IBD20W

Fusible Link Temperature
165 Degrees

Access Door Size
24x23

Pass / Fail / Abandoned
Pass

Comments / Corrections
Replaced fire damper added new door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-26

Facility Location
Justice Center Court Towers

Damper Location
12FL North Education Center

Inspector Name
Larry Coreno

Damper I.D. #
12FL-FD19 North

Damper Type
Vertical Fire Damper

Damper Size
8" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
Canvas

Pass / Fail / Abandoned
Pass

Comments / Corrections
. Take off canvas to inspect

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bench A.

Inspector Name
Tristan May

Damper I.D.
17FL-FD11

Damper Type
Vertical Fire Damper

Damper Size
14*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
17FL-FD12

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D. #
17FL-FD13

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
17FL-SD12

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D.
17FL-SD13

Damper Type
Vertical Smoke Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
Cut in access door.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bench A

Inspector Name
Tristan May

Damper I.D.
18FL-FD11

Damper Type
Vertical Fire Damper

Damper Size
14*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
18FL-FD12

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper not properly secured in wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D.
18FL-FD13

Damper Type
Vertical Fire Damper

Damper Size
10*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D.
18FL-FD14

Damper Type
Vertical Fire Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bench C

Inspector Name
Tristan May

Damper I.D. #
18FL-FD15

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D.
18FL-FD16

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D.
18FL-FD17

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D.
18FL-FD18

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Holding B

Inspector Name
Tristan May

Damper I.D.
18FL-FD19

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Holding D

Inspector Name
Tristan May

Damper I.D.
18FL-FD20

Damper Type
Vertical Fire Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Bench D

Inspector Name
Tristan May

Damper I.D.
18FL-FD21

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
18FL-SD12

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D.
18FL-SD13

Damper Type
Vertical Smoke Damper

Damper Size
10*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added access door.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D. #
18FL-SD14

Damper Type
Vertical Smoke Damper

Damper Size
20*14

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bench C

Inspector Name
Tristan May

Damper I.D. #
18FL-SD15

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D.
18FL-SD16

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D.
18FL-SD17

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D.
18FL-SD18

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Holding D

Inspector Name
Tristan May

Damper I.D. #
18FL-SD20

Damper Type
Vertical Smoke Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Bench D

Inspector Name
Tristan May

Damper I.D. #
18FL-SD21

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bench A

Inspector Name
Tristan May

Damper I.D.
19FL-FD11

Damper Type
Vertical Fire Damper

Damper Size
14*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
19FL-FD12

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Not properly secured in wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D. #
19FL-FD13

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D. #
19FL-FD14

Damper Type
Vertical Fire Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bench C

Inspector Name
Tristan May

Damper I.D.
19FL-FD15

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D. #
19FL-FD16

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D. #
19FL-FD17

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D.
19FL-FD18

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Angle not properly installed.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Holding B

Inspector Name
Tristan May

Damper I.D.
19FL-FD19

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Holding D

Inspector Name
Tristan May

Damper I.D. #
19FL-FD20

Damper Type
Vertical Fire Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Bench D

Inspector Name
Tristan May

Damper I.D.
19FL-FD21

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
19FL-SD12

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D.
19FL-SD13

Damper Type
Vertical Smoke Damper

Damper Size
10*6

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Cut in access door

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D.
19FL-SD14

Damper Type
Vertical Smoke Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Bench C

Inspector Name
Tristan May

Damper I.D. #
19FL-SD15

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-28

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D. #
19FL-SD16

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
11" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D. #
19FL-SD17

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D.
19FL-SD18

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Holding B

Inspector Name
Tristan May

Damper I.D. #
19FL-SD19

Damper Type
Vertical Smoke Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Holding D

Inspector Name
Tristan May

Damper I.D. #
19FL-SD20

Damper Type
Vertical Smoke Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-10-27

Facility Location
Justice Center Court Towers

Damper Location
Bench D

Inspector Name
Tristan May

Damper I.D.
19FL-SD21

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bench A

Inspector Name
Tristan May

Damper I.D.
20FL-FD11

Damper Type
Vertical Fire Damper

Damper Size
14*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D. #
20FL-FD12

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Angle not properly installed.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D. #
20FL-FD13

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D.
20FL-FD14

Damper Type
Vertical Fire Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bench C

Inspector Name
Tristan May

Damper I.D.
20FL-FD15

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D.
20FL-FD16

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D. #
20FL-SD12

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D. #
20FL-SD13

Damper Type
Vertical Smoke Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
Cut in access door.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D. #
20FL-SD14

Damper Type
Vertical Smoke Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bench C

Inspector Name
Tristan May

Damper I.D. #
20FL-SD15

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D.
20FL-SD16

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D. #
21FL-FD12

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D. #
21FL-FD13

Damper Type
Vertical Fire Damper

Damper Size
10*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D. #
21FL-FD14

Damper Type
Vertical Fire Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D. #
21FL-FD17

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D.
21FL-FD18

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Improper installation of angle.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding B

Inspector Name
Tristan May

Damper I.D.
21FL-FD19

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding D

Inspector Name
Tristan May

Damper I.D. #
21FL-FD20

Damper Type
Vertical Fire Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Bench D

Inspector Name
Tristan May

Damper I.D.
21FL-FD21

Damper Type
Vertical Fire Damper

Damper Size
8"R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6"R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
21FL-SD12

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D. #
21FL-SD14

Damper Type
Vertical Smoke Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D.
21FL-SD17

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D.
21FL-SD18

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding B

Inspector Name
Tristan May

Damper I.D.
21FL-SD19

Damper Type
Vertical Smoke Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added access door.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding D

Inspector Name
Tristan May

Damper I.D.
21FL-SD20

Damper Type
Vertical Smoke Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Bench D

Inspector Name
Tristan May

Damper I.D.
21FL-SD21

Damper Type
Vertical Smoke Damper

Damper Size
8"R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6"R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D. #
22FL-FD12

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D. #
22FL-FD13

Damper Type
Vertical Fire Damper

Damper Size
16*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D.
22FL-FD14

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Justice Center Court Towers

Damper Location
Bench C

Inspector Name
Tristan May

Damper I.D.
22FL-FD15

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D. #
22FL-FD16

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D.
22FL-FD17

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Fire damper not in wall.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D. #
22FL-FD18

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Holding B

Inspector Name
Tristan May

Damper I.D. #
22FL-FD19

Damper Type
Vertical Fire Damper

Damper Size
16*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*7

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Holding D

Inspector Name
Tristan May

Damper I.D. #
22FL-FD20

Damper Type
Vertical Fire Damper

Damper Size
10*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no breakaway connection.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Bench D

Inspector Name
Tristan May

Damper I.D. #
22FL-FD21

Damper Type
Vertical Fire Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
22FL-SD12

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D. #
22FL-SD13

Damper Type
Vertical Smoke Damper

Damper Size
16*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D. #
22FL-SD14

Damper Type
Vertical Smoke Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-03

Facility Location
Justice Center Court Towers

Damper Location
Bench C

Inspector Name
Tristan May

Damper I.D.
22FL-SD15

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D.
22FL-SD16

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D. #
22FL-SD17

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D.
22FL-SD18

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Bench D

Inspector Name
Tristan May

Damper I.D.
22FL-SD21

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-09-11

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D. #
22FL-SD24

Damper Type
Vertical Smoke Damper

Damper Size
Unknown

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
Unable to access damper.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
23FL-FD12

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Improper installation of angle.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D. #
23FL-FD13

Damper Type
Vertical Fire Damper

Damper Size
16*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D.
23FL-FD14

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D. #
23FL-FD16

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D.
23FL-FD17

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D. #
23FL-FD18

Damper Type
Vertical Fire Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6" R

Pass / Fail / Abandoned
Fail

Comments / Corrections
Improper installation of angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding B

Inspector Name
Tristan May

Damper I.D.
23FL-FD19

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*7

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding D

Inspector Name
Tristan May

Damper I.D. #
23FL-FD20

Damper Type
Vertical Fire Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-04

Facility Location
Justice Center Court Towers

Damper Location
Bailiff A

Inspector Name
Tristan May

Damper I.D.
23FL-SD12

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding A

Inspector Name
Tristan May

Damper I.D.
23FL-SD13

Damper Type
Vertical Smoke Damper

Damper Size
16*10

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Smoke damper, actuator and end switch have been removed, but still connected and laying on top of ductwork.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding C

Inspector Name
Tristan May

Damper I.D. #
23FL-SD14

Damper Type
Vertical Smoke Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
6*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Conference C

Inspector Name
Tristan May

Damper I.D.
23FL-SD16

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Conference D

Inspector Name
Tristan May

Damper I.D. #
23FL-SD17

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
10" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Bailiff B

Inspector Name
Tristan May

Damper I.D.
23FL-SD18

Damper Type
Vertical Smoke Damper

Damper Size
13" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
6" R

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding B.

Inspector Name
Tristan May

Damper I.D. #
23FL-SD19

Damper Type
Vertical Smoke Damper

Damper Size
8*6

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added access door

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-11-03

Facility Location
Justice Center Court Towers

Damper Location
Holding D

Inspector Name
Tristan May

Damper I.D. #
23FL-SD20

Damper Type
Vertical Smoke Damper

Damper Size
20*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24 high rise elevator room.

Inspector Name
Tristan May

Damper I.D.
24 HR elev room relief 2

Damper Type
Vertical Fire Damper

Damper Size
48*48

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle. Need 48*48 2*2 one side + tapcon

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ac1-r1

Damper Type
Horizontal Fire Damper

Damper Size
60*28

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, damper in floor

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical elevator lobby.

Inspector Name
Tristan May

Damper I.D. #
Ac1-s1

Damper Type
Horizontal Fire Damper

Damper Size
16"rnd

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, damper in floor, no sleeve

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical elevator lobby.

Inspector Name
Tristan May

Damper I.D.
Ac1-s2

Damper Type
Horizontal Fire Damper

Damper Size
10" rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, damper in floor no sleeve.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical elevator lobby.

Inspector Name
Tristan May

Damper I.D.
Ac1-s3

Damper Type
Horizontal Fire Damper

Damper Size
12"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle damper in the floor no sleeve

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical elevator lobby

Inspector Name
Tristan May

Damper I.D.
Ac1-s4

Damper Type
Horizontal Fire Damper

Damper Size
20"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
13*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle damper in the floor, no sleeve

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical elevator lobby.

Inspector Name
Tristan May

Damper I.D.
Ac1-s5

Damper Type
Vertical Fire Damper

Damper Size
24"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
13*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle damper in the floor, no sleeve

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D. #
Ac1-s6

Damper Type
Horizontal Fire Damper

Damper Size
23" rnd

Damper Manufacturer
Ruskin

Damper Model #
Ibd20

Fusible Link Temperature
165 Degrees

Access Door Size
23*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D. #
Ac1-s7

Damper Type
Horizontal Fire Damper

Damper Size
16" rnd

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, damper in floor.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D. #
Ac1-s8

Damper Type
Horizontal Fire Damper

Damper Size
13"rnd.

Damper Manufacturer
Ruskin

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
13*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ac1-s9

Damper Type
Horizontal Fire Damper

Damper Size
20" rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Angle not attached to damper. Space around damper

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D. #
Ac1-s11

Damper Type
Horizontal Fire Damper

Damper Size
15" rnd

Damper Manufacturer
Ruskin

Damper Model #
Ibd20

Fusible Link Temperature
165 Degrees

Access Door Size
15*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ac1-s12

Damper Type
Horizontal Fire Damper

Damper Size
14" rnd

Damper Manufacturer
Ruskin

Damper Model
Ibd20

Fusible Link Temperature
165 Degrees

Access Door Size
14*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D.
Ac2-fd ret1

Damper Type
Horizontal Fire Damper

Damper Size
60*30

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical elevator lobby.

Inspector Name
Tristan May

Damper I.D.
Ac2-r2

Damper Type
Vertical Fire Damper

Damper Size
54*36

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18*18

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle damper in the floor no sleeve.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical elevator lobby.

Inspector Name
Tristan May

Damper I.D.
Ac2-s1

Damper Type
Horizontal Fire Damper

Damper Size
36

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle, damper in the floor,no sleeve

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical elevator lobby.

Inspector Name
Tristan May

Damper I.D.
Ac2-s2

Damper Type
Horizontal Fire Damper

Damper Size
30"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
13*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle damper in the floor no sleeve

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D. #
Ac2-s3

Damper Type
Horizontal Fire Damper

Damper Size
14"rnd

Damper Manufacturer
Ruskin

Damper Model #
Ibd20

Fusible Link Temperature
165 Degrees

Access Door Size
14*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ac2-s4

Damper Type
Horizontal Fire Damper

Damper Size
13rnd

Damper Manufacturer
Ruskin

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D. #
Ac2-s5

Damper Type
Horizontal Fire Damper

Damper Size
12 rnd

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"rnd glass

Pass / Fail / Abandoned
Pass

Comments / Corrections
.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ac2-s6

Damper Type
Horizontal Fire Damper

Damper Size
18" rnd

Damper Manufacturer
Ruskin

Damper Model
Ibd20

Fusible Link Temperature
165 Degrees

Access Door Size
18*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D. #
Ac2-s7

Damper Type
Horizontal Fire Damper

Damper Size
12" rnd

Damper Manufacturer
Ruskin

Damper Model #
Dibd20

Fusible Link Temperature
165 Degrees

Access Door Size
12*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical room

Inspector Name
Tristan May

Damper I.D.
Ac2-s8

Damper Type
Horizontal Fire Damper

Damper Size
12" rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ac3-s1

Damper Type
Horizontal Fire Damper

Damper Size
23" rnd

Damper Manufacturer
Ruskin

Damper Model
Ibd20

Fusible Link Temperature
165 Degrees

Access Door Size
23*20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D.
Ac6-s1

Damper Type
Horizontal Fire Damper

Damper Size
22"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
22

Pass / Fail / Abandoned
Pass

Comments / Corrections
Limited access between duct and wall

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical.

Inspector Name
Tristan May

Damper I.D. #
Ac13-s1

Damper Type
Horizontal Fire Damper

Damper Size
23"rnd

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
23*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, damper in floor, no sleeve

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical

Inspector Name
Tristan May

Damper I.D. #
Ac14-r1

Damper Type
Horizontal Fire Damper

Damper Size
66*66

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
24*24

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no sleeve, damper in floor

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ac14-s1

Damper Type
Horizontal Fire Damper

Damper Size
26"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
26*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle no sleeve, damper in floor

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ac14-s2

Damper Type
Horizontal Fire Damper

Damper Size
26"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
26*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no sleeve, damper in floor

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ac14-s3

Damper Type
Horizontal Fire Damper

Damper Size
25"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
25*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no sleeve, damper in floor

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical

Inspector Name
Tristan May

Damper I.D.
Ac14-s4

Damper Type
Horizontal Fire Damper

Damper Size
27"rnd

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
27*20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no sleeve, damper in floor

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-19

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical

Inspector Name
Tristan May

Damper I.D.
Ac15-r1

Damper Type
Vertical Fire Damper

Damper Size
66*66

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
24*24

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve, no angle, damper in floor

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24fl high rise elevator room.

Inspector Name
Tristan May

Damper I.D.
Ac24-r1

Damper Type
Vertical Fire Damper

Damper Size
38*38

Damper Manufacturer
Ruskin

Damper Model
Ibd40

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24 FL elevator room.

Inspector Name
Tristan May

Damper I.D. #
Ac24-s1

Damper Type
Vertical Fire Damper

Damper Size
18*18

Damper Manufacturer
Ruskin

Damper Model #
Ibd40

Fusible Link Temperature
212 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24 high rise elevator room.

Inspector Name
Tristan May

Damper I.D.
Ac24-s2

Damper Type
Vertical Fire Damper

Damper Size
36*18

Damper Manufacturer
Ruskin

Damper Model
Ibd40

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
Limited access

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24 high rise elevator room.

Inspector Name
Tristan May

Damper I.D.
Ac24-s3

Damper Type
Vertical Fire Damper

Damper Size
36*18

Damper Manufacturer
Ruskin

Damper Model
Ibd40

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D.
Ahu506-fd ret

Damper Type
Horizontal Fire Damper

Damper Size
22*30

Damper Manufacturer
Ruskin

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D.
Ahu506-fd Supply

Damper Type
Horizontal Fire Damper

Damper Size
24*30

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-07

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D. #
Ef2-5fl

Damper Type
Horizontal Fire Damper

Damper Size
24*24

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, damper in floor, no sleeve

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical.

Inspector Name
Tristan May

Damper I.D. #
Ef2-24fl

Damper Type
Horizontal Fire Damper

Damper Size
34*36

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
24*24

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no sleeve, damper in floor

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D. #
Ef3-5fl

Damper Type
Horizontal Fire Damper

Damper Size
20*20

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-08

Facility Location
Justice Center Court Towers

Damper Location
24 mechanical.

Inspector Name
Tristan May

Damper I.D.
Ef3-24fl

Damper Type
Horizontal Fire Damper

Damper Size
32*34

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
24*24

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, no sleeve, damper in floor

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D.
Ef4-5fl

Damper Type
Horizontal Fire Damper

Damper Size
24*24

Damper Manufacturer
Ruskin

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18

Pass / Fail / Abandoned
Fail

Comments / Corrections
Need 1" and 1.5" screws to secure damper in duct. Gap around damper

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ef4-24fl

Damper Type
Horizontal Fire Damper

Damper Size
26*24

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18*18

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle, damper not in floor, no angle

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ef5-5fl

Damper Type
Horizontal Fire Damper

Damper Size
24*24

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Ef5-24fl

Damper Type
Horizontal Fire Damper

Damper Size
24*24

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
24*24

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle, damper not in floor, no sleeve

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24fl elevator room.

Inspector Name
Tristan May

Damper I.D.
Elv 1-2 1

Damper Type
Vertical Fire Damper

Damper Size
22*10

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-05

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D. #
Ex1-fd2

Damper Type
Horizontal Fire Damper

Damper Size
18*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-13

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria

Inspector Name
Tristan May

Damper I.D. #
G-3FL SD4

Damper Type
Vertical Smoke Damper

Damper Size
11*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
7*7

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
4FL Galleria.

Inspector Name
Tristan May

Damper I.D. #
G-4FL FD N R1

Damper Type
Vertical Fire Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
4FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-4FL SD N R1

Damper Type
Vertical Smoke Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
4FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-4FL SD1

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*4

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D. #
G-FL3 FD N R

Damper Type
Vertical Fire Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No breakaway connection

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-13

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria

Inspector Name
Tristan May

Damper I.D. #
G-FL3 FD S R

Damper Type
Vertical Fire Damper

Damper Size
36*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-FL3 FD1

Damper Type
Vertical Fire Damper

Damper Size
15" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*3

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D. #
G-FL3 FD2

Damper Type
Vertical Fire Damper

Damper Size
44*10

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle. No wall.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D. #
G-FL3 FD3

Damper Type
Vertical Fire Damper

Damper Size
24*14

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7*7

Pass / Fail / Abandoned
Fail

Comments / Corrections
No Angle.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-FL3 FD4

Damper Type
Vertical Fire Damper

Damper Size
10" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Flex

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve. No Angle

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D. #
G-FL3 SD N R

Damper Type
Vertical Smoke Damper

Damper Size
54*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-13

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D. #
G-FL3 SD S R

Damper Type
Vertical Smoke Damper

Damper Size
36*12

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
36*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-13

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-FL3 SD1

Damper Type
Vertical Smoke Damper

Damper Size
8" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
9*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-13

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-FL3 SD2

Damper Type
Vertical Smoke Damper

Damper Size
9" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
9*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-13

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-FL3 SD3

Damper Type
Vertical Smoke Damper

Damper Size
16*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-13

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-FL3 SD5

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
9*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-FL3 SD6

Damper Type
Vertical Smoke Damper

Damper Size
14*12

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
More than 2' away from fire barrier

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D. #
G-FL3 SD7

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*4

Pass / Fail / Abandoned
Fail

Comments / Corrections
More than 2' away from fire rated barrier

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-FL3 SD8

Damper Type
Vertical Smoke Damper

Damper Size
12" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
8*4

Pass / Fail / Abandoned
Fail

Comments / Corrections
More than 2' from fire rated barrier.

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-08-18

Facility Location
Justice Center Court Towers

Damper Location
3FL Galleria.

Inspector Name
Tristan May

Damper I.D.
G-FL3 SD9

Damper Type
Vertical Smoke Damper

Damper Size
10" R

Damper Manufacturer
Air Balance

Damper Model
Unknown

Fusible Link Temperature
N/A

Access Door Size
9*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24fl high rise elevator room

Inspector Name
Tristan May

Damper I.D.
H.r. Elev room relief 1

Damper Type
Vertical Fire Damper

Damper Size
48*48

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
No angle. Need 48*48 2*2 angle. One side + tapcon

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24fl elevator room.

Inspector Name
Tristan May

Damper I.D.
I1-s1

Damper Type
Vertical Fire Damper

Damper Size
22*10

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24 j elevator room.

Inspector Name
Tristan May

Damper I.D.
J elv-s1

Damper Type
Vertical Fire Damper

Damper Size
30*30

Damper Manufacturer
Ruskin

Damper Model
Ibd2

Fusible Link Temperature
212 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
Angle on back

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24fl j elevator room.

Inspector Name
Tristan May

Damper I.D. #
J elv-s2

Damper Type
Vertical Fire Damper

Damper Size
16*16

Damper Manufacturer
Ruskin

Damper Model #
Ibd2

Fusible Link Temperature
212 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
Angle on back side

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24fl mechanical.

Inspector Name
Tristan May

Damper I.D.
J elv-ta1

Damper Type
Vertical Fire Damper

Damper Size
48*30

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24 mechanical.

Inspector Name
Tristan May

Damper I.D.
J elv-ta2

Damper Type
Vertical Fire Damper

Damper Size
48*30

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-12

Facility Location
Justice Center Court Towers

Damper Location
24 j elevator room.

Inspector Name
Tristan May

Damper I.D.
Je-ex1

Damper Type
Vertical Fire Damper

Damper Size
38*38

Damper Manufacturer
Ruskin

Damper Model
Ibd2

Fusible Link Temperature
212 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
Angle on back

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical.

Inspector Name
Tristan May

Damper I.D.
Kitchen supply fan 1

Damper Type
Vertical Fire Damper

Damper Size
30*15

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D.
Mau2-east

Damper Type
Horizontal Fire Damper

Damper Size
30*24

Damper Manufacturer
Unknown

Damper Model
Unknown.

Fusible Link Temperature
165 Degrees

Access Door Size
16*14

Pass / Fail / Abandoned
Pass

Comments / Corrections
Cut welded angle

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-05-06

Facility Location
Justice Center Court Towers

Damper Location
5fl mechanical

Inspector Name
Tristan May

Damper I.D.
Mau2-west.

Damper Type
Horizontal Fire Damper

Damper Size
36*26

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16*14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Juvenile Justice Center

9300 Quincy Ave
Cleveland Ohio 44106

Fire/Smoke Damper Inspection Report

Visual Inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Juvenile Justice Center

9300 Quincy Ave
Cleveland Ohio 44106

Fire/Smoke Damper Inspection Report

Visual Inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 3, 2025

Project: Cuyahoga County
Juvenile Justice Center

Inspector(s):

- Larry Coreno, Certified Technician
- Tristan May, Certified Technician

Inspection and Test Date(s):

- November 11, 2024 – April 25, 2025

Duct Fabricators, Inc. “Fire Safety Division” inspected (470) dampers as noted on the following sheets. The dampers were visually inspected and photographed in the “exterior” and “interior” positions to confirm that they have not been altered and are free of any obstructions. Preventative maintenance was performed, and any deficiencies addressed.

(463) Dampers passed visual inspection
(7) Dampers failed due to reasons indicated on the report

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I.D. #	Damper Type	Damper Size	Damper Manufacturer	Damper Model #	Fusible Link Temperature	Access Door Size	Pass / Fail / Abandoned	Comments / Corrections
2024-11-22	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-R5	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-11-22	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-EX	Horizontal Fire Damper	10x8	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-11-22	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-S3	Vertical Fire Damper	15x13	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-22	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-S4	Vertical Fire Damper	16x14	Ruskin	IBD2	212 Degrees	14x14	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-S2	Horizontal Fire Damper	14x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-S1	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-S3	Horizontal Fire Damper	18x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU2-S4	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	6x6	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-S5	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-S6	Horizontal Fire Damper	10x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-R1	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-R2	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-R3	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-R4	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-R5	Horizontal Fire Damper	18x14	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU202-R6	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-R1	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-R2	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-R3	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None

2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-R4	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-R5	Horizontal Fire Damper	24x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-11-26	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-R6	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-S6	Horizontal Fire Damper	10x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-S5	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	6x6	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-S4	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	6x6	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-S3	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-S2	Horizontal Fire Damper	16x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU201-S1	Horizontal Fire Damper	25.5x16.5	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-EX	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	6x6	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-S5	Vertical Fire Damper	17x15	Ruskin	IBD2	212 Degrees	14x14	Pass	Added screws to the angle, screws under the duct seal
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-S8	Vertical Fire Damper	13x17	Ruskin	IBD2	212 Degrees	6x6	Pass	Added screws to the angle
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-S7	Vertical Fire Damper	13x23	Ruskin	IBD2	212 Degrees	6x6	Pass	Added screws to the angle, screws under duct seal
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-S6	Horizontal Fire Damper	18x16	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-R1	Vertical Fire Damper	23x11	Ruskin	IBD2	212 Degrees	8x8	Pass	Added screws to angle

2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-R2	Vertical Fire Damper	13x11	Ruskin	IBD2	212 Degrees	12x12	Pass	Screws under duct seal plus added screws
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-R3	Horizontal Fire Damper	12x8	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHI101-R4	Horizontal Fire Damper	16x16	Ruskin	IBD2	212 Degrees	16x16	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-R6	Vertical Fire Damper	9x9	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-S2	Vertical Fire Damper	15x15	Ruskin	IBD2	212 Degrees	12x12	Pass	Screws under the caulk plus we added a few
2024-12-02	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU101-S1	Vertical Fire Damper	13x23	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-S4	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-S5	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-S6	Horizontal Fire Damper	10x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-R1	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-R2	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-R3	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-R4	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-R5	Horizontal Fire Damper	18x14	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-R6	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-R1	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-R2	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-R3	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None

2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-R4	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-R5	Horizontal Fire Damper	24x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-R6	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-S5	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-S6	Horizontal Fire Damper	10x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-S4	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-S3	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-S2	Horizontal Fire Damper	16x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-13	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU301-S1	Horizontal Fire Damper	26x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-R6	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-R5	Horizontal Fire Damper	24x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-R4	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-R3	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-R2	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-R1	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-S3	Horizontal Fire Damper	18x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-S2	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 3	Larry Coreno	AHU302-S1	Horizontal Fire Damper	14x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-S1	Vertical Fire Damper	13x23	Ruskin	IBD2	212 Degrees	8x8	Pass	Screws under duct seal & West added some screws

2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-S2	Vertical Fire Damper	13x17	Ruskin	IBD2	212 Degrees	8x8	Pass	Screws under duct seal & added screws to the angle
2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-S4	Horizontal Fire Damper	10x8	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-R4	Horizontal Fire Damper	18x12	Ruskin	IBD2	212 Degrees	16x16	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-R3	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-S6	Vertical Fire Damper	17x15	Ruskin	IBD2	212 Degrees	16x16	Pass	Screws under duct seal & added screws to the angle
2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-S5	Vertical Fire Damper	15x17	Ruskin	IBD2	212 Degrees	14x14	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-R1	Vertical Fire Damper	12x12	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-R2	Vertical Fire Damper	13x19	Ruskin	IBD2	212 Degrees	10x10	Pass	Screws under duct seal
2024-12-20	Juvenile Justice Center	Penthouse 1	Larry Coreno	AHU102-S3	Vertical Fire Damper	13x11	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-R3	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-R2	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-R1	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-S2	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-S1	Horizontal Fire Damper	10x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHI401-S3	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-S4	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-S5	Horizontal Fire Damper	16x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None

2024-12-30	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU401-S6	Horizontal Fire Damper	26x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 2	Larry Coreno	AGU-005-S	Horizontal Fire Damper	40x22	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU-005-R	Horizontal Fire Damper	50x17	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU-004-S	Horizontal Fire Damper	48x22	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU-004-R	Horizontal Fire Damper	73x18	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU-002-R	Horizontal Fire Damper	64x17	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU-002-S	Horizontal Fire Damper	48x22	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU-001-S	Horizontal Fire Damper	40x20	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-30	Juvenile Justice Center	Penthouse 2	Larry Coreno	AHU-001-R	Horizontal Fire Damper	64x17	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU-008-S	Horizontal Fire Damper	24x24	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU-008-R	Horizontal Fire Damper	48x26	Ruskin	IBD2	212 Degrees	14x14	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU-009-R	Horizontal Fire Damper	58x18	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU-010-R	Horizontal Fire Damper	58x16	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	AGU-011-S	Horizontal Fire Damper	44x22	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU-011-R	Horizontal Fire Damper	67x18	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	MAU-001	Horizontal Fire Damper	30x18	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	MAU-002	Horizontal Fire Damper	34x26	Ruskin	IBD2	212 Degrees	18x18	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	MAU-004	Horizontal Fire Damper	38x18	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU-012-S	Horizontal Fire Damper	67x15	Ruskin	IBD2	212 Degrees	Man Door	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU-012-R	Horizontal Fire Damper	67x15	Ruskin	IBD2	212 Degrees	Man Door	Pass	None

2024-12-31	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHI402-S6	Horizontal Fire Damper	10x10	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-S5	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	6x6	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-S4	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	6x6	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-S3	Horizontal Fire Damper	18x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-S2	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-S1	Horizontal Fire Damper	14x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-R6	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-R5	Horizontal Fire Damper	18x14	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2024-12-31	Juvenile Justice Center	Penthouse 4	Larry Coreno	AHU402-R4	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-R1	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-R2	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-R3	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-R4	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-R6	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-R5	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-S1	Horizontal Fire Damper	24x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-S2	Horizontal Fire Damper	16x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-S3	Horizontal Fire Damper	16x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-S4	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-S5	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	8x8	Pass	None

2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU501-S6	Horizontal Fire Damper	10x10	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-S6	Horizontal Fire Damper	10x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-S5	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-S4	Horizontal Fire Damper	18x7	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-S3	Horizontal Fire Damper	18x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-S2	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-01-02	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-S1	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-01-03	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-R6	Horizontal Fire Damper	18x14	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm 208	Larry Coreno	IM122-FD6	Vertical Fire Damper	10x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2025-01-03	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-R5	Horizontal Fire Damper	16x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-03	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-R4	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-03	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHI502-R3	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-03	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-R1	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-03	Juvenile Justice Center	Penthouse 5	Larry Coreno	AHU502-R2	Horizontal Fire Damper	12x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm208	Larry Coreno	IM122-FD4	Horizontal Fire Damper	36x17	Ruskin	IBD2	212 Degrees	16x16	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm 208	Larry Coreno	IM122-FD3	Horizontal Fire Damper	24x16	Ruskin	IBD2	212 Degrees	16x16	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm 208	Larry Coreno	IM122-FD2	Horizontal Fire Damper	35.5x18.5	Ruskin	IBD2	212 Degrees	16x16	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm 208	Larry Coreno	IM122-FD1	Horizontal Fire Damper	10x8	Ruskin	IBD2	212 Degrees	8x8	Pass	None

2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm 208	Larry Coreno	IM122-FD7	Vertical Fire Damper	96x32	Ruskin	IBD2	212 Degrees	16x16	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm 208	Larry Coreno	IM122-FD5	Horizontal Fire Damper	24x18.5	Ruskin	IBD2	212 Degrees	16x16	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl South East Corridor	Larry Coreno	IM122-FSD2	Vertical Fire / Smoke Damper	60x40	Ruskin	FSD60	212 Degrees	16x16	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl South East Corridor	Larry Coreno	IM121-SD15	Vertical Smoke Damper	36x30	Greenheck	SMD201	N/A	Screen	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm 209	Larry Coreno	IM122-FD1	Horizontal Fire Damper	8x8	Ruskin	IBD2	212 Degrees	8x8	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm 209	Larry Coreno	IM121-FD2	Horizontal Fire Damper	32x14	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-01-03	Juvenile Justice Center	2nd Fl Mechanical Rm 209	Larry Coreno	IM121-FD3	Horizontal Fire Damper	30x18	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-01-14	Juvenile Justice Center	2nd Fl South Corridor Center	Larry Coreno	IM122-FSD1	Vertical Fire / Smoke Damper	60x30	Ruskin	FSD60	212 Degrees	16x16	Pass	None
2025-01-14	Juvenile Justice Center	2nd FL RM2402 TECHNOLOGY RM	Larry Coreno	IM122-FSD3	Vertical Fire / Smoke Damper	60x30	Ruskin	FSD60	212 Degrees	16x16	Pass	Rm 2402 Technology Rm
2025-01-14	Juvenile Justice Center	2nd FL	Larry Coreno	IM122-FSD6	Vertical Fire / Smoke Damper	20x16	Ruskin	FSD60	212 Degrees	8x8	Pass	None
2025-01-14	Juvenile Justice Center	2nd FL Closet	Larry Coreno	IM122-FSD5	Horizontal Fire / Smoke Damper	50x22	Greenheck	FSD311	212 Degrees	14x14	Pass	None
2025-01-14	Juvenile Justice Center	2nd FL Closet	Larry Coreno	IM122-FSD4	Vertical Fire / Smoke Damper	8x8	Ruskin	FSD60	212 Degrees	Grille	Pass	None
2025-01-14	Juvenile Justice Center	2nd FL Rm2826	Larry Coreno	IM121-SD5	Vertical Smoke Damper	24x12	Greenheck	SMD201	N/A	12x12	Pass	2nd FL Rm2826

2025-01-14	Juvenile Justice Center	2nd FL Rm2826	Larry Coreno	IM121-SD4	Vertical Smoke Damper	10x8	Greenheck	SMD201	N/A	6x6	Pass	2nd FL Rm 2826
2025-01-14	Juvenile Justice Center	2nd FL RM2806	Larry Coreno	IM121-SD1	Vertical Smoke Damper	24x12	Greenheck	SMD201	N/A	10x10	Pass	2nd FL Rm 2806
2025-01-14	Juvenile Justice Center	2nd FL Rm2806	Larry Coreno	IM121-SD2	Vertical Smoke Damper	14x12	Greenheck	SMD201	N/A	10x10	Pass	2nd FL Rm 2806
2025-01-14	Juvenile Justice Center	2nd FL Rm2826	Larry Coreno	IM121-SD3	Vertical Smoke Damper	14x12	Greenheck	SMD201	N/A	12x12	Pass	2nd FL Rm 2826
2025-01-14	Juvenile Justice Center	2nd FL Rm2805	Larry Coreno	IM121-SD6	Vertical Smoke Damper	26x12	Greenheck	SMD201	N/A	12x12	Pass	2nd FL Rm 2805
2025-01-14	Juvenile Justice Center	2nd FL Rm2805	Larry Coreno	IM121-SD7	Vertical Smoke Damper	18x12	Greenheck	SMD201	N/A	8x8	Pass	2nd FL Rm 2805
2025-01-14	Juvenile Justice Center	2nd FL Rm2805	Larry Coreno	IM121-SD8	Vertical Smoke Damper	42x16	Greenheck	SMD201	N/A	Open	Pass	2nd FL Rm 2805
2025-01-14	Juvenile Justice Center	2nd FL Rm2805	Larry Coreno	IM121-SD9	Vertical Smoke Damper	26x10	Greenheck	SMD201	N/A	12x12	Pass	2nd FL Rm 2805
2025-01-15	Juvenile Justice Center	2nd FL Rm 2802 Transportation	Larry Coreno	IM121-FSD3	Horizontal Fire / Smoke Damper	40x24	Ruskin	FSD60	212 Degrees	16x16	Pass	Transportation Rm2802
2025-01-15	Juvenile Justice Center	2nd FL Rm 2826 Wall down low across from shelves	Larry Coreno	IM121-FSD2	Horizontal Fire / Smoke Damper	48x24	Ruskin	FSD60	212 Degrees	16x16	Pass	Rm2826 Low on the wall across from shelves
2025-01-15	Juvenile Justice Center	2nd FL Transportation Rm	Larry Coreno	IM121-SD12	Vertical Smoke Damper	18x12	Greenheck	SMD201	N/A	12x12	Pass	2nd FL Transportation Rm
2025-01-15	Juvenile Justice Center	2nd FL Transportation Rm	Larry Coreno	IM121-SD11	Vertical Smoke Damper	8x8	Ruskin	SMD201	N/A	9x6 Oval	Pass	2nd FL Transportation Rm

2025-01-15	Juvenile Justice Center	2nd FL Transportation Rm	Larry Coreno	IM121-SD10	Vertical Smoke Damper	26x6	Greenheck	SMD201	N/A	Open	Pass	2nd FL Transportation Rm
2025-01-15	Juvenile Justice Center	2nd FL Bldg Maintenance Office	Larry Coreno	IM121-FD4	Horizontal Fire Damper	16x8	Ruskin	IBD2	212 Degrees	12x12	Pass	2nd FL Bldg Maintenance Office
2025-01-15	Juvenile Justice Center	2nd FL Bldg Maintenance Office	Larry Coreno	IM121-FD5	Horizontal Fire Damper	30x17	Ruskin	IBD2	212 Degrees	12x12	Pass	2nd FL Bldg Maintenance Office
2025-01-15	Juvenile Justice Center	2nd FL Bldg Maintenance Office	Larry Coreno	IM121-FD6	Horizontal Fire Damper	24x17	Ruskin	IBD2	212 Degrees	12x12	Pass	2nd FL Bldg Maintenance Office
2025-01-15	Juvenile Justice Center	2nd FL Rm 209	Larry Coreno	M203-FD6	Vertical Fire Damper	10x8	Ruskin	IBD2	212 Degrees	8x8	Pass	Visual only. Physical is done in the small gym & need a lift
2025-01-15	Juvenile Justice Center	2nd FL Rm 209	Larry Coreno	M203-FD5	Vertical Fire Damper	32x17	Ruskin	IBD2	212 Degrees	8x8	Pass	Visual only. Physical inspection in small the gym. Need a lift.
2025-01-15	Juvenile Justice Center	2nd FL Rm 209	Larry Coreno	M203-FD4	Vertical Fire Damper	30x20	Ruskin	IBD2	212 Degrees	6x18	Pass	Visual inspection only. Physical inspection in small gym. Need a lift
2025-01-15	Juvenile Justice Center	2nd FL Blue Print Rm	Larry Coreno	IM121-SD13	Vertical Smoke Damper	12x8	Ruskin	SD50	N/A	6x6	Pass	Blue Print Rm by freight elevator
2025-01-15	Juvenile Justice Center	2nd FL Blue Print Rm	Larry Coreno	IM121-SD14	Vertical Smoke Damper	12x10	Ruskin	SD50	N/A	6x6	Pass	Blue Print Rm by freight elevator
2025-01-16	Juvenile Justice Center	2nd FL Outside Rm2811	Larry Coreno	IM123-SD10	Vertical Smoke Damper	16x12	Greenheck	SMD201	N/A	Open	Pass	2nd FL Outside Rm 2811

2025-01-16	Juvenile Justice Center	2nd FL Rm 2811 Appeals	Larry Coreno	IM123-SD13	Vertical Smoke Damper	14x12	Greenheck	SMD201	N/A	12x12	Pass	2nd FL Rm 2811 Appeals
2025-01-16	Juvenile Justice Center	2nd FL Rm 2811 Appeals	Larry Coreno	IM123-SD12	Vertical Smoke Damper	10" Round	Greenheck	SMDR201	N/A	6x6	Pass	2nd FL Rm 2811 Appeals
2025-01-16	Juvenile Justice Center	2nd FL Rm 2110 Appeals	Larry Coreno	IM123-SD11	Vertical Smoke Damper	12x12	Greenheck	SMD201	N/A	Open	Pass	2nd FL Rm 2811 Appeals
2025-01-16	Juvenile Justice Center	2nd FL Technology Center Corridor	Larry Coreno	IM123-SD3	Vertical Smoke Damper	16" Round	Greenheck	SMDR60	N/A	9x6 Oval	Pass	Technology Center outside Rm2408
2025-01-16	Juvenile Justice Center	2nd FL Technology Center Corridor	Larry Coreno	IM123-SD1	Vertical Smoke Damper	14x12	Greenheck	SMD201	N/A	10x10	Pass	Technology Center Corridor outside Rm2415
2025-01-16	Juvenile Justice Center	2nd FL Technology Center Corridor	Larry Coreno	IM123-SD8	Vertical Smoke Damper	8" Round	Greenheck	SMDR201	N/A	Flex	Pass	Technology Center outside Rm2412
2025-01-16	Juvenile Justice Center	2nd FL Technology Center Corridor	Larry Coreno	IM123-SD2	Vertical Smoke Damper	14x12	Greenheck	SMD201	N/A	Open	Pass	2nd FL outside Rm2408 Corridor
2025-01-16	Juvenile Justice Center	2nd FL Mail Rm	Larry Coreno	IM123-SD16	Vertical Smoke Damper	10x10	Greenheck	SMD201	N/A	6x6	Pass	None
2025-01-16	Juvenile Justice Center	2nd FL Technology Center Corridor	Larry Coreno	IM123-SD7	Vertical Smoke Damper	8" Round	Greenheck	SMDR201	N/A	6x6	Pass	Technology Center Corridor outside Rm2411
2025-01-16	Juvenile Justice Center	2nd FL Technology Center Corridor	Larry Coreno	IM123-SD6	Vertical Smoke Damper	16x10	Greenheck	SMD201	N/A	6x6	Pass	Above refrigerator & copy machine
2025-01-16	Juvenile Justice Center	2nd FL Technology Center	Larry Coreno	IM123-SD5	Vertical Smoke Damper	14x12	Greenheck	SMD201	N/A	Open	Pass	Above Rm 2406

2025-01-16	Juvenile Justice Center	2nd FL Technology Center Rm2408	Larry Coreno	IM123-SD4	Vertical Smoke Damper	10x12	Greenheck	SMD201	N/A	8x8	Pass	Technology Center Rm2408 need CS6 Key
2025-01-16	Juvenile Justice Center	2nd FL Mail Rm	Larry Coreno	IM123-SD15	Vertical Smoke Damper	14" Round	Greenheck	SMDR201	N/A	9x6 Oval	Pass	Mail Rm
2025-01-17	Juvenile Justice Center	2nd FL Outside Rm 2811	Larry Coreno	IM123-SD9	Vertical Smoke Damper	12x12	Greenheck	SMD201	N/A	Open	Pass	2nd FL Outside 2811
2025-01-17	Juvenile Justice Center	2nd FL Women's bathroom	Larry Coreno	IM121-SD16	Vertical Smoke Damper	14x8	Ruskin	SD50	N/A	6x6	Pass	2nd FL Women's bathroom by cafeteria
2025-01-17	Juvenile Justice Center	9th FL Vestibule	Larry Coreno	IM192-FD1	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	10x10	Pass	9th FL Vestibule
2025-01-17	Juvenile Justice Center	9th FL Men's Bathroom	Larry Coreno	IM193-FSD1	Vertical Fire / Smoke Damper	16x24	Greenheck	FSD211	212 Degrees	12x12	Pass	9th FL Men's Bathroom
2025-01-17	Juvenile Justice Center	9th FL Vestibule	Larry Coreno	IM192-FSD5	Vertical Fire / Smoke Damper	16x10	Ruskin	FSD60	212 Degrees	12x12	Pass	9th FL Vestibule
2025-01-17	Juvenile Justice Center	9th FL Corridor	Larry Coreno	IM192-FSD1	Horizontal Fire / Smoke Damper	84x12	Ruskin	FSD60	212 Degrees	5x5	Pass	9th FL Corridor
2025-01-17	Juvenile Justice Center	9th FL Copy Rm	Larry Coreno	IM192-SD1	Vertical Smoke Damper	28x6	Greenheck	SMD201	N/A	8x8	Pass	None
2025-01-17	Juvenile Justice Center	9th FL Across Rm9702	Larry Coreno	IM192-SD2	Vertical Smoke Damper	8" Round	Greenheck	SMDR201	N/A	9x6 Oval	Pass	9th FL Across from Rm9702
2025-01-17	Juvenile Justice Center	9th FL Men's Bathroom	Larry Coreno	IM192-FSD4	Vertical Fire / Smoke Damper	36x10	Greenheck	FSD211	212 Degrees	10x10	Pass	9th FL Men's Bathroom
2025-01-17	Juvenile Justice Center	9th FL Women's Bathroom	Larry Coreno	IM192-FSD3	Vertical Fire / Smoke Damper	36x10	Greenheck	FSD211	212 Degrees	8x8	Pass	9th FL Women's Bathroom
2025-01-17	Juvenile Justice Center	9th FL Storage Rm	Larry Coreno	IM192-FSD2	Vertical Fire / Smoke Damper	8x8	Ruskin	FSD60	212 Degrees	Grille	Pass	9th FL Storage Rm

2025-01-31	Juvenile Justice Center	8FL Electrical Closet	Larry Coreno	IM182-FSD9	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	None
2025-01-31	Juvenile Justice Center	8FL East Next to Elevator 14 & 15	Larry Coreno	IM183-FSD1	Vertical Fire / Smoke Damper	12x8	Greenheck	FSD211	212 Degrees	12x12	Pass	8th FL East Next to Elevator 14 & 15
2025-01-31	Juvenile Justice Center	8FL Men's Bathroom	Larry Coreno	IM182-FSD2	Vertical Fire / Smoke Damper	14x8	Greenheck	FSD211	212 Degrees	8x8	Pass	8FL Men's Bathroom
2025-01-31	Juvenile Justice Center	8FL Women's Bathroom	Larry Coreno	IM182-FSD1	Vertical Fire / Smoke Damper	14x8	Greenheck	FSD211	212 Degrees	8x8	Pass	8FL Women's Bathroom
2025-01-31	Juvenile Justice Center	8FL Vestibule	Larry Coreno	IM182-FSD3	Vertical Fire / Smoke Damper	24x12	Greenheck	FSD211	212 Degrees	8x8	Pass	8FL Outside custodial closet
2025-01-31	Juvenile Justice Center	8FL Custodial closet	Larry Coreno	IM182-FSD4	Vertical Fire / Smoke Damper	8x8	Ruskin	FSD60	212 Degrees	Grille	Pass	8FL Custodial closet
2025-01-31	Juvenile Justice Center	8FL Main Corridor	Larry Coreno	IM182-FSD6	Vertical Fire / Smoke Damper	48x24	Ruskin	FSD60	212 Degrees	14x14	Pass	8FL
2025-01-31	Juvenile Justice Center	8FL Main Corridor	Larry Coreno	IM182-FSD5	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	16x16	Pass	8FL Main Corridor
2025-01-31	Juvenile Justice Center	8FL Electrical Closet	Larry Coreno	IM182-FSD7	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	8FL Electrical Closet
2025-01-31	Juvenile Justice Center	8FL Electrical Closet	Larry Coreno	IM182-FSD8	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	8FL Electrical Closet
2025-01-31	Juvenile Justice Center	8FL Main Corridor	Larry Coreno	IM182-FSD11	Vertical Fire / Smoke Damper	54x24	Ruskin	FSD60	212 Degrees	14x14	Pass	8FL Main Corridor
2025-01-31	Juvenile Justice Center	8FL Main Corridor	Larry Coreno	IM182-FSD12	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	14x14	Pass	8FL Main Corridor
2025-01-31	Juvenile Justice Center	8FL Electrical Closet	Larry Coreno	IM182-FSD10	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	8FL Electrical Closet

2025-01-31	Juvenile Justice Center	8FL West Corridor	Larry Coreno	IM181-FSD1	Vertical Fire / Smoke Damper	12x8	Greenheck	FSD211	212 Degrees	12x12	Pass	8FL West Corridor
2025-01-31	Juvenile Justice Center	7FL Vestibule	Larry Coreno	IM171-FSD6	Vertical Fire / Smoke Damper	16x10	Ruskin	FSD60	212 Degrees	12x12	Pass	7FL Vestibule
2025-01-31	Juvenile Justice Center	7FL Vestibule	Larry Coreno	IM172-FD1	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	10x10	Pass	7FL Vestibule
2025-01-31	Juvenile Justice Center	7FL Custodial closet	Larry Coreno	IM172-FSD5	Vertical Fire / Smoke Damper	8x8	Ruskin	FSD60	212 Degrees	Grille	Pass	7FL Custodial closet
2025-02-03	Juvenile Justice Center	7FL Next to Elevator 13 & 14	Larry Coreno	IM173-FSD1	Vertical Fire / Smoke Damper	12x8	Greenheck	FSD211	212 Degrees	12x12	Pass	7FL Next to Elevator 13 & 14
2025-02-03	Juvenile Justice Center	7FL Main Corridor	Larry Coreno	IM172-FSD7	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	Screen	Pass	7FL Main Corridor
2025-02-03	Juvenile Justice Center	7FL Main Corridor	Larry Coreno	IM172-FSD8	Vertical Fire / Smoke Damper	48x24	Ruskin	FSD60	212 Degrees	14x14	Pass	7FL Main Corridor
2025-02-03	Juvenile Justice Center	7FL Electrical Rm	Larry Coreno	IM172-FSD3	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	7FL Electrical Rm behind FSD7 & 8
2025-02-03	Juvenile Justice Center	7FL Electrical Rm	Larry Coreno	IM172-FSD4	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	7FL Electrical Rm behind FSD7&8
2025-02-03	Juvenile Justice Center	7FL Electrical Rm	Larry Coreno	IM172-FSD2	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	7FL Electrical Rm behind FSD 9 & 10
2025-02-03	Juvenile Justice Center	7FL Main Corridor	Larry Coreno	IM172-FSD1	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	7FL Main Corridor
2025-02-03	Juvenile Justice Center	7FL Main Corridor	Larry Coreno	IM172-FSD9	Vertical Fire / Smoke Damper	48x24	Ruskin	FSD60	212 Degrees	10x10	Pass	7FL Main Corridor
2025-02-03	Juvenile Justice Center	7FL Main Corridor	Larry Coreno	IM172-FSD10	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	12x12	Pass	7FL Main Corridor
2025-02-03	Juvenile Justice Center	7FL East behind elevator 3	Larry Coreno	IM171-FSD1	Vertical Fire / Smoke Damper	12x8	Greenheck	FSD211	212 Degrees	12x12	Pass	7FL East Behind Elevator 3

2025-02-03	Juvenile Justice Center	6FL Electrical Rm	Larry Coreno	IM162-FSD3	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	6FL Electrical Rm behind FSD 5 & 6
2025-02-03	Juvenile Justice Center	7FL Men's Bathroom	Larry Coreno	IM172-FSD11	Vertical Fire / Smoke Damper	14x8	Greenheck	FSD211	212 Degrees	12x12	Pass	None
2025-02-03	Juvenile Justice Center	7FL Women's Bathroom	Larry Coreno	IM172-FSD12	Vertical Fire / Smoke Damper	14x8	Greenheck	FSD211	212 Degrees	8x8	Pass	7FL Women's Bathroom
2025-02-03	Juvenile Justice Center	6FL Electrical Rm	Larry Coreno	IM162-FSD4	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	6FL Electrical Rm behind FSD 5 & 6
2025-02-03	Juvenile Justice Center	6FL Main Corridor	Larry Coreno	IM162-FSD8	Vertical Fire Damper	60x24	Ruskin	FSD60	212 Degrees	Screen	Pass	None
2025-02-04	Juvenile Justice Center	6FL Main Corridor	Larry Coreno	IM162-FSD6	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	16x16	Pass	6FL Main Corridor
2025-02-04	Juvenile Justice Center	6FL Main Corridor	Larry Coreno	IM162-FSD5	Vertical Fire / Smoke Damper	48x24	Ruskin	FSD60	212 Degrees	14x14	Pass	6FL Main Corridor
2025-02-04	Juvenile Justice Center	6FL Main Corridor	Larry Coreno	IM162-FSD7	Vertical Fire Damper	48x24	Ruskin	FSD60	212 Degrees	12x12	Pass	6FL Main Corridor
2025-02-04	Juvenile Justice Center	6FL Electrical Rm	Larry Coreno	IM162-FSD1	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	6FL Electrical Rm behind FSD 7 & 8
2025-02-04	Juvenile Justice Center	6FL Electrical Rm	Larry Coreno	IM162-FSD2	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	6FL Electrical Rm behind FSD 7 & 8
2025-02-04	Juvenile Justice Center	6FL East Corridor	Larry Coreno	IM161-FSD1	Vertical Fire / Smoke Damper	12x8	Greenheck	FSD211	212 Degrees	12x12	Pass	6FL East Corridor behind elevator 3
2025-02-04	Juvenile Justice Center	6FL West Corridor	Larry Coreno	IM163-FSD1	Vertical Fire / Smoke Damper	12x8	Greenheck	FSD211	212 Degrees	12x12	Pass	6FL West Corridor Next to elevator 14 & 15
2025-02-04	Juvenile Justice Center	Women's Bathroom	Larry Coreno	IM162-FSD9	Vertical Fire / Smoke Damper	14x8	Greenheck	FSD211	212 Degrees	12x12	Pass	Women's Bathroom

2025-02-04	Juvenile Justice Center	Men's Bathroom	Larry Coreno	IM162-FSD10	Vertical Fire / Smoke Damper	14x8	Greenheck	FSD211	212 Degrees	12x12	Pass	Men's Bathroom
2025-02-04	Juvenile Justice Center	6FL Custodial closet	Larry Coreno	IM162-FSD11	Vertical Fire / Smoke Damper	8x8	Ruskin	FSD60	212 Degrees	Grille	Pass	6FL Custodial closet
2025-02-04	Juvenile Justice Center	6FL Vestibule	Larry Coreno	IM162-FSD12	Vertical Fire / Smoke Damper	16x10	Ruskin	FSD60	212 Degrees	12x12	Pass	6FL Vestibule next to main elevators
2025-02-04	Juvenile Justice Center	5FL Women's Bathroom	Larry Coreno	IM152-FSD11	Vertical Fire / Smoke Damper	14x8	Greenheck	FSD211	212 Degrees	8x8	Pass	5FL Women's Bathroom
2025-02-04	Juvenile Justice Center	5FL Men's Bathroom	Larry Coreno	IM152-FSD12	Vertical Fire / Smoke Damper	14x8	Greenheck	FSD211	212 Degrees	8x8	Pass	5FL Men's Bathroom
2025-02-04	Juvenile Justice Center	5FL Custodial closet	Larry Coreno	IM152-FSD6	Vertical Fire / Smoke Damper	8x8	Ruskin	FSD60	212 Degrees	Grille	Pass	5FL Custodial closet next to main elevators
2025-02-04	Juvenile Justice Center	5FL Vestibule	Larry Coreno	IM152-FSD5	Vertical Fire / Smoke Damper	16x10	Ruskin	FSD60	212 Degrees	12x12	Pass	5FL Vestibule next to main elevators
2025-02-05	Juvenile Justice Center	5FL Vestibule	Larry Coreno	IM152-FD1	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	12x12	Pass	5FL Vestibule next to main elevators
2025-02-05	Juvenile Justice Center	5FL Corridor next 14 &15 elevators	Larry Coreno	IM153-FSD1	Vertical Fire / Smoke Damper	12x8	Greenheck	FSD211	212 Degrees	12x12	Pass	5FL Corridor next to 14& 15 elevators
2025-02-05	Juvenile Justice Center	5FL Main Corridor	Larry Coreno	IM152-FSD7	Vertical Fire / Smoke Damper	48x24	Ruskin	FSD60	212 Degrees	14x14	Pass	5FL Main Corridor
2025-02-05	Juvenile Justice Center	5FL Main Corridor	Larry Coreno	IM152-FSD8	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	Must go thru screen	Pass	5FL Main Corridor
2025-02-05	Juvenile Justice Center	5FL Electrical Rm	Larry Coreno	IM152-FSD3	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	5FL Electrical Rm behind FSD 7 & 8

2025-02-05	Juvenile Justice Center	5FL Electrical Rm	Larry Coreno	IM152-FSD4	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	5FL Electrical Rm behind FSD 7 & 8
2025-02-05	Juvenile Justice Center	5FL Electrical Rm	Larry Coreno	IM152-FSD1	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	5FL Electrical Rm behind FSD 9 & 10
2025-02-05	Juvenile Justice Center	5FL Electrical Rm	Larry Coreno	IM152-FSD2	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	5FL Electrical Rm behind FSD 9 & 10
2025-02-05	Juvenile Justice Center	5FL Main Corridor	Larry Coreno	IM152-FSD10	Vertical Fire / Smoke Damper	48x24	Ruskin	FSD60	212 Degrees	10x10	Pass	5FL Main Corridor Above cabinets
2025-02-05	Juvenile Justice Center	5FL Rm 5150	Larry Coreno	IM152-FD3	Vertical Fire Damper	18x18	Greenheck	DFD150	212 Degrees	Screen	Fail	5FL Rm 5150 No drywall on this side of the wall.
2025-02-05	Juvenile Justice Center	5FL Women's Bathroom	Larry Coreno	IM153-FSD1	Vertical Fire / Smoke Damper	10x8	Greenheck	FSD211	212 Degrees	8x7	Pass	5FL Women's Bathroom next to Elevator 3
2025-02-05	Juvenile Justice Center	5FL Main Corridor	Larry Coreno	IM152-FSD9	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	14x14	Pass	5FL Main Corridor Above cabinets
2025-02-05	Juvenile Justice Center	5FL Rm 5150	Larry Coreno	IM152-FD2	Vertical Fire Damper	18x18	Greenheck	DFD150	212 Degrees	Screen	Pass	5FL Rm 5150
2025-02-05	Juvenile Justice Center	4FL RM 4107	Larry Coreno	IM143-FSD1	Vertical Fire / Smoke Damper	12x10	Greenheck	FSD211	212 Degrees	8x8	Pass	4FL RM 4107
2025-02-05	Juvenile Justice Center	4FL RM 4405	Larry Coreno	IM143-SD1	Vertical Smoke Damper	10x12	Greenheck	SMD301	N/A	8x8	Pass	4FL RM 4405 Actuator RM 4406
2025-02-05	Juvenile Justice Center	5FL Corridor	Larry Coreno	IM152-SD1	Vertical Smoke Damper	12x10	Greenheck	SMD301	N/A	8x8	Pass	5FL Outside Rm #5146
2025-02-05	Juvenile Justice Center	4FL RM 4405	Larry Coreno	IM143-SD2	Vertical Smoke Damper	10" Round	Greenheck	SMRD301	N/A	9x6 Oval	Pass	4FL RM 4405

2025-02-05	Juvenile Justice Center	4FL Main Corridor	Larry Coreno	IM142-FSD8	Vertical Fire / Smoke Damper	60x20	Ruskin	FSD60	212 Degrees	12x12	Pass	None
2025-02-06	Juvenile Justice Center	4FL Main Corridor	Larry Coreno	IM142-FSD9	Vertical Fire / Smoke Damper	48x24	Greenheck	FSD60	212 Degrees	12x12	Pass	4FL Main Corridor
2025-02-06	Juvenile Justice Center	4FL Electrical Rm	Larry Coreno	IM142-FSD3	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	4FL Electrical Rm behind FSD 8 & 9
2025-02-06	Juvenile Justice Center	4FL Electrical Rm	Larry Coreno	IM142-FSD4	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	4FL Electrical Rm behind FSD 8 & 9
2025-02-06	Juvenile Justice Center	4FL Main Corridor	Larry Coreno	IM142-FSD10	Vertical Fire / Smoke Damper	54x24	Ruskin	FSD60	212 Degrees	12x12	Pass	4FL Main Corridor
2025-02-06	Juvenile Justice Center	4FL Main Corridor	Larry Coreno	IM142-FSD11	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	12x12	Pass	4FL Main Corridor
2025-02-06	Juvenile Justice Center	4FL RM 4610	Larry Coreno	IM142-SD1	Vertical Smoke Damper	10x10	Greenheck	SMD301	N/A	8x8	Pass	4FL RM 4610
2025-02-06	Juvenile Justice Center	4FL Electrical Rm	Larry Coreno	IM142-FSD1	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	4FL Electrical Rm behind FSD 10 & 11
2025-02-06	Juvenile Justice Center	4FL Electrical Rm	Larry Coreno	IM142-FSD2	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	4FL Electrical Rm behind FSD 10 &11
2025-02-06	Juvenile Justice Center	4FL Custodial closet	Larry Coreno	IM142-FSD5	Vertical Fire / Smoke Damper	8x8	Ruskin	FSD60	212 Degrees	Grille	Pass	4FL Custodial closet next to main elevators
2025-02-06	Juvenile Justice Center	4FL RM 4503	Larry Coreno	IM142-FSD6	Vertical Fire / Smoke Damper	20x10	Greenheck	FSD211	212 Degrees	6x6	Pass	4FL RM 4503
2025-02-06	Juvenile Justice Center	4FL RM 4308	Larry Coreno	IM142-FSD7	Vertical Fire / Smoke Damper	20x10	Greenheck	FSD211	212 Degrees	6x6	Pass	4FL RM 4308
2025-02-06	Juvenile Justice Center	4FL RM 4313	Larry Coreno	IM142-SD2	Vertical Smoke Damper	26x6	Greenheck	SMD301	N/A	Open	Pass	4FL RM 4313

2025-02-06	Juvenile Justice Center	4FL RM 4812	Larry Coreno	IM141-SD4	Vertical Smoke Damper	8" Round	Greenheck	SMDR301	N/A	9x6 Oval	Pass	4FL Above door Rm 4812
2025-02-06	Juvenile Justice Center	4FL RM 4812	Larry Coreno	IM141-SD5	Vertical Smoke Damper	8" Round	Greenheck	SMDR301	N/A	9x6 Oval	Pass	4Fl above door Rm 4812
2025-02-06	Juvenile Justice Center	4FL Rm 4812	Larry Coreno	IM141-SD6	Vertical Smoke Damper	6" Round	Greenheck	SMDR301	N/A	9x6 Oval	Pass	Above door Rm4812
2025-02-07	Juvenile Justice Center	4FL RM 4805	Larry Coreno	IM141-SD8	Vertical Smoke Damper	10" Round	Greenheck	SMDR301	N/A	9x6 Oval	Pass	4FL Above refrigerator Rm 4805
2025-02-07	Juvenile Justice Center	4FL RM 4805	Larry Coreno	IM141-SD7	Vertical Smoke Damper	10" Round	Greenheck	SMDR301	N/A	9x6 Oval	Pass	4FL Above refrigerator Rm 4805
2025-02-07	Juvenile Justice Center	4FL RM 4805	Larry Coreno	IM141-SD10	Vertical Smoke Damper	15x16	Greenheck	SMD301	N/A	12x12	Pass	4FL Hallway above Refrigerator
2025-02-07	Juvenile Justice Center	4FL Women's Bathroom	Larry Coreno	IM141-FSD1	Vertical Fire / Smoke Damper	8x8	Greenheck	FSD211	212 Degrees	8x8	Pass	4FL Women's Bathroom remove time with grille in it
2025-02-07	Juvenile Justice Center	4FL Corridor	Larry Coreno	IM141-SD3	Vertical Smoke Damper	26x6	Greenheck	SMD301	N/A	Open	Pass	4FL Corridor outside women's bathroom
2025-02-07	Juvenile Justice Center	4FL Main Corridor	Larry Coreno	IM141-SD2	Vertical Smoke Damper	26x6	Greenheck	SMD301	N/A	Open	Pass	4FL Main Corridor
2025-02-07	Juvenile Justice Center	4FL Main Corridor	Larry Coreno	IM141-SD1	Vertical Smoke Damper	14" Round	Greenheck	SMDR301	N/A	9x6 Oval	Pass	4FL Main Corridor
2025-02-07	Juvenile Justice Center	4FL Main Corridor	Larry Coreno	IM141-SD10	Vertical Smoke Damper	14" Round	Greenheck	SMDR301	N/A	9x6 Oval	Pass	4FL Corridor outside children & family service unit

2025-02-07	Juvenile Justice Center	4FL Main Corridor	Larry Coreno	IM141-SD11	Vertical Smoke Damper	14" Round	Greenheck	SMDR301	N/A	3x3	Pass	4FL Main Corridor outside Children &F Family Unit
2025-02-07	Juvenile Justice Center	10FL Penthouse	Larry Coreno	AHU TO2-R	Horizontal Fire / Smoke Damper	120x60	Ruskin	FSD60	212 Degrees	14x14	Pass	10FL Penthouse
2025-02-07	Juvenile Justice Center	10FL Penthouse	Larry Coreno	AHU TO2-S	Horizontal Fire / Smoke Damper	78x60	Ruskin	FSD60	212 Degrees	14x14	Pass	10FL Penthouse
2025-02-07	Juvenile Justice Center	10FL Penthouse	Larry Coreno	AHU TO1-R	Horizontal Fire / Smoke Damper	120x60	Ruskin	FSD60	212 Degrees	14x14	Pass	10FL Penthouse
2025-02-07	Juvenile Justice Center	10FL Penthouse	Larry Coreno	AHU TO1-S	Horizontal Fire / Smoke Damper	78x60	Ruskin	FSD60	212 Degrees	20x20	Pass	10FL Penthouse
2025-02-07	Juvenile Justice Center	10FL Penthouse	Larry Coreno	AHU TO1-R2	Vertical Smoke Damper	50x50	Ruskin	SD60	N/A	14x14	Pass	10FL Penthouse behind TO1 unit
2025-02-07	Juvenile Justice Center	10FL Penthouse	Larry Coreno	AHU TO1-R2	Vertical Fire Damper	50x50	Greenheck	DFDTT210	212 Degrees	14x14	Pass	10FL Penthouse behind TO1 unit
2025-02-07	Juvenile Justice Center	10FL Penthouse	Larry Coreno	PH-FSD1	Vertical Fire / Smoke Damper	30x30	Ruskin	FSD60	212 Degrees	14x14	Pass	10FL Penthouse in front of elevator
2025-02-07	Juvenile Justice Center	10FL Penthouse	Larry Coreno	PH-FSD2	Vertical Fire / Smoke Damper	30x30	Ruskin	FSD60	212 Degrees	18x18	Pass	10FL Penthouse in front of elevator
2025-02-10	Juvenile Justice Center	10FL Penthouse RM911	Larry Coreno	PH-FSD4	Horizontal Fire / Smoke Damper	60x18	Ruskin	FSD60	212 Degrees	14x14	Pass	10FL Penthouse RM911
2025-02-10	Juvenile Justice Center	10FL Penthouse RM911	Larry Coreno	PH-FSD3	Horizontal Fire / Smoke Damper	38x24	Ruskin	FSD60	212 Degrees	14x14	Pass	10FL Penthouse RM911

2025-02-10	Juvenile Justice Center	10FL Penthouse RM911	Larry Coreno	PH-FSD5	Horizontal Fire / Smoke Damper	38x24	Ruskin	FSD60	212 Degrees	14x14	Pass	10FL Penthouse RM911
2025-02-10	Juvenile Justice Center	10FL Penthouse RM 908	Larry Coreno	PH-FD3	Horizontal Fire Damper	42x42	Ruskin	IBD2	212 Degrees	16x16	Pass	10FL Penthouse Rm908 Mezzanine
2025-02-10	Juvenile Justice Center	10FL Penthouse RM908	Larry Coreno	PH-FD2	Vertical Fire Damper	24x20	Ruskin	IBD2	212 Degrees	Grille	Pass	10FL Penthouse RM908
2025-02-10	Juvenile Justice Center	3FL Electrical Rm	Larry Coreno	IM132-FSD3	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	3FL Electrical Rm behind FSD 6&7
2025-02-10	Juvenile Justice Center	3FL Electrical Rm	Larry Coreno	IM132-FSD4	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	3FL Electrical Rm behind FSD 6 & 7
2025-02-10	Juvenile Justice Center	3FL Main Corridor	Larry Coreno	IM132-FSD6	Vertical Fire / Smoke Damper	50x24	Ruskin	FSD60	212 Degrees	10x10	Pass	3FL Main Corridor
2025-02-10	Juvenile Justice Center	3FL Main Corridor	Larry Coreno	IM132-FSD7	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	Screen	Pass	3FL Main Corridor
2025-02-10	Juvenile Justice Center	10FL Penthouse RM908	Larry Coreno	PH-FD1	Vertical Fire Damper	36x16	Ruskin	IBD2	212 Degrees	Grille	Pass	10FL Penthouse RM908
2025-02-10	Juvenile Justice Center	3FL RM3106	Larry Coreno	IM133-FSD2	Vertical Fire / Smoke Damper	12x10	Greenheck	FSD311	212 Degrees	6x6	Pass	3FL RM3106
2025-02-10	Juvenile Justice Center	3FL Rm3106	Larry Coreno	IM133-SD8	Vertical Smoke Damper	26x8	Greenheck	FSD311	N/A	Open	Pass	3FL Outside RM3106
2025-02-10	Juvenile Justice Center	3FL RM 3106	Larry Coreno	IM133-SD7	Vertical Smoke Damper	12x10	Greenheck	SMD301	N/A	6x6	Pass	3FL Outside Rm 3106
2025-02-10	Juvenile Justice Center	3FL RM 3109	Larry Coreno	IM133-SD6	Vertical Smoke Damper	6" Round	Greenheck	SMDR301	N/A	8x8	Pass	3FL RM3109
2025-02-10	Juvenile Justice Center	3FL RM3209	Larry Coreno	IM133-SD5	Vertical Smoke Damper	26x6	Greenheck	SMD301	N/A	Open	Pass	3FL Outside Rm 3209

2025-02-10	Juvenile Justice Center	3FL RM 3207	Larry Coreno	IM133-SD4	Vertical Smoke Damper	36x16	Greenheck	SMD301	N/A	Open	Pass	3FL Outside RM 3207
2025-02-10	Juvenile Justice Center	3FL RM 3206	Larry Coreno	IM133-FSD1	Vertical Fire / Smoke Damper	10" Round	Greenheck	FSDR511	212 Degrees	9x6 Oval	Pass	3FL RM 3206
2025-02-10	Juvenile Justice Center	3FL RM3206	Larry Coreno	IM133-SD3	Vertical Smoke Damper	8x10	Greenheck	SMD201	N/A	8x8	Pass	3FL RM 3206
2025-02-10	Juvenile Justice Center	3FL Rm3206	Larry Coreno	IM133-SD9	Vertical Smoke Damper	16x12	Greenheck	SMD201	N/A	12x12	Pass	3FL RM 3206/ This was marked SD1.SD1 is 8" Round same room.
2025-02-11	Juvenile Justice Center	3FL RM 3206	Larry Coreno	IM133-SD2	Vertical Smoke Damper	10x10	Greenheck	SMD201	N/A	8x8	Pass	3FL RM 3206
2025-02-11	Juvenile Justice Center	2FL Main Corridor Damper doesn't exist.	Larry Coreno	IM121-FSD1	Vertical Fire / Smoke Damper	60x30	Ruskin	FSD60	212 Degrees	Screen	Pass	2FL IM121-FSD1 was changed to IM121-SD15
2025-02-11	Juvenile Justice Center	3FL RM 3206	Larry Coreno	IM133-SD1	Vertical Smoke Damper	8" Round	Greenheck	SMDR511	N/A	9x6 Oval	Pass	3FL Rm 3206
2025-02-11	Juvenile Justice Center	3FL Training center	Larry Coreno	IM132-FSD8	Vertical Fire / Smoke Damper	60x30	Ruskin	FSD60	212 Degrees	14x14	Pass	3FL Training center
2025-02-11	Juvenile Justice Center	3FL Training center	Larry Coreno	IM133-FSD9	Vertical Fire / Smoke Damper	60x24	Ruskin	FSD60	212 Degrees	16x16	Pass	3FL Training center
2025-02-11	Juvenile Justice Center	3FL Training center electrical Rm	Larry Coreno	IM133-FSD1	Vertical Fire / Smoke Damper	12x20	Ruskin	FSD60	212 Degrees	6x6	Pass	3FL Training center electrical Rm
2025-02-11	Juvenile Justice Center	3FL Training center electrical Rm	Larry Coreno	IM132-FSD2	Vertical Fire / Smoke Damper	30x12	Ruskin	FSD60	212 Degrees	6x6	Pass	3FL Training center electrical Rm
2025-02-11	Juvenile Justice Center	3FL Mediation Rm 3810	Larry Coreno	IM132-SD2	Vertical Smoke Damper	26x6	Greenheck	SMD301	N/A	Open	Pass	3FL Mediation Rm 3810

2025-02-11	Juvenile Justice Center	3FL Mediation Rm 3811	Larry Coreno	IM131-SD1	Vertical Smoke Damper	10x8	Greenheck	SMD301	N/A	8x8	Pass	3FL Mediation outside Rm 3811
2025-02-11	Juvenile Justice Center	3FL Women's Bathroom	Larry Coreno	IM131--FSD1	Vertical Fire / Smoke Damper	12x10	Greenheck	FSD311	212 Degrees	8x8	Pass	3FL Women's Bathroom
2025-02-11	Juvenile Justice Center	3FL Vestibule	Larry Coreno	IM132-FD1	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	10x10	Pass	3FL Vestibule
2025-02-11	Juvenile Justice Center	3FL Custodial Closet	Larry Coreno	IM132-FSD5	Vertical Fire / Smoke Damper	8x8	Ruskin	FSD60	212 Degrees	Grille	Pass	3FL CUSTODIAL CLOSET
2025-02-11	Juvenile Justice Center	Stairwell 5 9FL	Larry Coreno	STR5-FD1	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 5 9FL
2025-02-11	Juvenile Justice Center	Stairwell 5 7FL	Larry Coreno	STR5-FD2	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 5 7Fl
2025-02-11	Juvenile Justice Center	Stairwell 5 5FL	Larry Coreno	STR5-FD3	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 5 5FL
2025-02-11	Juvenile Justice Center	Stairwell 5 4FL	Larry Coreno	STR5-FD4	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 5 4FL
2025-02-11	Juvenile Justice Center	Stairwell 5 3FL	Larry Coreno	STR5-FD5	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 5 3FL
2025-02-11	Juvenile Justice Center	Stairwell 6 9FL	Larry Coreno	STR6-FD1	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 6 9FL
2025-02-11	Juvenile Justice Center	Stairwell 6 7FL	Larry Coreno	STR6-FD2	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 6 7FL
2025-02-13	Juvenile Justice Center	Stairwell 6 5fl	Larry Coreno	STR6-FD3	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 6 5fl
2025-02-13	Juvenile Justice Center	Stairwell 6 1FL	Larry Coreno	STR6-FD5	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 6 1FL
2025-02-13	Juvenile Justice Center	Stairwell 6 3FL	Larry Coreno	STR6-FD4	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 6 3fl
2025-02-13	Juvenile Justice Center	Stairwell 7 9FL	Larry Coreno	STR7-FD5	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 7 9FL
2025-02-13	Juvenile Justice Center	Stairwell 7 7FL	Larry Coreno	STR7-FD4	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 7 7FL
2025-02-13	Juvenile Justice Center	Stairwell 7 5FL	Larry Coreno	STR7-FD3	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 7 5FL
2025-02-13	Juvenile Justice Center	Stairwell 7 3FL	Larry Coreno	STR7-FD2	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell 7 3FL

2025-02-13	Juvenile Justice Center	Stairwell 7 FL 2FL	Larry Coreno	STR7-FD1	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Stairwell7 2FL
2025-02-13	Juvenile Justice Center	1FL Vestibule	Larry Coreno	M204.2-FD6	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	12x12	Pass	1FL Vestibule outside Main elevator
2025-02-13	Juvenile Justice Center	1FL Custodial closet	Larry Coreno	M204.2-FSD1	Vertical Fire / Smoke Damper	30x30	Ruskin	FSD60	212 Degrees	12x12	Pass	1FL Custodial closet
2025-02-13	Juvenile Justice Center	1FL Custodial closet	Larry Coreno	M204.2-SD4	Vertical Smoke Damper	6x6	Ruskin	SD50	N/A	6x6	Pass	1FL Custodial closet
2025-02-13	Juvenile Justice Center	1FL Outside Rm IS138	Larry Coreno	M204.2-FSD2	Vertical Smoke Damper	24x14	Ruskin	FSD60	212 Degrees	8x8 patch	Pass	1Fl Outside Rm IS138. Just found it. Very high & hard to get to because of sprinkler & conduit pipes.
2025-02-13	Juvenile Justice Center	1FL Outside Diagnostic Clinic	Larry Coreno	M203-SD17	Vertical Smoke Damper	10" Round	Ruskin	SDR25	N/A	9x6 Oval	Pass	1FL Outside Diagnostic Clinic
2025-02-14	Juvenile Justice Center	1FL Clerks Office	Larry Coreno	M203-SD18	Vertical Smoke Damper	8x12	Greenheck	SMD201	N/A	10x10	Pass	1FL Clerks Office
2025-02-14	Juvenile Justice Center	1FL Time Clock Corridor	Larry Coreno	M204.1-SD1	Vertical Smoke Damper	8" Round	Ruskin	SDR25	N/A	4x4	Pass	1FL Time Clock Corridor
2025-02-14	Juvenile Justice Center	1FL Administration reception Rm501	Larry Coreno	M204.1-SD2	Vertical Smoke Damper	10" Round	Ruskin	SDR25	N/A	4x4	Pass	1FL Administration Reception A501
2025-02-14	Juvenile Justice Center	1FL Administration File Rm A512	Larry Coreno	M204.1-FSD1	Vertical Fire / Smoke Damper	24x12	Ruskin	FSD60	212 Degrees	Remove Duct	Pass	1FL Administration File Rm. A512
2025-02-14	Juvenile Justice Center	1FL Training Storage Closet	Larry Coreno	M205-SD1	Vertical Smoke Damper	8x10	Ruskin	SD50	N/A	2x2	Pass	1FL Training Storage Closet

2025-02-14	Juvenile Justice Center	1FL Training Storage Closet	Larry Coreno	M205-SD2	Vertical Smoke Damper	6" Round	Ruskin	SDR25	N/A	Remove Flex	Pass	1FL Training Storage Closet
2025-02-14	Juvenile Justice Center	1FL Training Storage Closet	Larry Coreno	M205-SD3	Vertical Smoke Damper	24x6	Ruskin	SD50	N/A	3x3	Pass	1FL Training Storage Closet
2025-02-14	Juvenile Justice Center	1FL Classroom E126	Larry Coreno	M205-SD7	Vertical Smoke Damper	24x6	Ruskin	FSD60	N/A	Open	Pass	1FL Classroom E126
2025-02-14	Juvenile Justice Center	1FL Corridor outside stairwell 7	Larry Coreno	M205-FD2	Vertical Fire Damper	8" Round	Ruskin	IBD2	212 Degrees	Remove pipe	Pass	1FL Corridor Outside Stairwell 7
2025-02-14	Juvenile Justice Center	1FL Above fire exit	Larry Coreno	M205-FD1	Vertical Fire Damper	14x12	Ruskin	IBD2	212 Degrees	Open	Pass	1FL Above fire exit
2025-02-14	Juvenile Justice Center	1FL Classroom E126	Larry Coreno	M205-SD6	Vertical Smoke Damper	12x8	Ruskin	FSD60	N/A	Remove Flex	Pass	1FL Classroom E126 Storage Closet
2025-02-14	Juvenile Justice Center	1FL Education Lounge E109	Larry Coreno	M206-SD2	Vertical Smoke Damper	6" Round	Ruskin	SDR25	N/A	4x4	Pass	1FL Education Lounge E109
2025-02-14	Juvenile Justice Center	1FL Education Lounge E109	Larry Coreno	M206-SD2	Vertical Smoke Damper	8" Round	Ruskin	SDR25	N/A	4x4	Pass	1FL Education Lounge E109
2025-02-14	Juvenile Justice Center	Education Lounge E110	Larry Coreno	M206-FSD1	Vertical Fire Damper	24x6	Ruskin	FSD60	N/A	Open	Pass	1FL Education Lounge E110
2025-02-14	Juvenile Justice Center	Gym storage room	Larry Coreno	M207-FSD1	Vertical Fire Damper	48x24	Ruskin	FSD60	N/A	12x12	Pass	M207-FSD1 Gym storage room
2025-02-14	Juvenile Justice Center	Large gym storage room	Larry Coreno	M207-FSD2	Vertical Fire / Smoke Damper	26x22	Ruskin	FSD60	N/A	Patch	Pass	M207-FSD2 LARGE GYM STORAGE
2025-02-17	Juvenile Justice Center	LL Basement	Larry Coreno	Basement - FD2	Vertical Fire Damper	10" Round	Ruskin	IBD2	212 Degrees	Screen	Pass	LL Basement outside Main elevator
2025-02-17	Juvenile Justice Center	LL Basement	Larry Coreno	Basement - FD3	Vertical Fire Damper	32x20	Ruskin	IBD2	212 Degrees	10x10	Pass	LL Basement outside Main elevator
2025-02-17	Juvenile Justice Center	LL Basement	Larry Coreno	Basement - FD1	Vertical Fire Damper	35x25.5	Ruskin	IBD2	212 Degrees	12x12	Pass	LL Basement RmLL104

2025-02-17	Juvenile Justice Center	1FL Home Detention H322	Larry Coreno	M204.2-SD6	Vertical Smoke Damper	38x18	Ruskin	SD50	N/A	12x12	Pass	1FL Home Detention H322
2025-02-17	Juvenile Justice Center	1FL Home Detention H322	Larry Coreno	M204.2-SD5	Vertical Smoke Damper	30x18	Ruskin	SD50	N/A	12x12	Pass	1FL Home Detention H322
2025-02-17	Juvenile Justice Center	1FL Home Detention H317	Larry Coreno	M204.2-FD5	Vertical Fire Damper	20x10	Ruskin	IBD2	212 Degrees	12x12	Fail	1FL Home Detention H317 Welded angle
2025-02-17	Juvenile Justice Center	1FL Home Detention H317	Larry Coreno	M204.2-FD4	Vertical Fire Damper	28x10	Ruskin	IBD2	212 Degrees	12x12	Fail	1FL Home Detention H317 Welded angle
2025-02-17	Juvenile Justice Center	1FL Home Detention H317	Larry Coreno	M204.2-FD3	Vertical Fire Damper	8" Round	Ruskin	IBD2	212 Degrees	6x9 Oval	Fail	1FL Home Detention H317 welded angle
2025-02-17	Juvenile Justice Center	1FL Visitation V430	Larry Coreno	M204.2-SD3	Vertical Smoke Damper	24x6	Ruskin	SD 50	N/A	Open	Pass	1FL Visitation V430
2025-02-17	Juvenile Justice Center	1FL Visitation V429	Larry Coreno	M204.2-SD1	Vertical Smoke Damper	6" Round	Ruskin	SDR25	N/A	4x4	Pass	1FL Visitation V429
2025-02-17	Juvenile Justice Center	1FL Visitation V430	Larry Coreno	M204.2-SD2	Vertical Smoke Damper	8" Round	Ruskin	SDR25	N/A	3x3	Pass	1FL Visitation V430
2025-02-17	Juvenile Justice Center	Large gym storage room	Larry Coreno	M207-SD1	Vertical Smoke Damper	8" Round	Ruskin	SD50	N/A	4x4	Pass	None
2025-02-18	Juvenile Justice Center	Medical cooridor	Tristan May	M203-SD2	Vertical Smoke Damper	6" Round	Ruskin	SD50	N/A	Patch	Pass	None
2025-02-18	Juvenile Justice Center	Medical cooridor	Tristan May	M203-SD1	Vertical Smoke Damper	6" Round	Ruskin	SD50	N/A	Patch	Pass	None
2025-02-18	Juvenile Justice Center	Medical waiting room	Tristan May	M203-FD1	Vertical Fire Damper	10x10	Ruskin	IBD2	212 Degrees	8x8	Fail	Welded angle

2025-02-18	Juvenile Justice Center	Medical waiting room	Tristan May	M203-FD2	Vertical Fire Damper	10x8	Ruskin	IBD2	212 Degrees	Patch	Pass	None
2025-02-18	Juvenile Justice Center	Medical waiting room	Tristan May	M203-SD3	Vertical Smoke Damper	10x8	Ruskin	SD50	N/A	Patch	Pass	None
2025-02-18	Juvenile Justice Center	1st FL V430 Visitation Search Room	Tristan May	M204.2-FD1	Vertical Fire Damper	10x10	Ruskin	IBD2	212 Degrees	8x8	Fail	Welded angle
2025-02-18	Juvenile Justice Center	In Hallway between recycling and visitation search room	Tristan May	M204.2-FD7	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Patch	Pass	New Fire Damper
2025-02-18	Juvenile Justice Center	L437 Recycling	Tristan May	M204.2-FD2	Vertical Fire Damper	28x14	Ruskin	IBD2	212 Degrees	10x10	Pass	None
2025-02-27	Juvenile Justice Center	Elevator Equipment Room	Tristan May	M201-FD2	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Grille	Pass	Loading dock equipment room
2025-02-27	Juvenile Justice Center	Medical Hallway	Tristan May	M203-SD5	Vertical Smoke Damper	12x10	Ruskin	SD50	N/A	8x8	Pass	None
2025-02-27	Juvenile Justice Center	Medical Files M607	Tristan May	M203-SD11	Vertical Smoke Damper	6"Round	Ruskin	SDR25	N/A	4x4 Patch	Pass	Medical Files M607
2025-02-27	Juvenile Justice Center	Recycling #943	Tristan May	M201-SD11	Vertical Smoke Damper	18x12	Ruskin	SD50	N/A	12x12	Pass	None
2025-02-27	Juvenile Justice Center	Room S929	Tristan May	M201-SD13	Vertical Smoke Damper	10" Round	Ruskin	SDR25	N/A	3x2 Patch	Pass	Loading dock Rm 929
2025-02-27	Juvenile Justice Center	Pharmacy	Tristan May	M203-FD3	Vertical Fire Damper	12x6	Ruskin	IBD2	212 Degrees	10x10	Fail	Medical Pharmacy Welded angle
2025-02-27	Juvenile Justice Center	Medical Hallway	Tristan May	M203-SD4	Vertical Smoke Damper	8x6	Ruskin	SD50	N/A	4x4 Patch	Pass	Medical Hallway
2025-02-27	Juvenile Justice Center	Medical Supply Room	Tristan May	M203-SD10	Vertical Smoke Damper	24x16	Ruskin	SD50	N/A	12x12	Pass	Medical Supply Room

2025-02-27	Juvenile Justice Center	Recycling #943	Tristan May	M201-FSD3	Vertical Fire / Smoke Damper	10x10	Ruskin	FSD60	212 Degrees	8x8	Pass	None
2025-02-27	Juvenile Justice Center	Pharmacy	Tristan May	M203-SD8	Vertical Smoke Damper	10x8	Ruskin	SD50	N/A	8x8	Pass	Medical Pharmacy
2025-02-27	Juvenile Justice Center	Elevator Equipment Room	Tristan May	M201-FD1	Vertical Fire Damper	24x8	Ruskin	IBD2	212 Degrees	5x4 Patch	Pass	Loading dock equipment room
2025-02-27	Juvenile Justice Center	Medical Hallway	Tristan May	M203-SD6	Vertical Smoke Damper	8x8	Ruskin	SD50	N/A	4x4 Patch	Pass	Medical Hallway
2025-02-27	Juvenile Justice Center	Medical Supply Room	Tristan May	M203-SD7	Vertical Smoke Damper	30x18	Ruskin	SD50	N/A	12x12	Pass	Medical Supply Room
2025-02-27	Juvenile Justice Center	Medical Files M607	Tristan May	M203-SD12	Vertical Smoke Damper	8" Round	Ruskin	SDR25	N/A	4x4 Patch	Pass	Medical Files
2025-02-27	Juvenile Justice Center	Medical Supply Room	Tristan May	M203-SD9	Vertical Smoke Damper	24x16	Ruskin	SD50	N/A	12x12	Pass	Medical Supply Room
2025-02-27	Juvenile Justice Center	Central Mechanical	Tristan May	M201-SD12	Vertical Smoke Damper	12x6	Ruskin	SD50	N/A	6x6	Pass	Loading dock mechanical room
2025-02-28	Juvenile Justice Center	Kitchen Dry Storage	Tristan May	M202-SD3	Vertical Smoke Damper	10" Round	Ruskin	SDR25	N/A	6x6 Patch	Pass	Kitchen Dry Storage
2025-02-28	Juvenile Justice Center	Kitchen Dry Storage	Tristan May	M202-SD2	Vertical Smoke Damper	14x8	Ruskin	SD50	N/A	Grille	Pass	Kitchen Dry Storage
2025-02-28	Juvenile Justice Center	Kitchen Dry Storage	Tristan May	M202-SD4	Vertical Smoke Damper	6" Round	Ruskin	SDR25	N/A	Grille	Pass	None
2025-02-28	Juvenile Justice Center	Dinning Hall	Tristan May	M202-SD1	Vertical Smoke Damper	8x8	Ruskin	SD50	N/A	7x7 Patch	Pass	Dinning Hall
2025-02-28	Juvenile Justice Center	Dinning Hall	Tristan May	M202-FSD1	Vertical Fire / Smoke Damper	48x22	Ruskin	FSD60	212 Degrees	12x12	Pass	Dinning Hall

2025-02-28	Juvenile Justice Center	Dinning Hall	Tristan May	M202-FSD2	Vertical Fire / Smoke Damper	50x12	Ruskin	FSD60	212 Degrees	12x12	Pass	Dinning Hall
2025-02-28	Juvenile Justice Center	Kitchen Storage	Tristan May	M202-SD5	Vertical Smoke Damper	8"Round	Ruskin	SDR25	N/A	9x6 Oval	Pass	Kitchen Storage
2025-02-28	Juvenile Justice Center	Intake	Tristan May	M202-SD7	Vertical Smoke Damper	8" Round	Ruskin	SDR25	N/A	4x4 Patch	Pass	Intake
2025-02-28	Juvenile Justice Center	Intake	Tristan May	M202-SD6	Vertical Smoke Damper	12x6	Ruskin	SD50	N/A	6x6	Pass	Intake
2025-03-20	Juvenile Justice Center	House 1 B Pod 2nd FL	Larry Coreno	Unit1-FD9	Vertical Fire Damper	8x8	Ruskin	IBD2	212 Degrees	4x4	Pass	House 1 B Pod 2nd FL
2025-03-20	Juvenile Justice Center	House 1 B Pod 2nd FL	Larry Coreno	Unit1-FD16	Vertical Fire Damper	8x8	Ruskin	IBD2	212 Degrees	4x4	Pass	House1 2nd FL
2025-03-20	Juvenile Justice Center	House 1 B Pod 2nd FL	Larry Coreno	Unit1-FD10	Vertical Fire Damper	17x15	Ruskin	IBD2	212 Degrees	8x8	Pass	House 1 B Pod 2nd FL
2025-03-20	Juvenile Justice Center	House 1 B Pod 2ND FL	Larry Coreno	Unit1-FD14	Vertical Fire Damper	17x15	Ruskin	IBD2	165 Degrees	10x10	Pass	House 1 B Pod 2nd FL
2025-03-20	Juvenile Justice Center	House 1 B Pod 2nd FL	Larry Coreno	Unit1-FD15	Vertical Fire Damper	13x9	Ruskin	IBD2	212 Degrees	10x10	Pass	House1 2nd Fl
2025-03-20	Juvenile Justice Center	House 1 B Pod 2nd FL	Larry Coreno	Unit1-FD11	Vertical Fire Damper	17x15	Ruskin	IBD2	212 Degrees	12x12	Pass	House 1 B Pod 2nd FL
2025-03-20	Juvenile Justice Center	House 1 B Pod 2nd FL	Larry Coreno	Unit1-FD12	Vertical Fire Damper	17x15	Ruskin	IBD2	212 Degrees	12x12	Pass	House 1 B Pod 2nd FL
2025-03-20	Juvenile Justice Center	House 1 2nd FL B pod	Larry Coreno	Unit1-FD13	Vertical Fire Damper	13x9	Ruskin	IBD2	212 Degrees	10x10	Pass	House 1 B Pod 2nd FL
2025-03-20	Juvenile Justice Center	House 1 2nd FL	Larry Coreno	Unit1-FD1	Vertical Fire Damper	16x14	Ruskin	IBD2	212 Degrees	10x10	Pass	House1 2nd Fl
2025-03-20	Juvenile Justice Center	House 1 2nd FL	Larry Coreno	Unit1-FD2	Vertical Fire Damper	16x10	Ruskin	IBD2	212 Degrees	10x10	Pass	House 1 2nd FL
2025-03-20	Juvenile Justice Center	House 1 2nd FL	Larry Coreno	Unit1-FD4	Vertical Fire Damper	12x8	Ruskin	IBD2	212 Degrees	10x10	Pass	House 1 2nd FL
2025-03-20	Juvenile Justice Center	House 1 2nd FL	Larry Coreno	Unit1-FD3	Vertical Fire Damper	10x8	Ruskin	IBD2	212 Degrees	8x8	Pass	House 1 2nd FL
2025-03-20	Juvenile Justice Center	House 1 2nd FL	Larry Coreno	Unit1-FD8	Vertical Fire Damper	18x16	Ruskin	IBD2	212 Degrees	12x12	Pass	None
2025-03-20	Juvenile Justice Center	House 1 2nd FL	Larry Coreno	Unit1-FD7	Vertical Fire Damper	14x16	Ruskin	IBD2	212 Degrees	12x12	Pass	House 1 2nd FL

2025-03-20	Juvenile Justice Center	House 1 2nd FL	Larry Coreno	Unit1-FD5	Vertical Fire Damper	12x8	Ruskin	IBD2	212 Degrees	4x8	Pass	House1 2nd Fl
2025-03-20	Juvenile Justice Center	House 1 2nd FL	Larry Coreno	Unit1-FD6	Vertical Fire Damper	10x10	Ruskin	IBD2	212 Degrees	10x10	Pass	House 1 2nd FL
2025-03-21	Juvenile Justice Center	House 5 storage room	Larry Coreno	Unit5-SD2	Vertical Smoke Damper	6x6	Ruskin	SD50	N/A	6x6	Pass	House 5 Rm5D01
2025-03-21	Juvenile Justice Center	House 5 storage room	Larry Coreno	Unit5-SD1	Vertical Smoke Damper	6x6	Ruskin	SD50	N/A	6x6	Pass	House 5 Rm 5DS1 storage room
2025-03-21	Juvenile Justice Center	House 4 Rm 4D01	Larry Coreno	Unit4-SD2	Vertical Smoke Damper	6x6	Ruskin	SD50	N/A	6x6	Pass	House 4 Rm 4D01
2025-03-21	Juvenile Justice Center	House 1 Rm1DS1	Larry Coreno	Unit1-FSD2	Vertical Fire / Smoke Damper	6x6	Ruskin	FSD60	212 Degrees	6x6	Pass	House 1 Rm 1DS1
2025-03-21	Juvenile Justice Center	House 4 Rm 4DS1	Larry Coreno	Unit4-SD1	Vertical Smoke Damper	6x6	Ruskin	SD50	N/A	6x6	Pass	House 4 Rm 4DS1
2025-03-21	Juvenile Justice Center	House 3 Rm 3DS1 Storage Rm	Larry Coreno	Unit 3-SD2	Vertical Smoke Damper	6x6	Ruskin	SD50	N/A	6x6	Pass	House 3 Rm 3DS1 Storage Rm
2025-03-21	Juvenile Justice Center	House 3 Rm 3DS1 Storage Rm	Larry Coreno	Unit3-SD1	Vertical Smoke Damper	6x6	Ruskin	SD50	N/A	6x6	Pass	House 3 Rm 3DS1 Storage Rm
2025-03-21	Juvenile Justice Center	House 2 Rm 2DS1	Larry Coreno	Unit2-SD2	Vertical Smoke Damper	6x6	Ruskin	SD50	N/A	6x6	Pass	House 2 Rm 2DS1 Storage Rm
2025-03-21	Juvenile Justice Center	House 2 Rm 2D01	Larry Coreno	Unit-SD1	Vertical Smoke Damper	6x6	Ruskin	SD50	N/A	6x6	Pass	House 2 Rm 2D01
2025-03-21	Juvenile Justice Center	House 1 Rm1DS1	Larry Coreno	Unit1-FSD2	Vertical Fire / Smoke Damper	6x6	Ruskin	FSD60	212 Degrees	6x6	Pass	House 1 Rm1DS1
2025-03-21	Juvenile Justice Center	Small Gym Storage Rm	Larry Coreno	M203-SD13	Vertical Smoke Damper	8x8	Greenheck	SMD201	N/A	Bird screen	Pass	Small Gym storage room
2025-03-21	Juvenile Justice Center	Small Gym storage room	Larry Coreno	M203-SD14	Vertical Smoke Damper	8x8	Greenheck	SMD201	N/A	4x4	Pass	Small Gym storage room

2025-03-21	Juvenile Justice Center	Small Gym storage room	Larry Coreno	M203-SD15	Vertical Smoke Damper	8x8	Greenheck	SMD201	N/A	4x4	Pass	Small Gym storage room
2025-03-21	Juvenile Justice Center	Small Gym storage room	Larry Coreno	M203-SD16	Vertical Smoke Damper	8x8	Greenheck	SMD 201	N/A	Bird Screen	Pass	Small Gym storage room
2025-03-21	Juvenile Justice Center	Bulk storage Rm S90 l	Larry Coreno	M201-FSD2	Vertical Fire / Smoke Damper	10x8	Ruskin	FSD60	212 Degrees	4x4	Pass	Bulk storage RmS901
2025-03-21	Juvenile Justice Center	Bulk storage RmS901	Larry Coreno	M201-SD10	Vertical Smoke Damper	14x14	Ruskin	SD50	N/A	4x4	Pass	Bulk Storage RmS901
2025-04-04	Juvenile Justice Center	1ST FL RM S907	Kaitlyn McElroy	M201-SD6	Vertical Smoke Damper	10x6	Ruskin	SD50	N/A	8x8	Pass	1ST FL RM S 907
2025-04-04	Juvenile Justice Center	1ST FL RM S907	Kaitlyn McElroy	M201-SD3	Vertical Smoke Damper	24x17	Ruskin	SD50	N/A	12x12	Pass	1ST FL RM S907
2025-04-04	Juvenile Justice Center	1ST FL RM S907	Kaitlyn McElroy	M201-SD2	Vertical Smoke Damper	30x17	Ruskin	SD50	N/A	12x12	Pass	1st Fl Rm S907
2025-04-04	Juvenile Justice Center	1ST FL RM S907	Kaitlyn McElroy	M201-FSD1	Vertical Fire / Smoke Damper	10x8	Ruskin	FSD60	212 Degrees	8x8	Pass	1ST FL RM S907
2025-04-04	Juvenile Justice Center	1ST FL RM S907	Kaitlyn McElroy	M201-SD	Vertical Smoke Damper	16x8	Ruskin	SD50	N/A	12x12	Pass	1St FL Rm 907
2025-04-04	Juvenile Justice Center	1ST FL Rm907	Kaitlyn McElroy	M201-SD4	Vertical Smoke Damper	6" Round	Ruskin	SDR25	N/A	5x5	Pass	1st FL Rm S907
2025-04-04	Juvenile Justice Center	1FL RM S907	Kaitlyn McElroy	M201-SD1	Vertical Smoke Damper	10" Round	Ruskin	SDR25	N/A	5x5	Pass	1FL RM S907
2025-04-04	Juvenile Justice Center	1st FL Rm S911	Kaitlyn McElroy	M201-SD7	Vertical Smoke Damper	8" Round	Ruskin	SDR25	N/A	4x4	Pass	1FL Rm S911
2025-04-04	Juvenile Justice Center	1FL Rm S913	Kaitlyn McElroy	M201-SD8	Vertical Smoke Damper	12x6	Ruskin	SD50	N/A	8x8	Pass	1FL Rm S913

2025-04-04	Juvenile Justice Center	1FL Rm S913	Kaitlyn McElroy	M201-SD9	Vertical Smoke Damper	10x6	Ruskin	SD50	N/A	8x8	Pass	1FL Rm S913
2025-04-08	Juvenile Justice Center	1FL Intake RM N715	Larry Coreno	M202-FSD3	Vertical Fire / Smoke Damper	10x7	Ruskin	FSD60	212 Degrees	8x8	Pass	1FL Intake RM N715
2025-04-08	Juvenile Justice Center	1Fl Intake Rm N715	Larry Coreno	M202-SD9	Vertical Smoke Damper	10x10	Ruskin	SD50	N/A	8x8	Pass	1FL Intake RM N715
2025-04-08	Juvenile Justice Center	1FL Intake Outside Rm715	Larry Coreno	M202-SD10	Vertical Smoke Damper	16x12	Ruskin	SD50	N/A	8x8	Pass	1ST FL Intake outside Rm N715
2025-04-08	Juvenile Justice Center	1FL Intake Rm N719	Larry Coreno	M202-SD8	Vertical Smoke Damper	12x8	Ruskin	SD50	N/A	8x8	Pass	1FL Intake RM N719
2025-04-10	Juvenile Justice Center	1st FL Intake RM N715	Larry Coreno	AHU-009-S	Horizontal Fire Damper	26x26	Ruskin	IBD2	212 Degrees	24x24	Pass	1st FL Intake RM N715
2025-04-10	Juvenile Justice Center	1st FL Intake RM	Larry Coreno	AHU-010-S	Horizontal Fire Damper	25x25	Ruskin	IBD2	212 Degrees	24x24	Pass	1st FL Intake RM
2025-04-10	Juvenile Justice Center	1FL Unit 1 Pod B 2nd FL	Larry Coreno	Unit1-FD9	Vertical Fire Damper	8x8	Ruskin	IBD2	212 Degrees	4x4	Pass	New angle added. Unit1 Pod B 2nd FL
2025-04-24	Juvenile Justice Center	10FL Mechanical Rm East	Larry Coreno	10FL-E-R3	Vertical Fire Damper	48x24	Air Balance	119C	165 Degrees	16x16	Pass	None
2025-04-25	Juvenile Justice Center	Above the door Rm4610 prosecutors	Larry Coreno	IM141-SD16	Vertical Smoke Damper	10" Round	Greenheck	SMDR301	N/A	9x6 Oval	Pass	Above door of Rm 4610 prosecutors
2025-04-25	Juvenile Justice Center	Prosecutor children & family unit	Larry Coreno	IM141-SD13	Vertical Smoke Damper	10x8	Greenheck	SMD211	N/A	8x8	Pass	Prosecutor children & family unit
2025-04-25	Juvenile Justice Center	Prosecutor children & family unit	Larry Coreno	IM141-SD12	Vertical Smoke Damper	8" Round	Greenheck	SMDR301	N/A	9x6 Oval	Pass	Prosecutor children & family unit
2025-04-25	Juvenile Justice Center	Prosecutor children & family unit	Larry Coreno	IM141-SD14	Vertical Smoke Damper	26x12	Greenheck	SMD211	N/A	5x5	Pass	Prosecutor children & family unit
2025-04-25	Juvenile Justice Center	Prosecutor children & family unit	Larry Coreno	IM141-SD15	Vertical Smoke Damper	8x10	Greenheck	SMD211	N/A	8x8	Pass	Prosecutor children & family unit

2025-04-25	Juvenile Justice Center	4FL Rm4404	Larry Coreno	IM142-SD3	Vertical Smoke Damper	26x6	Greenheck	SMD211	N/A	Open	Pass	4FL Rm4404

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-02-07

Facility Location
Juvenile Justice Center

Damper Location
10FL Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU TO1-R

Damper Type
Horizontal Fire / Smoke Damper

Damper Size
120x60

Damper Manufacturer
Ruskin

Damper Model #
FSD60

Fusible Link Temperature
212 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
10FL Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-02-07

Facility Location
Juvenile Justice Center

Damper Location
10FL Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU TO1-R2

Damper Type
Horizontal Fire Damper

Damper Size
50x50

Damper Manufacturer
Greenheck

Damper Model #
DFDTT210

Fusible Link Temperature
212 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
10FL Penthouse behind TO1 unit

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: September 16th, 2024

Project: Cuyahoga County
Medical Examiner's Building

Inspector(s): James Futrell, Certified Technician

Inspection and Test Date(s): August & September 2024

Duct Fabricators, Inc. "Fire Safety Division" inspected the One Hundred Four (104) fire dampers noted on the following sheets for proper installation. The dampers were then tested and photographed in the "open" and "closed" positions to confirm that they were functioning as designed.

(86) dampers passed the inspection and functional testing.
(18) dampers failed the inspection for reasons listed on the report.

NOTES: NFPA 80 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers located in patient care facilities are to be inspected and tested every six years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
1	2024-08-26	County Examiner Bldg.	Men's bathroom 6FL	James Futrell	FD-01	Vertical Fire Damper	8"/10"	Unknown	Unknown	165 Degrees	8"/6"	Fail	No Fire sleeve/No Frams
2	2024-08-26	County Examiner Bldg.	Mech Rm 606	James Futrell	FD-02	Horizontal Fire Damper	6"/10"	Unknown	unknown	165 Degrees	6"/6"	Pass	None
3	2024-08-26	County Examiner Bldg.	Mech Rm 606 6FL	James Futrell	FD-03	Horizontal Fire Damper	6"/10"	Unknown	unknown	165 Degrees	6"/6"	Pass	None
4	2024-08-26	County Examiner Bldg.	Women's Bathroom 6 FL	James Futrell	FD-04	Vertical Fire Damper	10"/8"	Unknown	Unknown	165 Degrees	8"/6"	Fail	No fire sleeve/No frams
5	2024-08-26	County Examiner Bldg.	Mech RM 605	James Futrell	FD-05	Vertical Fire Damper	12"/10"	Unknown	Unknown	165 Degrees	12"/10". Grill	Pass	None
6	2024-08-26	County Examiner Bldg.	Mech RM 5Th Floor	James Futrell	FD-06	Vertical Fire Damper	40"/9"	Unknown	Unknown	165 Degrees	6"/6"	Pass	None
7	2024-08-26	County Examiner Bldg.	Mech Rm 606	James Futrell	FD-07	Horizontal Fire Damper	36"/14"	Unknown	Unknown	165 Degrees	8"/8" -(2)	Pass	2 Dampers inside duct
8	2024-08-26	County Examiner Bldg.	Mech RM 5TH FL	James Futrell	FD-08	Vertical Fire Damper	14"/14"	Unknown	Unknown	165 Degrees	6"/6"	Pass	None
9	2024-08-26	County Examiner Bldg.	Mech RM 5TH. FL	James Futrell	FD-09	Vertical Fire Damper	36"/12"	Unknown	Unknown	165 Degrees	8"/8"	Fail	Damper is unaccessible/open air between Dampers 9/10
10	2024-08-26	County Examiner Bldg.	Mech RM 5TH FL	James Futrell	FD-10	Vertical Fire Damper	30"/10"	Unknown	Unknown	165 Degrees	8"/8"	Fail	Damper is unaccessible/open air between FD-10/9
11	2024-08-27	County Examiner Bldg.	Mech RM 5Th FL Door	James Futrell	FD-11	Vertical Fire Damper	48"/12"	Unknown	Unknown	165 Degrees	8"/8"	Pass	None
12	2024-08-27	County Examiner Bldg.	Hallway 5TH. FL	James Futrell	FD-12	Vertical Fire Damper	10"/6"	Unknown	Unknown	165 Degrees	6"/6"	Pass	None
13	2024-08-27	County Examiner Bldg.	Hallway 5TH. FL	James Futrell	FD-13	Vertical Fire Damper	10"/6"	Unknown	Unknown	165 Degrees	6"/6"	Pass	None
14	2024-08-27	County Examiner Bldg.	Hallway 5TH. FL	James Futrell	FD-14	Vertical Fire Damper	40"/7"	Unknown	Unknown	165 Degrees	6"/6"	Pass	None
15	2024-08-27	County Examiner Bldg.	Men's Restroom 5Th FL	James Futrell	FD-15	Vertical Fire Damper	10"/8"	Unknown	Unknown	165 Degrees	8"/6"	Fail	No damper sleeve/No Frams
16	2024-08-27	County Examiner Bldg.	RM 502	James Futrell	FD-16	Vertical Fire Damper	6"/6"	Unknown	Unknown	165 Degrees	5"/5"	Fail	No damper sleeve/Curtain not in wall/No Frams
17	2024-08-27	County Examiner Bldg.	RM 504 Mech RM	James Futrell	FD-17	Vertical Fire Damper	8" Round	Unknown	Unknown	165 Degrees	10"/6"	Pass	None
18	2024-08-27	County Examiner Bldg.	Door 505	James Futrell	FD-18	Vertical Fire Damper	12"/6"	Unknown	Unknown	165 Degrees	Grill	Pass	None
19	2024-08-27	County Examiner Bldg.	Rm-404. Mech Rm	James Futrell	FD-19	Vertical Fire Damper	28"/18"	Unknown	Unknown	165 Degrees	12"/12"	Pass	None
20	2024-08-27	County Examiner Bldg.	RM 405 Mech Rm	James Futrell	FD-20	Vertical Fire Damper	28"/18"	Unknown	Unknown	165 Degrees	12"/12"	Pass	None

21	2024-08-27	County Examiner Bldg.	RM-405. Mech. Rm	James Futrell	FD-21	Vertical Fire Damper	20"/10"	Unknown	Unknown	165 Degrees	10"/10"	Pass	Cut in access door
22	2024-08-27	County Examiner Bldg.	RM -405 Mech Rm	James Futrell	FD-22	Vertical Fire Damper	10"/6"	Unknown	Unknown	165 Degrees	10"/10"	Pass	Cut in access door
23	2024-08-28	County Examiner Bldg.	Men's Bathroom	James Futrell	FD-23	Vertical Fire Damper	8"/10"	Unknown	Unknown	165 Degrees	8"/6"	Fail	No damper sleeve/No Frams/Cement at wall
24	2024-08-28	County Examiner Bldg.	Mech RM-404 behind Men's bathroom	James Futrell	FD-24	Vertical Fire Damper	10"/6"	Unknown	Unknown	165 Degrees	10"/10"	Pass	Cut in access door
25	2024-09-04	County Examiner Bldg.	Mech RM 406	James Futrell	FD-25	Vertical Fire Damper	40/14	Unknown	Unknown	165 Degrees	16/16	Pass	Installed access door
26	2024-08-28	County Examiner Bldg.	Mech RM 406	James Futrell	FD-26	Vertical Fire Damper	10/8	Unknown	Unknown	165 Degrees	10/10	Pass	Install access door
27	2024-08-28	County Examiner Bldg.	Closet 402	James Futrell	FD-27	Vertical Fire Damper	28/18	Unknown	Unknown	165 Degrees	12/12	Pass	None
28	2024-08-28	County Examiner Bldg.	4th floor Women's Bathroom	James Futrell	FD-28	Vertical Fire Damper	10/8	Unknown	Unknown	165 Degrees	8/8	Pass	Install access door
29	2024-08-28	County Examiner Bldg.	4th floor Women's Bathroom	James Futrell	FD-29	Vertical Fire Damper	72/24	Unknown	Unknown	165 Degrees	18/18	Pass	None
30	2024-08-28	County Examiner Bldg.	Mech RM 404	James Futrell	FD-30	Vertical Fire Damper	6inch round	Unknown	Unknown	165 Degrees	10/6	Pass	Install access door
31	2024-08-29	County Examiner Bldg.	4th floor hallway	James Futrell	FD-31	Vertical Fire Damper	96/20	Unknown	Unknown	165 Degrees	16/16	Pass	Remove abandoned balance Dampers to can access to fire damper
32	2024-08-29	County Examiner Bldg.	3rd floor mech room	James Futrell	FD-32	Vertical Fire Damper	28/18	Unknown	Unknown	165 Degrees	12/12	Pass	None
33	2024-08-29	County Examiner Bldg.	3rd floor mech room	James Futrell	FD-33	Vertical Fire Damper	22/12	Unknown	Unknown	165 Degrees	10/10	Pass	Install access door
34	2024-08-29	County Examiner Bldg.	3rd floor mech room	James Futrell	FD-34	Vertical Fire Damper	6 inch round	Unknown	Unknown	165 Degrees	10/6	Pass	Install access door , install new heat link, damper was found in closed position
35	2024-08-29	County Examiner Bldg.	3rd floor men's bathroom	James Futrell	FD-35	Vertical Fire Damper	54/16	Unknown	Unknown	165 Degrees	12/12	Pass	None
36	2024-08-29	County Examiner Bldg.	3rd floor men's room, mech room	James Futrell	FD-36	Vertical Fire Damper	34/18	Unknown	Unknown	165 Degrees	12/12	Pass	None
37	2024-08-29	County Examiner Bldg.	3rd floor men's room,mech room	James Futrell	FD-37	Vertical Fire Damper	34/18	Unknown	Unknown	165 Degrees	14/14	Pass	Repair retaining angle frame , install access door
38	2024-08-29	County Examiner Bldg.	3rd floor hallway	James Futrell	FD-38	Vertical Fire Damper	48/16	Unknown	Unknown	165 Degrees	10/10	Pass	Install access door

39	2024-08-29	County Examiner Bldg.	3rd floor hallway	James Futrell	FD-39	Vertical Fire Damper	38/14	Unknown	Unknown	165 Degrees	12/12	Pass	Add retaining angle frame , on both sides of wall
40	2024-08-29	County Examiner Bldg.	3rd floor hallway	James Futrell	FD-40	Vertical Fire Damper	36/14	Unknown	Unknown	165 Degrees	Open	Pass	None
41	2024-08-29	County Examiner Bldg.	3rd floor hallway	James Futrell	FD-41	Vertical Fire Damper	36/14	Unknown	Unknown	165 Degrees	Open	Pass	None
42	2024-08-29	County Examiner Bldg.	3rd floor hallway	James Futrell	FD-42	Vertical Fire Damper	20/14	Unknown	Unknown	165 Degrees	16/16	Pass	None
43	2024-08-29	County Examiner Bldg.	3rd floor hallway by women bathroom	James Futrell	FD-43	Vertical Fire Damper	24/14	Unknown	Unknown	165 Degrees	12/12	Fail	No retaining angle, conduit in annular space
44	2024-09-04	County Examiner Bldg.	3rd floor hallway by women bathroom	James Futrell	FD-44	Vertical Fire / Smoke Damper	94/19	Unknown	Unknown	165 Degrees	Open	Pass	None
45	2024-08-29	County Examiner Bldg.	3rd floor by evidence	James Futrell	FD-45	Vertical Fire Damper	48/18	Unknown	Unknown	165 Degrees	Open	Pass	None
46	2024-09-04	County Examiner Bldg.	Mech Room 605	James Futrell	FD-46	Horizontal Fire Damper	66/20	Unknown	Unknown	165 Degrees	24/24	Pass	None
47	2024-09-04	County Examiner Bldg.	Mech RM 605	James Futrell	FD-47	Horizontal Fire Damper	66/24	Unknown	Unknown	165 Degrees	24/24	Pass	None
48	2024-09-04	County Examiner Bldg.	4th floor hallway	James Futrell	FD-48	Vertical Fire Damper	70/16	Unknown	Unknown	165 Degrees	18/18	Pass	None
49	2024-09-04	County Examiner Bldg.	4th floor hallway	James Futrell	FD-49	Vertical Fire Damper	60/30	Unknown	Unknown	165 Degrees	18/18	Pass	None
50	2024-09-04	County Examiner Bldg.	3rd floor suite 308	James Futrell	FD-50	Vertical Fire Damper	16/8	Unknown	Unknown	165 Degrees	Open	Pass	None
51	2024-09-04	County Examiner Bldg.	3rd floor suite 308	James Futrell	FD-51	Vertical Fire Damper	40/18	Unknown	Unknown	165 Degrees	Open	Pass	None
52	2024-09-04	County Examiner Bldg.	3rd floor suite 308	James Futrell	FD-52	Vertical Fire Damper	28/14	Unknown	Unknown	165 Degrees	16/16	Pass	Install access door
53	2024-09-04	County Examiner Bldg.	3rd floor server room	James Futrell	FD-53	Vertical Fire Damper	8inch round	Unknown	Unknown	165 Degrees	6/10	Pass	None
54	2024-09-04	County Examiner Bldg.	3rd floor Fire Arms Ref Room	James Futrell	FD-54	Vertical Fire Damper	36/16	Unknown	Unknown	165 Degrees	Open	Pass	None
55	2024-09-04	County Examiner Bldg.	3rd floor Fire Arms Ref Room	James Futrell	FD-55	Vertical Fire Damper	48/16	Unknown	Unknown	165 Degrees	16/16	Pass	None
56	2024-09-04	County Examiner Bldg.	3rd floor Fire Arms Ref Room	James Futrell	FD-56	Vertical Fire Damper	14/10	Unknown	Unknown	165 Degrees	Open	Pass	None
57	2024-09-04	County Examiner Bldg.	3rd floor Fire Arms Ref Room	James Futrell	FD-57	Vertical Fire Damper	24/20	Unknown	Unknown	165 Degrees	Open	Pass	None
58	2024-09-04	County Examiner Bldg.	3rd floor Fire Arms Ref Room	James Futrell	FD-58	Vertical Fire Damper	8 inch round	Unknown	Unknown	165 Degrees	6/10	Pass	None
59	2024-09-04	County Examiner Bldg.	3rd floor Rm325	James Futrell	FD-59	Vertical Fire Damper	24/14	Unknown	Unknown	165 Degrees	Open	Pass	None

60	2024-09-04	County Examiner Bldg.	3rd floor Finger print back hallway	James Futrell	FD-60	Vertical Fire Damper	6 inch round	Unknown	Unknown	165 Degrees	Inaccessible	Fail	Inaccessible
61	2024-09-04	County Examiner Bldg.	3rd floor by Morgue elevator	James Futrell	FD-61	Vertical Fire Damper	48/16	Unknown	Unknown	165 Degrees	16/16	Pass	None
62	2024-09-04	County Examiner Bldg.	3rd floor by Morgue elevator	James Futrell	FD-62	Vertical Fire Damper	6 inch round	Unknown	Unknown	165 Degrees	5/8	Pass	None
63	2024-09-05	County Examiner Bldg.	2nd floor mech room	James Futrell	FD-63	Vertical Fire Damper	66/20	Unknown	Unknown	165 Degrees	18/18	Pass	Install access door , damper is two separate curtains
64	2024-09-05	County Examiner Bldg.	2nd floor mech room	James Futrell	FD-64	Vertical Fire Damper	66/32	Unknown	Unknown	165 Degrees	20/20	Pass	Install access door , damper is two separate curtains
65	2024-09-05	County Examiner Bldg.	2nd floor mech room	James Futrell	FD-65	Vertical Fire Damper	20/12	Unknown	Unknown	165 Degrees	14/14	Pass	Install access door, access located on top of duct
66	2024-09-05	County Examiner Bldg.	2nd floor mech room	James Futrell	FD-66	Vertical Fire Damper	20/12	Unknown	Unknown	165 Degrees	8/8	Pass	Install access door, located on top of duct
67	2024-09-05	County Examiner Bldg.	2nd floor mech room	James Futrell	FD-67	Vertical Fire Damper	20/12	Unknown	Unknown	165 Degrees	8/8	Pass	None
68	2024-09-05	County Examiner Bldg.	2nd floor mech room	James Futrell	FD-68	Vertical Fire Damper	20/12	Unknown	Unknown	165 Degrees	8/8	Pass	None
69	2024-09-05	County Examiner Bldg.	2nd floor mech room	James Futrell	FD-69	Vertical Fire Damper	8inch round	Unknown	Unknown	165 Degrees	Remove flex	Pass	None
70	2024-09-05	County Examiner Bldg.	2nd floor hallway by electrical room B	James Futrell	FD-70	Vertical Fire / Smoke Damper	18inch round	Ruskin	FSD60	165 Degrees	12/10	Pass	None
71	2024-09-05	County Examiner Bldg.	2nd floor electric rm B	James Futrell	FD-71	Vertical Fire / Smoke Damper	10/6	Ruskin	Unknown 10/6	165 Degrees	Remove grille for access	Pass	None
72	2024-09-05	County Examiner Bldg.	2nd floor hard lid by RM 202	James Futrell	FD-72	Vertical Fire Damper	28/14	Unknown	Unknown	165 Degrees	14/14	Pass	Install access door
73	2024-09-05	County Examiner Bldg.	2nd floor men's bathroom	James Futrell	FD-73	Vertical Fire Damper	8/10	Unknown	Unknown	165 Degrees	8/6	Fail	No annular space,no retaining frame
74	2024-09-05	County Examiner Bldg.	2nd floor hallway	James Futrell	FD-74	Vertical Fire Damper	24/12	Unknown	Unknown	165 Degrees	18/12	Pass	None
75	2024-09-05	County Examiner Bldg.	2nd floor hallway	James Futrell	FD-75	Vertical Fire Damper	14/6	Unknown	Unknown	165 Degrees	8/8	Pass	Install access door
76	2024-09-06	County Examiner Bldg.	2nd floor hallway	James Futrell	FD-76	Vertical Fire Damper	14/6	Unknown	Unknown	165 Degrees	12/12	Fail	Seal tight in annular space, retaining angle missing
77	2024-09-06	County Examiner Bldg.	2nd floor women bathroom	James Futrell	FD-77	Vertical Fire Damper	10/8	Unknown	Unknown	165 Degrees	6/8	Fail	No annular space , no retaining frame
78	2024-09-06	County Examiner Bldg.	3rd floor evidence	James Futrell	FD-78	Vertical Fire Damper	40/16	Ruskin	Unknown	165 Degrees	16/16	Pass	None

79	2024-09-06	County Examiner Bldg.	3rd floor evidence	James Futrell	FSD-79	Vertical Fire / Smoke Damper	48/16	Ruskin	Unknown	165 Degrees	16/16	Fail	No retaining frame
80	2024-09-06	County Examiner Bldg.	3rd floor evidence drying room	James Futrell	FD-80	Vertical Fire Damper	48/18	Unknown	Unknown	165 Degrees	16/16	Pass	None
81	2024-09-06	County Examiner Bldg.	3rd floor evidence lobby	James Futrell	FD-82	Vertical Fire Damper	22/12	Ruskin	Unknown	165 Degrees	12/12	Pass	None
82	2024-09-06	County Examiner Bldg.	3rd floor evidence lobby	James Futrell	FSD-81	Vertical Fire / Smoke Damper	96/20	Unknown	Unknown	165 Degrees	16/16	Pass	None
83	2024-09-06	County Examiner Bldg.	3rd floor chemistry hallway	James Futrell	FD-83	Vertical Fire Damper	48/18	Ruskin	Unknown	165 Degrees	Open	Pass	None
84	2024-09-06	County Examiner Bldg.	1st floor room 123	James Futrell	FD-84	Vertical Fire Damper	12inch round	Ruskin	Unknown	212 Degrees	12/8	Pass	Install access door
86	2024-09-06	County Examiner Bldg.	1st floor women bathroom	James Futrell	FD-85	Vertical Fire Damper	36/12	Unknown	Unknown	165 Degrees	12/12	Fail	No sleeve, no retaining frame
87	2024-09-12	County Examiner Bldg.	1st floor women bathroom	James Futrell	FD-86	Vertical Fire Damper	36/12	Unknown	Unknown	165 Degrees	12/12	Fail	No annular space, no retaining frame, no sleeve
88	2024-09-12	County Examiner Bldg.	1st floor women bathroom	James Futrell	FD-87	Vertical Fire Damper	10/6	Unknown	Unknown	165 Degrees	6/6	Pass	None
89	2024-09-12	County Examiner Bldg.	1st floor conference room hallway	James Futrell	FD-88	Vertical Fire Damper	46/10	Unknown	Unknown	165 Degrees	16/16	Pass	None
90	2024-09-12	County Examiner Bldg.	1st floor men's bathroom	James Futrell	FD-89	Vertical Fire Damper	10/6	Unknown	Unknown	165 Degrees	8/8	Pass	None
91	2024-09-12	County Examiner Bldg.	2nd fl 202 info services	James Futrell	FD-90	Vertical Fire Damper	15 inch round	Unknown	Unknown	165 Degrees	10/6	Pass	None
92	2024-09-12	County Examiner Bldg.	2nd fl info services 202	James Futrell	FD-91	Vertical Fire Damper	12 inch round	Unknown	Unknown	165 Degrees	Open	Abandoned	Found closed left as is, marked as abandoned
93	2024-09-12	County Examiner Bldg.	2nd fl data center build room	James Futrell	FD-92	Vertical Fire Damper	70/16	Unknown	Unknown	165 Degrees	12/12	Pass	Duct has two curtains in it
94	2024-09-12	County Examiner Bldg.	2nd fl data center build room	James Futrell	FD-93	Vertical Fire Damper	96/18	Unknown	Unknown	165 Degrees	40/18	Pass	Remove abandoned volume damper, install access door , damper is two separate curtains
95	2024-09-12	County Examiner Bldg.	2nd fl 201M	James Futrell	FD-94	Vertical Fire Damper	20/10	Unknown	Unknown	165 Degrees	12/12	Pass	None
96	2024-09-13	County Examiner Bldg.	Ground floor women bathroom	James Futrell	FD-95	Vertical Fire Damper	12/10	Unknown	Unknown	165 Degrees	8/8	Fail	No annular space, no retaining frame, no sleeve

97	2024-09-13	County Examiner Bldg.	Ground floor women bathroom	James Futrell	FD-96	Vertical Fire Damper	10/8	Unknown	Unknown	165 Degrees	8/8	Fail	No annular space, no retaining frame, no sleeve
98	2024-09-13	County Examiner Bldg.	Ground floor women bathroom	James Futrell	FD-97	Vertical Fire Damper	12/10	Unknown	Unknown	165 Degrees	8/8	Fail	No annular space, no retaining frame, no sleeve
99	2024-09-13	County Examiner Bldg.	Ground floor room 022	James Futrell	FD-98	Vertical Fire Damper	24/5	Unknown	Unknown	165 Degrees	10/10	Pass	None
100	2024-09-13	County Examiner Bldg.	Ground floor mech room 025	James Futrell	FD-99	Vertical Fire Damper	76/42	Unknown	Unknown	165 Degrees	16/16	Pass	Damper is two separate curtains
101	2024-09-13	County Examiner Bldg.	Vehicle bay	James Futrell	FD-100	Vertical Fire Damper	48/24	Unknown	Unknown	165 Degrees	Open	Pass	None
102	2024-09-13	County Examiner Bldg.	Vehicle bay	James Futrell	FD-101	Vertical Fire Damper	30/20	Unknown	Unknown	165 Degrees	14/14	Pass	None
103	2024-09-13	County Examiner Bldg.	Vehicle bay	James Futrell	FD-102	Vertical Fire Damper	32/20	Unknown	Unknown	165 Degrees	12/12	Pass	None
104	2024-09-13	County Examiner Bldg.	Vehicle bay	James Futrell	FD-103	Vertical Fire Damper	14/12	Unknown	Unknown	165 Degrees	12/12	Pass	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Men's bathroom 6FL

Inspector Name
James Futrell

Damper I.D. #
FD-1

Damper Type
Vertical Fire Damper

Damper Size
8"/10"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"/6"

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve/No retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Mech Rm 606

Inspector Name
James Futrell

Damper I.D. #
FD-2

Damper Type
Horizontal Fire Damper

Damper Size
6"/10"

Damper Manufacturer
Unknown

Damper Model #
unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6"/6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Mech Rm 606 6FL

Inspector Name
James Futrell

Damper I.D. #
FD-3

Damper Type
Horizontal Fire Damper

Damper Size
6"/10"

Damper Manufacturer
Unknown

Damper Model #
unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6"/6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Women's Bathroom 6 FL

Inspector Name
James Futrell

Damper I.D. #
FD-4

Damper Type
Vertical Fire Damper

Damper Size
10"/8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"/6"

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve/No retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 605

Inspector Name
James Futrell

Damper I.D. #
FD-5

Damper Type
Vertical Fire Damper

Damper Size
12"/10"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"/10" Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 5Th Floor

Inspector Name
James Futrell

Damper I.D. #
FD-6

Damper Type
Vertical Fire Damper

Damper Size
40"/9"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6"/6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Mech Rm 606

Inspector Name
James Futrell

Damper I.D. #
FD-7

Damper Type
Horizontal Fire Damper

Damper Size
36"/14"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"/8" (2)

Pass / Fail / Abandoned
Pass

Comments / Corrections
2 Dampers inside duct

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 5TH FL

Inspector Name
James Futrell

Damper I.D. #
FD-8

Damper Type
Vertical Fire Damper

Damper Size
14"/14"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6"/6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 5TH. FL

Inspector Name
James Futrell

Damper I.D. #
FD-9

Damper Type
Vertical Fire Damper

Damper Size
36"/12"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"/8"

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper is inaccessible/open air between Dampers 9/10

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-26

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 5TH FL

Inspector Name
James Futrell

Damper I.D. #
FD-10

Damper Type
Vertical Fire Damper

Damper Size
30"/10"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"/8"

Pass / Fail / Abandoned
Fail

Comments / Corrections
Damper is inaccessible/open air between FD-10/9

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 5Th FL Door

Inspector Name
James Futrell

Damper I.D. #
FD-11

Damper Type
Vertical Fire Damper

Damper Size
48"/12"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"/8"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
Hallway 5TH. FL

Inspector Name
James Futrell

Damper I.D. #
FD-12

Damper Type
Vertical Fire Damper

Damper Size
10"/6"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6"/6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
Hallway 5TH. FL

Inspector Name
James Futrell

Damper I.D. #
FD-13

Damper Type
Vertical Fire Damper

Damper Size
10"/6"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6"/6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
Hallway 5TH. FL

Inspector Name
James Futrell

Damper I.D. #
FD-14

Damper Type
Vertical Fire Damper

Damper Size
40"/7"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6"/6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
Men's Restroom 5Th FL

Inspector Name
James Futrell

Damper I.D. #
FD-15

Damper Type
Vertical Fire Damper

Damper Size
10"/8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"/6"

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve or retaining angles

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
RM 502

Inspector Name
James Futrell

Damper I.D. #
FD-16

Damper Type
Vertical Fire Damper

Damper Size
6"/6"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
5"/5"

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve/Curtain not in wall/No retaining angles

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
RM 504 Mech RM

Inspector Name
James Futrell

Damper I.D. #
FD-17

Damper Type
Vertical Fire Damper

Damper Size
8" Round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10"/6"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
Door 505

Inspector Name
James Futrell

Damper I.D. #
FD-18

Damper Type
Vertical Fire Damper

Damper Size
12"/6"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
Rm-404. Mech Rm

Inspector Name
James Futrell

Damper I.D. #
FD-19

Damper Type
Vertical Fire Damper

Damper Size
28"/18"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"/12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
RM 405 Mech Rm

Inspector Name
James Futrell

Damper I.D. #
FD-20

Damper Type
Vertical Fire Damper

Damper Size
28"/18"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"/12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
RM-405 Mech. Rm

Inspector Name
James Futrell

Damper I.D. #
FD-21

Damper Type
Vertical Fire Damper

Damper Size
20"/10"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10"/10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Cut in access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-27

Facility Location
County Examiner Bldg.

Damper Location
RM -405 Mech Rm

Inspector Name
James Futrell

Damper I.D. #
FD-22

Damper Type
Vertical Fire Damper

Damper Size
10"/6"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10"/10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Cut in access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-28

Facility Location
County Examiner Bldg.

Damper Location
Men's Bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-23

Damper Type
Vertical Fire Damper

Damper Size
8"/10"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8"/6"

Pass / Fail / Abandoned
Fail

Comments / Corrections
No damper sleeve/No retaining angle/
Cement filled annular space

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-28

Facility Location
County Examiner Bldg.

Damper Location
Mech RM-404 behind Men's bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-24

Damper Type
Vertical Fire Damper

Damper Size
10"/6"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10"/10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 406

Inspector Name
James Futrell

Damper I.D. #
FD-25

Damper Type
Vertical Fire Damper

Damper Size
40/14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-28

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 406

Inspector Name
James Futrell

Damper I.D. #
FD-26

Damper Type
Vertical Fire Damper

Damper Size
10/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Install access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-28

Facility Location
County Examiner Bldg.

Damper Location
Closet 402

Inspector Name
James Futrell

Damper I.D. #
FD-27

Damper Type
Vertical Fire Damper

Damper Size
28/18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-28

Facility Location
County Examiner Bldg.

Damper Location
4th floor Women's Bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-28

Damper Type
Vertical Fire Damper

Damper Size
10/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-28

Facility Location
County Examiner Bldg.

Damper Location
4th floor Women's Bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-29

Damper Type
Vertical Fire Damper

Damper Size
72/24

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18/18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-28

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 404

Inspector Name
James Futrell

Damper I.D. #
FD-30

Damper Type
Vertical Fire Damper

Damper Size
6-inch round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/6

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
4th floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-31

Damper Type
Vertical Fire Damper

Damper Size
96/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
Remove abandoned balancing damper to access to fire damper

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-32

Damper Type
Vertical Fire Damper

Damper Size
28/18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-33

Damper Type
Vertical Fire Damper

Damper Size
22/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-34

Damper Type
Vertical Fire Damper

Damper Size
6-inch round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/6

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed access door & link. Damper was found in closed position

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor men's bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-35

Damper Type
Vertical Fire Damper

Damper Size
54/16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor men's room, mech room

Inspector Name
James Futrell

Damper I.D. #
FD-36

Damper Type
Vertical Fire Damper

Damper Size
34/18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor men's room,mech room

Inspector Name
James Futrell

Damper I.D. #
FD-37

Damper Type
Vertical Fire Damper

Damper Size
34/18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14/14

Pass / Fail / Abandoned
Pass

Comments / Corrections
Repaired retaining angle, installed access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-38

Damper Type
Vertical Fire Damper

Damper Size
48/16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-39

Damper Type
Vertical Fire Damper

Damper Size
38/14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle on both sides of wall

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-40

Damper Type
Vertical Fire Damper

Damper Size
36/14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-41

Damper Type
Vertical Fire Damper

Damper Size
36/14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-42

Damper Type
Vertical Fire Damper

Damper Size
20/14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor hallway by women bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-43

Damper Type
Vertical Fire Damper

Damper Size
24/14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No retaining angle, conduit in annular space

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor hallway by women bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-44

Damper Type
Vertical Fire / Smoke Damper

Damper Size
94/19

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-29

Facility Location
County Examiner Bldg.

Damper Location
3rd floor by evidence

Inspector Name
James Futrell

Damper I.D. #
FD-45

Damper Type
Vertical Fire Damper

Damper Size
48/18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
Mech Room 605

Inspector Name
James Futrell

Damper I.D. #
FD-46

Damper Type
Horizontal Fire Damper

Damper Size
66/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
24/24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
Mech RM 605

Inspector Name
James Futrell

Damper I.D. #
FD-47

Damper Type
Horizontal Fire Damper

Damper Size
66/24

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
24/24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
4th floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-48

Damper Type
Vertical Fire Damper

Damper Size
70/16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18/18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
4th floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-49

Damper Type
Vertical Fire Damper

Damper Size
60/30

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18/18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor suite 308

Inspector Name
James Futrell

Damper I.D. #
FD-50

Damper Type
Vertical Fire Damper

Damper Size
16/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor suite 308

Inspector Name
James Futrell

Damper I.D. #
FD-51

Damper Type
Vertical Fire Damper

Damper Size
40/18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor suite 308

Inspector Name
James Futrell

Damper I.D. #
FD-52

Damper Type
Vertical Fire Damper

Damper Size
28/14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
Install access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor server room

Inspector Name
James Futrell

Damper I.D. #
FD-53

Damper Type
Vertical Fire Damper

Damper Size
8-inch round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor Fire Arms Ref Room

Inspector Name
James Futrell

Damper I.D. #
FD-54

Damper Type
Vertical Fire Damper

Damper Size
36/16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor Fire Arms Ref Room

Inspector Name
James Futrell

Damper I.D. #
FD-55

Damper Type
Vertical Fire Damper

Damper Size
48/16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor Fire Arms Ref Room

Inspector Name
James Futrell

Damper I.D. #
FD-56

Damper Type
Vertical Fire Damper

Damper Size
14/10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor Fire Arms Ref Room

Inspector Name
James Futrell

Damper I.D. #
FD-57

Damper Type
Vertical Fire Damper

Damper Size
24/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor Fire Arms Ref Room

Inspector Name
James Futrell

Damper I.D. #
FD-58

Damper Type
Vertical Fire Damper

Damper Size
8 inch round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor Rm325

Inspector Name
James Futrell

Damper I.D. #
FD-59

Damper Type
Vertical Fire Damper

Damper Size
24/14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor Finger print back hallway

Inspector Name
James Futrell

Damper I.D. #
FD-60

Damper Type
Vertical Fire Damper

Damper Size
6 inch round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Inaccessible

Pass / Fail / Abandoned
Fail

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor by Morgue elevator

Inspector Name
James Futrell

Damper I.D. #
FD-61

Damper Type
Vertical Fire Damper

Damper Size
48/16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-04

Facility Location
County Examiner Bldg.

Damper Location
3rd floor by Morgue elevator

Inspector Name
James Futrell

Damper I.D. #
FD-62

Damper Type
Vertical Fire Damper

Damper Size
6 inch round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
5/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-63

Damper Type
Vertical Fire Damper

Damper Size
66/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18/18

Pass / Fail / Abandoned
Pass

Comments / Corrections
Install access door , damper is two separate curtains

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-64

Damper Type
Vertical Fire Damper

Damper Size
66/32

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
20/20

Pass / Fail / Abandoned
Pass

Comments / Corrections
Install access door , damper is two separate curtains

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-65

Damper Type
Vertical Fire Damper

Damper Size
20/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14/14

Pass / Fail / Abandoned
Pass

Comments / Corrections
Install access door, access located on top of duct

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-66

Damper Type
Vertical Fire Damper

Damper Size
20/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Install access door, located on top of duct

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-67

Damper Type
Vertical Fire Damper

Damper Size
20/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-68

Damper Type
Vertical Fire Damper

Damper Size
20/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor mech room

Inspector Name
James Futrell

Damper I.D. #
FD-69

Damper Type
Vertical Fire Damper

Damper Size
8inch round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Remove flex

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor hallway by electrical room B

Inspector Name
James Futrell

Damper I.D. #
FD-70

Damper Type
Vertical Fire / Smoke Damper

Damper Size
18inch round

Damper Manufacturer
Ruskin

Damper Model #
FSD60

Fusible Link Temperature
165 Degrees

Access Door Size
12/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor electric rm B

Inspector Name
James Futrell

Damper I.D. #
FD-71

Damper Type
Vertical Fire / Smoke Damper

Damper Size
10/6

Damper Manufacturer
Ruskin

Damper Model #
Unknown 10/6

Fusible Link Temperature
165 Degrees

Access Door Size
Remove grille for access

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor hard lid by RM 202

Inspector Name
James Futrell

Damper I.D. #
FD-72

Damper Type
Vertical Fire Damper

Damper Size
28/14

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14/14

Pass / Fail / Abandoned
Pass

Comments / Corrections
Install access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor men's bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-73

Damper Type
Vertical Fire Damper

Damper Size
8/10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/6

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space,no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-74

Damper Type
Vertical Fire Damper

Damper Size
24/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
18/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-05

Facility Location
County Examiner Bldg.

Damper Location
2nd floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-75

Damper Type
Vertical Fire Damper

Damper Size
14/6

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Install access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
2nd floor hallway

Inspector Name
James Futrell

Damper I.D. #
FD-76

Damper Type
Vertical Fire Damper

Damper Size
14/6

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Seal tight in annular space, retaining angle missing

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
2nd floor women bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-77

Damper Type
Vertical Fire Damper

Damper Size
10/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6/8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space , no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
3rd floor evidence

Inspector Name
James Futrell

Damper I.D. #
FD-78

Damper Type
Vertical Fire Damper

Damper Size
40/16

Damper Manufacturer
Ruskin

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
3rd floor evidence

Inspector Name
James Futrell

Damper I.D. #
FSD-79

Damper Type
Vertical Fire / Smoke Damper

Damper Size
48/16

Damper Manufacturer
Ruskin

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Fail

Comments / Corrections
No retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
3rd floor evidence drying room

Inspector Name
James Futrell

Damper I.D. #
FD-80

Damper Type
Vertical Fire Damper

Damper Size
48/18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
3rd floor evidence lobby

Inspector Name
James Futrell

Damper I.D. #
FSD-81

Damper Type
Vertical Fire / Smoke Damper

Damper Size
96/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
3rd floor evidence lobby

Inspector Name
James Futrell

Damper I.D. #
FD-82

Damper Type
Vertical Fire Damper

Damper Size
22/12

Damper Manufacturer
Ruskin

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
3rd floor chemistry hallway

Inspector Name
James Futrell

Damper I.D. #
FD-83

Damper Type
Vertical Fire Damper

Damper Size
48/18

Damper Manufacturer
Ruskin

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
1st floor room 123

Inspector Name
James Futrell

Damper I.D. #
FD-84

Damper Type
Vertical Fire Damper

Damper Size
12-inch round

Damper Manufacturer
Ruskin

Damper Model #
Unknown

Fusible Link Temperature
212 Degrees

Access Door Size
12/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Install access door

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-06

Facility Location
County Examiner Bldg.

Damper Location
1st floor women bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-85

Damper Type
Vertical Fire Damper

Damper Size
36/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No sleeve, no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-12

Facility Location
County Examiner Bldg.

Damper Location
1st floor women bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-86

Damper Type
Vertical Fire Damper

Damper Size
36/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space, no retaining frame, no sleeve

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-12

Facility Location
County Examiner Bldg.

Damper Location
1st floor women bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-87

Damper Type
Vertical Fire Damper

Damper Size
10/6

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6/6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-12

Facility Location
County Examiner Bldg.

Damper Location
1st floor conference room hallway

Inspector Name
James Futrell

Damper I.D. #
FD-88

Damper Type
Vertical Fire Damper

Damper Size
46/10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-12

Facility Location
County Examiner Bldg.

Damper Location
1st floor men's bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-89

Damper Type
Vertical Fire Damper

Damper Size
10/6

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-12

Facility Location
County Examiner Bldg.

Damper Location
2nd fl 202 info services

Inspector Name
James Futrell

Damper I.D. #
FD-90

Damper Type
Vertical Fire Damper

Damper Size
15 inch round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-12

Facility Location
County Examiner Bldg.

Damper Location
2nd fl info services 202

Inspector Name
James Futrell

Damper I.D. #
FD-91

Damper Type
Vertical Fire Damper

Damper Size
12 inch round

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Abandoned

Comments / Corrections
Found closed left as is, marked as abandoned

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-12

Facility Location
County Examiner Bldg.

Damper Location
2nd fl data center build room

Inspector Name
James Futrell

Damper I.D. #
FD-92

Damper Type
Vertical Fire Damper

Damper Size
70/16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Duct has two curtains in it

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-12

Facility Location
County Examiner Bldg.

Damper Location
2nd fl data center build room

Inspector Name
James Futrell

Damper I.D. #
FD-93

Damper Type
Vertical Fire Damper

Damper Size
96/18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
40/18

Pass / Fail / Abandoned
Pass

Comments / Corrections
Remove abandoned volume damper, install access door.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-12

Facility Location
County Examiner Bldg.

Damper Location
2nd fl 201M

Inspector Name
James Futrell

Damper I.D. #
FD-94

Damper Type
Vertical Fire Damper

Damper Size
20/10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-13

Facility Location
County Examiner Bldg.

Damper Location
Ground floor women bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-95

Damper Type
Vertical Fire Damper

Damper Size
12/10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space, no retaining frame, no sleeve

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-13

Facility Location
County Examiner Bldg.

Damper Location
Ground floor women bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-96

Damper Type
Vertical Fire Damper

Damper Size
10/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space, no retaining frame, no sleeve

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-13

Facility Location
County Examiner Bldg.

Damper Location
Ground floor women bathroom

Inspector Name
James Futrell

Damper I.D. #
FD-97

Damper Type
Vertical Fire Damper

Damper Size
12/10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Fail

Comments / Corrections
No annular space, no retaining frame, no sleeve

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-13

Facility Location
County Examiner Bldg.

Damper Location
Ground floor room 022

Inspector Name
James Futrell

Damper I.D. #
FD-98

Damper Type
Vertical Fire Damper

Damper Size
24/5

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-13

Facility Location
County Examiner Bldg.

Damper Location
Ground floor mech room 025

Inspector Name
James Futrell

Damper I.D. #
FD-99

Damper Type
Vertical Fire Damper

Damper Size
76/42

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
Damper is two separate curtains

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-13

Facility Location
County Examiner Bldg.

Damper Location
Vehicle bay

Inspector Name
James Futrell

Damper I.D. #
FD-100

Damper Type
Vertical Fire Damper

Damper Size
48/24

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-13

Facility Location
County Examiner Bldg.

Damper Location
Vehicle bay

Inspector Name
James Futrell

Damper I.D. #
FD-101

Damper Type
Vertical Fire Damper

Damper Size
30/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
14/14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-13

Facility Location
County Examiner Bldg.

Damper Location
Vehicle bay

Inspector Name
James Futrell

Damper I.D. #
FD-102

Damper Type
Vertical Fire Damper

Damper Size
32/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-13

Facility Location
County Examiner Bldg.

Damper Location
Vehicle bay

Inspector Name
James Futrell

Damper I.D. #
FD-103

Damper Type
Vertical Fire Damper

Damper Size
14/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Metzenbaum Center Building

3343 Community College Avenue
Cleveland, Ohio 44115

Fire/Smoke Damper Inspection Report

Visual Inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 3, 2025

Project: Cuyahoga County
Metzenbaum Center

Inspector(s):

- Larry Coreno, Certified Technician
- Tristan May, Certified Technician

Inspection and Test Date(s):

- April 12, 2025 – April 16, 2025

Duct Fabricators, Inc. “Fire Safety Division” inspected forty-four (44) dampers as noted on the following sheets. The dampers were visually inspected and photographed in the “exterior” and “interior” positions to confirm that they have not been altered and are free of any obstructions. Preventative maintenance was performed, and any deficiencies addressed.

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Facility Location	Damper Location	Damper I.D. #	Damper Type	Damper Size	Damper Manufacturer	Damper Model #	Pass / Fail / Abandoned	Comments
Metzenbaum Center	1st Fl E Wing	E FD-3	Vertical Fire Damper	14x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-4	Vertical Fire Damper	14x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-5	Vertical Fire Damper	8x8	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-6	Vertical Fire Damper	8x8	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-7	Vertical Fire Damper	8x8	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-8	Vertical Fire Damper	8x8	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-9	Vertical Fire Damper	10x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-10	Vertical Fire Damper	10x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1ST FL E Wing	E FD-11	Vertical Fire Damper	14x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-12	Vertical Fire Damper	14x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-13	Vertical Fire Damper	14x12	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL E Wing	E FD-14	Vertical Fire Damper	16x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL D Wing	D FD-4	Vertical Fire Damper	14x12	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL D Wing	D FD-3	Vertical Fire Damper	16x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL D Wing	D FD-5	Vertical Fire Damper	14x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1ST FL D Wing	D FD-6	Vertical Fire Damper	14x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL D Wing	D FD-7	Vertical Fire Damper	10*10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st Floor D Wing	D FD-8	Vertical Fire Damper	10*10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL D Wing	D FD-9	Vertical Fire Damper	8*10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st Floor D Wing	D FD-10	Vertical Fire Damper	8*10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL D Wing	D FD-13	Vertical Fire Damper	14*10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL D Wing	D FD-14	Vertical Fire Damper	14*10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL D Wing	D FD-11	Vertical Fire Damper	10x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	1st FL D Wing	D FD-12	Vertical Fire Damper	10x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	Penthouse	AHU1-R1	Horizontal Fire Damper	36x12	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	E FD-1	Horizontal Fire Damper	36x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	Penthouse	D FD-1	Horizontal Fire Damper	36x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	Penthouse	D FD-2	Horizontal Fire Damper	36x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	Penthouse	E FD-2	Horizontal Fire Damper	36x10	Ruskin	IBD20	Pass	None
Metzenbaum Center	Penthouse	AHU2-R2	Horizontal Fire Damper	23.75x9.75	Ruskin	IBD2	Pass	None
Metzenbaum Center	Penthouse	AHU2-R3	Horizontal Fire Damper	36x12	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU2-R4	Horizontal Fire Damper	24x10	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU2-R8	Vertical Fire Damper	36x36	Unknown	Unknown	Pass	None

Metzenbaum Center	Penthouse	AHU2-R9	Vertical Fire Damper	36x36	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU2-R5	Horizontal Fire Damper	24x10	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU1-R5	Horizontal Fire Damper	10x10	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU1-R4	Horizontal Fire Damper	32x12	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU2-R3	Horizontal Fire Damper	10x10	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU1-R7	Vertical Fire Damper	36x36	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU1-R2	Horizontal Fire Damper	24x10	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU1-R6	Vertical Fire Damper	36x36	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU2-R1	Horizontal Fire Damper	24x10	Unknown	Unknown	Pass	None
Metzenbaum Center	Penthouse	AHU2-R6	Vertical Fire Damper	36x36	Unknown	Unknown	Abandoned	None
Metzenbaum Center	Penthouse	AHU2-R7	Vertical Fire Damper	36x36	Unknown	Unknown	Abandoned	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU1-R1

Damper Type
Horizontal Fire Damper

Damper Size
36x12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU1-R2

Damper Type
Horizontal Fire Damper

Damper Size
24x10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-R3

Damper Type
Horizontal Fire Damper

Damper Size
10x10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU1-R4

Damper Type
Horizontal Fire Damper

Damper Size
32x12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D.
AHU1-R5

Damper Type
Horizontal Fire Damper

Damper Size
10x10

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU1-R6

Damper Type
Vertical Fire Damper

Damper Size
36x36

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D.
AHU1-R7

Damper Type
Vertical Fire Damper

Damper Size
36x36

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-R1

Damper Type
Horizontal Fire Damper

Damper Size
24x10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-R2

Damper Type
Horizontal Fire Damper

Damper Size
23.75x9.75

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-R3

Damper Type
Horizontal Fire Damper

Damper Size
36x12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-R4

Damper Type
Horizontal Fire Damper

Damper Size
24x10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-R5

Damper Type
Horizontal Fire Damper

Damper Size
24x10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D.
AHU2-R6

Damper Type
Vertical Fire Damper

Damper Size
36x36

Damper Manufacturer
Unknown

Damper Model
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Abandoned

Comments / Corrections
Was removed during renovation of D & E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-R7

Damper Type
Vertical Fire Damper

Damper Size
36x36

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Abandoned

Comments / Corrections
Was removed during renovation of D & E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-R8

Damper Type
Vertical Fire Damper

Damper Size
36x36

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-16

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AHU2-R9

Damper Type
Vertical Fire Damper

Damper Size
36x36

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Tristan May

Damper I.D. #
D FD-1

Damper Type
Horizontal Fire Damper

Damper Size
36x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Tristan May

Damper I.D. #
D FD-2

Damper Type
Horizontal Fire Damper

Damper Size
36x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-14

Facility Location
Metzenbaum Center

Damper Location
1st FL D Wing

Inspector Name
Larry Coreno

Damper I.D.
D FD-3

Damper Type
Vertical Fire Damper

Damper Size
16x10

Damper Manufacturer
Ruskin

Damper Model
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing. Tile is to tight to access doors & it will damage ceiling tile & grid.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-14

Facility Location
Metzenbaum Center

Damper Location
1st FL D Wing

Inspector Name
Larry Coreno

Damper I.D.
D FD-4

Damper Type
Vertical Fire Damper

Damper Size
14x12

Damper Manufacturer
Ruskin

Damper Model
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing. Tile is way tight to access doors. It will damage grid & tile.

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-14

Facility Location
Metzenbaum Center

Damper Location
1st FL D Wing

Inspector Name
Larry Coreno

Damper I.D. #
D FD-5

Damper Type
Vertical Fire Damper

Damper Size
14x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-14

Facility Location
Metzenbaum Center

Damper Location
1ST FL D Wing

Inspector Name
Tristan May

Damper I.D. #
D FD-6

Damper Type
Vertical Fire Damper

Damper Size
14x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
1st FL D Wing

Inspector Name
Tristan May

Damper I.D. #
D FD-7

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
1st Floor D Wing

Inspector Name
Tristan May

Damper I.D. #
D FD-8

Damper Type
Vertical Fire Damper

Damper Size
10*10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
10*10

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
1st FL D Wing

Inspector Name
Tristan May

Damper I.D.
D FD-9

Damper Type
Vertical Fire Damper

Damper Size
8*10

Damper Manufacturer
Ruskin

Damper Model
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
1st Floor D Wing

Inspector Name
Tristan May

Damper I.D.
D FD-10

Damper Type
Vertical Fire Damper

Damper Size
8*10

Damper Manufacturer
Ruskin

Damper Model
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8*8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
1st FL D Wing

Inspector Name
Tristan May

Damper I.D. #
D FD-11

Damper Type
Vertical Fire Damper

Damper Size
10x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
1st FL D Wing

Inspector Name
Larry Coreno

Damper I.D. #
D FD-12

Damper Type
Vertical Fire Damper

Damper Size
10x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
1st FL D Wing

Inspector Name
Tristan May

Damper I.D. #
D FD-13

Damper Type
Vertical Fire Damper

Damper Size
14*10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL D Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
1ST FL D Wing

Inspector Name
Tristan May

Damper I.D.
D FD-14

Damper Type
Vertical Fire Damper

Damper Size
14*10

Damper Manufacturer
Ruskin

Damper Model
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12*12

Pass / Fail / Abandoned
Pass

Comments / Corrections
D Wing 1st FL

Exterior Picture of Damper


Interior Picture of Damper


Picture of Damper I.D. Label


Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
E FD-1

Damper Type
Horizontal Fire Damper

Damper Size
36x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-15

Facility Location
Metzenbaum Center

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
E FD-2

Damper Type
Horizontal Fire Damper

Damper Size
36x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Penthouse

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st Fl E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-3

Damper Type
Vertical Fire Damper

Damper Size
14x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-4

Damper Type
Vertical Fire Damper

Damper Size
14x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-5

Damper Type
Vertical Fire Damper

Damper Size
8x8

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-6

Damper Type
Vertical Fire Damper

Damper Size
8x8

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-7

Damper Type
Vertical Fire Damper

Damper Size
8x8

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-8

Damper Type
Vertical Fire Damper

Damper Size
8x8

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-9

Damper Type
Vertical Fire Damper

Damper Size
10x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-10

Damper Type
Vertical Fire Damper

Damper Size
10x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1ST FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-11

Damper Type
Vertical Fire Damper

Damper Size
14x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-12

Damper Type
Vertical Fire Damper

Damper Size
14x10

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Justice Center Court Towers

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D. #
E FD-13

Damper Type
Vertical Fire Damper

Damper Size
14x12

Damper Manufacturer
Ruskin

Damper Model #
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-04-12

Facility Location
Metzenbaum Center

Damper Location
1st FL E Wing

Inspector Name
Larry Coreno

Damper I.D.
E FD-14

Damper Type
Vertical Fire Damper

Damper Size
16x10

Damper Manufacturer
Ruskin

Damper Model
IBD20

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
1st FL E Wing

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Old Courthouse

1 Lakeside Ave E.
Cleveland, Ohio 44114

Fire/Smoke Damper Inspection Report

Visual Inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Old Courthouse

1 Lakeside Ave E.
Cleveland, Ohio 44114

Fire/Smoke Damper Inspection Report

Visual Inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 3, 2025

Project: Cuyahoga County
Old Courthouse

Inspector(s):

- Larry Coreno, Certified Technician

Inspection and Test Date(s):

- October 30, 2024 – November 11, 2024

Duct Fabricators, Inc. “Fire Safety Division” inspected (176) dampers as noted on the following sheets. The dampers were visually inspected and photographed in the “exterior” and “interior” positions to confirm that they have not been altered and are free of any obstructions. Preventative maintenance was performed, and any deficiencies addressed.

(174) dampers passed visual inspection
(1) damper failed due to reasons indicated on the report
(1) damper was replaced (AC3-S2) on 1/20/25 due to broken spring
Physical report has been provided

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.
Thereafter, dampers are to be visually inspected every two (2) years and functionally tested every four (4) years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I.D. #	Damper Type	Damper Size	Damper Manufacturer	Damper Model #	Fusible Link Temperature	Access Door Size	Pass / Fail / Abandoned	Comments / Corrections
2024-10-30	Old Courthouse	4FL Library	Larry Coreno	AC17-S2	Horizontal Fire Damper	23x12	Ruskin	IBD2OW	165 Degrees	10x10	Pass	None
2024-10-30	Old Courthouse	4FL Library NE	Larry Coreno	AC16-R1	Horizontal Fire Damper	19.5x13	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-10-30	Old Courthouse	4FL Library NE	Larry Coreno	AC16-R2	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-10-30	Old Courthouse	4FL Library NE	Larry Coreno	AC16-R3	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-10-30	Old Courthouse	4FL Library NE	Larry Coreno	AC16-R4	Horizontal Fire Damper	9x5	Ruskin	IBD2	165 Degrees	Remove duct	Pass	None
2024-10-30	Old Courthouse	4Fl Library NE	Larry Coreno	AC16-S1	Horizontal Fire Damper	14x7.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-10-30	Old Courthouse	4FL Library NE	Larry Coreno	AC16-S2	Horizontal Fire Damper	8.5x6	Ruskin	IBD2	165 Degrees	6x6	Pass	None
2024-10-30	Old Courthouse	4FL Library NE	Larry Coreno	AC17-S1	Horizontal Fire Damper	23x12	Ruskin	IBD2OW	165 Degrees	10x10	Pass	None
2024-10-30	Old Courthouse	4FL Library NE	Larry Coreno	AC17-S3	Horizontal Fire Damper	32x21	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-10-30	Old Courthouse	4FL Library NE	Larry Coreno	AC17-S4	Horizontal Fire Damper	15.5x12.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-10-30	Old Courthouse	4FL Library NE	Larry Coreno	AC17-S5	Horizontal Fire Damper	23.5x14.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-01	Old Courthouse	4FL Library NE	Larry Coreno	AC18-R1	Horizontal Fire Damper	17.5x13.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-01	Old Courthouse	4FL Library NE	Larry Coreno	AC18-R2	Horizontal Fire Damper	17.5x13.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-01	Old Courthouse	4FL Library NE	Larry Coreno	AC18-R3	Horizontal Fire Damper	19.5x12.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-01	Old Courthouse	4FL Library NE	Larry Coreno	AC18-R4	Horizontal Fire Damper	19.5x12.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-01	Old Courthouse	4FL Library NE	Larry Coreno	AC18-R5	Horizontal Fire Damper	19.5x12.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-01	Old Courthouse	4FL Library SE	Larry Coreno	AC18-R6	Horizontal Fire Damper	17.5x12.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-01	Old Courthouse	4FL Library NE	Larry Coreno	AC18-S1	Horizontal Fire Damper	18.5x14.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None

2024-11-01	Old Courthouse	4FL Library NE	Larry Coreno	AC18-S2	Horizontal Fire Damper	18.5x14.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-01	Old Courthouse	4FL Library NE	Larry Coreno	AC18-S3	Horizontal Fire Damper	19.5x14.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-01	Old Courthouse	4FL Library S	Larry Coreno	AC19-R1	Horizontal Fire Damper	31.5x16.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-01	Old Courthouse	4FL Library S	Larry Coreno	AC19-S1	Horizontal Fire Damper	35.5x16.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-01	Old Courthouse	4FL Library S	Larry Coreno	AC19-S2	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	16x12	Pass	None
2024-11-01	Old Courthouse	4FL Library S	Larry Coreno	AC19-S3	Horizontal Fire Damper	29.5x17.5	Ruskin	IBD2	165 Degrees	20x20	Pass	None
2024-11-01	Old Courthouse	4FL Library E	Larry Coreno	AC20-R1	Horizontal Fire Damper	11.5x11.5	Ruskin	IBD2	165 Degrees	10x10	Pass	None
2024-11-01	Old Courthouse	4FL Library E	Larry Coreno	AC20-R2	Horizontal Fire Damper	19.5x12.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-01	Old Courthouse	4FL Library E	Larry Coreno	AC20-R3	Horizontal Fire Damper	29.5x14.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-01	Old Courthouse	4FL Library E	Larry Coreno	AC20-R4	Horizontal Fire Damper	19.5x13.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-01	Old Courthouse	4FL Library E	Larry Coreno	AC20-R5	Horizontal Fire Damper	19.5x13.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-01	Old Courthouse	4FL Library E	Larry Coreno	AC20-S1	Horizontal Fire Damper	9.5x9.5	Ruskin	IBD2	165 Degrees	10x10	Pass	None
2024-11-01	Old Courthouse	4FL Library E	Larry Coreno	AC20-S2	Horizontal Fire Damper	14.5x10.5	Ruskin	IBD2	165 Degrees	10x10	Pass	None
2024-11-04	Old Courthouse	4FL Library SE	Larry Coreno	AC12-R1	Horizontal Fire Damper	25.5x12.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-04	Old Courthouse	4FL Library	Larry Coreno	AC12-R12	Horizontal Fire Damper	19x10.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-04	Old Courthouse	4FL Library South	Larry Coreno	AC12-R3	Horizontal Fire Damper	29.5x14.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-04	Old Courthouse	4FL Library South	Larry Coreno	AC12-R4	Horizontal Fire Damper	27.5x11.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-04	Old Courthouse	4FL Library South	Larry Coreno	AC12-R5	Horizontal Fire Damper	17.5x10.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-04	Old Courthouse	4FL Library SE	Larry Coreno	AC12-S1	Horizontal Fire Damper	31.5x14.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None

2024-11-04	Old Courthouse	4FL Library SE	Larry Coreno	AC12-S2	Horizontal Fire Damper	17.5x8.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-04	Old Courthouse	4FL Library SE	Larry Coreno	AC12-S3	Horizontal Fire Damper	31.5x16.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-04	Old Courthouse	4FL Library South	Larry Coreno	AC12-S4	Horizontal Fire Damper	20.5x15.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-04	Old Courthouse	4FL Library South	Larry Coreno	AC13-R1	Horizontal Fire Damper	29.5x23.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-04	Old Courthouse	4FL Library South	Larry Coreno	AC13-S1	Horizontal Fire Damper	30.5x16.5	Ruskin	IBD2	165 Degrees	20x20	Pass	None
2024-11-04	Old Courthouse	4FL Library South	Larry Coreno	AC13-S2	Horizontal Fire Damper	15.5x12.5	Ruskin	IBD2	165 Degrees	10x10	Pass	None
2024-11-04	Old Courthouse	4FL Library South	Larry Coreno	AC13-S3	Horizontal Fire Damper	29.5x24.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-04	Old Courthouse	4FL Library SW	Larry Coreno	AC20-R6	Vertical Fire Damper	11.5x6	Ruskin	IBD2	165 Degrees	10x10	Pass	None
2024-11-04	Old Courthouse	4FL Library	Larry Coreno	AC20-S3	Vertical Fire Damper	14.5x8.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-05	Old Courthouse	4FL Library SW	Larry Coreno	AC14-R1	Horizontal Fire Damper	17.5x10.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-05	Old Courthouse	4FL Library SW	Larry Coreno	AC14-R2	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-05	Old Courthouse	4FL Library North	Larry Coreno	AC14-R3	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-05	Old Courthouse	4FL Library SW	Larry Coreno	AC14-R4	Horizontal Fire Damper	19.5x11.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-05	Old Courthouse	4FL Library SW	Larry Coreno	AC14-R5	Horizontal Fire Damper	22x13	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-05	Old Courthouse	4FL Library North	Larry Coreno	AC14-R6	Horizontal Fire Damper	17.5x10.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-05	Old Courthouse	4FL Library SW	Larry Coreno	AC14-S1	Horizontal Fire Damper	21.5x10.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-05	Old Courthouse	4FL Library SW	Larry Coreno	AC14-S2	Horizontal Fire Damper	17.5x8	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-05	Old Courthouse	4FL Library North	Larry Coreno	AC14-S3	Horizontal Fire Damper	31.5x9.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-05	Old Courthouse	4FL Library NE	Larry Coreno	AC15-R1	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None

2024-11-05	Old Courthouse	4FL Library NE	Larry Coreno	AC15-R2	Horizontal Fire Damper	25.5x16.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-05	Old Courthouse	4FL Library NE	Larry Coreno	AC15-R3	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-05	Old Courthouse	4FL Library NE	Larry Coreno	AC15-R4	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-05	Old Courthouse	4FL Library NE	Larry Coreno	AC15-R5	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-05	Old Courthouse	4FL Library NE	Larry Coreno	AC15-R6	Horizontal Fire Damper	10x6	Ruskin	IBD2	165 Degrees	8x8	Pass	None
2024-11-05	Old Courthouse	4FL Library North East	Larry Coreno	AC15-S1	Horizontal Fire Damper	19.5x10.5	Ruskin	IBD2	165 Degrees	10x10	Pass	None
2024-11-05	Old Courthouse	4FL Library NE	Larry Coreno	AC15-S2	Horizontal Fire Damper	14.5x10.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-05	Old Courthouse	4FL Library NE	Larry Coreno	AC15-S3	Horizontal Fire Damper	16.5x10.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-05	Old Courthouse	4FL Library NE	Larry Coreno	AC15-S4	Horizontal Fire Damper	25.5x14.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-06	Old Courthouse	Penthouse	Larry Coreno	AC22-S1	Horizontal Fire Damper	22.5x15	Ruskin	IBD2OW	165 Degrees	10x10	Pass	Breakaway connection
2024-11-06	Old Courthouse	Penthouse	Larry Coreno	AC23-R1	Horizontal Fire Damper	27x14	Ruskin	IBD2OW	165 Degrees	14x14	Pass	Breakaway connection
2024-11-06	Old Courthouse	Penthouse	Larry Coreno	AC23-R2	Vertical Fire Damper	18x10	Ruskin	IBD2	165 Degrees	14x14	Fail	Wires going thru Annular space, rigid connection
2024-11-06	Old Courthouse	Penthouse	Larry Coreno	AC23-S1	Horizontal Fire Damper	29x13	Ruskin	IBD2OW	165 Degrees	16x16	Pass	Breakaway connection
2024-11-06	Old Courthouse	Penthouse	Larry Coreno	AC23-S2	Vertical Fire Damper	28.5x8	Ruskin	IBD2	165 Degrees	16x16	Pass	Rigid connection
2024-11-06	Old Courthouse	Penthouse	Larry Coreno	AC24-R1	Horizontal Fire Damper	29x15	Ruskin	IBD2OW	165 Degrees	16x16	Pass	Breakaway connection
2024-11-06	Old Courthouse	Penthouse	Larry Coreno	AC24-R1	Horizontal Fire Damper	23x14	Ruskin	IBD2OW	165 Degrees	12x12	Pass	Breakaway connection
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	AC4-R1	Vertical Fire Damper	28x33	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None

2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	AC5-R1	Vertical Fire Damper	36x36	Unknown	Unknown	165 Degrees	Open	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	AC9-R1	Vertical Fire Damper	22x24	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R1	Vertical Fire Damper	16x15	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R10	Vertical Fire Damper	12x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R11	Vertical Fire Damper	22x18	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R2	Vertical Fire Damper	18x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R3	Vertical Fire Damper	24x14	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R4	Vertical Fire Damper	24x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R5	Vertical Fire Damper	18x17	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R6	Vertical Fire Damper	24x15	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R7	Vertical Fire Damper	18x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R8	Vertical Fire Damper	32x24	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-08	Old Courthouse	Sub Basement North	Larry Coreno	SB-R9	Vertical Fire Damper	32x24	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None

2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	AC1-R1	Vertical Fire Damper	24x29	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement North East	Larry Coreno	AC2-R1	Vertical Fire Damper	32x38	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	AC8-R1	Vertical Fire Damper	20x24	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement North Wall	Larry Coreno	SB-R12	Vertical Fire Damper	22x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement North	Larry Coreno	SB-R13	Vertical Fire Damper	12x11	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement	Larry Coreno	SB-R14	Vertical Fire Damper	16x20	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement North East	Larry Coreno	SB-R15	Vertical Fire Damper	24x22	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement North East	Larry Coreno	SB-R16	Vertical Fire Damper	30x29.5	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement North East	Larry Coreno	SB-R17	Vertical Fire Damper	30x29	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R18	Vertical Fire Damper	16x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R19	Vertical Fire Damper	25x20	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R20	Vertical Fire Damper	24x22	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R21	Vertical Fire Damper	24x22	M&T Engineering	Unknown	195 Degrees	Screen	Pass	None

2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R22	Vertical Fire Damper	24x22	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R23	Vertical Fire Damper	24x22	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R24	Vertical Fire Damper	24x22	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R25	Vertical Fire Damper	20x20	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement	Larry Coreno	SB-R26	Vertical Fire Damper	24x11	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R27	Vertical Fire Damper	32x29	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-11	Old Courthouse	Sub Basement South	Larry Coreno	SB-R28	Vertical Fire Damper	32x29	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement West	Larry Coreno	AC6-R1	Vertical Fire Damper	22x26	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	AC7-R1	Vertical Fire Damper	34x28	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SB-R29	Vertical Fire Damper	15x13	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SB-R30	Vertical Fire Damper	24x11	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SB-R31	Vertical Fire Damper	24x16	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SB-R32	Vertical Fire Damper	24x22	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None

2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SB-R33	Vertical Fire Damper	24x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SB-R34	Vertical Fire Damper	16x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SB-R35	Vertical Fire Damper	16x25	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SB-R36	Vertical Fire Damper	25x25	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SB-R38	Vertical Fire Damper	22x14	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement West	Larry Coreno	SB-R39	Vertical Fire Damper	30x29	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement West	Larry Coreno	SB-R40	Vertical Fire Damper	30x35	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement West	Larry Coreno	SB-R41	Vertical Fire Damper	11.5x24	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement	Larry Coreno	SB-R42	Vertical Fire Damper	16x14	Ruskin	IBD2	165 Degrees	Open	Pass	None
2024-11-12	Old Courthouse	Sub Basement West	Larry Coreno	SB-R43	Vertical Fire Damper	12x12	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement West	Larry Coreno	SB-R44	Vertical Fire Damper	24x14	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement West	Larry Coreno	SB-R45	Vertical Fire Damper	30x28.5	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Sub Basement West	Larry Coreno	SB-R46	Vertical Fire Damper	20x20	Ruskin	IBD2	165 Degrees	Screen	Pass	None

2024-11-12	Old Courthouse	Sub Basement West	Larry Coreno	SB-R47	Vertical Fire Damper	16x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-12	Old Courthouse	Basement West	Larry Coreno	SB-R48	Horizontal Fire Damper	17.5x13.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-12	Old Courthouse	Sub Basement South	Larry Coreno	SN-R37	Vertical Fire Damper	22x15	M&T Engineering	Unknown	165 Degrees	Screen	Pass	None
2024-11-13	Old Courthouse	Sub Basement North	Larry Coreno	AC5-S1	Horizontal Fire Damper	23.5x14.5	Ruskin	IBD2	165 Degrees	16x16	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement North	Larry Coreno	AC5-S2	Horizontal Fire Damper	25.5x12.5	Ruskin	IBD2	165 Degrees	15x5	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement North	Larry Coreno	AC5-S3	Horizontal Fire Damper	25.5x12.5	Ruskin	IBD2	165 Degrees	24x24	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement North	Larry Coreno	AC5-S4	Horizontal Fire Damper	21.5x12.5	Ruskin	IBD2	165 Degrees	14x14	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement North	Larry Coreno	AC5-S5	Horizontal Fire Damper	19.5x12.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-13	Old Courthouse	Sub Basement North	Larry Coreno	AC5-S6	Horizontal Fire Damper	21.5x12.5	Ruskin	IBD2	165 Degrees	16x16	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement North	Larry Coreno	AC5-S7	Horizontal Fire Damper	21.5x12.5	Ruskin	IBD2	165 Degrees	16x16	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement North	Larry Coreno	AC5-S8	Horizontal Fire Damper	23.5x12.5	Ruskin	IBD2	165 Degrees	18x18	Pass	One sided angle
2024-11-13	Old Courthouse	Basement West	Larry Coreno	AC6-R1	Horizontal Fire Damper	37x15	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-13	Old Courthouse	Basement West	Larry Coreno	AC6-S2	Horizontal Fire Damper	22.5x15.5	Ruskin	IBD2	165 Degrees	12x12	Pass	Lots of pipes in the way to do physical
2024-11-13	Old Courthouse	Basement West	Larry Coreno	AC6-S3	Horizontal Fire Damper	13.5x7.5	Ruskin	IBD2	165 Degrees	8x5	Pass	None

2024-11-13	Old Courthouse	Sub Basement South West	Larry Coreno	AC7-S1	Horizontal Fire Damper	17.5x14.5	Ruskin	IBD2	165 Degrees	18x18	Pass	One side angle
2024-11-13	Old Courthouse	Sub Basement West	Larry Coreno	AC7-S2	Horizontal Fire Damper	17.5x14.5	Ruskin	IBD2	165 Degrees	16x16	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement West	Larry Coreno	AC7-S3	Horizontal Fire Damper	13.5x14.5	Ruskin	IBD2	165 Degrees	12x12	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement West	Larry Coreno	AC7-S4	Horizontal Fire Damper	15.5x14.5	Ruskin	IBD2	165 Degrees	12x12	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement West	Larry Coreno	AC7-S5	Horizontal Fire Damper	27.5x16.5	Ruskin	IBD2	165 Degrees	10x12 patch	Pass	None
2024-11-13	Old Courthouse	Sub Basement West	Larry Coreno	AC7-S6	Horizontal Fire Damper	31.5x19.5	Ruskin	IBD2	165 Degrees	18x18	Pass	One sided angle
2024-11-13	Old Courthouse	Sub Basement West Outside Wall	Larry Coreno	SB -R49	Vertical Fire Damper	27.5x21.5	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC1-OA	Vertical Fire Damper	47x15	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC1-S1	Horizontal Fire Damper	23.5x15.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC1-S2	Horizontal Fire Damper	16.5x15.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC1-S3	Horizontal Fire Damper	16.5x13.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-14	Old Courthouse	Sub Basement North East	Larry Coreno	AC2-OA	Vertical Fire Damper	35.5x35.5	Ruskin	IBD2	165 Degrees	20x20	Pass	None

2024-11-14	Old Courthouse	Sub Basement North East	Larry Coreno	AC2-S1	Horizontal Fire Damper	23.5x14.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-14	Old Courthouse	Sub Basement North East	Larry Coreno	AC2-S2	Horizontal Fire Damper	23.5x16.5	Ruskin	IBD2	165 Degrees	18x18	Pass	None
2024-11-14	Old Courthouse	Sub Basement North East	Larry Coreno	AC2-S3	Horizontal Fire Damper	15.5x12.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-14	Old Courthouse	Sub Basement North East	Larry Coreno	AC2-S4	Horizontal Fire Damper	35x19.5	Ruskin	IBD2	165 Degrees	20x20	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC3-R1	Horizontal Fire Damper	19.5x9.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC3-S1	Horizontal Fire Damper	17x18	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC3-S2	Horizontal Fire Damper	19.5x16.5	Air Balance	Unknown	165 Degrees	12x12	Fail	Broken spring
2025-20-01	Old Courthouse	Sub Basement East	Larry Coreno	AC3-S2	Horizontal Fire Damper	19.5x16.5	Ruskin	IBD2	165 Degrees	12x12	Pass	Installed new fire damper
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC8-S1	Horizontal Fire Damper	17.5x16.5	Ruskin	IBD2	165 Degrees	16x16	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC8-S2	Horizontal Fire Damper	19.5x16.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	AC8-S3	Horizontal Fire Damper	17.5x16.5	Ruskin	IBD2	165 Degrees	12x12	Pass	None
2024-11-14	Old Courthouse	Sub Basement East	Larry Coreno	SB-R50	Vertical Fire Damper	16x12	Ruskin	IBD2	165 Degrees	Open	Pass	None
2024-11-15	Old Courthouse	Sub Basement North	Larry Coreno	AC10-OA	Vertical Fire Damper	35.5x16.5	Ruskin	IBD2	165 Degrees	20x20	Pass	None

2024-11-15	Old Courthouse	Sub Basement North	Larry Coreno	AC10-R1	Horizontal Fire Damper	15.5x15.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-15	Old Courthouse	Sub Basement North	Larry Coreno	AC10-S1	Horizontal Fire Damper	27.5x15.5	Ruskin	IBD2	165 Degrees	20x20	Pass	None
2024-11-15	Old Courthouse	Sub Basement North West	Larry Coreno	AC4-OA	Vertical Fire Damper	46x24	Ruskin	IBD2	165 Degrees	18x18	Pass	Engineer for the building has OA damper in closed position
2024-11-15	Old Courthouse	Sub Basement North West	Larry Coreno	AC4-S1	Horizontal Fire Damper	15.5x10.5	Ruskin	IBD2	165 Degrees	14x14	Pass	None
2024-11-15	Old Courthouse	Sub Basement North West	Larry Coreno	AC4-S2	Horizontal Fire Damper	21.5x14.5	Ruskin	IBD2	165 Degrees	20x20	Pass	None
2024-11-15	Old Courthouse	Sub Basement North West	Larry Coreno	AC4-S3	Horizontal Fire Damper	29.5x15.5	Ruskin	IBD2	165 Degrees	20x20	Pass	None
2024-11-15	Old Courthouse	Sub Basement North West	Larry Coreno	AC4-S4	Horizontal Fire Damper	25.5x12.5	Ruskin	IBD2	165 Degrees	20x20	Pass	None
2024-11-15	Old Courthouse	Sub Basement North West	Larry Coreno	ELV-RM3-R	Vertical Fire Damper	30x14	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-15	Old Courthouse	Sub Basement North West	Larry Coreno	ELV-RM3-S	Vertical Fire Damper	18x14	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-15	Old Courthouse	Sub Basement North	Larry Coreno	ELV-RM4-R	Vertical Fire Damper	30x14	Ruskin	IBD2	165 Degrees	Screen	Pass	None
2024-11-15	Old Courthouse	Sub Basement North	Larry Coreno	ELV-RM4-S	Vertical Fire Damper	18x14	Ruskin	IBD2	165 Degrees	Screen	Pass	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC1-OA

Damper Type
Vertical Fire Damper

Damper Size
47x15

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
AC1-R1

Damper Type
Vertical Fire Damper

Damper Size
24x29

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC1-S1

Damper Type
Horizontal Fire Damper

Damper Size
23.5x15.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC1-S2

Damper Type
Horizontal Fire Damper

Damper Size
16.5x15.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC1-S3

Damper Type
Horizontal Fire Damper

Damper Size
16.5x13.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement North East

Inspector Name
Larry Coreno

Damper I.D. #
AC2-OA

Damper Type
Vertical Fire Damper

Damper Size
35.5x35.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement North East

Inspector Name
Larry Coreno

Damper I.D. #
AC2-R1

Damper Type
Vertical Fire Damper

Damper Size
32x38

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement North East

Inspector Name
Larry Coreno

Damper I.D. #
AC2-S1

Damper Type
Horizontal Fire Damper

Damper Size
23.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement North East

Inspector Name
Larry Coreno

Damper I.D. #
AC2-S2

Damper Type
Horizontal Fire Damper

Damper Size
23.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement North East

Inspector Name
Larry Coreno

Damper I.D. #
AC2-S3

Damper Type
Horizontal Fire Damper

Damper Size
15.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement North East

Inspector Name
Larry Coreno

Damper I.D. #
AC2-S4

Damper Type
Horizontal Fire Damper

Damper Size
35x19.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC3-R1

Damper Type
Horizontal Fire Damper

Damper Size
19.5x9.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC3-S1

Damper Type
Horizontal Fire Damper

Damper Size
17x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2025-01-20

Facility Location
Old Courthouse

Damper Location
Sub Basement

Inspector Name
Larry Coreno

Damper I.D. #
AC3-S2

Damper Type
Horizontal Fire Damper

Damper Size
141/4x171/4

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed new fire damper

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC3-S2

Damper Type
Horizontal Fire Damper

Damper Size
19.5x16.5

Damper Manufacturer
Air Balance

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Broken spring

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North West

Inspector Name
Larry Coreno

Damper I.D. #
AC4-OA

Damper Type
Vertical Fire Damper

Damper Size
46x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
Engineer for the building has OA damper in closed position

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC4-R1

Damper Type
Vertical Fire Damper

Damper Size
28x33

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North West

Inspector Name
Larry Coreno

Damper I.D. #
AC4-S1

Damper Type
Horizontal Fire Damper

Damper Size
15.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North West

Inspector Name
Larry Coreno

Damper I.D. #
AC4-S2

Damper Type
Horizontal Fire Damper

Damper Size
21.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North West

Inspector Name
Larry Coreno

Damper I.D. #
AC4-S3

Damper Type
Horizontal Fire Damper

Damper Size
29.5x15.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North West

Inspector Name
Larry Coreno

Damper I.D. #
AC4-S4

Damper Type
Horizontal Fire Damper

Damper Size
25.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC5-R1

Damper Type
Vertical Fire Damper

Damper Size
36x36

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC5-S1

Damper Type
Horizontal Fire Damper

Damper Size
23.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC5-S2

Damper Type
Horizontal Fire Damper

Damper Size
25.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
15x5

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC5-S3

Damper Type
Horizontal Fire Damper

Damper Size
25.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC5-S4

Damper Type
Horizontal Fire Damper

Damper Size
21.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC5-S5

Damper Type
Horizontal Fire Damper

Damper Size
19.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC5-S6

Damper Type
Horizontal Fire Damper

Damper Size
21.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC5-S7

Damper Type
Horizontal Fire Damper

Damper Size
21.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC5-S8

Damper Type
Horizontal Fire Damper

Damper Size
23.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
AC6-R1

Damper Type
Vertical Fire Damper

Damper Size
22x26

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Basement West

Inspector Name
Larry Coreno

Damper I.D. #
AC6-S1

Damper Type
Horizontal Fire Damper

Damper Size
37x15

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Basement West

Inspector Name
Larry Coreno

Damper I.D.
AC6-S2

Damper Type
Horizontal Fire Damper

Damper Size
22.5x15.5

Damper Manufacturer
Ruskin

Damper Model
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Lots of pipes in the way to do physical

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Basement West

Inspector Name
Larry Coreno

Damper I.D. #
AC6-S3

Damper Type
Horizontal Fire Damper

Damper Size
13.5x7.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
8x5

Pass / Fail / Abandoned
Fail

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
AC7-R1

Damper Type
Vertical Fire Damper

Damper Size
34x28

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement South West

Inspector Name
Larry Coreno

Damper I.D. #
AC7-S1

Damper Type
Horizontal Fire Damper

Damper Size
17.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
One side angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
AC7-S2

Damper Type
Horizontal Fire Damper

Damper Size
17.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
AC7-S3

Damper Type
Horizontal Fire Damper

Damper Size
13.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
AC7-S4

Damper Type
Horizontal Fire Damper

Damper Size
15.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
AC7-S5

Damper Type
Horizontal Fire Damper

Damper Size
27.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
10x12 patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
AC7-S6

Damper Type
Horizontal Fire Damper

Damper Size
31.5x19.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
One sided angle

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
AC8-R1

Damper Type
Vertical Fire Damper

Damper Size
20x24

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC8-S1

Damper Type
Horizontal Fire Damper

Damper Size
17.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC8-S2

Damper Type
Horizontal Fire Damper

Damper Size
19.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
AC8-S3

Damper Type
Horizontal Fire Damper

Damper Size
17.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC9-R1

Damper Type
Vertical Fire Damper

Damper Size
22x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC10-OA

Damper Type
Vertical Fire Damper

Damper Size
35.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC10-R1

Damper Type
Horizontal Fire Damper

Damper Size
15.5x15.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
AC10-S1

Damper Type
Horizontal Fire Damper

Damper Size
27.5x15.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library SE

Inspector Name
Larry Coreno

Damper I.D. #
AC12-R1

Damper Type
Horizontal Fire Damper

Damper Size
25.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library

Inspector Name
Larry Coreno

Damper I.D. #
AC12-R2

Damper Type
Horizontal Fire Damper

Damper Size
19x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library South

Inspector Name
Larry Coreno

Damper I.D. #
AC12-R3

Damper Type
Horizontal Fire Damper

Damper Size
29.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library South

Inspector Name
Larry Coreno

Damper I.D. #
AC12-R4

Damper Type
Horizontal Fire Damper

Damper Size
27.5x11.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library South

Inspector Name
Larry Coreno

Damper I.D. #
AC12-R5

Damper Type
Horizontal Fire Damper

Damper Size
17.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library SE

Inspector Name
Larry Coreno

Damper I.D. #
AC12-S1

Damper Type
Horizontal Fire Damper

Damper Size
31.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library SE

Inspector Name
Larry Coreno

Damper I.D. #
AC12-S2

Damper Type
Horizontal Fire Damper

Damper Size
17.5x8.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library SE

Inspector Name
Larry Coreno

Damper I.D. #
AC12-S3

Damper Type
Horizontal Fire Damper

Damper Size
31.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library South

Inspector Name
Larry Coreno

Damper I.D. #
AC12-S4

Damper Type
Horizontal Fire Damper

Damper Size
20.5x15.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library South

Inspector Name
Larry Coreno

Damper I.D. #
AC13-R1

Damper Type
Horizontal Fire Damper

Damper Size
29.5x23.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library South

Inspector Name
Larry Coreno

Damper I.D. #
AC13-S1

Damper Type
Horizontal Fire Damper

Damper Size
30.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library South

Inspector Name
Larry Coreno

Damper I.D. #
AC13-S2

Damper Type
Horizontal Fire Damper

Damper Size
15.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library South

Inspector Name
Larry Coreno

Damper I.D. #
AC13-S3

Damper Type
Horizontal Fire Damper

Damper Size
29.5x24.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library SW

Inspector Name
Larry Coreno

Damper I.D. #
AC14-R1

Damper Type
Horizontal Fire Damper

Damper Size
17.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library SW

Inspector Name
Larry Coreno

Damper I.D. #
AC14-R2

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library North

Inspector Name
Larry Coreno

Damper I.D. #
AC14-R3

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library SW

Inspector Name
Larry Coreno

Damper I.D. #
AC14-R4

Damper Type
Horizontal Fire Damper

Damper Size
19.5x11.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library SW

Inspector Name
Larry Coreno

Damper I.D. #
AC14-R5

Damper Type
Horizontal Fire Damper

Damper Size
22x13

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library North

Inspector Name
Larry Coreno

Damper I.D. #
AC14-R6

Damper Type
Horizontal Fire Damper

Damper Size
17.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library SW

Inspector Name
Larry Coreno

Damper I.D. #
AC14-S1

Damper Type
Horizontal Fire Damper

Damper Size
21.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library SW

Inspector Name
Larry Coreno

Damper I.D. #
AC14-S2

Damper Type
Horizontal Fire Damper

Damper Size
17.5x8

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library North

Inspector Name
Larry Coreno

Damper I.D. #
AC14-S3

Damper Type
Horizontal Fire Damper

Damper Size
31.5x9.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC15-R1

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC15-R2

Damper Type
Horizontal Fire Damper

Damper Size
25.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC15-R3

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC15-R4

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC15-R5

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC15-R6

Damper Type
Horizontal Fire Damper

Damper Size
10x6

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library North East

Inspector Name
Larry Coreno

Damper I.D. #
AC15-S1

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC15-S2

Damper Type
Horizontal Fire Damper

Damper Size
14.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC15-S3

Damper Type
Horizontal Fire Damper

Damper Size
16.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-05

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC15-S4

Damper Type
Horizontal Fire Damper

Damper Size
25.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC16-R1

Damper Type
Horizontal Fire Damper

Damper Size
19.5x13

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC16-R2

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC16-R3

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC16-R4

Damper Type
Horizontal Fire Damper

Damper Size
9x5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Remove duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4Fl Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC16-S1

Damper Type
Horizontal Fire Damper

Damper Size
14x7.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC16-S2

Damper Type
Horizontal Fire Damper

Damper Size
8.5x6

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
6x6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Virgil E Brown Center

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC17-R1

Damper Type
Horizontal Fire Damper

Damper Size
47.5x23.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC17-S1

Damper Type
Horizontal Fire Damper

Damper Size
23x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2OW

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library

Inspector Name
Larry Coreno

Damper I.D. #
AC17-S2

Damper Type
Horizontal Fire Damper

Damper Size
23x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2OW

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D.
AC17-S3

Damper Type
Horizontal Fire Damper

Damper Size
32x21

Damper Manufacturer
Ruskin

Damper Model
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC17-S4

Damper Type
Horizontal Fire Damper

Damper Size
15.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-30

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC17-S5

Damper Type
Horizontal Fire Damper

Damper Size
23.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC18-R1

Damper Type
Horizontal Fire Damper

Damper Size
17.5x13.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC18-R2

Damper Type
Horizontal Fire Damper

Damper Size
17.5x13.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC18-R3

Damper Type
Horizontal Fire Damper

Damper Size
19.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC18-R4

Damper Type
Horizontal Fire Damper

Damper Size
19.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC18-R5

Damper Type
Horizontal Fire Damper

Damper Size
19.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library SE

Inspector Name
Larry Coreno

Damper I.D. #
AC18-R6

Damper Type
Horizontal Fire Damper

Damper Size
17.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC18-S1

Damper Type
Horizontal Fire Damper

Damper Size
18.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC18-S2

Damper Type
Horizontal Fire Damper

Damper Size
18.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library NE

Inspector Name
Larry Coreno

Damper I.D. #
AC18-S3

Damper Type
Horizontal Fire Damper

Damper Size
19.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library S

Inspector Name
Larry Coreno

Damper I.D. #
AC19-R1

Damper Type
Horizontal Fire Damper

Damper Size
31.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library S

Inspector Name
Larry Coreno

Damper I.D. #
AC19-S1

Damper Type
Horizontal Fire Damper

Damper Size
35.5x16.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library S

Inspector Name
Larry Coreno

Damper I.D. #
AC19-S2

Damper Type
Horizontal Fire Damper

Damper Size
19.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library S

Inspector Name
Larry Coreno

Damper I.D. #
AC19-S3

Damper Type
Horizontal Fire Damper

Damper Size
29.5x17.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library E

Inspector Name
Larry Coreno

Damper I.D. #
AC20-R1

Damper Type
Horizontal Fire Damper

Damper Size
11.5x11.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library E

Inspector Name
Larry Coreno

Damper I.D. #
AC20-R2

Damper Type
Horizontal Fire Damper

Damper Size
19.5x12.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library E

Inspector Name
Larry Coreno

Damper I.D. #
AC20-R3

Damper Type
Horizontal Fire Damper

Damper Size
29.5x14.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library E

Inspector Name
Larry Coreno

Damper I.D. #
AC20-R4

Damper Type
Horizontal Fire Damper

Damper Size
19.5x13.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library E

Inspector Name
Larry Coreno

Damper I.D. #
AC20-R5

Damper Type
Horizontal Fire Damper

Damper Size
19.5x13.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library SW

Inspector Name
Larry Coreno

Damper I.D. #
AC20-R6

Damper Type
Vertical Fire Damper

Damper Size
11.5x6

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library E

Inspector Name
Larry Coreno

Damper I.D. #
AC20-S1

Damper Type
Horizontal Fire Damper

Damper Size
9.5x9.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-01

Facility Location
Old Courthouse

Damper Location
4FL Library E

Inspector Name
Larry Coreno

Damper I.D. #
AC20-S2

Damper Type
Horizontal Fire Damper

Damper Size
14.5x10.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-04

Facility Location
Old Courthouse

Damper Location
4FL Library

Inspector Name
Larry Coreno

Damper I.D. #
AC20-S3

Damper Type
Vertical Fire Damper

Damper Size
14.5x8.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-06

Facility Location
Old Courthouse

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AC22-S1

Damper Type
Horizontal Fire Damper

Damper Size
22.5x15

Damper Manufacturer
Ruskin

Damper Model #
IBD2OW

Fusible Link Temperature
165 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Breakaway connection

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-06

Facility Location
Old Courthouse

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AC23-R1

Damper Type
Horizontal Fire Damper

Damper Size
27x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2OW

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
Breakaway connection

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-06

Facility Location
Old Courthouse

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D.
AC23-R2

Damper Type
Vertical Fire Damper

Damper Size
18x10

Damper Manufacturer
Ruskin

Damper Model
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wires going thru Annular space, rigid connection

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-06

Facility Location
Old Courthouse

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AC23-S1

Damper Type
Horizontal Fire Damper

Damper Size
29x13

Damper Manufacturer
Ruskin

Damper Model #
IBD2OW

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
Breakaway connection

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-06

Facility Location
Old Courthouse

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AC23-S2

Damper Type
Vertical Fire Damper

Damper Size
28.5x8

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
Rigid connection

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-06

Facility Location
Old Courthouse

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AC24-R1

Damper Type
Horizontal Fire Damper

Damper Size
29x15

Damper Manufacturer
Ruskin

Damper Model #
IBD2OW

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
Breakaway connection

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-06

Facility Location
Old Courthouse

Damper Location
Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
AC24-S1

Damper Type
Horizontal Fire Damper

Damper Size
23x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2OW

Fusible Link Temperature
165 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Breakaway connection

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S1

Damper Type
Vertical Fire Damper

Damper Size
12" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North West

Inspector Name
Larry Coreno

Damper I.D. #
ELV-RM3-R

Damper Type
Vertical Fire Damper

Damper Size
30x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North West

Inspector Name
Larry Coreno

Damper I.D. #
ELV-RM3-S

Damper Type
Vertical Fire Damper

Damper Size
18x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
ELV-RM4-R

Damper Type
Vertical Fire Damper

Damper Size
30x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-15

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
ELV-RM4-S

Damper Type
Vertical Fire Damper

Damper Size
18x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R1

Damper Type
Vertical Fire Damper

Damper Size
16x15

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R2

Damper Type
Vertical Fire Damper

Damper Size
18x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R3

Damper Type
Vertical Fire Damper

Damper Size
24x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R4

Damper Type
Vertical Fire Damper

Damper Size
24x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R5

Damper Type
Vertical Fire Damper

Damper Size
18x17

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R6

Damper Type
Vertical Fire Damper

Damper Size
24x15

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R7

Damper Type
Vertical Fire Damper

Damper Size
18x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R8

Damper Type
Vertical Fire Damper

Damper Size
32x24

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R9

Damper Type
Vertical Fire Damper

Damper Size
32x24

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R10

Damper Type
Vertical Fire Damper

Damper Size
12x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-08

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R11

Damper Type
Vertical Fire Damper

Damper Size
22x18

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement North Wall

Inspector Name
Larry Coreno

Damper I.D. #
SB-R12

Damper Type
Vertical Fire Damper

Damper Size
22x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement North

Inspector Name
Larry Coreno

Damper I.D. #
SB-R13

Damper Type
Vertical Fire Damper

Damper Size
12x11

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement

Inspector Name
Larry Coreno

Damper I.D. #
SB-R14

Damper Type
Vertical Fire Damper

Damper Size
16x20

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement North East

Inspector Name
Larry Coreno

Damper I.D. #
SB-R15

Damper Type
Vertical Fire Damper

Damper Size
24x22

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement North East

Inspector Name
Larry Coreno

Damper I.D. #
SB-R16

Damper Type
Vertical Fire Damper

Damper Size
30x29.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement North East

Inspector Name
Larry Coreno

Damper I.D. #
SB-R17

Damper Type
Vertical Fire Damper

Damper Size
30x29

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R18

Damper Type
Vertical Fire Damper

Damper Size
16x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R19

Damper Type
Vertical Fire Damper

Damper Size
25x20

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R20

Damper Type
Vertical Fire Damper

Damper Size
24x22

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R21

Damper Type
Vertical Fire Damper

Damper Size
24x22

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
195 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R22

Damper Type
Vertical Fire Damper

Damper Size
24x22

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R23

Damper Type
Vertical Fire Damper

Damper Size
24x22

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R24

Damper Type
Vertical Fire Damper

Damper Size
24x22

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R25

Damper Type
Vertical Fire Damper

Damper Size
20x20

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement

Inspector Name
Larry Coreno

Damper I.D. #
SB-R26

Damper Type
Vertical Fire Damper

Damper Size
24x11

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R27

Damper Type
Vertical Fire Damper

Damper Size
32x29

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-11

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R28

Damper Type
Vertical Fire Damper

Damper Size
32x29

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R29

Damper Type
Vertical Fire Damper

Damper Size
15x13

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R30

Damper Type
Vertical Fire Damper

Damper Size
24x11

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R31

Damper Type
Vertical Fire Damper

Damper Size
24x16

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Fail

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R32

Damper Type
Vertical Fire Damper

Damper Size
24x22

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R33

Damper Type
Vertical Fire Damper

Damper Size
24x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R34

Damper Type
Vertical Fire Damper

Damper Size
16x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R35

Damper Type
Vertical Fire Damper

Damper Size
16x25

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R36

Damper Type
Vertical Fire Damper

Damper Size
25x25

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R37

Damper Type
Vertical Fire Damper

Damper Size
22x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement South

Inspector Name
Larry Coreno

Damper I.D. #
SB-R38

Damper Type
Vertical Fire Damper

Damper Size
22x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
SB-R39

Damper Type
Vertical Fire Damper

Damper Size
30x29

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
SB-R40

Damper Type
Vertical Fire Damper

Damper Size
30x35

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
SB-R41

Damper Type
Vertical Fire Damper

Damper Size
11.5x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement

Inspector Name
Larry Coreno

Damper I.D. #
SB-R42

Damper Type
Vertical Fire Damper

Damper Size
16x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
SB-R43

Damper Type
Vertical Fire Damper

Damper Size
12x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
SB-R44

Damper Type
Vertical Fire Damper

Damper Size
24x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
SB-R45

Damper Type
Vertical Fire Damper

Damper Size
30x28.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
SB-R46

Damper Type
Vertical Fire Damper

Damper Size
20x20

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Sub Basement West

Inspector Name
Larry Coreno

Damper I.D. #
SB-R47

Damper Type
Vertical Fire Damper

Damper Size
16x15

Damper Manufacturer
M&T Engineering

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-12

Facility Location
Old Courthouse

Damper Location
Basement West

Inspector Name
Larry Coreno

Damper I.D. #
SB-R48

Damper Type
Horizontal Fire Damper

Damper Size
17.5x13.5

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-13

Facility Location
Old Courthouse

Damper Location
Sub Basement West Outside Wall

Inspector Name
Larry Coreno

Damper I.D.
SB-R49

Damper Type
Vertical Fire Damper

Damper Size
27.5x21.5

Damper Manufacturer
Ruskin

Damper Model
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-11-14

Facility Location
Old Courthouse

Damper Location
Sub Basement East

Inspector Name
Larry Coreno

Damper I.D. #
SB-R50

Damper Type
Vertical Fire Damper

Damper Size
16x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Cuyahoga County
Virgil E Brown

641 Payne Ave
Cleveland, Ohio 44114

Visual Fire Damper Inspection Report
November 12, 2024

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: November 12, 2024

Project: Virgil E Brown

Inspector(s): Larry Coreno, Certified Technician

Inspection and Test Date(s):

- September 30, 2024 – October 23, 2024

Duct Fabricators, Inc. “Fire Safety Division” Visually inspected Two hundred and fifty-nine fire dampers for proper installation. The dampers were then visually inspected and photographed exteriorly and interiorly to confirm that the dampers are in proper working condition.

All 259 dampers have passed inspection

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers are to be visually inspected every two years and functionally tested every four years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
1	2024-10-16	Virgil E Brown Center	1FL North Mechanical Rm	Larry Coreno	AHU1.1-OA	Vertical Fire Damper	96x24	Ruskin	IBD2	212 Degrees	16x16	Pass	None
2	2024-10-16	Virgil E Brown Center	1FL North Mechanical Rm	Larry Coreno	AHU1.1-RA	Vertical Fire Damper	96x60	Ruskin	IBD2	212 Degrees	Open	Pass	None
3	2024-10-16	Virgil E Brown Center	1FL North East Corridor	Larry Coreno	AHU1.1-S01	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
4	2024-10-16	Virgil E Brown Center	1FL North East Corridor	Larry Coreno	AHU1.1-S02	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
5	2024-10-17	Virgil E Brown Center	1FL North IT Rm	Larry Coreno	AHU1.1-S03	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
6	2024-10-17	Virgil E Brown Center	1FL North East Corridor	Larry Coreno	AHU1.1-S04	Vertical Fire Damper	12x9	Ruskin	IBD2	212 Degrees	18x18	Pass	None
7	2024-10-17	Virgil E Brown Center	1FL North East Corridor	Larry Coreno	AHU1.1-S05	Vertical Fire Damper	11x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
8	2024-10-17	Virgil E Brown Center	1FL North East Corridor	Larry Coreno	AHU1.1-S06	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
9	2024-10-17	Virgil E Brown Center	1FL North West Corridor	Larry Coreno	AHU1.1-S07	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
10	2024-10-17	Virgil E Brown Center	1FL North West Corridor	Larry Coreno	AHU1.1-S08	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
11	2024-10-17	Virgil E Brown Center	1FL North West Corridor	Larry Coreno	AHU1.1-S09	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
12	2024-10-17	Virgil E Brown Center	1FL North West IT Rm	Larry Coreno	AHU1.1-S10	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
13	2024-10-17	Virgil E Brown Center	1FL North West Corridor	Larry Coreno	AHU1.1-S11	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
14	2024-10-16	Virgil E Brown Center	1FL South Mechanical Rm	Larry Coreno	AHU1.2-OA	Vertical Fire Damper	96x24	Ruskin	IBD2	212 Degrees	16x16	Pass	None
15	2024-10-16	Virgil E Brown Center	1FL South Mechanical Rm	Larry Coreno	AHU1.2-RA	Vertical Fire Damper	96x60	Ruskin	IBD2	212 Degrees	Open	Pass	None
16	2024-10-15	Virgil E Brown Center	1FL South West Rm 180	Larry Coreno	AHU1.2-S01	Vertical Fire Damper	36x18	Ruskin	IBD20W	212 Degrees	12x12	Pass	None
17	2024-10-15	Virgil E Brown Center	1FL South West Rm 180	Larry Coreno	AHU1.2-S02	Vertical Fire Damper	36x8	Ruskin	IBD20W	212 Degrees	12x12	Pass	None
18	2024-10-15	Virgil E Brown Center	1FL South West Corridor	Larry Coreno	AHU1.2-S03	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
19	2024-10-15	Virgil E Brown Center	1FL South West Corridor	Larry Coreno	AHU1.2-S04	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
20	2024-10-15	Virgil E Brown Center	1FL South IT Rm	Larry Coreno	AHU1.2-S05	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
21	2024-10-15	Virgil E Brown Center	1FL South West Corridor	Larry Coreno	AHU1.2-S06	Vertical Fire Damper	17x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
22	2024-10-15	Virgil E Brown Center	1FL South West Corridor	Larry Coreno	AHU1.2-S07	Vertical Fire Damper	17x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
23	2024-10-15	Virgil E Brown Center	1FL South West Corridor	Larry Coreno	AHU1.2-S08	Vertical Fire Damper	14x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
24	2024-10-15	Virgil E Brown Center	1FL South West Corridor	Larry Coreno	AHU1.2-S09	Vertical Fire Damper	17x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
25	2024-10-15	Virgil E Brown Center	1FL South West Corridor	Larry Coreno	AHU1.2-S10	Vertical Fire Damper	16x10	Ruskin	IBD2	212 Degrees	18x18	Pass	None
26	2024-10-15	Virgil E Brown Center	2FL South West Corridor	Larry Coreno	AHU1.2-S11	Vertical Fire Damper	36x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
27	2024-10-15	Virgil E Brown Center	1FL South Over Entrance Doors	Larry Coreno	AHU1.2-S12	Vertical Fire Damper	42x16	Ruskin	IBD2	212 Degrees	Grille	Pass	None
28	2024-10-15	Virgil E Brown Center	1FL South Over Entrance Doors	Larry Coreno	AHU1.2-S13	Vertical Fire Damper	42x16	Ruskin	IBD2	212 Degrees	Grille	Pass	None
29	2024-10-16	Virgil E Brown Center	1FL South East Corridor	Larry Coreno	AHU1.2-S14	Vertical Fire Damper	36x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
30	2024-10-16	Virgil E Brown Center	1FL South East Corridor	Larry Coreno	AHU1.2-S15	Vertical Fire Damper	28x10	Ruskin	IBD2	212 Degrees	20x20	Pass	None
31	2024-10-16	Virgil E Brown Center	1FL South East Rm170	Larry Coreno	AHU1.2-S16	Vertical Fire Damper	32x12	Ruskin	IBD2	212 Degrees	12x12	Pass	None
32	2024-10-16	Virgil E Brown Center	1FL South East Rm 170	Larry Coreno	AHU1.2-S17	Vertical Fire Damper	18x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
33	2024-10-16	Virgil E Brown Center	1FL South East Corridor	Larry Coreno	AHU1.2-S18	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
34	2024-10-16	Virgil E Brown Center	1FL South East IT Rm	Larry Coreno	AHU1.2-S19	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
35	2024-10-15	Virgil E Brown Center	1FL South East Corridor	Larry Coreno	AHU1.2-S20	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
36	2024-10-15	Virgil E Brown Center	1FL South East Corridor	Larry Coreno	AHU1.2-S21	Vertical Fire Damper	8" Round	Ruskin	IBD2	212 Degrees	8x6	Pass	None
37	2024-10-10	Virgil E Brown Center	2FL North Mechanical Rm	Larry Coreno	AHU2.1-OA	Vertical Fire Damper	96x24	Ruskin	IBD2	212 Degrees	16x16	Pass	None
38	2024-10-10	Virgil E Brown Center	2FL North Mechanical Rm	Larry Coreno	AHU2.1-RA	Vertical Fire Damper	96x60	Ruskin	IBD2	212 Degrees	Open	Pass	None
39	2024-10-10	Virgil E Brown Center	2FL North East Corridor	Larry Coreno	AHU2.1-S01	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
40	2024-10-10	Virgil E Brown Center	2FL North East Corridor	Larry Coreno	AHU2.1-S02	Vertical Fire Damper	14x8 Oval	Ruskin	IBD2	212 Degrees	Flex	Pass	None
41	2024-10-10	Virgil E Brown Center	2FL North East Corridor	Larry Coreno	AHU2.1-S03	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
42	2024-10-10	Virgil E Brown Center	2FL North East IT Rm	Larry Coreno	AHU2.1-S04	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
43	2024-10-10	Virgil E Brown Center	2FL North East Corridor	Larry Coreno	AHU2.1-S05	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	24x24	Pass	None
44	2024-10-10	Virgil E Brown Center	2FL North East Corridor	Larry Coreno	AHU2.1-S06	Vertical Fire Damper	20x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
45	2024-10-10	Virgil E Brown Center	2FL North East Rm 210E	Larry Coreno	AHU2.1-S07	Vertical Fire Damper	28x10	Ruskin	IBD2	212 Degrees	20x20	Pass	None
46	2024-10-10	Virgil E Brown Center	2FL North East Rm 2	Larry Coreno	AHU2.1-S08	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	16x16	Pass	None
47	2024-10-09	Virgil E Brown Center	2FL North Conference Rm 2A	Larry Coreno	AHU2.1-S09	Vertical Fire Damper	8" Round	Ruskin	IBD2	212 Degrees	16x16	Pass	None
48	2024-10-15	Virgil E Brown Center	2FL North Rm209	Larry Coreno	AHU2.1-S10	Vertical Fire Damper	8" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
49	2024-10-09	Virgil E Brown Center	2FL North West Rm 210W	Larry Coreno	AHU2.1-S11	Vertical Fire Damper	34x10	Ruskin	IBD2	212 Degrees	18x18	Pass	None
50	2024-10-09	Virgil E Brown Center	2FL North West Corridor	Larry Coreno	AHU2.1-S12	Vertical Fire Damper	20x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
51	2024-10-10	Virgil E Brown Center	2FL North West Corridor	Larry Coreno	AHU2.1-S13	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
52	2024-10-10	Virgil E Brown Center	2FL North West Corridor	Larry Coreno	AHU2.1-S14	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
53	2024-10-10	Virgil E Brown Center	2FL North West IT Rm	Larry Coreno	AHU2.1-S15	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
54	2024-10-10	Virgil E Brown Center	2FL North West Corridor	Larry Coreno	AHU2.1-S16	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
55	2024-10-11	Virgil E Brown Center	2FL South Mechanical Rm	Larry Coreno	AHU2.2-OA	Vertical Fire Damper	96x24	Ruskin	IBD2	212 Degrees	16x16	Pass	None
56	2024-10-11	Virgil E Brown Center	2FL South Mechanical Rm	Larry Coreno	AHU2.2-RA	Vertical Fire Damper	96x60	Ruskin	IBD2	212 Degrees	Open	Pass	None
57	2024-10-11	Virgil E Brown Center	2FL South West Rm270	Larry Coreno	AHU2.2-S01	Vertical Fire Damper	36x8	Ruskin	IBD2	212 Degrees	12x12	Pass	None
58	2024-10-11	Virgil E Brown Center	2FL South West Rm 270	Larry Coreno	AHU2.2-S02	Vertical Fire Damper	36x8	Ruskin	IBD2	212 Degrees	12x12	Pass	None
59	2024-10-11	Virgil E Brown Center	2FL South West Corridor	Larry Coreno	AHU2.2-S03	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
60	2024-10-11	Virgil E Brown Center	2FL South West Corridor	Larry Coreno	AHU2.2-S04	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
61	2024-10-11	Virgil E Brown Center	2FL South West Corridor	Larry Coreno	AHU2.2-S05	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
62	2024-10-11	Virgil E Brown Center	2FL South West Corridor	Larry Coreno	AHU2.2-S06	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
63	2024-10-11	Virgil E Brown Center	2FL South West Corridor	Larry Coreno	AHU2.2-S07	Vertical Fire Damper	16x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
64	2024-10-15	Virgil E Brown Center	2FL South West Rm 260w	Larry Coreno	AHU2.2-S08	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
65	2024-10-15	Virgil E Brown Center	2FL South West Rm 260W	Larry Coreno	AHU2.2-S09	Vertical Fire Damper	32x10	Ruskin	IBD2	212 Degrees	18x18	Pass	None
66	2024-10-11	Virgil E Brown Center	2FL South Conference Rm 2C	Larry Coreno	AHU2.2-S10	Vertical Fire Damper	12" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
67	2024-10-11	Virgil E Brown Center	2FL South Conference Rm 2B	Larry Coreno	AHU2.2-S11	Vertical Fire Damper	12" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
68	2024-10-11	Virgil E Brown Center	2FL South East Office	Larry Coreno	AHU2.2-S12	Vertical Fire Damper	34x10	Ruskin	IBD2	212 Degrees	18x18	Pass	None
69	2024-10-11	Virgil E Brown Center	2FL South East Office	Larry Coreno	AHU2.2-S13	Vertical Fire Damper	6R	Ruskin	IBD2	212 Degrees	18x18	Pass	None
70	2024-10-11	Virgil E Brown Center	2FL South East Corridor	Larry Coreno	AHU2.2-S14	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
71	2024-10-11	Virgil E Brown Center	2FL South East Corridor	Larry Coreno	AHU2.2-S15	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
72	2024-10-11	Virgil E Brown Center	2FL Communication Room	Larry Coreno	AHU2.2-S16	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
73	2024-10-11	Virgil E Brown Center	2FL South East Corridor	Larry Coreno	AHU2.2-S17	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
74	2024-10-11	Virgil E Brown Center	2FL Room 240E	Larry Coreno	AHU2.2-S18	Vertical Fire Damper	18x10	Ruskin	IBD2	212 Degrees	12x12	Pass	None
75	2024-10-04	Virgil E Brown Center	3FL North Mechanical Rm	Larry Coreno	AHU3.1-OA	Vertical Fire Damper	96x24	Ruskin	IBD2	212 Degrees	16x16	Pass	None
76	2024-10-04	Virgil E Brown Center	3FL North Mechanical Rm	Larry Coreno	AHU3.1-RA	Vertical Fire Damper	96x60	Ruskin	IBD2	212 Degrees	Open	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
77	2024-10-08	Virgil E Brown Center	3FL North East Corridor	Larry Coreno	AHU3.1-S01	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
78	2024-10-08	Virgil E Brown Center	3FL North East Corridor	Larry Coreno	AHU3.1-S02	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
79	2024-10-15	Virgil E Brown Center	3FL North IT Rm	Larry Coreno	AHU3.1-S03	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
80	2024-10-15	Virgil E Brown Center	3FL North East Corridor	Larry Coreno	AHU3.1-S04	Vertical Fire Damper	8" Round	Ruskin	IBD2	212 Degrees	18X18	Pass	None
81	2024-10-08	Virgil E Brown Center	3FL North East Corridor	Larry Coreno	AHU3.1-S05	Vertical Fire Damper	40x12	Ruskin	IBD2	212 Degrees	18x18	Pass	None
82	2024-10-08	Virgil E Brown Center	3FL North East Corridor	Larry Coreno	AHU3.1-S06	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
83	2024-10-08	Virgil E Brown Center	3FL North West Corridor	Larry Coreno	AHU3.1-S07	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
84	2024-10-08	Virgil E Brown Center	3FL North West Rm 330	Larry Coreno	AHU3.1-S08	Vertical Fire Damper	20x10	Ruskin	IBD2	212 Degrees	18x18	Pass	None
85	2024-10-08	Virgil E Brown Center	3FL North West Corridor	Larry Coreno	AHU3.1-S09	Vertical Fire Damper	16" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
86	2024-10-08	Virgil E Brown Center	3FL North West Corridor	Larry Coreno	AHU3.1-S10	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
87	2024-10-08	Virgil E Brown Center	3FL North West Corridor	Larry Coreno	AHU3.1-S11	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
88	2024-10-08	Virgil E Brown Center	3FL North West IT Rm	Larry Coreno	AHU3.1-S12	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
89	2024-10-08	Virgil E Brown Center	3FL North West Corridor	Larry Coreno	AHU3.1-S13	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
90	2024-10-08	Virgil E Brown Center	3FL North West Rm 300	Larry Coreno	AHU3.1-S14	Vertical Fire Damper	20x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
91	2024-10-09	Virgil E Brown Center	3FL South East Rm 350N	Larry Coreno	AHU3.1-S16	Vertical Fire Damper	18x8	Ruskin	IBD2	212 Degrees	10x10	Pass	None
92	2024-10-04	Virgil E Brown Center	3FL South Mechanical Rm	Larry Coreno	AHU3.2-OA	Vertical Fire Damper	96x24	Ruskin	IBD2	212 Degrees	16x16	Pass	None
93	2024-10-04	Virgil E Brown Center	3FL South Mechanical Rm	Larry Coreno	AHU3.2-RA	Vertical Fire Damper	96x60	Ruskin	IBD2	212 Degrees	Open	Pass	None
94	2024-10-08	Virgil E Brown Center	3FL Rm 390	Larry Coreno	AHU3.2-S01	Vertical Fire Damper	36x8	Ruskin	IBD2	212 Degrees	12x12	Pass	None
95	2024-10-09	Virgil E Brown Center	3FL South West Rm 390	Larry Coreno	AHU3.2-S02	Vertical Fire Damper	36x8	Ruskin	IBD2	212 Degrees	12x12	Pass	None
96	2024-10-09	Virgil E Brown Center	3FL South West Corridor	Larry Coreno	AHU3.2-S03	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
97	2024-10-09	Virgil E Brown Center	3FL South West Corridor	Larry Coreno	AHU3.2-S04	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
98	2024-10-09	Virgil E Brown Center	3FL South West IT Rm	Larry Coreno	AHU3.2-S05	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
99	2024-10-09	Virgil E Brown Center	3FL South West Corridor	Larry Coreno	AHU3.2-S06	Vertical Fire Damper	14x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
100	2024-10-09	Virgil E Brown Center	3FL South West Corridor	Larry Coreno	AHU3.2-S07	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
101	2024-10-09	Virgil E Brown Center	3FL South West Corridor	Larry Coreno	AHU3.2-S08	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
102	2024-10-09	Virgil E Brown Center	3FL South East Corridor	Larry Coreno	AHU3.2-S09	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
103	2024-10-09	Virgil E Brown Center	3FL South East Corridor	Larry Coreno	AHU3.2-S10	Vertical Fire Damper	20x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
104	2024-10-09	Virgil E Brown Center	3FL South East Corridor	Larry Coreno	AHU3.2-S11	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
105	2024-10-09	Virgil E Brown Center	3FL South East Corridor	Larry Coreno	AHU3.2-S12	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
106	2024-10-09	Virgil E Brown Center	3FL South East IT Rm	Larry Coreno	AHU3.2-S13	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
107	2024-10-08	Virgil E Brown Center	3FL South East Corridor	Larry Coreno	AHU3.2-S14	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
108	2024-10-09	Virgil E Brown Center	3FL South East Corridor Rm 350S	Larry Coreno	AHU3.2-S16	Vertical Fire Damper	18x8 Oval	Ruskin	IBD2	212 Degrees	10x10	Pass	None
109	2024-10-04	Virgil E Brown Center	4FL North Mechanical Rm	Larry Coreno	AHU4.1-OA	Vertical Fire Damper	96x24	Ruskin	IBD2	212 Degrees	16x16	Pass	None
110	2024-10-04	Virgil E Brown Center	4FL North Mechanical Rm	Larry Coreno	AHU4.1-RA	Vertical Fire Damper	96x60	Ruskin	IBD2	212 Degrees	Open	Pass	None
111	2024-10-03	Virgil E Brown Center	4FL North East Corridor	Larry Coreno	AHU4.1-S01	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
112	2024-10-03	Virgil E Brown Center	4FL North East Corridor	Larry Coreno	AHU4.1-S02	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
113	2024-10-03	Virgil E Brown Center	4FL North East IT Rm	Larry Coreno	AHU4.1-S03	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
114	2024-10-03	Virgil E Brown Center	4FL North East Corridor	Larry Coreno	AHU4.1-S04	Vertical Fire Damper	5" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
115	2024-10-03	Virgil E Brown Center	4FL North East Corridor	Larry Coreno	AHU4.1-S05	Vertical Fire Damper	16" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
116	2024-10-03	Virgil E Brown Center	4FL North East Corridor	Larry Coreno	AHU4.1-S06	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
117	2024-10-02	Virgil E Brown Center	4FL North West Corridor	Larry Coreno	AHU4.1-S07	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
118	2024-10-03	Virgil E Brown Center	4FL North West Corridor	Larry Coreno	AHU4.1-S08	Vertical Fire Damper	11x8 Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
119	2024-10-03	Virgil E Brown Center	4FL North West Corridor	Larry Coreno	AHU4.1-S09	Vertical Fire Damper	16" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
120	2024-10-03	Virgil E Brown Center	4FL North West Corridor	Larry Coreno	AHU4.1-S10	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
121	2024-10-03	Virgil E Brown Center	4FL South West IT Rm	Larry Coreno	AHU4.1-S11	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
122	2024-10-03	Virgil E Brown Center	4FL North West Corridor	Larry Coreno	AHU4.1-S12	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
123	2024-10-04	Virgil E Brown Center	4FL South Mechanical Rm	Larry Coreno	AHU4.2-OA	Vertical Fire Damper	96x24	Ruskin	IBD2	212 Degrees	16x16	Pass	None
124	2024-10-04	Virgil E Brown Center	4FL South Mechanical Rm	Larry Coreno	AHU4.2-RA	Vertical Fire Damper	96x60	Ruskin	IBD2	212 Degrees	Open	Pass	None
125	2024-10-04	Virgil E Brown Center	4FL South West Corridor	Larry Coreno	AHU4.2-S01	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
126	2024-10-04	Virgil E Brown Center	4FL South West Corridor	Larry Coreno	AHU4.2-S02	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
127	2024-10-04	Virgil E Brown Center	4FL South West Corridor	Larry Coreno	AHU4.2-S03	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
128	2024-10-03	Virgil E Brown Center	4FL South West Corridor	Larry Coreno	AHU4.2-S04	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
129	2024-10-03	Virgil E Brown Center	4FL North East Corridor	Larry Coreno	AHU4.2-S05	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
130	2024-10-03	Virgil E Brown Center	4FL South East Corridor	Larry Coreno	AHU4.2-S06	Vertical Fire Damper	6"Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
131	2024-10-03	Virgil E Brown Center	4FL South East Corridor	Larry Coreno	AHU4.2-S07	Vertical Fire Damper	56x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
132	2024-10-03	Virgil E Brown Center	4FL South East Corridor	Larry Coreno	AHU4.2-S08	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
133	2024-10-03	Virgil E Brown Center	4FL Center East Rm 420E	Larry Coreno	AHU4.2-S09	Vertical Fire Damper	20x9	Ruskin	IBD2	212 Degrees	14x14	Pass	None
134	2024-10-03	Virgil E Brown Center	4FL South East Corridor	Larry Coreno	AHU4.2-S10	Vertical Fire Damper	56x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
135	2024-10-04	Virgil E Brown Center	4FL South Rm 450	Larry Coreno	AHU4.2-S11	Vertical Fire Damper	36x8	Ruskin	IBD20W	212 Degrees	12x12	Pass	None
136	2024-10-04	Virgil E Brown Center	4FL South West Rm 450	Larry Coreno	AHU4.2-S12	Vertical Fire Damper	36x8	Ruskin	IBD20W	212 Degrees	12x12	Pass	None
137	2024-10-01	Virgil E Brown Center	5FL North Mechanical Rm	Larry Coreno	AHU5.1-OA	Vertical Fire Damper	96x36	Ruskin	IBD2	212 Degrees	18x18	Pass	None
138	2024-10-01	Virgil E Brown Center	5FL Mechanical Rm	Larry Coreno	AHU5.1-RA	Vertical Fire Damper	96x84	Ruskin	IBD2	212 Degrees	Open	Pass	None
139	2024-10-01	Virgil E Brown Center	5FL North East Corridor	Larry Coreno	AHU5.1-S01	Vertical Fire Damper	56x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
140	2024-10-01	Virgil E Brown Center	5FL North East Corridor	Larry Coreno	AHU5.1-S02	Vertical Fire Damper	56x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
141	2024-09-30	Virgil E Brown Center	5FL North Rm 520 Conference Rm 5B	Larry Coreno	AHU5.1-S03	Vertical Fire Damper	36x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
142	2024-09-30	Virgil E Brown Center	5FL North Rm 520 Conference Rm 5A	Larry Coreno	AHU5.1-S04	Vertical Fire Damper	36x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
143	2024-10-01	Virgil E Brown Center	5FL North West Corridor	Larry Coreno	AHU5.1-S05	Vertical Fire Damper	56x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
144	2024-10-01	Virgil E Brown Center	5FL North West Corridor	Larry Coreno	AHU5.1-S06	Vertical Fire Damper	56x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
145	2024-10-01	Virgil E Brown Center	5FL North West IT Rm	Larry Coreno	AHU5.1-S07	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
146	2024-10-01	Virgil E Brown Center	5FL North East IT Rm	Larry Coreno	AHU5.1-S08	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
147	2024-09-30	Virgil E Brown Center	5FL North West Corridor	Larry Coreno	AHU5.1-S09	Vertical Fire Damper	10" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
148	2024-09-30	Virgil E Brown Center	5FL North Rm 520 Waiting Rm	Larry Coreno	AHU5.1-S10	Vertical Fire Damper	40x10	Ruskin	IBD2	212 Degrees	16x16	Pass	None
149	2024-10-01	Virgil E Brown Center	5FL North East Corridor	Larry Coreno	AHU5.1-S11	Vertical Fire Damper	18x10	Ruskin	IBD2	212 Degrees	18x18	Pass	None
150	2024-10-01	Virgil E Brown Center	5FL North East Corridor	Larry Coreno	AHU5.1-S12	Vertical Fire Damper	10" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
151	2024-09-30	Virgil E Brown Center	5FL North East Rm 520	Larry Coreno	AHU5.1-S13	Vertical Fire Damper	34x10	Ruskin	IBD2	212 Degrees	16x16	Pass	None
152	2024-10-01	Virgil E Brown Center	5FL North Waiting Rm 520	Larry Coreno	AHU5.1-S14	Vertical Fire Damper	144x6	Ruskin	IBD2	212 Degrees	Grille	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
153	2024-10-01	Virgil E Brown Center	5FL South Mechanical Room	Larry Coreno	AHU5.2-OA	Vertical Fire Damper	96x36	Ruskin	IBD2	212 Degrees	16x16	Pass	None
154	2024-10-02	Virgil E Brown Center	5FL South Copy Rm	Larry Coreno	AHU5.2-R1	Vertical Fire Damper	24x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
155	2024-10-01	Virgil E Brown Center	5FL South Mechanical Room	Larry Coreno	AHU5.2-RA	Vertical Fire Damper	96x84	Ruskin	IBD2	212 Degrees	Open	Pass	None
156	2024-10-01	Virgil E Brown Center	5FL South East Corridor	Larry Coreno	AHU5.2-S01	Vertical Fire Damper	56x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
157	2024-10-01	Virgil E Brown Center	5FL South East Corridor	Larry Coreno	AHU5.2-S02	Vertical Fire Damper	56x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
158	2024-10-02	Virgil E Brown Center	5FL South Conference Rm 5D	Larry Coreno	AHU5.2-S03	Vertical Fire Damper	36x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
159	2024-10-02	Virgil E Brown Center	5FL South Conference Rm 5D	Larry Coreno	AHU5.2-S04	Vertical Fire Damper	36x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
160	2024-10-02	Virgil E Brown Center	5FL South West Corridor	Larry Coreno	AHU5.2-S05	Vertical Fire Damper	56x18	Ruskin	IBD2	212 Degrees	16x16	Pass	None
161	2024-10-02	Virgil E Brown Center	5FL South West Corridor	Larry Coreno	AHU5.2-S06	Vertical Fire Damper	56x18	Ruskin	IBD2	212 Degrees	18x18	Pass	None
162	2024-10-02	Virgil E Brown Center	5FL South West IT RM	Larry Coreno	AHU5.2-S07	Vertical Fire Damper	8x19	Ruskin	IBD2	212 Degrees	Open	Pass	None
163	2024-10-02	Virgil E Brown Center	5FL South East IT Rm	Larry Coreno	AHU5.2-S08	Vertical Fire Damper	8x10	Ruskin	IBD2	212 Degrees	Open	Pass	None
164	2024-10-01	Virgil E Brown Center	5FL South Copy Rm	Larry Coreno	AHU5.2-S09	Vertical Fire Damper	16" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
165	2024-10-01	Virgil E Brown Center	5FL South Copy Rm	Larry Coreno	AHU5.2-S10	Vertical Fire Damper	16" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
166	2024-10-02	Virgil E Brown Center	5FL Copy Rm Announcement Office	Larry Coreno	AHU5.2-S11	Vertical Fire Damper	8" Round	Ruskin	IBD2	212 Degrees	Flex	Pass	None
167	2024-10-02	Virgil E Brown Center	5FL South Conference Rm 570S	Larry Coreno	AHU5.2-S12	Vertical Fire Damper	44x12	Ruskin	IBD2	212 Degrees	18x18	Pass	None
168	2024-10-02	Virgil E Brown Center	5FL South Rm 570	Larry Coreno	AHU5.2-S13	Vertical Fire Damper	46x10	Ruskin	IBD2	212 Degrees	16x16	Pass	None
169	2024-10-02	Virgil E Brown Center	5FL South East Corridor	Larry Coreno	AHU5.2-S14	Vertical Fire Damper	8" Round	Ruskin	IBD2	212 Degrees	20x20	Pass	None
170	2024-10-02	Virgil E Brown Center	5FL South East Corridor	Larry Coreno	AHU5.2-S15	Vertical Fire Damper	16" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
171	2024-10-02	Virgil E Brown Center	5FL South West Corridor	Larry Coreno	AHU5.2-S16	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
172	2024-10-02	Virgil E Brown Center	5FL South West Corridor	Larry Coreno	AHU5.2-S17	Vertical Fire Damper	20x10	Ruskin	IBD2	212 Degrees	14x14	Pass	None
173	2024-10-02	Virgil E Brown Center	5FL South Rm 570S	Larry Coreno	AHU5.2-S18	Vertical Fire Damper	144x6	Ruskin	IBD2	212 Degrees	Grille	Pass	None
174	2024-10-18	Virgil E Brown Center	Ground FL Mechanical Rm	Larry Coreno	AHUG.1-OA	Vertical Fire Damper	96x20	Ruskin	IBD2	212 Degrees	18x18	Pass	None
175	2024-10-18	Virgil E Brown Center	Ground FL North Mechanical Rm	Larry Coreno	AHUG.1-RA	Vertical Fire Damper	96x48	Ruskin	IBD2	212 Degrees	Open	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
176	2024-10-21	Virgil E Brown Center	GND FL North East Corridor	Larry Coreno	AHUG.1-S01	Vertical Fire Damper	16x10	Ruskin	IBD2	212 Degrees	12x12	Pass	None
177	2024-10-21	Virgil E Brown Center	GND FL North East Corridor	Larry Coreno	AHUG.1-S02	Vertical Fire Damper	46x16	Ruskin	IBD2	212 Degrees	16x16	Pass	None
178	2024-10-18	Virgil E Brown Center	GND FL North East Corridor	Larry Coreno	AHUG.1-S03	Vertical Fire Damper	46x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
179	2024-10-18	Virgil E Brown Center	GND FL North IT Rm	Larry Coreno	AHUG.1-S04	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
180	2024-10-18	Virgil E Brown Center	GND FL Rm 88	Larry Coreno	AHUG.1-S05	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	Remove Flex	Pass	None
181	2024-10-18	Virgil E Brown Center	GND FL North East Corridor	Larry Coreno	AHUG.1-S06	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
182	2024-10-18	Virgil E Brown Center	GND FL North East Corridor	Larry Coreno	AHUG.1-S07	Vertical Fire Damper	14" Oval	Ruskin	IBD2	212 Degrees	16x16	Pass	None
183	2024-10-18	Virgil E Brown Center	GND FL North East Corridor	Larry Coreno	AHUG.1-S08	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	16x16	Pass	None
184	2024-10-18	Virgil E Brown Center	GND FL North East Corridor	Larry Coreno	AHUG.1-S09	Vertical Fire Damper	28x10	Ruskin	IBD2	212 Degrees	16x16	Pass	None
185	2024-10-18	Virgil E Brown Center	GND FL North West Corridor	Larry Coreno	AHUG.1-S10	Vertical Fire Damper	10" Oval	Ruskin	IBD2	212 Degrees	16x16	Pass	None
186	2024-10-18	Virgil E Brown Center	GND FL North West Corridor	Larry Coreno	AHUG.1-S11	Vertical Fire Damper	5" Round	Ruskin	IBD2	212 Degrees	16x16	Pass	None
187	2024-10-18	Virgil E Brown Center	GND FL North Genetic Testing	Larry Coreno	AHUG.1-S12	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	Flex	Pass	None
188	2024-10-21	Virgil E Brown Center	GND FL North West Corridor	Larry Coreno	AHUG.1-S13	Vertical Fire Damper	46x16	Ruskin	IBD2	212 Degrees	16x16	Pass	None
189	2024-10-21	Virgil E Brown Center	GND FL North IT Rm	Larry Coreno	AHUG.1-S14	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
190	2024-10-21	Virgil E Brown Center	GND FL North West Corridor	Larry Coreno	AHUG.1-S15	Vertical Fire Damper	46x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
191	2024-10-21	Virgil E Brown Center	GND FL North West Rm 40	Larry Coreno	AHUG.1-S16	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	Flex	Pass	None
192	2024-10-21	Virgil E Brown Center	GND FL South Mechanical Rm	Larry Coreno	AHUG.2-OA	Vertical Fire Damper	96x20	Ruskin	IBD2	212 Degrees	16x16	Pass	None
193	2024-10-21	Virgil E Brown Center	GND FL South Mechanical Rm	Larry Coreno	AHUG.2-RA	Vertical Fire Damper	96x48	Ruskin	IBD2	212 Degrees	Open	Pass	None
194	2024-10-22	Virgil E Brown Center	GND FL South West Corridor	Larry Coreno	AHUG.2-S01	Vertical Fire Damper	12" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
195	2024-10-22	Virgil E Brown Center	GND FL South West Corridor	Larry Coreno	AHUG.2-S02	Vertical Fire Damper	46x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
196	2024-10-22	Virgil E Brown Center	GND FL South West Corridor	Larry Coreno	AHUG.2-S03	Vertical Fire Damper	46x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
197	2024-10-22	Virgil E Brown Center	GND FL South West IT Rm	Larry Coreno	AHUG.2-S04	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
198	2024-10-21	Virgil E Brown Center	GND FL South West Corridor	Larry Coreno	AHUG.2-S05	Vertical Fire Damper	36x12	Ruskin	IBD2	165 Degrees	18x18	Pass	None
199	2024-10-21	Virgil E Brown Center	GND FL South West	Larry Coreno	AHUG.2-S06	Vertical Fire Damper	14" Oval	Ruskin	IBD2	212 Degrees	16x16	Pass	None
200	2024-10-21	Virgil E Brown Center	GND FL South East Rm 77	Larry Coreno	AHUG.2-S07	Vertical Fire Damper	20x10	Ruskin	IBD2	212 Degrees	8x8	Pass	None
201	2024-10-21	Virgil E Brown Center	GND FL South East Corridor	Larry Coreno	AHUG.2-S08	Vertical Fire Damper	46x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
202	2024-10-21	Virgil E Brown Center	GND FL South IT Rm	Larry Coreno	AHUG.2-S09	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
203	2024-10-21	Virgil E Brown Center	GND FL South East Corridor	Larry Coreno	AHUG.2-S10	Vertical Fire Damper	46x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
204	2024-10-21	Virgil E Brown Center	GND FL South East Corridor	Larry Coreno	AHUG.2-S11	Vertical Fire Damper	16" Oval	Ruskin	IBD2	212 Degrees	18x18	Pass	None
205	2024-10-21	Virgil E Brown Center	GND FL South East Corridor	Larry Coreno	AHUG.2-S12	Vertical Fire Damper	6" Round	Ruskin	IBD2	212 Degrees	18x18	Pass	None
206	2024-10-22	Virgil E Brown Center	Payne Ave Lobby under stairs	Larry Coreno	AHUG.3-R1	Vertical Fire Damper	54x18	Ruskin	IBD2	212 Degrees	Screen	Pass	None
207	2024-10-22	Virgil E Brown Center	GND FL South Mechanical Rm AHU3	Larry Coreno	AHUG.3-R2	Horizontal Fire Damper	18x16	Ruskin	IBD2	212 Degrees	12x12	Pass	None
208	2024-10-22	Virgil E Brown Center	GND FL South Mechanical Rm AHU 3	Larry Coreno	AHUG.3-S1	Vertical Fire Damper	16x12	Ruskin	IBD2	212 Degrees	14x14	Pass	None
209	2024-10-22	Virgil E Brown Center	GND South Mechanical Rm AHU 3	Larry Coreno	AHUG.3-S2	Vertical Fire Damper	16x12	Ruskin	IBD2	212 Degrees	14x14	Pass	None
210	2024-10-22	Virgil E Brown Center	GND FL South Mechanical Rm AHU 3	Larry Coreno	AHUG.3-S3	Vertical Fire Damper	26x8	Ruskin	IBD2	212 Degrees	14x14	Pass	None
211	2024-10-22	Virgil E Brown Center	GND FL South Mechanical Rm AHU 3	Larry Coreno	AHUG.3-S4	Vertical Fire Damper	14x10	Ruskin	IBD2	212 Degrees	12x12	Pass	None
212	2024-10-23	Virgil E Brown Center	Lower Level North Mechanical Rm	Larry Coreno	AHULL.1-OA	Vertical Fire Damper	96x18	Ruskin	IBD2	212 Degrees	16x16	Pass	None
213	2024-10-23	Virgil E Brown Center	Lower Level North Mechanical Rm	Larry Coreno	AHULL.1-RA	Vertical Fire Damper	96x32	Ruskin	IBD2	212 Degrees	Open	Pass	None
214	2024-10-23	Virgil E Brown Center	Lower Level North West IT Rm	Larry Coreno	AHULL.1-S1	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
215	2024-10-23	Virgil E Brown Center	Lower Level North East IT Rm	Larry Coreno	AHULL.1-S2	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
216	2024-10-22	Virgil E Brown Center	Lower Level South Mechanical Rm	Larry Coreno	AHULL.2-OA	Vertical Fire Damper	96x18	Ruskin	IBD2	212 Degrees	16x16	Pass	None
217	2024-10-22	Virgil E Brown Center	Lower Level South Mechanical Rm	Larry Coreno	AHULL.2-RA	Vertical Fire Damper	96x32	Ruskin	IBD2	350 Degrees	Open	Pass	None
218	2024-10-22	Virgil E Brown Center	Lower Level South West IT Rm	Larry Coreno	AHULL.2-S1	Vertical Fire Damper	24x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
219	2024-10-22	Virgil E Brown Center	Lower Level South West Rm 7	Larry Coreno	AHULL.2-S2	Vertical Fire Damper	18x12	Ruskin	IBD2	212 Degrees	12x12	Pass	None
220	2024-10-22	Virgil E Brown Center	Lower Level South Lounge	Larry Coreno	AHULL.2-S3	Vertical Fire Damper	22x10	Ruskin	IBD2	212 Degrees	18x18	Pass	None
221	2024-10-22	Virgil E Brown Center	Lower Level South East Document Dept	Larry Coreno	AHULL.2-S4	Vertical Fire Damper	10" Round	Ruskin	IBD2	212 Degrees	8x6	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
222	2024-10-22	Virgil E Brown Center	Lower Level South Document Dept	Larry Coreno	AHULL.2-S5	Vertical Fire Damper	28x12	Ruskin	IBD2	212 Degrees	12x12	Pass	None
223	2024-10-22	Virgil E Brown Center	Lower Level South East IT Rm	Larry Coreno	AHULL.2-S6	Vertical Fire Damper	8x12	Ruskin	IBD2	212 Degrees	Open	Pass	None
224	2024-10-23	Virgil E Brown Center	Lower Level East Office	Larry Coreno	AHULL.2-S7	Vertical Fire Damper	8x8	Ruskin	IBD2	212 Degrees	6x6	Pass	None
225													
226	2024-10-18	Virgil E Brown Center	Loading Dock	Larry Coreno	Dock EA-1	Horizontal Fire Damper	30x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
227	2024-10-18	Virgil E Brown Center	Loading Dock	Larry Coreno	Dock EA-2	Horizontal Fire Damper	30x12	Ruskin	IBD2	212 Degrees	24x24	Pass	None
228	2024-10-18	Virgil E Brown Center	Loading Dock	Larry Coreno	Dock EA-3	Horizontal Fire Damper	47.25x11.25	Ruskin	IBD23	212 Degrees	24x24	Pass	None
229	2024-10-17	Virgil E Brown Center	South Penthouse	Larry Coreno	EF07-PH	Horizontal Fire Damper	48x18	Ruskin	IBD2	212 Degrees	24x24	Pass	None
230	2024-10-16	Virgil E Brown Center	1FL South Mechanical Rm	Larry Coreno	EF07-1	Horizontal Fire Damper	22x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
231	2024-10-11	Virgil E Brown Center	2FL South Mechanical Rm	Larry Coreno	EF07-2	Horizontal Fire Damper	26x18	Ruskin	IBD2	212 Degrees	20x20	Pass	None
232	2024-10-08	Virgil E Brown Center	3FL South Mechanical Rm	Larry Coreno	EF07-3	Horizontal Fire Damper	36x20	Ruskin	IBD2	212 Degrees	24x24	Pass	None
233	2024-10-04	Virgil E Brown Center	4FL South Mechanical Rm	Larry Coreno	EF07-4	Horizontal Fire Damper	36x20	Ruskin	IBD2	212 Degrees	24x24	Pass	None
234	2024-10-01	Virgil E Brown Center	5FL South Mechanical Room	Larry Coreno	EF07-5	Horizontal Fire Damper	40x20	Ruskin	IBD2	212 Degrees	24x24	Pass	None
235	2024-10-21	Virgil E Brown Center	GND FL South Mechanical Rm	Larry Coreno	EF07-GND	Horizontal Fire Damper	20x14	Ruskin	IBD2	212 Degrees	18x18	Pass	None
236	2024-10-16	Virgil E Brown Center	1FL North Mechanical Rm	Larry Coreno	EF10-1	Horizontal Fire Damper	22x16	Ruskin	IBD2	212 Degrees	18x18	Pass	None
237	2024-10-10	Virgil E Brown Center	2FL North Mechanical Rm	Larry Coreno	EF10-2	Horizontal Fire Damper	26x18	Ruskin	IBD2	212 Degrees	20x20	Pass	None
238	2024-10-04	Virgil E Brown Center	3FL North Mechanical Rm	Larry Coreno	EF10-3	Horizontal Fire Damper	36x18	Ruskin	IBD2	212 Degrees	24x24	Pass	None
239	2024-10-04	Virgil E Brown Center	4FL North Mechanical Room	Larry Coreno	EF10-4	Horizontal Fire Damper	36x20	Ruskin	IBD2	212 Degrees	18x18	Pass	None
240	2024-10-01	Virgil E Brown Center	5FL Mechanical Rm	Larry Coreno	EF10-5	Horizontal Fire Damper	40x18	Ruskin	IBD2	212 Degrees	24x24	Pass	None
241	2024-10-18	Virgil E Brown Center	Ground FL Mechanical Rm	Larry Coreno	EF10-GND	Horizontal Fire Damper	14x20	Ruskin	IBD2	212 Degrees	18x18	Pass	None
242	2024-10-23	Virgil E Brown Center	Lower Level North East Fire Panel Rm	Larry Coreno	EF18-1	Vertical Fire Damper	12x12	Ruskin	IBD2	212 Degrees	8x8	Pass	None
243	2024-10-23	Virgil E Brown Center	Lower Level North East Outside Wall	Larry Coreno	EF18-2	Vertical Fire Damper	12x12	Ruskin	IBD2	212 Degrees	8x8	Pass	None
244	2024-10-23	Virgil E Brown Center	Lower Level North East Transformer Rm	Larry Coreno	EF18-3	Vertical Fire Damper	12x14	Ruskin	IBD2	212 Degrees	Grille	Pass	None

#	Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper I D	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
245	2024-10-23	Virgil E Brown Center	Lower Level North East Generator Rm	Larry Coreno	EF18-OA	Vertical Fire Damper	40x24	Ruskin	IBD2	212 Degrees	18x18	Pass	None
246	2024-10-23	Virgil E Brown Center	Lower Level North Generator Rm	Larry Coreno	EF25-1	Vertical Fire Damper	12x12	Ruskin	IBD2	212 Degrees	10x8	Pass	None
247	2024-10-23	Virgil E Brown Center	Lower Level East outside wall	Larry Coreno	LL-RA-1	Vertical Fire Damper	24x28	Ruskin	IBD2	212 Degrees	Grille	Pass	None
248	2024-10-23	Virgil E Brown Center	Lower Level North East Outside Wall	Larry Coreno	LL-RA-2	Vertical Fire Damper	48x66	Ruskin	IBD2	212 Degrees	Grille	Pass	None
249	2024-10-23	Virgil E Brown Center	Lower Level North East Outside Wall	Larry Coreno	LL-RA-3	Vertical Fire Damper	24x28	Ruskin	IBD2	212 Degrees	Grille	Pass	None
250	2024-10-23	Virgil E Brown Center	Lower Level North East Generator Rm	Larry Coreno	LL-RA-4	Vertical Fire Damper	60x84	Ruskin	IBD2	212 Degrees	Grille	Pass	None
251	2024-10-23	Virgil E Brown Center	Lower Level North East Mechanical Rm	Larry Coreno	LL-TA-1	Vertical Fire Damper	48x18	Ruskin	IBD2	212 Degrees	Screen	Pass	None
252	2024-10-23	Virgil E Brown Center	Lower Level North East Mechanical Rm	Larry Coreno	LL-TA-2	Vertical Fire Damper	12x12	Ruskin	IBD2	212 Degrees	Screen	Pass	None
253	2024-10-23	Virgil E Brown Center	Lower Level East Office	Larry Coreno	LL-TA-3	Vertical Fire Damper	12x12	Ruskin	IBD2	212 Degrees	Screen	Pass	None
254	2024-10-17	Virgil E Brown Center	North Penthouse	Larry Coreno	PH.1-OA	Vertical Fire Damper	120x48	Ruskin	IBD2	212 Degrees	24x24	Pass	None
255	2024-10-17	Virgil E Brown Center	North Penthouse	Larry Coreno	PH.1-RA	Vertical Fire Damper	108x48	Ruskin	IBD2	212 Degrees	24x24	Pass	None
256	2024-10-17	Virgil E Brown Center	South Penthouse	Larry Coreno	PH.2-OA1	Vertical Fire Damper	114x48	Ruskin	IBD2	212 Degrees	24x24	Pass	None
257	2024-10-17	Virgil E Brown Center	South Penthouse	Larry Coreno	PH.2-OA2	Vertical Fire Damper	96x48	Ruskin	IBD2	212 Degrees	24x24	Pass	None
258	2024-10-17	Virgil E Brown Center	GND FL South Penthouse	Larry Coreno	PH.2-OA3	Vertical Fire Damper	48x48	Ruskin	IBD2	212 Degrees	Grille	Pass	None
259	2024-10-17	Virgil E Brown Center	South Penthouse	Larry Coreno	PH.2-RA	Vertical Fire Damper	108x48	Ruskin	IBD2	212 Degrees	24x24	Pass	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-OA

Damper Type
Vertical Fire Damper

Damper Size
96x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-RA

Damper Type
Vertical Fire Damper

Damper Size
96x60

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S1

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S2

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
1FL North IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S3

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
1FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S4

Damper Type
Vertical Fire Damper

Damper Size
12x9

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
1FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S5

Damper Type
Vertical Fire Damper

Damper Size
11x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
1FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S6

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
1FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S7

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
1FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S8

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
1FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S9

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
1FL North West IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S10

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
1FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.1-S11

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-OA

Damper Type
Vertical Fire Damper

Damper Size
96x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-RA

Damper Type
Vertical Fire Damper

Damper Size
96x60

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South West Rm 180

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S1

Damper Type
Vertical Fire Damper

Damper Size
36x18

Damper Manufacturer
Ruskin

Damper Model #
IBD20W

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South West Rm 180

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S2

Damper Type
Vertical Fire Damper

Damper Size
36x8

Damper Manufacturer
Ruskin

Damper Model #
IBD20W

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S3

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S4

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S5

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S6

Damper Type
Vertical Fire Damper

Damper Size
17x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S7

Damper Type
Vertical Fire Damper

Damper Size
17x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S8

Damper Type
Vertical Fire Damper

Damper Size
14x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S9

Damper Type
Vertical Fire Damper

Damper Size
17x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S10

Damper Type
Vertical Fire Damper

Damper Size
16x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S11

Damper Type
Vertical Fire Damper

Damper Size
36x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South Over Entrance Doors

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S12

Damper Type
Vertical Fire Damper

Damper Size
42x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South Over Entrance Doors

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S13

Damper Type
Vertical Fire Damper

Damper Size
42x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S14

Damper Type
Vertical Fire Damper

Damper Size
36x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S15

Damper Type
Vertical Fire Damper

Damper Size
28x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL South East Rm170

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S16

Damper Type
Vertical Fire Damper

Damper Size
32x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL South East Rm 170

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S17

Damper Type
Vertical Fire Damper

Damper Size
18x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S18

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL South East IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S19

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S20

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
1FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU1.2-S21

Damper Type
Vertical Fire Damper

Damper Size
8" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
8x6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-OA

Damper Type
Vertical Fire Damper

Damper Size
96x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-RA

Damper Type
Vertical Fire Damper

Damper Size
96x60

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S1

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S2

Damper Type
Vertical Fire Damper

Damper Size
14x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Flex

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S3

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North East IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S4

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S5

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S6

Damper Type
Vertical Fire Damper

Damper Size
20x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North East Rm 210E

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S7

Damper Type
Vertical Fire Damper

Damper Size
28x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North East Rm 2

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S8

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
2FL North Conference Rm 2A

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S9

Damper Type
Vertical Fire Damper

Damper Size
8" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
2FL North Rm209

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S10

Damper Type
Vertical Fire Damper

Damper Size
8" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
2FL North West Rm 210W

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S11

Damper Type
Vertical Fire Damper

Damper Size
34x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
2FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S12

Damper Type
Vertical Fire Damper

Damper Size
20x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S13

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S14

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North West IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S15

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.1-S16

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-OA

Damper Type
Vertical Fire Damper

Damper Size
96x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-RA

Damper Type
Vertical Fire Damper

Damper Size
96x60

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Rm270

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S1

Damper Type
Vertical Fire Damper

Damper Size
36x8

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Rm 270

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S2

Damper Type
Vertical Fire Damper

Damper Size
36x8

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S3

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S4

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S5

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S6

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S7

Damper Type
Vertical Fire Damper

Damper Size
16x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Rm 260w

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S8

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
2FL South West Rm 260W

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S9

Damper Type
Vertical Fire Damper

Damper Size
32x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South Conference Rm 2C

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S10

Damper Type
Vertical Fire Damper

Damper Size
12" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South Conference Rm 2B

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S11

Damper Type
Vertical Fire Damper

Damper Size
12" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South East Office

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S12

Damper Type
Vertical Fire Damper

Damper Size
34x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South East Office

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S13

Damper Type
Vertical Fire Damper

Damper Size
6R

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S14

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S15

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL Communication Room

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S16

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S17

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL Room 240E

Inspector Name
Larry Coreno

Damper I.D. #
AHU2.2-S18

Damper Type
Vertical Fire Damper

Damper Size
18x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
3FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-OA

Damper Type
Vertical Fire Damper

Damper Size
96x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
3FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-RA

Damper Type
Vertical Fire Damper

Damper Size
96x60

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S1

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S2

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
3FL North IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S3

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-15

Facility Location
Virgil E Brown Center

Damper Location
3FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S4

Damper Type
Vertical Fire Damper

Damper Size
8" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18X18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S5

Damper Type
Vertical Fire Damper

Damper Size
40x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S6

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S7

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North West Rm 330

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S8

Damper Type
Vertical Fire Damper

Damper Size
20x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S9

Damper Type
Vertical Fire Damper

Damper Size
16" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S10

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S11

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North West IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S12

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S13

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL North West Rm 300

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S14

Damper Type
Vertical Fire Damper

Damper Size
20x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South East Rm 350N

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.1-S16

Damper Type
Vertical Fire Damper

Damper Size
18x8

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
3FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-OA

Damper Type
Vertical Fire Damper

Damper Size
96x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
3FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-RA

Damper Type
Vertical Fire Damper

Damper Size
96x60

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL Rm 390

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S1

Damper Type
Vertical Fire Damper

Damper Size
36x8

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South West Rm 390

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S2

Damper Type
Vertical Fire Damper

Damper Size
36x8

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S3

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S4

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South West IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S5

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S6

Damper Type
Vertical Fire Damper

Damper Size
14x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S7

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S8

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S9

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S10

Damper Type
Vertical Fire Damper

Damper Size
20x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S11

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S12

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South East IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S13

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S14

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-09

Facility Location
Virgil E Brown Center

Damper Location
3FL South East Corridor Rm 350S

Inspector Name
Larry Coreno

Damper I.D. #
AHU3.2-S16

Damper Type
Vertical Fire Damper

Damper Size
18x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
10x10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-OA

Damper Type
Vertical Fire Damper

Damper Size
96x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-RA

Damper Type
Vertical Fire Damper

Damper Size
96x60

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S1

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S2

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North East IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S3

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S4

Damper Type
Vertical Fire Damper

Damper Size
5" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S5

Damper Type
Vertical Fire Damper

Damper Size
16" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S6

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
4FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S7

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S8

Damper Type
Vertical Fire Damper

Damper Size
11x8 Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S9

Damper Type
Vertical Fire Damper

Damper Size
16" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S10

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL South West IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S11

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.1-S12

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-OA

Damper Type
Vertical Fire Damper

Damper Size
96x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-RA

Damper Type
Vertical Fire Damper

Damper Size
96x60

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S1

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S2

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S3

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S4

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S5

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S6

Damper Type
Vertical Fire Damper

Damper Size
6"Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S7

Damper Type
Vertical Fire Damper

Damper Size
56x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S8

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL Center East Rm 420E

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S9

Damper Type
Vertical Fire Damper

Damper Size
20x9

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-03

Facility Location
Virgil E Brown Center

Damper Location
4FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S10

Damper Type
Vertical Fire Damper

Damper Size
56x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL South Rm 450

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S11

Damper Type
Vertical Fire Damper

Damper Size
36x8

Damper Manufacturer
Ruskin

Damper Model #
IBD20W

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL South West Rm 450

Inspector Name
Larry Coreno

Damper I.D. #
AHU4.2-S12

Damper Type
Vertical Fire Damper

Damper Size
36x8

Damper Manufacturer
Ruskin

Damper Model #
IBD20W

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-OA

Damper Type
Vertical Fire Damper

Damper Size
96x36

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-RA

Damper Type
Vertical Fire Damper

Damper Size
96x84

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S1

Damper Type
Vertical Fire Damper

Damper Size
56x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S2

Damper Type
Vertical Fire Damper

Damper Size
56x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-30

Facility Location
Virgil E Brown Center

Damper Location
5FL North Rm 520 Conference Rm 5B

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S3

Damper Type
Vertical Fire Damper

Damper Size
36x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-30

Facility Location
Virgil E Brown Center

Damper Location
5FL North Rm 520 Conference Rm 5A

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S4

Damper Type
Vertical Fire Damper

Damper Size
36x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil Brown

Damper Location
5FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S5

Damper Type
Vertical Fire Damper

Damper Size
56x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S6

Damper Type
Vertical Fire Damper

Damper Size
56x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL North West IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S7

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL North East IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S8

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-30

Facility Location
Virgil E Brown Center

Damper Location
5FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S9

Damper Type
Vertical Fire Damper

Damper Size
10" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-30

Facility Location
Virgil E Brown Center

Damper Location
5FL North Rm 520 Waiting Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S10

Damper Type
Vertical Fire Damper

Damper Size
40x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S11

Damper Type
Vertical Fire Damper

Damper Size
18x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S12

Damper Type
Vertical Fire Damper

Damper Size
10" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-09-30

Facility Location
Virgil E Brown Center

Damper Location
5FL North East Rm 520

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S13

Damper Type
Vertical Fire Damper

Damper Size
34x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL North Waiting Rm 520

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.1-S14

Damper Type
Vertical Fire Damper

Damper Size
144x6

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
Not able to get to angle on backside to verify.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL South Mechanical Room

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-OA

Damper Type
Vertical Fire Damper

Damper Size
96x36

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South Copy Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-R1

Damper Type
Vertical Fire Damper

Damper Size
24x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL South Mechanical Room

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-RA

Damper Type
Vertical Fire Damper

Damper Size
96x84

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S1

Damper Type
Vertical Fire Damper

Damper Size
56x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S2

Damper Type
Vertical Fire Damper

Damper Size
56x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South Conference Rm 5D

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S3

Damper Type
Vertical Fire Damper

Damper Size
36x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South Conference Rm 5D

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S4

Damper Type
Vertical Fire Damper

Damper Size
36x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S5

Damper Type
Vertical Fire Damper

Damper Size
56x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S6

Damper Type
Vertical Fire Damper

Damper Size
56x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South West IT RM

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S7

Damper Type
Vertical Fire Damper

Damper Size
8x19

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South East IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S8

Damper Type
Vertical Fire Damper

Damper Size
8x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL South Copy Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S9

Damper Type
Vertical Fire Damper

Damper Size
16" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL South Copy Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S10

Damper Type
Vertical Fire Damper

Damper Size
16" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL Copy Rm Announcement Office

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S11

Damper Type
Vertical Fire Damper

Damper Size
8" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Flex

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



ds

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South Conference Rm 570S

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S12

Damper Type
Vertical Fire Damper

Damper Size
44x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South Rm 570

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S13

Damper Type
Vertical Fire Damper

Damper Size
46x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S14

Damper Type
Vertical Fire Damper

Damper Size
8" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S15

Damper Type
Vertical Fire Damper

Damper Size
16" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S16

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S17

Damper Type
Vertical Fire Damper

Damper Size
20x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-02

Facility Location
Virgil E Brown Center

Damper Location
5FL South Rm 570S

Inspector Name
Larry Coreno

Damper I.D. #
AHU5.2-S18

Damper Type
Vertical Fire Damper

Damper Size
144x6

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
Back of the damper has sheetmetal around it. Damper is in drywall soffit.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
Ground FL Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-OA

Damper Type
Vertical Fire Damper

Damper Size
96x20

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
Ground FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-RA

Damper Type
Vertical Fire Damper

Damper Size
96x48

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S1

Damper Type
Vertical Fire Damper

Damper Size
16x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S2

Damper Type
Vertical Fire Damper

Damper Size
46x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S3

Damper Type
Vertical Fire Damper

Damper Size
46x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL North IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S4

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL Rm 88

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S5

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Remove Flex

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S6

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S7

Damper Type
Vertical Fire Damper

Damper Size
14" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S8

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL North East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S9

Damper Type
Vertical Fire Damper

Damper Size
28x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S10

Damper Type
Vertical Fire Damper

Damper Size
10" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S11

Damper Type
Vertical Fire Damper

Damper Size
5" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
GND FL North Genetic Testing

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S12

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Flex

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S13

Damper Type
Vertical Fire Damper

Damper Size
46x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL North IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S14

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL North West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S15

Damper Type
Vertical Fire Damper

Damper Size
46x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL North West Rm 40

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.1-S16

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Flex

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-OA

Damper Type
Vertical Fire Damper

Damper Size
96x20

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-RA

Damper Type
Vertical Fire Damper

Damper Size
96x48

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S1

Damper Type
Vertical Fire Damper

Damper Size
12" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S2

Damper Type
Vertical Fire Damper

Damper Size
46x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S3

Damper Type
Vertical Fire Damper

Damper Size
46x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND FL South West IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S4

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South West Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S5

Damper Type
Vertical Fire Damper

Damper Size
36x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South West

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S6

Damper Type
Vertical Fire Damper

Damper Size
14" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South East Rm 77

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S7

Damper Type
Vertical Fire Damper

Damper Size
20x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S8

Damper Type
Vertical Fire Damper

Damper Size
46x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S9

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S10

Damper Type
Vertical Fire Damper

Damper Size
46x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S11

Damper Type
Vertical Fire Damper

Damper Size
16" Oval

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South East Corridor

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.2-S12

Damper Type
Vertical Fire Damper

Damper Size
6" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
Payne Ave Lobby under stairs

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.3-R1

Damper Type
Vertical Fire Damper

Damper Size
54x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND FL South Mechanical Rm AHU3

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.3-R2

Damper Type
Horizontal Fire Damper

Damper Size
18x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND FL South Mechanical Rm AHU 3

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.3-S1

Damper Type
Vertical Fire Damper

Damper Size
16x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND South Mechanical Rm AHU 3

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.3-S2

Damper Type
Vertical Fire Damper

Damper Size
16x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND FL South Mechanical Rm AHU 3

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.3-S3

Damper Type
Vertical Fire Damper

Damper Size
26x8

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
14x14

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
GND FL South Mechanical Rm AHU 3

Inspector Name
Larry Coreno

Damper I.D. #
AHUG.3-S4

Damper Type
Vertical Fire Damper

Damper Size
14x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.1-OA

Damper Type
Vertical Fire Damper

Damper Size
96x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.1-RA

Damper Type
Vertical Fire Damper

Damper Size
96x32

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North West IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.1-S1

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.1-S2

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
Lower Level South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.2-OA

Damper Type
Vertical Fire Damper

Damper Size
96x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
Lower Level South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.2-RA

Damper Type
Vertical Fire Damper

Damper Size
96x32

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
350 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
Lower Level South West IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.2-S1

Damper Type
Vertical Fire Damper

Damper Size
24x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
Lower Level South West Rm 7

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.2-S2

Damper Type
Vertical Fire Damper

Damper Size
18x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
Lower Level South Lounge

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.2-S3

Damper Type
Vertical Fire Damper

Damper Size
22x10

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
Lower Level South East Document Dept

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.2-S4

Damper Type
Vertical Fire Damper

Damper Size
10" Round

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
8x6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
Lower Level South Document Dept

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.2-S5

Damper Type
Vertical Fire Damper

Damper Size
28x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
12x12

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-22

Facility Location
Virgil E Brown Center

Damper Location
Lower Level South East IT Rm

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.2-S6

Damper Type
Vertical Fire Damper

Damper Size
8x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level East Office

Inspector Name
Larry Coreno

Damper I.D. #
AHULL.2-S7

Damper Type
Vertical Fire Damper

Damper Size
8x8

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
6x6

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
Loading Dock

Inspector Name
Larry Coreno

Damper I.D. #
Dock EA-1

Damper Type
Horizontal Fire Damper

Damper Size
30x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
Loading Dock

Inspector Name
Larry Coreno

Damper I.D. #
Dock EA-2

Damper Type
Horizontal Fire Damper

Damper Size
30x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
Loading Dock

Inspector Name
Larry Coreno

Damper I.D. #
Dock EA-3

Damper Type
Horizontal Fire Damper

Damper Size
47.25x11.25

Damper Manufacturer
Ruskin

Damper Model #
IBD23

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
South Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
EF7- PH

Damper Type
Horizontal Fire Damper

Damper Size
48x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF7-1

Damper Type
Horizontal Fire Damper

Damper Size
22x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-11

Facility Location
Virgil E Brown Center

Damper Location
2FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF7-2

Damper Type
Horizontal Fire Damper

Damper Size
26x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-08

Facility Location
Virgil E Brown Center

Damper Location
3FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF7-3

Damper Type
Horizontal Fire Damper

Damper Size
36x20

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF7-4

Damper Type
Horizontal Fire Damper

Damper Size
36x20

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL South Mechanical Room

Inspector Name
Larry Coreno

Damper I.D. #
EF7-5

Damper Type
Horizontal Fire Damper

Damper Size
40x20

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-21

Facility Location
Virgil E Brown Center

Damper Location
GND FL South Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF7-GND

Damper Type
Horizontal Fire Damper

Damper Size
20x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-16

Facility Location
Virgil E Brown Center

Damper Location
1FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF10-1

Damper Type
Horizontal Fire Damper

Damper Size
22x16

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-10

Facility Location
Virgil E Brown Center

Damper Location
2FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF10-2

Damper Type
Horizontal Fire Damper

Damper Size
26x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
20x20

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
3FL North Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF10-3

Damper Type
Horizontal Fire Damper

Damper Size
36x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-04

Facility Location
Virgil E Brown Center

Damper Location
4FL North Mechanical Room

Inspector Name
Larry Coreno

Damper I.D. #
EF10-4

Damper Type
Horizontal Fire Damper

Damper Size
36x20

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-01

Facility Location
Virgil E Brown Center

Damper Location
5FL Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF10-5

Damper Type
Horizontal Fire Damper

Damper Size
40x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-18

Facility Location
Virgil E Brown Center

Damper Location
Ground FL Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF10-GND

Damper Type
Horizontal Fire Damper

Damper Size
14x20

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East Fire Panel Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF18-1

Damper Type
Vertical Fire Damper

Damper Size
12x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East Outside Wall

Inspector Name
Larry Coreno

Damper I.D. #
EF18-2

Damper Type
Vertical Fire Damper

Damper Size
12x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
8x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East Transformer Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF18-3

Damper Type
Vertical Fire Damper

Damper Size
12x14

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East Generator Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF18-OA

Damper Type
Vertical Fire Damper

Damper Size
40x24

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
18x18

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North Generator Rm

Inspector Name
Larry Coreno

Damper I.D. #
EF25-1

Damper Type
Vertical Fire Damper

Damper Size
12x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
10x8

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level East outside wall

Inspector Name
Larry Coreno

Damper I.D. #
LL-RA-1

Damper Type
Vertical Fire Damper

Damper Size
24x28

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East Outside Wall

Inspector Name
Larry Coreno

Damper I.D. #
LL-RA-2

Damper Type
Vertical Fire Damper

Damper Size
48x66

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East Outside Wall

Inspector Name
Larry Coreno

Damper I.D. #
LL-RA-3

Damper Type
Vertical Fire Damper

Damper Size
24x28

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East Generator Rm

Inspector Name
Larry Coreno

Damper I.D. #
LL-RA-4

Damper Type
Vertical Fire Damper

Damper Size
60x84

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
LL-TA-1

Damper Type
Vertical Fire Damper

Damper Size
48x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level North East Mechanical Rm

Inspector Name
Larry Coreno

Damper I.D. #
LL-TA-2

Damper Type
Vertical Fire Damper

Damper Size
12x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-23

Facility Location
Virgil E Brown Center

Damper Location
Lower Level East Office

Inspector Name
Larry Coreno

Damper I.D. #
LL-TA-3

Damper Type
Vertical Fire Damper

Damper Size
12x12

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Screen

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
North Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
PH.1-OA

Damper Type
Vertical Fire Damper

Damper Size
120x48

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
North Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
PH.1-RA

Damper Type
Vertical Fire Damper

Damper Size
108x48

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
South Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
PH.2-OA1

Damper Type
Vertical Fire Damper

Damper Size
114x48

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
South Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
PH.2-OA2

Damper Type
Vertical Fire Damper

Damper Size
96x48

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
GND FL South Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
PH.2-OA3

Damper Type
Vertical Fire Damper

Damper Size
48x48

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
Grille

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-10-17

Facility Location
Virgil E Brown Center

Damper Location
South Penthouse

Inspector Name
Larry Coreno

Damper I.D. #
PH.2-RA

Damper Type
Vertical Fire Damper

Damper Size
108x48

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
212 Degrees

Access Door Size
24x24

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Cuyahoga County
William Patrick Day
2421 Community College Ave, Cleveland, OH 44115

Fire/Smoke Damper Inspection Report

AUGUST 2024 Physical Inspections

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER NFPA

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

Report Date: September 2024

Project: Cuyahoga County
William Patrick Day

Inspector(s):

- Dan Tulcewicz, Certified Technician
- Tristan May, Certified Technician
- James Futrell, Certified Technician

Inspection and Test Date(s):

- August 2024

Duct Fabricators, Inc. “Fire Safety Division” inspected the Eighty-Two (82) fire dampers noted on the following sheets for proper installation. The dampers were then tested and photographed in the “open” and “closed” positions to confirm that they were functioning as designed.

(48) dampers passed the inspection and functional testing.
(34) dampers failed the inspection due to reasons indicated in the report.

NOTES: NFPA 80 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers located in patient care facilities are to be inspected and tested every six years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper ID	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
2024-08-01	William Patrick Day	E188	Dan Tulcewicz	FD-01	Vertical Fire Damper	18"x8"	Unknown	Unknown	165 Degrees	10"x12"	Pass	Added retaining angle.
2024-08-01	William Patrick Day	E189	Dan Tulcewicz	FD-02	Vertical Fire Damper	18"x8"	Unknown	Unknown	165 Degrees	12"x10"	Pass	Added retaining angle.
2024-08-08	William Patrick Day	E190	Dan Tulcewicz	FD-03	Vertical Fire Damper	18"x8"	Unknown	Unknown	165 Degrees	12"x10"	Pass	Added retaining angle.
2024-08-08	William Patrick Day	E193	Dan Tulcewicz	FD-04	Vertical Fire Damper	18"x8"	Unknown	Unknown	165 Degrees	12"x10"	Pass	Added retaining angle to the wall.
2024-08-08	William Patrick Day	E195	Dan Tulcewicz	FD-05	Vertical Fire Damper	16"x8"	Unknown	Unknown	165 Degrees	12"x10"	Pass	Added retaining angle to the wall.
2024-08-12	William Patrick Day	E135A Corridor	Dan Tulcewicz	FD-06	Vertical Fire Damper	12"x8"	Unknown	Unknown	165 Degrees	12"x10"	Pass	None
2024-08-12	William Patrick Day	E135A Corridor	Dan Tulcewicz	FD-07	Vertical Fire Damper	48"x16"	Unknown	Unknown	165 Degrees	Open	Pass	Install retaining angle to the wall.
2024-08-12	William Patrick Day	E135A Corridor	Dan Tulcewicz	FD-08	Vertical Fire Damper	48"x16"	Unknown	Unknown	165 Degrees	Open	Pass	Install retaining angle to the wall.
2024-08-13	William Patrick Day	Room 229	Dan Tulcewicz	FD-09	Horizontal Fire Damper	12/12	Unknown	Unknown	165 Degrees	NA	Pass	Added angle frame
2024-08-13	William Patrick Day	Room 229	Dan Tulcewicz	FD-10	Horizontal Fire Damper	10/6	Unknown	Unknown	165 Degrees	6/8	Pass	Add angle retaining frame and screws to sleeve
2024-08-13	William Patrick Day	E192	Dan Tulcewicz	FD-11	Horizontal Fire Damper	16/8	Unknown	Unknown	165 Degrees	12/10	Pass	Add frame to sleeve
2024-08-13	William Patrick Day	E194	Dan Tulcewicz	FD-12	Horizontal Fire Damper	16/8	Unknown	Unknown	165 Degrees	12/8	Pass	Add angle to sleeve.
2024-08-12	William Patrick Day	Conference room A #208	Dan Tulcewicz	FD-12a	Vertical Fire Damper	12"x8"	Unknown	Unknown	165 Degrees	12"x10"	Pass	Installed retaining angles
2024-08-13	William Patrick Day	E191	Dan Tulcewicz	FD-13	Horizontal Fire Damper	16/8	Unknown	Unknown	165 Degrees	12/10	Pass	Added angle frame
2024-08-13	William Patrick Day	Hallway E176 corridor	James Futrell	FD-14	Horizontal Fire Damper	80/32	Unknown	Unknown	165 Degrees	NA	Pass	Added angle frame
2024-08-12	William Patrick Day	E135A Corridor.	Dan Tulcewicz	FD-15	Vertical Fire Damper	12"x6"	Unknown	Unknown	165 Degrees	12"x10"	Pass	Install retaining angle to the wall on both sides.
2024-08-13	William Patrick Day	Corridor E176	James Futrell	FD-16	Horizontal Fire Damper	80x32	Unknown	Unknown	165 Degrees	Open	Pass	Added angle frame
2024-08-13	William Patrick Day	E 176 corridor	James Futrell	FD-17	Horizontal Fire Damper	12/6	Unknown	Unknown	165 Degrees	7/6	Pass	Added angle frame
2024-08-13	William Patrick Day	E-176 Corridor	James Futrell	FD-18	Horizontal Fire Damper	12/6	Unknown	Unknown	165 Degrees	8/6	Pass	Added angle frame
2024-08-14	William Patrick Day	E135A Corridor	Tristan May	FD-19	Vertical Fire Damper	48x16"	Unknown	Unknown	165 Degrees	Open	Pass	Added angle
2024-08-14	William Patrick Day	E135A Corridor	Tristan May	FD-20	Vertical Fire Damper	48*16	Unknown	Unknown	165 Degrees	Open	Fail	Added angle. Wires ran through damper. Fire proofing spray stuck to curtain also preventing damper operation
2024-08-14	William Patrick Day	E135 Corridor	Tristan May	FD-21	Vertical Fire Damper	6x16"	Unknown	Unknown	165 Degrees	10x12"	Pass	Added angle frame
2024-08-14	William Patrick Day	134A Corridor	Tristan May	FD-23	Vertical Fire Damper	48x16"	Unknown	U300G	165 Degrees	Open	Pass	Added angle frame
2024-08-14	William Patrick Day	E135 Corridor	Tristan May	FD-24	Vertical Fire Damper	48x16"	Unknown	U350G	165 Degrees	Open	Pass	Added angle frame

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper ID	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
2024-08-14	William Patrick Day	E135 Corridor	Tristan May	FD-25	Vertical Fire Damper	48x16"	Unknown	U250G	165 Degrees	Open	Fail	Added angle. Wire through damper
2024-08-14	William Patrick Day	E135 Corridor	Tristan May	FD-26	Vertical Fire Damper	48x16"	Unknown	U250G	165 Degrees	Open	Pass	Added angle both sides of wall
2024-08-14	William Patrick Day	E-172	James Futrell	FD-27	Vertical Fire Damper	24/10	Unknown	Unknown	165 Degrees	10/12	Pass	Added angle frame
2024-08-14	William Patrick Day	Rm-E 172 C	James Futrell	FD-28	Vertical Fire Damper	60/24	Unknown	Unknown	165 Degrees	Open	Fail	Communication cables going through damper, an added angle frame to sleeve.
2024-08-14	William Patrick Day	E176 office1	James Futrell	FD-29	Vertical Fire Damper	70/21	Unknown	Unknown	165 Degrees	Open	Pass	Added angle frame
2024-08-14	William Patrick Day	E176 office1	James Futrell	FD-30	Vertical Fire Damper	10/20	Unknown	Unknown	165 Degrees	10/12	Pass	Add retaining angle
2024-08-14	William Patrick Day	Room 232	James Futrell	FD-31	Vertical Fire Damper	42/16	Unknown	Unknown	165 Degrees	Open	Fail	Failed due to screw in curtain track, cables going through top and bottom of opening in wall, improper installation of fusible link, an damper is installed out of level.
2024-08-14	William Patrick Day	Room 232	James Futrell	FD-32	Vertical Fire Damper	50/21	Unknown	Unknown	165 Degrees	Open	Pass	Add retaining angle
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-33	Vertical Fire Damper	6x20	Unknown	Unknown	165 Degrees	6x8"	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-34	Vertical Fire Damper	7x20	Unknown	Unknown	165 Degrees	6x8	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-35	Vertical Fire Damper	6x20"	Unknown	Unknown	165 Degrees	6x8"	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-37	Vertical Fire Damper	11x20	Unknown	Unknown	165 Degrees	10x12	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-38	Vertical Fire Damper	6*20	Unknown	Unknown	165 Degrees	8*6	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-39	Vertical Fire Damper	6*20	Unknown	Unknown	165 Degrees	6*8	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-40	Vertical Fire Damper	13*20	Unknown	Unknown	165 Degrees	12*10*	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123	Tristan May	FD-41	Vertical Fire Damper	6*20	Unknown	Unknown	165 Degrees	Patch	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-42	Vertical Fire Damper	7*20	Unknown	Unknown	165 Degrees	Patch	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123	Tristan May	FD-43	Vertical Fire Damper	6*20	Unknown	Unknown	165 Degrees	Patch	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123	Tristan May	FD-44	Vertical Fire Damper	6*20	Unknown	Unknown	165 Degrees	Patch	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-45	Vertical Fire Damper	11*20	Unknown	Unknown	165 Degrees	Patch	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-46	Vertical Fire Damper	6*20	Unknown	Unknown	165 Degrees	Patch	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-14	William Patrick Day	E123 Vestibule	Tristan May	FD-47	Vertical Fire Damper	6*20	Unknown	Unknown	165 Degrees	Patch	Fail	Wire through annular space, sleeve not through wall, breakaway connection in wall.
2024-08-15	William Patrick Day	Room 232	James Futrell	FD-48	Vertical Fire Damper	11/20	Unknown	Unknown	165 Degrees	10/12	Pass	Add retaining angle

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper ID	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
2024-08-15	William Patrick Day	Room 232	James Futrell	FD-49	Vertical Fire Damper	11/20	Unknown	Unknown	165 Degrees	10/12	Pass	Add retaining angle
2024-08-15	William Patrick Day	Room 232	James Futrell	FD-50	Vertical Fire Damper	9/20	Unknown	Unknown	165 Degrees	6/8	Pass	Add retaining angle
2024-08-15	William Patrick Day	Kitchen E128	Tristan May	FD-51	Vertical Fire Damper	48*16	Unknown	Unknown	165 Degrees	Grill	Pass	None
2024-08-15	William Patrick Day	E128 Kitchen	Tristan May	FD-52	Vertical Fire Damper	48*16	Unknown	Unknown	165 Degrees	Grill	Pass	None
2024-08-15	William Patrick Day	E147	James Futrell	FD-53	Vertical Fire Damper	8/4	Unknown	Unknown	165 Degrees	8/6	Fail	Pneumatic lines an conduit in sleeve
2024-08-15	William Patrick Day	Room G1	James Futrell	FD-54	Vertical Fire Damper	48/15	Unknown	Unknown	165 Degrees	16/16	Pass	None
2024-08-15	William Patrick Day	Room G1	James Futrell	FD-55	Vertical Fire Damper	36/16	Unknown	Unknown	165 Degrees	16/16	Pass	None
2024-08-15	William Patrick Day	Room G2	James Futrell	FD-56	Vertical Fire Damper	30/24	Unknown	Unknown	165 Degrees	12/10	Pass	Add retaining angle
2024-08-15	William Patrick Day	E138 mechanical	Tristan May	FD-57	Vertical Fire Damper	60*24	Unknown	U200G	165 Degrees	Open	Pass	Add angle
2024-08-15	William Patrick Day	E138 Mechanical	Tristan May	FD-58	Vertical Fire Damper	42*12	Unknown	Unknown	165 Degrees	Open	Pass	Add angle
2024-08-20	William Patrick Day	Mechanical room E138	Tristan May	FD-59	Vertical Fire Damper	60*24	Unknown	Unknown	165 Degrees	Grill	Pass	None
2024-08-20	William Patrick Day	E138 mechanical room.	Tristan May	FD-60	Vertical Fire Damper	24"x10"	Unknown	Unknown	165 Degrees	Open duct	Pass	None
2024-08-15	William Patrick Day	Room G2	James Futrell	FD-61	Vertical Fire Damper	16/8	Unknown	Unknown	165 Degrees	8/8	Fail	Multiple infractions, one being unable to properly retain
2024-08-20	William Patrick Day	Room G-2	James Futrell	FD-62	Horizontal Fire Damper	14/12	Unknown	Unknown	165 Degrees	6/10	Pass	None
2024-08-19	William Patrick Day	E160	Tristan May	FD-63	Vertical Fire Damper	16*8	Unknown	Unknown	165 Degrees	12*10	Fail	Sleeve not long enough.
2024-08-19	William Patrick Day	E198	Tristan May	FD-64	Vertical Fire Damper	16*8	Unknown	Unknown	165 Degrees	10x12	Fail	Copper line through annular space, sleeve to short.
2024-08-19	William Patrick Day	E157	Tristan May	FD-65	Vertical Fire Damper	18"x8"	Unknown	Unknown	165 Degrees	12*10	Fail	Sleeve not long enough
2024-08-19	William Patrick Day	E159	Tristan May	FD-66	Vertical Fire Damper	18"x8"	Unknown	Unknown	165 Degrees	12"x10"	Fail	Sleeve not long enough
2024-08-19	William Patrick Day	E161	Tristan May	FD-67	Vertical Fire Damper	8*18	Unknown	Unknown	165 Degrees	10*12	Fail	Sleeve not long enough
2024-08-19	William Patrick Day	E163	Tristan May	FD-68	Vertical Fire Damper	18"x8"	Unknown	Unknown	165 Degrees	12"x10"	Fail	Sleeve not long enough.
2024-08-19	William Patrick Day	E165	Tristan May	FD-69	Vertical Fire Damper	12*18	Unknown	Unknown	165 Degrees	10*12	Fail	Sleeve not long enough
2024-08-20	William Patrick Day	E176 Hallway	James Futrell	FD-70	Vertical Fire Damper	11/20	Unknown	Unknown	165 Degrees	10/12	Fail	Door too far from curtain, breakaway joint in wall no retaining frame
2024-08-20	William Patrick Day	E176 Hallway	James Futrell	FD-71	Vertical Fire Damper	11/20	Unknown	Unknown	165 Degrees	10/20	Fail	Door too far away from curtain, breakaway joint in wall and no retaining frame
2024-08-20	William Patrick Day	E176 Hallway	James Futrell	FD-72	Vertical Fire Damper	9/20	Unknown	Unknown	165 Degrees	6/8	Fail	Door too far away from curtain, breakaway joint in wall and no retaining frame

Date of Inspection	Facility Location	Damper Location	Inspector Name	Damper ID	Damper Type	Damper Size	Damper Manufacturer	Damper Model	Fusible Link Temperature	Access Door Size	Pass Fail Abandoned	Comments Corrections
2024-08-20	William Patrick Day	E176 Hallway	James Futrell	FD-73	Vertical Fire Damper	9/20	Unknown	Unknown	165 Degrees	6/8	Fail	Door too far away from curtain, breakaway joint in wall and no retaining frame
2024-08-20	William Patrick Day	E176 Hallway	James Futrell	FD-74	Vertical Fire Damper	11/20	Unknown	Unknown	165 Degrees	10/20	Fail	Door too far away from curtain, break away joint in wall and no retaining frame
2024-08-20	William Patrick Day	E176 Hallway	James Futrell	FD-75	Vertical Fire Damper	11/20	Unknown	Unknown	165 Degrees	10/12	Fail	Door too far away from curtain breakaway joint in wall and no retaining frame
2024-08-20	William Patrick Day	E176 Hallway	James Futrell	FD-76	Vertical Fire Damper	6/20	Unknown	Unknown	165 Degrees	10/12	Fail	Door too far away from curtain breakaway joint in wall and no retaining frame
2024-08-20	William Patrick Day	Room 192A	James Futrell	FD-77	Vertical Fire Damper	10/4	Unknown	Unknown	165 Degrees	8/6	Pass	Add retaining angle
2024-08-20	William Patrick Day	E176 KS Office	James Futrell	FD-78	Vertical Fire Damper	20/8	Unknown	Unknown	165 Degrees	10/12	Pass	Add retaining angle frame
2024-08-20	William Patrick Day	E194A	James Futrell	FD-79	Vertical Fire Damper	10/4	Unknown	Unknown	165 Degrees	10/12	Pass	Add retaining angle
2024-08-21	William Patrick Day	E182	James Futrell	FD-80	Vertical Fire Damper	8*6	Unknown	Unknown	165 Degrees	8*6	Pass	Add angle to wall
2024-08-21	William Patrick Day	E182	Tristan May	FD-81	Vertical Fire Damper	12*12	Unknown	Unknown	165 Degrees	Open	Pass	None
2024-08-21	William Patrick Day	E170	James Futrell	FD-82	Vertical Fire Damper	10*20	Unknown	Unknown	165 Degrees	Patch	Pass	Add angle
2024-08-21	William Patrick Day	E170	James Futrell	FD-83	Vertical Fire Damper	32*16	Unknown	Unknown	165 Degrees	Open	Pass	None

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-01

Facility Location
William Patrick Day

Damper Location
E188

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-1

Damper Type
Vertical Fire Damper

Damper Size
18"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10"x12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-01

Facility Location
William Patrick Day

Damper Location
E189

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-2

Damper Type
Vertical Fire Damper

Damper Size
18"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-08

Facility Location
William Patrick Day

Damper Location
E190

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-3

Damper Type
Vertical Fire Damper

Damper Size
18"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-08

Facility Location
William Patrick Day

Damper Location
E193

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-4

Damper Type
Vertical Fire Damper

Damper Size
18"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-08

Facility Location
William Patrick Day

Damper Location
E195

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-5

Damper Type
Vertical Fire Damper

Damper Size
16"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-12

Facility Location
William Patrick Day

Damper Location
E135A Corridor

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-6

Damper Type
Vertical Fire Damper

Damper Size
12"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-12

Facility Location
William Patrick Day

Damper Location
E135A Corridor

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-7

Damper Type
Vertical Fire Damper

Damper Size
48"x16"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-12

Facility Location
William Patrick Day

Damper Location
E135A Corridor

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-8

Damper Type
Vertical Fire Damper

Damper Size
48"x16"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-13

Facility Location
William Patrick Day

Damper Location
Room 229

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-9

Damper Type
Horizontal Fire Damper

Damper Size
12/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
NA

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-13

Facility Location
William Patrick Day

Damper Location
Room 229

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-10

Damper Type
Horizontal Fire Damper

Damper Size
10/6

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Add angle retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-13

Facility Location
William Patrick Day

Damper Location
E192

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-11

Damper Type
Horizontal Fire Damper

Damper Size
16/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angles.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-13

Facility Location
William Patrick Day

Damper Location
E194

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-12

Damper Type
Horizontal Fire Damper

Damper Size
16/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angles.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-12

Facility Location
William Patrick Day

Damper Location
Conference room A #208

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-12a

Damper Type
Vertical Fire Damper

Damper Size
12"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-13

Facility Location
William Patrick Day

Damper Location
E191

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-13

Damper Type
Horizontal Fire Damper

Damper Size
16/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angles.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-13

Facility Location
William Patrick Day

Damper Location
Hallway E176 corridor

Inspector Name
James Futrell

Damper I.D. #
FD-14

Damper Type
Horizontal Fire Damper

Damper Size
80/32

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
NA

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angles.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-12

Facility Location
William Patrick Day

Damper Location
E135A Corridor.

Inspector Name
Dan Tulcewicz

Damper I.D. #
FD-15

Damper Type
Vertical Fire Damper

Damper Size
12"x6"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x10"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Installed retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-13

Facility Location
William Patrick Day

Damper Location
Corridor E176

Inspector Name
James Futrell

Damper I.D. #
FD-16

Damper Type
Horizontal Fire Damper

Damper Size
80x32

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angles.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-13

Facility Location
William Patrick Day

Damper Location
E 176 corridor

Inspector Name
James Futrell

Damper I.D. #
FD-17

Damper Type
Horizontal Fire Damper

Damper Size
12/6

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
7/6

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angles.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-13

Facility Location
William Patrick Day

Damper Location
E-176 Corridor

Inspector Name
James Futrell

Damper I.D. #
FD-18

Damper Type
Horizontal Fire Damper

Damper Size
12/6

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/6

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angles.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E135A Corridor

Inspector Name
Tristan May

Damper I.D. #
FD-19

Damper Type
Vertical Fire Damper

Damper Size
48x16"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E135A Corridor

Inspector Name
Tristan May

Damper I.D. #
FD-20

Damper Type
Vertical Fire Damper

Damper Size
48*16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
Added angle. Wires through damper. Fire proofing stuck to curtain.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E135 Corridor

Inspector Name
Tristan May

Damper I.D. #
FD-21

Damper Type
Vertical Fire Damper

Damper Size
6x16"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10x12"

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining anlge.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
134A Corridor

Inspector Name
Tristan May

Damper I.D. #
FD-23

Damper Type
Vertical Fire Damper

Damper Size
48x16"

Damper Manufacturer
Unknown

Damper Model #
U300G

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E135 Corridor

Inspector Name
Tristan May

Damper I.D. #
FD-24

Damper Type
Vertical Fire Damper

Damper Size
48x16"

Damper Manufacturer
Unknown

Damper Model #
U350G

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E135 Corridor

Inspector Name
Tristan May

Damper I.D. #
FD-25

Damper Type
Vertical Fire Damper

Damper Size
48x16"

Damper Manufacturer
Unknown

Damper Model #
U250G

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
Added retaining angle. Wire through damper

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E135 Corridor

Inspector Name
Tristan May

Damper I.D. #
FD-26

Damper Type
Vertical Fire Damper

Damper Size
48x16"

Damper Manufacturer
Unknown

Damper Model #
U250G

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E-172

Inspector Name
James Futrell

Damper I.D. #
FD-27

Damper Type
Vertical Fire Damper

Damper Size
24/10

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angles.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
Rm-E 172 C

Inspector Name
James Futrell

Damper I.D. #
FD-28

Damper Type
Vertical Fire Damper

Damper Size
60/24

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
Communication cables going through damper, an added retaining angle.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E176 office1

Inspector Name
James Futrell

Damper I.D. #
FD-29

Damper Type
Vertical Fire Damper

Damper Size
70/21

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E176 office1

Inspector Name
James Futrell

Damper I.D. #
FD-30

Damper Type
Vertical Fire Damper

Damper Size
10/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
Room 232

Inspector Name
James Futrell

Damper I.D. #
FD-31

Damper Type
Vertical Fire Damper

Damper Size
42/16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Fail

Comments / Corrections
Screw in curtain track, cables in annular space, improper installation of fusible link

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
Room 232

Inspector Name
James Futrell

Damper I.D. #
FD-32

Damper Type
Vertical Fire Damper

Damper Size
50/21

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-33

Damper Type
Vertical Fire Damper

Damper Size
6x20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6x8"

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire through annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-34

Damper Type
Vertical Fire Damper

Damper Size
7x20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6x8

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire through annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-35

Damper Type
Vertical Fire Damper

Damper Size
6x20"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6x8"

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire through annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-37

Damper Type
Vertical Fire Damper

Damper Size
11x20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10x12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire through annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-38

Damper Type
Vertical Fire Damper

Damper Size
6*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*6

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire through annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-39

Damper Type
Vertical Fire Damper

Damper Size
6*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6*8

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire through annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-40

Damper Type
Vertical Fire Damper

Damper Size
13*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*10*

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire through annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123

Inspector Name
Tristan May

Damper I.D. #
FD-41

Damper Type
Vertical Fire Damper

Damper Size
6*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire through annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-42

Damper Type
Vertical Fire Damper

Damper Size
7*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire through annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123

Inspector Name
Tristan May

Damper I.D. #
FD-43

Damper Type
Vertical Fire Damper

Damper Size
6*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire in annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123

Inspector Name
Tristan May

Damper I.D. #
FD-44

Damper Type
Vertical Fire Damper

Damper Size
6*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire in annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-45

Damper Type
Vertical Fire Damper

Damper Size
11*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire in annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-46

Damper Type
Vertical Fire Damper

Damper Size
6*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire in annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-14

Facility Location
William Patrick Day

Damper Location
E123 Vestibule

Inspector Name
Tristan May

Damper I.D. #
FD-47

Damper Type
Vertical Fire Damper

Damper Size
6*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Fail

Comments / Corrections
Wire in annular space, sleeve not through wall.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
Room 232

Inspector Name
James Futrell

Damper I.D. #
FD-48

Damper Type
Vertical Fire Damper

Damper Size
11/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
Room 232

Inspector Name
James Futrell

Damper I.D. #
FD-49

Damper Type
Vertical Fire Damper

Damper Size
11/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
Room 232

Inspector Name
James Futrell

Damper I.D. #
FD-50

Damper Type
Vertical Fire Damper

Damper Size
9/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6/8

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
Kitchen E128

Inspector Name
Tristan May

Damper I.D. #
FD-51

Damper Type
Vertical Fire Damper

Damper Size
48*16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
E128 Kitchen

Inspector Name
Tristan May

Damper I.D. #
FD-52

Damper Type
Vertical Fire Damper

Damper Size
48*16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
E147

Inspector Name
James Futrell

Damper I.D. #
FD-53

Damper Type
Vertical Fire Damper

Damper Size
8/4

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/6

Pass / Fail / Abandoned
Fail

Comments / Corrections
Pneumatic lines and conduit in annular space.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
Room G1

Inspector Name
James Futrell

Damper I.D. #
FD-54

Damper Type
Vertical Fire Damper

Damper Size
48/15

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
Room G1

Inspector Name
James Futrell

Damper I.D. #
FD-55

Damper Type
Vertical Fire Damper

Damper Size
36/16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
16/16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
Room G2

Inspector Name
James Futrell

Damper I.D. #
FD-56

Damper Type
Vertical Fire Damper

Damper Size
30/24

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
E138 mechanical

Inspector Name
Tristan May

Damper I.D. #
FD-57

Damper Type
Vertical Fire Damper

Damper Size
60*24

Damper Manufacturer
Unknown

Damper Model #
U200G

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Add angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
E138 Mechanical

Inspector Name
Tristan May

Damper I.D. #
FD-58

Damper Type
Vertical Fire Damper

Damper Size
42*12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
Mechanical room E138

Inspector Name
Tristan May

Damper I.D. #
FD-59

Damper Type
Vertical Fire Damper

Damper Size
60*24

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Grill

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E138 mechanical room.

Inspector Name
Tristan May

Damper I.D. #
FD-60

Damper Type
Vertical Fire Damper

Damper Size
24"x10"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open duct

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-15

Facility Location
William Patrick Day

Damper Location
Room G2

Inspector Name
James Futrell

Damper I.D. #
FD-61

Damper Type
Vertical Fire Damper

Damper Size
16/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/8

Pass / Fail / Abandoned
Fail

Comments / Corrections
Multiple infractions. This requires reworking the duct/wall opening.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
Room G-2

Inspector Name
James Futrell

Damper I.D. #
FD-62

Damper Type
Horizontal Fire Damper

Damper Size
14/12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6/10

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-19

Facility Location
William Patrick Day

Damper Location
E160

Inspector Name
Tristan May

Damper I.D. #
FD-63

Damper Type
Vertical Fire Damper

Damper Size
16*8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*10

Pass / Fail / Abandoned
Fail

Comments / Corrections
Sleeve not long enough.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-19

Facility Location
William Patrick Day

Damper Location
E198

Inspector Name
Tristan May

Damper I.D. #
FD-64

Damper Type
Vertical Fire Damper

Damper Size
16*8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10x12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Copper line through annular space, sleeve to short.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-19

Facility Location
William Patrick Day

Damper Location
E157

Inspector Name
Tristan May

Damper I.D. #
FD-65

Damper Type
Vertical Fire Damper

Damper Size
18"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12*10

Pass / Fail / Abandoned
Fail

Comments / Corrections
Sleeve not long enough

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-19

Facility Location
William Patrick Day

Damper Location
E159

Inspector Name
Tristan May

Damper I.D. #
FD-66

Damper Type
Vertical Fire Damper

Damper Size
18"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x10"

Pass / Fail / Abandoned
Fail

Comments / Corrections
Sleeve not long enough

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-19

Facility Location
William Patrick Day

Damper Location
E161

Inspector Name
Tristan May

Damper I.D. #
FD-67

Damper Type
Vertical Fire Damper

Damper Size
8*18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Sleeve not long enough

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-19

Facility Location
William Patrick Day

Damper Location
E163

Inspector Name
Tristan May

Damper I.D. #
FD-68

Damper Type
Vertical Fire Damper

Damper Size
18"x8"

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
12"x10"

Pass / Fail / Abandoned
Fail

Comments / Corrections
Sleeve not long enough.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-19

Facility Location
William Patrick Day

Damper Location
E165

Inspector Name
Tristan May

Damper I.D. #
FD-69

Damper Type
Vertical Fire Damper

Damper Size
12*18

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10*12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Sleeve not long enough

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E176 Hallway

Inspector Name
James Futrell

Damper I.D. #
FD-70

Damper Type
Vertical Fire Damper

Damper Size
11/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Door too far from curtain, breakaway joint in wall no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E176 Hallway

Inspector Name
James Futrell

Damper I.D. #
FD-71

Damper Type
Vertical Fire Damper

Damper Size
11/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/20

Pass / Fail / Abandoned
Fail

Comments / Corrections
Door too far away, breakaway joint in wall and no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E176 Hallway

Inspector Name
James Futrell

Damper I.D. #
FD-72

Damper Type
Vertical Fire Damper

Damper Size
9/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6/8

Pass / Fail / Abandoned
Fail

Comments / Corrections
Door too far away, breakaway joint in wall and no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E176 Hallway

Inspector Name
James Futrell

Damper I.D. #
FD-73

Damper Type
Vertical Fire Damper

Damper Size
9/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
6/8

Pass / Fail / Abandoned
Fail

Comments / Corrections
Door too far away, breakaway joint in wall and no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E176 Hallway

Inspector Name
James Futrell

Damper I.D. #
FD-74

Damper Type
Vertical Fire Damper

Damper Size
11/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/20

Pass / Fail / Abandoned
Fail

Comments / Corrections
Door too far away from curtain, break away joint in wall and no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E176 Hallway

Inspector Name
James Futrell

Damper I.D. #
FD-75

Damper Type
Vertical Fire Damper

Damper Size
11/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Door too far away, breakaway joint in wall and no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E176 Hallway

Inspector Name
James Futrell

Damper I.D. #
FD-76

Damper Type
Vertical Fire Damper

Damper Size
6/20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/12

Pass / Fail / Abandoned
Fail

Comments / Corrections
Door too far away, breakaway joint in wall and no retaining frame

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
Room 192A

Inspector Name
James Futrell

Damper I.D. #
FD-77

Damper Type
Vertical Fire Damper

Damper Size
10/4

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8/6

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E176 KS Office

Inspector Name
James Futrell

Damper I.D. #
FD-78

Damper Type
Vertical Fire Damper

Damper Size
20/8

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angles

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-20

Facility Location
William Patrick Day

Damper Location
E194A

Inspector Name
James Futrell

Damper I.D. #
FD-79

Damper Type
Vertical Fire Damper

Damper Size
10/4

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
10/12

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added retaining angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-21

Facility Location
Justice Center Court Towers

Damper Location
E182

Inspector Name
James Futrell

Damper I.D. #
FD-80

Damper Type
Vertical Fire Damper

Damper Size
8*6

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
8*6

Pass / Fail / Abandoned
Pass

Comments / Corrections
Add angle to wall

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-21

Facility Location
William Patrick Day

Damper Location
E182

Inspector Name
Tristan May

Damper I.D. #
FD-81

Damper Type
Vertical Fire Damper

Damper Size
12*12

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-21

Facility Location
William Patrick Day

Damper Location
E170

Inspector Name
James Futrell

Damper I.D. #
FD-82

Damper Type
Vertical Fire Damper

Damper Size
10*20

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Patch

Pass / Fail / Abandoned
Pass

Comments / Corrections
Added angle

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F:216-391-2492

FIRE SAFETY DIVISION
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2024-08-21

Facility Location
William Patrick Day

Damper Location
E170

Inspector Name
James Futrell

Damper I.D. #
FD-83

Damper Type
Vertical Fire Damper

Damper Size
32*16

Damper Manufacturer
Unknown

Damper Model #
Unknown

Fusible Link Temperature
165 Degrees

Access Door Size
Open

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

