

# Huntington Park Garage Overview

**Department of Public Works** 

01/05/16



#### Scope of Work

- Structural Repairs concrete girder repairs/concrete patching/waterproofing
- Mechanical, Electrical, Plumbing & Fire Protection Upgrades
  - Replacement of exhaust fans and ducts
  - Repair of electrical conduit and electrical panel replacement
  - Drainage system upgrades
  - Fire suppression and alarm system replacement
  - Four (4) elevator replacements
  - Security camera installation, parking controls



#### Scope of Work


- Architectural / Aesthetic & Security Enhancements
  - Comprehensive way finding and signage
  - Elevator Improvements
  - Security system
  - Lighting
  - Painting



#### Scope of Work

- Accessibility
- Improvements over the years, yet many barriers remain
- Items identified for upgrade include:
  - Directional signage throughout, particularly accessible and exit routes
  - Ramps along route to elevators
  - Audible signals at elevators
  - Door hardware





Concrete Wall distress showing delamination and exposed corroded reinforcing steel



Concrete Wall crack with active water leakage





Typical concrete corbel distress with delaminated concrete and exposed reinforcing steel. Also, loss of bearing of double-tee stem



Concrete corbel with significant distress. Double tee beams required temporary shoring due to loss of bearing





Concrete column with significant concrete loss and corroded reinforcing steel



Typical distress at column corbel





Girder required shoring due to web distress




Typical distress at girder flange





Girder with significant distress



Emergency shoring had to be provided for this girder in Dec. 2014



**HVAC System** 



Exhaust fan and motor not performing properly. Need to be replaced.



Deteriorated, collapsed duct main



### **HVAC System**



Exhaust duct branches missing



Electric cabinet heater units in need of replacement in office areas



### Electrical System



Corroded electrical conduits



Typical outdated electrical equipment



### **Electrical System**



Corroded electrical conduits and hangar



Inadequate lighting in stairwells



### Plumbing System



Original roof drain



Typical leaking roof drain causing damage to structure



### Plumbing System



Gutter discharging to sidewalk



No roof drains or gutter to direct water away from sidewalk



### Fire Protection System



Extensive corrosion on FP mains, branch lines, fittings, and couplings




Typical extensive corrosion on mains for dry standpipe system.



### Fire Protection System



Extensive corrosion on FP mains, branch lines, fittings, and couplings




Corrosion on existing riser equipment/Leaking underground supply



#### **Architectural Conditions**



Ponding water and vegetation at roof penthouse



Newer modified bitumen roofing membrane with several inches of ponding water



#### **Architectural Conditions**



Typical ticket booth



Typical corrosion at base of hinged door leaf, frame, and threshold



### Accessibility



Poor visibility of accessible signage and call button; ramp to elevator is too steep and currently not enough room to install proper ramp



Typical non-compliant ramp



### Accessibility




Exit path not visible, sign not illuminated and obstructed by existing ductwork



Exit sign not illuminated




### Levels 1 & 2 Striping Plans





### Levels 3 & 4 Striping Plans






### Distribution of Parking Spaces

	Pre-Construction (2011)	Post-Construction (2017)		
Total Available Spaces	1,100	1,179		
Administrative Building Monthly	118	0		
Government Monthly 1st Shift	382	382		
Non-Government Monthly	52	0		
Hotel Valet / Self Park	0	410		
Convention Center	0	100		
Total Monthly Parkers	552	892		
Transient Spaces Available	548	287		



### Other County Parking Facilities

	Current Monthly Passes	Monthly Passes Available
Courthouse Square (105 Spaces)	65	40
Summit Lot (36 Spaces)	0	36





### Re-Distribution of Parking Spaces

	Pre-Construction (2011)	Post-Construction (2017)		
Total Available Spaces	1,100	1,179		
Administrative Building Monthly	118	0		
Government Monthly 1st Shift	382	306		
Non-Government Monthly	52	0		
Hotel Valet / Self Park	0	410		
Convention Center	0	100		
Total Monthly Parkers	552	816		
Transient Spaces Available	548	363		



### Parking Rate Study- (Garages)



#### **Garage Rate Information**

1. Great Lakes Science Center ( ABM Parking Services)

> Max Rate: \$ 11.00 Monthly Rate: \$ 65.00

2. 55 Public Square (ABM Parking Services)

Max Rate: \$ 10.00 Monthly Rate: \$210.00

3. Tower City Center ( ABM Parking Services)

Max Rate: \$ 16.00 Monthly Rate: \$ 200.00

4. 200 Public Square (Standard Parking)

Max Rate: \$ 15.00 Monthly Rate: N/A

5. Memorial Plaza (Standard Parking)

Max Rate: \$ 13.00 Monthly Rate: N/A

6. Penton Media (ABM Parking Services)

Max Rate: \$ 12.00 Monthly Rate: \$ 200.00


7. North Point (Standard Parking)

Max Rate: \$ 12.00

Monthly Rate: \$ 170.00



### Parking Rate Study- (Surface Lots)






### Existing / Proposed Rates

	Justice Center / Huntington Park Garage		Courthouse Square Surface Lot		Summit Surface Lot	
	Existing	Proposed	Existing	Proposed	Existing	Proposed
Daily Max	\$8	\$10	\$8	-	\$5	-
Government Monthly	\$85	\$105	\$85	\$85	-	\$85
Reserved Monthly (24/7)	-	\$200	-	-	-	-



#### Other Transportation Options

- GCRTA / County Employee
  Discounted Bus Pass
- Other Garages / Surface Lots
- GCRTA Trolley Service
  - Red Line runs every ten minutes





#### Muni Lot / GCRTA Waterfront Line





#### Additional Surface Lots

