883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





Report Date: July 17, 2020

<u>Project</u>: Cuyahoga County Animal Shelter

<u>Inspector(s)</u>: Julie Gue, Certified Technician

## Inspection and Test Date(s):

• June 25, 2020

Duct Fabricators, Inc. "Fire Safety Division" inspected the four (4) fire dampers for proper installation. The dampers were then tested and photographed in the "open" and "closed" positions to confirm that they were functioning as designed.

All dampers have passed the inspection and functional testing.

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers are to be visually inspected every two years and functionally tested every four years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

## Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





## <u>Fire / Smoke / Fire & Smoke Damper</u> <u>Composite Inspection Report</u>

	FD/SD/FSD	<u>I.D.#</u>	<u>Size</u>	Manufacturer	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1	FD	FD-1	8" Round	Ruskin	CFDR5	PASS	PASS	NONE
2	FD	FD-2	6" round	Ruskin	CFDR5	PASS	PASS	NONE
3	FD	FD-3	6" round	Ruskin	CFDR5	PASS	PASS	NONE
4	FD	FD-4	8" round	Ruskin	CFDR5	PASS	PASS	NONE
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								

Inspector:Julie GueSA = Supply AirFD = Fire DamperInspection Dates:25-Jun-20RA = Return AirSD = Smoke Damper

Facility: Animal shelter EA = Exhaust Air FSD = Fire Smoke Damper