

Cuyahoga County
Animal Shelter

9500 Sweet Valley Drive
Valley View, Ohio 44125

Visual Inspections

Fire Damper Inspection Report

Duct Fabricators, Inc.

FIRE SAFETY DIVISION

MEMBER



VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-09-15

Facility Location

County Animal Shelter

Damper Location

Visitation corridor

Inspector Name

Julie Gue

Damper I.D. #

AS-FD2

Damper Type

Ceiling Radiation Damper

Damper Size

6" Round

Damper Manufacturer

Ruskin

Damper Model #

CFDR5

Fusible Link Temperature

165 Degrees

Access Door Size

Diffuser

Pass / Fail / Abandoned

Pass

Comments / Corrections

None


Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Report Date: September 15, 2022

Project: Cuyahoga County
Animal Shelter

Inspector(s):
Julianne Gue, Certified Technician
Dan Tulcewicz, Certified Technician

Inspection and Test Date(s):
September 15, 2022

Duct Fabricators, Inc. "Fire Safety Division" visually inspected Four dampers for proper installation. The exterior and interior of each damper was photographed to confirm that the dampers were free of any obstructions or modifications. Preventative maintenance was performed to enhance the longevity and reliability of the damper.

NOTES: NFPA 80 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers located in patient care facilities are to be inspected and tested every six years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-09-15

Facility Location

County Animal Shelter

Damper Location

Visitation corridor

Inspector Name

Julie Gue

Damper I.D. #

AS-FD1

Damper Type

Ceiling Radiation Damper

Damper Size

8" Round

Damper Manufacturer

Ruskin

Damper Model #

CFDR5

Fusible Link Temperature

165 Degrees

Access Door Size

Diffuser

Pass / Fail / Abandoned

Pass

Comments / Corrections

None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



Cuyahoga County
Animal Shelter

9500 Sweet Valley Drive
Valley View, Ohio 44125

Visual Inspections

Fire Damper Inspection Report

Duct Fabricators, Inc.

FIRE SAFETY DIVISION



VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-09-15

Facility Location

County Animal Shelter

Damper Location

Visitation corridor

Inspector Name

Julie Gue

Damper I.D. #

AS-FD3

Damper Type

Vertical Fire Damper

Damper Size

6" Round

Damper Manufacturer

Ruskin

Damper Model #

CFDR5

Fusible Link Temperature

165 Degrees

Access Door Size

Diffuser

Pass / Fail / Abandoned

Pass

Comments / Corrections

None


Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label



VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-09-15

Facility Location

County Animal Shelter

Damper Location

Surgery corridor

Inspector Name

Julie Gue

Damper I.D. #

AS-FD4

Damper Type

Ceiling Radiation Damper

Damper Size

8" round

Damper Manufacturer

Ruskin

Damper Model #

CFDR5

Fusible Link Temperature

165 Degrees

Access Door Size

Diffuser

Pass / Fail / Abandoned

Pass

Comments / Corrections

None

Exterior Picture of Damper



Interior Picture of Damper



Picture of Damper I.D. Label

