883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Coridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-1

Damper Type

Vertical Fire Damper

Damper Size

12x6

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

9x9

Pass / Fail / Abandoned

Pass

Comments / Corrections


None

Picture of Damper in Open Position





Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-2

Damper Type

Vertical Fire Damper

Damper Size

34x10

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

16x16

Pass / Fail / Abandoned

Pass

Comments / Corrections

None

Picture of Damper in Open Position





Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-3

Damper Type

Vertical Fire Damper

Damper Size

32x14

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

16x16

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-4

Damper Type

Vertical Fire Damper

Damper Size

32x12

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

16x16

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-5

Damper Type

Vertical Fire Damper

Damper Size

30x10

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

16x16

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-6

Damper Type

Vertical Fire Damper

Damper Size

18x12

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

12x12

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-7

Damper Type

Vertical Fire Damper

Damper Size

18x12

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

16x16

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-8

Damper Type

Vertical Fire Damper

Damper Size

10x6

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

8x8

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-9

Damper Type

Vertical Fire Damper

Damper Size

18x8

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

14x14

Pass / Fail / Abandoned

Pass

Comments / Corrections


None

Picture of Damper in Open Position





Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-10

Damper Type

Vertical Fire Damper

Damper Size

22x14

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

8x8

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-11

Damper Type

Vertical Fire Damper

Damper Size

24x10

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

12x12

Pass / Fail / Abandoned

Pass

Comments / Corrections

None

Picture of Damper in Open Position





Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-12

Damper Type

Vertical Fire Damper

Damper Size

12x6

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

10x10

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-13

Damper Type

Vertical Fire Damper

Damper Size

34x10

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

16x16

Pass / Fail / Abandoned

Pass

Comments / Corrections


None

Picture of Damper in Open Position





Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-14

Damper Type

Vertical Fire Damper

Damper Size

34x10

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

16x16

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Public Works

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-15

Damper Type

Vertical Fire Damper

Damper Size

50x14

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

16x16

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Public Works

Damper Location

2nd Floor Corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-16

Damper Type

Vertical Fire Damper

Damper Size

28x12

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

14x14

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd floor corridor

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-17

Damper Type

Vertical Fire Damper

Damper Size

12x8

Damper Manufacturer

Nailor

Damper Model #

0124-12V

Fusible Link Temperature

165 Degrees

Access Door Size

10x10

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-18

Damper Type

Vertical Fire Damper

Damper Size

14x10

Damper Manufacturer

Greenheck

Damper Model #

FD150VA

Fusible Link Temperature

165 Degrees

Access Door Size

10x10

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-19

Damper Type

Vertical Fire Damper

Damper Size

18x12

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

14x14

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

Male Dorm 4

Inspector Name

Larry Coreno

Damper I.D. #

FD-20

Damper Type

Horizontal Fire Damper

Damper Size

28x12

Damper Manufacturer

Greenheck

Damper Model #

FD150AH

Fusible Link Temperature

165 Degrees

Access Door Size

12x12

Pass / Fail / Abandoned

Pass

Comments / Corrections


None

Picture of Damper in Open Position





Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

Male Dorm 4

Inspector Name

Larry Coreno

Damper I.D. #

FD-21

Damper Type

Horizontal Fire Damper

Damper Size

44x12

Damper Manufacturer

Greenheck

Damper Model #

FD150HA

Fusible Link Temperature

165 Degrees

Access Door Size

12x12

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

Male Dorm 5

Inspector Name

Larry Coreno

Damper I.D. #

FD-22

Damper Type

Horizontal Fire Damper

Damper Size

30x14

Damper Manufacturer

Greenheck

Damper Model #

FD150HA

Fusible Link Temperature

165 Degrees

Access Door Size

12x12

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-23

Damper Type

Vertical Fire Damper

Damper Size

20x12

Damper Manufacturer

Greenheck

Damper Model #

FD150VA

Fusible Link Temperature

165 Degrees

Access Door Size

8x8

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-24

Damper Type

Vertical Fire Damper

Damper Size

18x10

Damper Manufacturer

Greenheck

Damper Model #

FD150VA

Fusible Link Temperature

165 Degrees

Access Door Size

12x12

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Public Works

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-25

Damper Type

Vertical Fire Damper

Damper Size

20x16

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

8x8

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-26

Damper Type

Vertical Fire Damper

Damper Size

26x10

Damper Manufacturer

Greenheck

Damper Model #

FD150VA

Fusible Link Temperature

165 Degrees

Access Door Size

14x14

Pass / Fail / Abandoned

Pass

Comments / Corrections


None

Picture of Damper in Open Position





Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-27

Damper Type

Vertical Fire Damper

Damper Size

10x6

Damper Manufacturer

Greenheck

Damper Model #

FD150VA

Fusible Link Temperature

165 Degrees

Access Door Size

9x6

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-28

Damper Type

Vertical Fire Damper

Damper Size

8"

Damper Manufacturer

Greenheck

Damper Model #

FD150VA

Fusible Link Temperature

165 Degrees

Access Door Size

12x8

Pass / Fail / Abandoned

Pass

Comments / Corrections


None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-29

Damper Type

Vertical Fire Damper

Damper Size

14x8

Damper Manufacturer

Greenheck

Damper Model #

FD150VA

Fusible Link Temperature

165 Degrees

Access Door Size

8x7

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-30

Damper Type

Vertical Fire Damper

Damper Size

14x6

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

10x10

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-31

Damper Type

Vertical Fire Damper

Damper Size

12x6

Damper Manufacturer

Greenheck

Damper Model #

FD150VA

Fusible Link Temperature

165 Degrees

Access Door Size

10x10

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-32

Damper Type

Vertical Fire Damper

Damper Size

16x10

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

9x9

Pass / Fail / Abandoned

Pass

Comments / Corrections

None



Picture of Damper in Closed Position



Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-11-02

Facility Location

Bedford City Jail

Damper Location

2nd Floor Corridor

Inspector Name

Larry Coreno

Damper I.D. #

FD-33

Damper Type

Vertical Fire Damper

Damper Size

16x6

Damper Manufacturer

Greenheck

Damper Model #

FD150AV

Fusible Link Temperature

165 Degrees

Access Door Size

12x12

Pass / Fail / Abandoned

Pass

Comments / Corrections


None

Picture of Damper in Open Position





Picture of Damper I.D. Label



883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





<u>Fire / Smoke / Fire & Smoke Damper</u> <u>Composite Inspection Report</u>

	FD/SD/FSD	<u>I.D.#</u>	<u>Size</u>	Manufacturer	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1	FD	FD 1	12×6	Greenheck	FD150AV	Pass	Pass	None
2	FD	FD 2	34×10	Greenheck	FD150AV	Pass	Pass	None
3	FD	FD 3	32×14	Greenheck	FD150AV	Pass	Pass	None
4	FD	FD4	32×12	Greenheck	FD150AV	Pass	Pass	None
5	FD	FD 5	30×10	Greenheck	FD150AV	Pass	Pass	None
6	FD	FD 6	18×12	Greenheck	FD150AV	Pass	Pass	None
7	FD	FD7	18×12	Greenheck	FD150AV	Pass	Pass	None
8	FD	FD8	10×6	Greenheck	FD150AV	Pass	Pass	None
9	FD	FD9	18×8	Greenheck	FD150AV	Pass	Pass	None
10	FD	FD10	22×14	Greenheck	FD150AV	Pass	Pass	None
11	FD	FD 11	24×10	Greenheck	FD150AV	Pass	Pass	None
12	FD	FD 12	12×6	Greenheck	FD150AV	Pass	Pass	None
13	FD	FD 13	34×10	Greenheck	FD150AV	Pass	Pass	None
14	FD	FD 14	34×10	Greenheck	FD150AV	Pass	Pass	None
15	FD	FD 15	28×12	Greenheck	FD150AV	Pass	Pass	None
16	FD	FD 16	28×12	Greenheck	FD150AV	Pass	Pass	None
17	FD	FD 17	12×8	Greenheck	FD150AV	Pass	Pass	None
18	FD	FD 18	14×10	Greenheck	FD150AV	Pass	Pass	None
19	FD	FD 19	18×12	Greenheck	FD150AV	Pass	Pass	None
20	FD	FD 20	28×12	Greenheck	FD150AV	Pass	Pass	None

<u>Inspector:</u> Dan Tulcewicz/ Larry Coreno

<u>Inspection Dates:</u>

Dan Tulcewicz/ Larry Coreno SA = Supply Air FD = Fire DamperNovember 2 2022 RA = Return Air SD = Smoke Damper

Facility: Bedford Jail EA = Exhaust Air FSD = Fire Smoke Damper

883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





Report Date: December 1, 2022

<u>Project</u>: Bedford jail

Inspector(s):

- Julianne Gue, Certified Technician
- Dan Tulcewicz

Inspection and Test Date(s):

• November 2, 2022

Duct Fabricators, Inc. "Fire Safety Division" inspected thirty-four dampers for proper installation. The dampers were then tested and photographed in the "open" and "closed" positions to confirm that they were functioning as designed. Any dampers that have performed unsatisfactorily have been corrected.

NOTES: NFPA 80 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. At a minimum, dampers shall be visually inspected every two years and functionally inspected every four years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





<u>Fire / Smoke / Fire & Smoke Damper</u> <u>Composite Inspection Report</u>

FD = Fire Damper

	FD/SD/FSD	<u>I.D.#</u>	<u>Size</u>	Manufacturer	Model	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
21	FD	FD 21	28X12	Greenheck	FD150AH	Pass	Pass	None
22	FD	FD 22	28X1	Greenheck	FD150AH	Pass	Pass	None
23	FD	FD 23	30X14	Greenheck	FD150AH	Pass	Pass	None
24	FD	FD 24	18×10	Greenheck	FD150AV	Pass	Pass	None
25	FD	FD 25	20X16	Greenheck	FD150AV	Pass	Pass	None
26	FD	FD 26	26X10	Greenheck	FD150AV	Pass	Pass	None
27	FD	FD 27	10X6	Greenheck	FD150AV	Pass	Pass	None
28	FD	FD 28	10X6	Greenheck	FD150AV	Pass	Pass	None
29	FD	FD19	9X6	Greenheck	FD150AV	Pass	Pass	None
30	FD	FD 29	18X8	Greenheck	FD150AV	Pass	Pass	None
31	FD	FD 30	14X8	Greenheck	FD150AV	Pass	Pass	None
32	FD	FD31	14X6	Greenheck	FD150AV	Pass	Pass	None
33	FD	FD 32	19X10	Greenheck	FD150AV	Pass	Pass	None
34	FD	FD 33	16X6	Greenheck	FD150AV	Pass	Pass	None
35	FD	FD 34	24x6	Nailer	D-124-12W	Pass	Pass	<u>None</u>

<u>Inspector:</u> Dan Tulcewicz Larry Coreno

Inspection Dates:

11-Nov-22 RA = Return Air SD = Smoke Damper

SA = Supply Air

Facility: Bedford jail EA = Exhaust Air FSD = Fire Smoke Damper