

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	P1-EX1	14x6	Air Balance	Unkown	Pass	N/A	None
FD	P1-EX2	60x12	Air Balance	Unkown	Pass	N/A	None
FD	P1-EX3	120x7	Air Balance	Unkown	Pass	N/A	None
FD	P1-EX4	108x8	Air Balance	Unkown	Pass	N/A	None
FD	P1-FD R1	70x14	Air Balance	Unkown	Pass	N/A	None
FD	P1-FD R2	70x14	Air Balance	Unkown	Pass	N/A	None
FD	P1-FD S1	96x30	Air Balance	Unkown	Pass	N/A	None
FD	P2-FD S1	26x12	Air Balance	Unkown	Pass	N/A	None
FD	P2-FD 1	24x24	Air Balance	Unkown	Pass	N/A	None
FD	P2-FD2	24x24	Air Balance	Unkown	Pass	N/A	None

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: 27-Dec-22  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1	FD	1FL-FD N Return	60x12	Air Balance	Unknown	Pass	N/A	None
2	SD	1FL-SD N Return	60x12	Air Balance	Unknown	Pass	N/A	Zone NR
3	SD	1FL-SD1 North	8" R	Air Balance	Unknown	Pass	N/A	Zone 1
4	SD	1FL-SD2 North	8" R	Air Balance	Unknown	Pass	N/A	Zone 1
5	SD	1FL-SD3 North	11" R	Air Balance	Unknown	Pass	N/A	Zone 3
6	SD	1FL-SD4 North	10" R	Air Balance	Unknown	Pass	N/A	Zone 6
7	SD	1FL-SD5 North	8" R	Air Balance	Unknown	Pass	N/A	Zone 1
8	SD	1FL-SD S Return	60x12	Air Balance	Unknown	Pass	N/A	Zone SR
9	SD	1FL-SD1 South	14" R	Air Balance	Unknown	Pass	N/A	Zone 2
10	SD	1FL-SD2 South	13" R	Air Balance	Unknown	Pass	N/A	Zone 1
11	SD	1FL-SD3 South	11" R	Air Balance	Unknown	Pass	N/A	Zone 4
12	SD	1FLFD4 South	12x8	Air Balance	Unknown	Pass	N/A	None

Inspector: Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 1-Mar-23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
13	FD	2FL-FD N Return	60x12	Air Balance	Unknown	Pass	N/A	Added access in shaft
14	SD	2FL-SD N Return	60x12	Air Balance	Unknown	Pass	N/A	Zone NR
15	FD	2FL-FD1 North	12x10	Air Balance	Unknown	Pass	N/A	None
16	FD	2FL-FD2 North	12" R	Air Balance	Unknown	Pass	N/A	None
17	SD	2FL-SD2 North	12" R	Air Balance	Unknown	Pass	N/A	Zone 2
18	FD	2FL-FD3 North	13"	Air Balance	Unknown	Pass	N/A	None
19	SD	2FL-SD3 North	13"	Air Balance	Unknown	Pass	N/A	Zone 1
20	FD	2FL-FD4 North	9" R	Air Balance	Unknown	Pass	N/A	None
21	SD	2FL-SD4 North	9" R	Air Balance	Unknown	Pass	N/A	Zone 1
22	FD	2FL-FD5 North	10" R	Air Balance	Unknown	Pass	N/A	None
23	SD	2FL-SD5 North	10" R	Air Balance	Unknown	Pass	N/A	Zone 6
24	FD	2FL-FD6 North	10" R	Air Balance	Unknown	Pass	N/A	None
25	SD	2FL-SD6 North	10" R	Air Balance	Unknown	Pass	N/A	Zone 5
26	FD	2FL-FD7 North	7" R	Air Balance	Unknown	Pass	N/A	None
27	SD	2FL-SD7 North	7" R	Air Balance	Unknown	Pass	N/A	Zone 9
28	FD	2FL-FD8 North	9" R	Air Balance	Unknown	Pass	N/A	None
29	SD	2FL-SD8 North	9" R	Air Balance	Unknown	Pass	N/A	Zone 6

Inspector: Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 12/21/22, 2/27/23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
30	FD	2FL-FD1 South	15" Round	Air Balance	Unknown	Pass	N/A	None
31	SD	2FL-SD1 South	15" Round	Air Balance	Unknown	Pass	N/A	Zone 4
32	FD	2FL-FD2 South	13" Round	Air Balance	Unknown	Pass	N/A	None
33	SD	2FL-SD2 South	13" Round	Air Balance	Unknown	Pass	N/A	zone 1
34	FD	2FL-FD3 South	12" Round	Air Balance	Unknown	Pass	N/A	None
35	SD	2FL-SD3 South	12" Round	Air Balance	Unknown	Pass	N/A	Zone 3
36	FD	2FL-FD4 South	8" Round	Air Balance	Unknown	Pass	N/A	None
37	SD	2FL-SD4 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
38	FD	2FL-FD5 South	9" Round	Air Balance	Unknown	Pass	N/A	None
39	SD	2FL-SD5 South	9" Round	Air Balance	Unknown	Pass	N/A	Zone 7
40	FD	2FL-FD6 South	8" Round	Air Balance	Unknown	Pass	N/A	None
41	SD	2FL-SD6 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9
42	FD	2FL-FD7 South	12" Round	Air Balance	Unknown	Pass	N/A	None
43	SD	2FL-SD7 South	12" Round	Air Balance	Unknown	Pass	N/A	Zone 8

Inspector: Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 28-Feb-23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	2FL-FD1 N Shaft	14x6	Air Balance	Unknown	Pass	N/A	None
FD	2FL-FD2 N Shaft	10" R	Air Balance	Unknown	Pass	N/A	None
FD	2FL-FD3 N Shaft	15" R	Air Balance	Unknown	Pass	N/A	None
FD	2FL-FD4 N Shaft	11" R	Air Balance	Unknown	Pass	N/A	None
FD	2FL-FD5 N Shaft	16x8	Air Balance	Unknown	Pass	N/A	None
FD	2FL-FD1 S Shaft	12x6	Air Balance	Unknown	Pass	N/A	None
FD	2FL-FD2 S Shaft	11" R	Air Balance	Unknown	Pass	N/A	None
FD	2FL-FD3 S Shaft	18" R	Air Balance	Unknown	Pass	N/A	None
FD	2FL-FD4 S Shaft	14" R	Air Balance	Unknown	Pass	N/A	None
FD	2FL-FD Return S Shaft	60x12	Air Balance	Unknown	Pass	N/A	None

Inspector: Julie Gue/ D Tulcewicz/ L Coreno  
Inspection Dates: 12/21/2022, 2/27/23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
54	FD	3FL-FD N Rturn	60x12	Air Balance	Unknown	Pass	N/A	None
55	SD	3FL-SD N Rturn	60x12	Air Balance	Unknown	Pass	N/A	Zone NR
56	FD	3FL-FD 1 North	8" R	Ruskin	IBD20	Pass	N/A	None
57	FD	3FL-FD2 North	6" R	Ruskin	IBD20	Pass	N/A	None
58	FD	3FL-FD3 North	16x10	Air Balance	Unknown	Pass	N/A	None
59	FD	3FL-FD4 North	9" R	Air Balance	Unknown	Pass	N/A	None
60	SD	3FL-SD4 North	9" R	Air Balance	Unknown	Pass	N/A	Zone 6
61	FD	3FL-FD5 North	18x12	Ruskin	IBD20	Pass	N/A	None
62	FD	3FL-FD6 North	18x12	Ruskin	IBD20	Pass	N/A	None
63	FD	3FL-FD7 North	12" R	Air Balance	Unknown	Pass	N/A	None
64	SD	3FL-SD7 North	12" R	Air Balance	Unknown	Pass	N/A	Zone 1
65	FD	3FL-FD8 North	8" R	Air Balance	Unknown	Pass	N/A	None
66	SD	3FLSD8 North	8" R	Air Balance	Unknown	Pass	N/A	Zone 1
67	FD	3FL-FD9 North	12x10	Ruskin	IBD20	Pass	N/A	None
68	FD	3FL-FD10 North	12x10	Ruskin	IBD20	Pass	N/A	None
69	FD	3FL-FD11 North	34x12	Ruskin	IBD20	Pass	N/A	None
70	FD	3FL-FD12 North	26x12	Ruskin	IBD20	Pass	N/A	None
71	FD	3FL-FD13 North	30x18	Ruskin	IBD20	Pass	N/A	None
72	FD	3FL-FD14 North	10" R	Ruskin	IBD20	Pass	N/A	None
73	FD	3FL-FD15 North	8" R	Ruskin	IBD20	Pass	N/A	None

Inspector: Julianne Gue/D Tulcewicz  
Inspection Dates: 1/10/23, 2/28/23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
79	FD	3FL-FD S Return	60x12	Air Balance	Unknown	Pass	N/A	None
80	SD	3FL-SD S Return	60x12	Air Balance	Unknown	Pass	N/A	None
81	FD	3FL-FD1 South	10x6	Air Balance	Unknown	Pass	N/A	None
82	FD	3FL-FD2 South	16" R	Air Balance	Unknown	Pass	N/A	None
83	SD	3FL-SD2 South	16" R	Air Balance	Unknown	Pass	N/A	Zone 2
84	FD	3FL-FD3South	12" R	Air Balance	Unknown	Pass	N/A	None
85	SD	3FL-SD3South	12" R	Air Balance	Unknown	Pass	N/A	Zone GA1
86	FD	3FL-FD4 South	12" R	Air Balance	Unknown	Pass	N/A	None
87	SD	3FL-SD4 South	12" R	Air Balance	Unknown	Pass	N/A	Zone G3S
88	FD	3FL-FD5South	14x10	Air Balance	Unknown	Pass	N/A	None
89	FD	3FL-FD7 South	8" R	Air Balance	Unknown	Pass	N/A	None
90	SD	3FLSD7 South	8" R	Air Balance	Unknown	Pass	N/A	Zone 5
91	FD	3FL-FD8 South	13" R	Air Balance	Unknown	Pass	N/A	none
92	SD	3FL-FD8 South	13" R	Air Balance	Unknown	Pass	N/A	Zone 4
93	FSD	3FL-FSD1 South	10" R	Ruskin	Unknown	Pass	N/A	Zone 2

Inspector: Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 28-Feb-23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
94	FD	4FL-FD N Return	60x12	Air Balance	Unknown	Pass	N/A	None
95	SD	4FL-SD N Return	60x12	Air Balance	Unknown	Pass	N/A	Zone NR
96	FD	4FL-FD1 North	12" R	Air Balance	Unknown	Pass	N/A	None
97	SD	4FL-SD 1 North	12" R	Air Balance	Unknown	Pass	N/A	Zone 5
98	FD	4FL-FD2 North	9" R	Air Balance	Unknown	Pass	N/A	None
99	SD	4FL-SD2 North	9" R	Air Balance	Unknown	Pass	N/A	Zone 6
100	FD	4FL-FD3 North	20x10	Air Balance	Unknown	Pass	N/A	None
101	FD	4FL-FD4 North	8" R	Air Balance	Unknown	Pass	N/A	None
102	SD	4FL-SD4 North	8" R	Air Balance	Unknown	Pass	N/A	Zone 7
103	FD	4FL-FD5 North	11" R	Air Balance	Unknown	Pass	N/A	None
104	SD	4FL-SD5 North	11" R	Air Balance	Unknown	Pass	N/A	Zone 7
105	FD	4FL-FD6 North	11" R	Air Balance	Unknown	Pass	N/A	None
106	SD	4FL-SD6 North	11" R	Air Balance	Unknown	Pass	N/A	Zone 8
107	FD	4FL-FD7 North	10x8	Air Balance	Unknown	Pass	N/A	None
108	FD	4FL-FD8 North	24x15	Air Balance	Unknown	Pass	N/A	None

Inspector: Julie Gue /D Tulcewicz  
Inspection Dates: 16-Feb-23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
119	FD	6FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
120	SD	6FL-SD N Return	60X12	Air Balance	Unknown	Pass	Pass	Zone NR
121	FD	6FL-FD S Return	60X12	Air Balance	Unknown	Pass	Pass	None
122	SD	6FL-SD S Return	60X12	Air Balance	Unknown	Pass	Pass	Zone SR
123	FD	6FL-FD1 North	12" Round	Air Balance	Unknown	Pass	Pass	None
124	SD	6FL-SD1 North	12" Round	Air Balance	Unknown	Pass	Pass	Zone 7
125	FD	6FL-FD2 North	8" Round	Air Balance	Unknown	Pass	Pass	None
126	SD	6FL-SD2 North	8" Round	Air Balance	Unknown	Pass	Pass	Zone 1
127	FD	6FL-FD3 North	8" Round	Air Balance	Unknown	Pass	Pass	None
128	SD	6FL-SD3 North	8" Round	Air Balance	Unknown	Pass	Pass	Zone 1
129	FD	6FL-FD4 North	20X10	Air Balance	Unknown	Pass	Pass	None
130	FD	6FL-FD5 North	8" Round	Air Balance	Unknown	Pass	Pass	None
131	SD	6FL-SD5 North	8" Round	Air Balance	Unknown	Pass	Pass	Zone 1
132	FD	6FL-FD6 North	12" Round	Air Balance	Unknown	Pass	Pass	None
133	SD	6FL-SD6 North	12" Round	Air Balance	Unknown	Pass	Pass	Zone 8
134	FD	6FL-FD7 North	9" Round	Air Balance	Unknown	Pass	Pass	None
135	SD	6FL-SD7 North	9" Round	Air Balance	Unknown	Pass	Pass	Zone 6
136	FD	6FL-FD8 North	10" Round	Air Balance	Unknown	Pass	Pass	None
137	SD	6FL-SD8 North	10" Round	Air Balance	Unknown	Pass	Pass	Zone 9
138	FSD	6FL-FSD1 North	16" Round	Ruskin	Unknown	Pass	Pass	Zone 2

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 2/15/2023  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
139	FSD	6FL-FSD1 South	12" Round	Ruskin	Unknown	Pass	N/A	Zone 3
140	FSD	6FL-FSD2 South	12" Round	Ruskin	Unknown	Pass	N/A	Zone 4
141	FD	6FL-FD1 South	8" Round	Air Balance	Unknown	Pass	N/A	None
142	SD	6FL-SD1 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
143	FD	6FL-FD2 South	8" Round	Air Balance	Unknown	Pass	N/A	None
144	SD	6FL-SD2 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
145	FD	6FL-FD3 South	12X8	Air Balance	Unknown	Pass	N/A	None
146	FD	6FL-FD4 South	8" Round	Air Balance	Unknown	Pass	N/A	None
147	SD	6FL-SD4 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
148	FD	6FL-FD5 South	10" Round	Air Balance	Unknown	Pass	N/A	None
149	SD	6FL-SD5 South	10" Round	Air Balance	Unknown	Pass	N/A	Zone 6
150	FD	6FL-FD6 South	12" Round	Air Balance	Unknown	Pass	N/A	None
151	SD	6FL-SD South	12" Round	Air Balance	Unknown	Pass	N/A	Zone 5

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 2/15/2023  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	6FL-FD1 Shaft 1	26x28	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD2 Shaft 1	23" R	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD3 Shaft 1	22" R	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD4 Shaft 1	25" R	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD5 Shaft 1	24x24	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD1 Shaft 2	26"R	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD2 Shaft 2	29 R	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FDRA Shaft 2	66X66	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD1 Shaft 3	66x66	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD2Shaft 3	28" R	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD3 Shaft 3	26" R	Ruskin	IBD2OW	Pass	N/A	None
FD	6FL-FD1 Shaft 4	36x34	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD2 Shaft 4	30" R	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD3 Shaft 4	30" R	Ruskin	IBD2OW	Pass	N/A	None
FD	6FL-FD4 Shaft 4	26x26	Air Balance	Unknown	Pass	N/A	None
FD	6FL-FD5 Shaft 4	22" R	Air Balance	Unknown	Pass	N/A	None

Inspector: Julie Gue/ D Tulcewicz  
Inspection Dates: 12/20/22, 12/21/22  
Facility: Justice Center Court Tower

SA = Supply Air  
 RA = Return Air  
 EA = Exhaust Air  
 FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
169	FD	7FL-FD1 North	13" Round	Air Balance	Unknown	Pass	N/A	None
170	SD	7FL-SD1 North	13" Round	Air Balance	Unknown	Pass	N/A	Zone 6
171	FD	7FL-FD2 North	8" Round	Air Balance	Unknown	Pass	N/A	None
172	SD	7FL-SD2 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
173	FD	7FL-FD3 North	8" Round	Air Balance	Unknown	Pass	N/A	None
174	SD	7FL-SD3 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
175	FD	7FL-FD4 North	11" Round	Air Balance	Unknown	Pass	N/A	None
176	SD	7FL-SD4 North	11" Round	Air Balance	Unknown	Pass	N/A	Zone 7
177	FD	7FL-FD5 North	16x8	Air Balance	Unknown	Pass	N/A	None
178	FD	7FL-FD6 North	8" Round	Air Balance	Unknown	Pass	N/A	None
179	SD	7FL-SD6 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
180	FD	7FL-FD7 North	11" Round	Air Balance	Unknown	Pass	N/A	None
181	SD	7FL-SD7 North	11" Round	Air Balance	Unknown	Pass	N/A	Zone
182	FD	7FL-FD8 North	12" Round	Air Balance	Unknown	Pass	N/A	None
183	SD	7FL-SD8 North	12" Round	Air Balance	Unknown	Pass	N/A	Zone8
184	FD	7FL-FD N Return	60x12	Air Balance	Unknown	Pass	N/A	None
185	SD	7FL-SD N Return	60x12	Air Balance	Unknown	Pass	N/A	Zone NR

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: 2/14/23, 2/15/23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
186	FSD	7FL-FSD1 South	14" Round	Air Balance	Unknown	Pass	N/A	Zone 2
187	FSD	7FL-FSD2 South	13" Round	Air Balance	Unknown	Pass	N/A	Zone 4
188	FD	7FL-FD1 South	14x8	Air Balance	Unknown	Pass	N/A	None
189	FD	7FL-FD2 South	8" Round	Air Balance	Unknown	Pass	N/A	None
190	SD	7FL-SD2 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
191	FD	7FL-FD3 South	8" Round	Air Balance	Unknown	Pass	N/A	None
192	SD	7FL-SD3 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
193	FD	7FL-FD4 South	13" Round	Air Balance	Unknown	Pass	N/A	None
194	SD	7FL-SD South	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
195	FD	7FL-FD5 South	8" Round	Air Balance	Unknown	Pass	N/A	None
196	SD	7FL-SD5 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
197	FD	7FL-FD6 South	14X8	Air Balance	Unknown	Pass	N/A	None
198	FD	7FL-FD7 South	10" Round	Air Balance	Unknown	Pass	N/A	None
199	SD	7FL-SD7 South	10" Round	Air Balance	Unknown	Pass	N/A	Zone 5
200	FD	7FL-FD S Return	60x12	Air Balance	Unknown	Pass	N/A	None
201	SD	7FL-SD S Return	60x12	Air Balance	Unknown	Pass	N/A	Zone SR

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 2/14/23, 2/15/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
202	FD	8FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
203	SD	8FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
204	FD	8FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
205	SD	8FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
206	FD	8FL-FD1 North	8" Round	Air Balance	Unknown	Pass	N/A	None
207	SD	8FL-SD1 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
208	FD	8FL-FD2 North	16x10	Air Balance	Unknown	Pass	N/A	None
209	FD	8FL-FD3 North	9" Round	Air Balance	Unknown	Pass	N/A	None
210	SD	8FL-SD3 North	9" Round	Air Balance	Unknown	Pass	N/A	Zone 7
211	FD	8FL-FD4 North	8" Round	Air Balance	Unknown	Pass	N/A	None
212	SD	8FL-SD4 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
213	FD	8FL- FD5 North	8" Round	Air Balance	Unknown	Pass	N/A	None
214	SD	8FL- SD5 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
215	FD	8FL-FD6 North	10" Round	Air Balance	Unknown	Pass	N/A	None
216	SD	8FL-SD6 North	10" Round	Air Balance	Unknown	Pass	N/A	Zone 6
217	FD	8FL-FD7 North	12x8	Air Balance	Unknown	Pass	N/A	None
218	FD	8FL-FD8 North	11" Round	Air Balance	Unknown	Pass	N/A	ABANDONED
219	SD	8FL-SD8 North	11" Round	Air Balance	Unknown	Pass	N/A	ABANDONED
220	FSD	8FL-FSD1 North	14" Round	Air Balance	Unknown	Pass	N/A	Zone 8

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 2/14/23 , 2/15/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
221	FSD	8FL-FSD2 North	11" Round	Ruskin	Unknown	Pass	N/A	Zone 9
222	FD	8FL-FD1 South	16x10	Air Balance	Unknown	Pass	N/A	None
223	FD	8FL-FD2 South	11" Round	Air Balance	Unknown	Pass	N/A	None
224	SD	8FL-SD2 South	11" Round	Air Balance	Unknown	Pass	N/A	Zone 2
225	FD	8FL-FD3 South	8" Round	Air Balance	Unknown	Pass	N/A	None
226	SD	8FL-SD3 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
227	FD	8FL-FD4 South	8" Round	Air Balance	Unknown	Pass	N/A	None
228	SD	8FL-SD4 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
229	FD	8FL-FD5 South	13" Round	Air Balance	Unknown	Pass	N/A	None
230	SD	8FL-SD5 South	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
231	FD	8FL-FD6 South	20x12	Air Balance	Unknown	Pass	N/A	None
232	FD	8FL-FD7 South	8" Round	Air Balance	Unknown	Pass	N/A	None
233	SD	8FL-SD7 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
234	FD	8FL-FD8 South	12" Round	Air Balance	Unknown	Pass	N/A	None
235	SD	8FL-SD8 South	12" Round	Air Balance	Unknown	Pass	N/A	Zone 4
236	FSD	8FL-FSD1 South	14" Round	Ruskin	Unknown	Pass	N/A	Zone 2
237	FSD	8FL-FSD2 South	14" Round	Ruskin	Unknown	Pass	N/A	Zone 4

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 2/14/23, 2/15/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
238	FD	9FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
239	SD	9FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
240	FD	9FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
241	SD	9FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
242	FD	9FL-FD1 North	10" Round	Air Balance	Unknown	Pass	N/A	None
243	SD	9FL-SD1 North	10" Round	Air Balance	Unknown	Pass	N/A	Zone 7
244	FD	9FL-FD2 North	8" Round	Air Balance	Unknown	Pass	N/A	None
245	SD	9FL-SD2 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
246	FD	9FL-FD3 North	14x8 Round	Air Balance	Unknown	Pass	N/A	None
247	FD	9FL-FD4 North	8" Round	Air Balance	Unknown	Pass	N/A	None
248	SD	9FL-SD4 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
249	FD	9FL-FD5 North	8" Round	Air Balance	Unknown	Pass	N/A	None
250	SD	9FL-SD5 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
251	FD	9FL-FD6 North	12" Round	Air Balance	Unknown	Pass	N/A	None
252	SD	9FL-SD6 North	12" Round	Air Balance	Unknown	Pass	N/A	Zone 6
253	FD	9FL-FD7 North	16x10	Air Balance	Unknown	Pass	N/A	None
254	FD	9FL-FD8 North	12" Round	Air Balance	Unknown	Pass	N/A	None
255	SD	9FL-SD8 North	12" Round	Air Balance	Unknown	Pass	N/A	Zone 8
256	FD	9FL-FD9 North	7" Round	Air Balance	Unknown	Pass	N/A	None
257	SD	9FL-SD9 North	7" Round	Air Balance	Unknown	Pass	N/A	Zone 9

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 2/9/23, 2/13/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
258	FSD	9FL-FSD1 North	14" Round	Ruskin	Unknown	Pass	N/A	Zone 6
259	FSD	9FL-FSD2 North	10" Round	Air Balance	Unknown	Pass	N/A	Zone 10
260	FD	9FL-FD1 South	16X10	Air Balance	Unknown	Pass	N/A	None
261	FD	9FL-FD2 South	8" Round	Air Balance	Unknown	Pass	N/A	None
262	SD	9FL-SD2 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
263	FD	9FL-FD3 South	8" Round	Air Balance	Unknown	Pass	N/A	None
264	SD	9FL-SD3 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
265	FD	9FL-FD4 South	13" Round	Air Balance	Unknown	Pass	N/A	None
266	SD	9FL-SD4 South	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
267	FD	9FL-FD5 South	8" Round	Air Balance	Unknown	Pass	N/A	None
268	SD	9FL-SD5 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
269	FD	9FL-FD6 South	11" Round	Air Balance	Unknown	Pass	N/A	None
270	SD	9FL-SD6 South	11" Round	Air Balance	Unknown	Pass	N/A	Zone 4
271	FD	9FL-FD7 South	9" Round	Air Balance	Unknown	Pass	N/A	None
272	SD	9FL-SD7 South	9" Round	Air Balance	Unknown	Pass	N/A	Zone 10
273	FSD	9FL-FSD1 South	14" Round	Ruskin	Unknown	Pass	N/A	Zone 2
274	FSD	9FL-FSD2 South	14" Round	Ruskin	Unknown	Pass	N/A	Zone 5

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 2/9/23, 2/13/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	10FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	10FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	10FL-FD1 North	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD1 North	11" Round	Air Balance	Unknown	Pass	N/A	Zone
FD	10FL-FD2 North	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD2 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	10FL-FD3 North	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD3 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	10FL-FD4 North	16x10	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD5 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	10FL-FD6 North	9" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD6 North	9" Round	Air Balance	Unknown	Pass	N/A	Zone 8
FD	10FL-FD7 North	12" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD7 North	12" Round	Air Balance	Unknown	Pass	N/A	Zone 10
FD	10FL-FD8 North	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD8 North	11" Round	Air Balance	Unknown	Pass	N/A	Zone 5

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 1/26/23, 2/9/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	10FL-FD1 South	16x12	Air Balance	Unknown	Pass	N/A	None
FD	10FL-FD2 South	14" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD2 South	14" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	10FL-FD3 South	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD3 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	10FL-FD4 South	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD4 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	10FL-FD5 South	10" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD5 South	10" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	10FL-FD6 South	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD6 South	8" Round	Air Balance	Unknown	Pass	N/A	none
FD	10FL-FD7 South	10" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD7 South	10" Round	Air Balance	Unknown	Pass	N/A	Zone 6
FD	10FL-FD8 South	10" Round	Air Balance	Unknown	Pass	N/A	None
SD	10FL-SD8 South	10" Round	Air Balance	Unknown	Pass	N/A	Zone 5
FSD	10FL-FSD1 South	16" Round	Ruskin	Unknown	Pass	N/A	Zone 3

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 1/26/23, 2/9/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	11FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	11FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	11FL-FD1 North	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD1 North	6" Round	Air Balance	Unknown	Pass	N/A	Zone 11
FD	11FL-FD2 North	9" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD2 North	9" Round	Air Balance	Unknown	Pass	N/A	Zone 10
FD	11FL-FD3 North	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD3 North	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	11FI-FD4 North	10x8	Air Balance	Unknown	Pass	N/A	None
FD	11FL-FD5 North	12" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD5 North	12" Round	Air Balance	Unknown	Pass	N/A	Zone 7
FD	11FL-FD6 North	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD6 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	11FL-FD7 North	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD7 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	11FL-FD8 North	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD8 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 2/1/23, 2/2/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	11FL-FD9 North	10" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD9 North	10" Round	Air Balance	Unknown	Pass	N/A	Zone8
FD	11FL-FD1 South	24X10	Air Balance	Unknown	Pass	N/A	None
FD	11FL-FD2 South	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD2 South	13" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	11FL-FD3 South	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD3 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	11FL-FD4 South	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD4 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	11FL-FD5 South	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD5 South	8" Round	Air Balance	Unknown	Pass	N/A	None
FD	11FL-FD6 South	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD6 South	12" Round	Air Balance	Unknown	Pass	N/A	Zone 4
FD	11FL-FD7 South	10" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD7 South	10" Round	Air Balance	Unknown	Pass	N/A	Zone 6
FD	11FL-FD8 South	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD8 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 11
FD	11FL-FD9 South	9" Round	Air Balance	Unknown	Pass	N/A	None
SD	11FL-SD9 South	9" Round	Air Balance	Unknown	Pass	N/A	None

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 2/1/23, 2/2/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	12FL-FD15 North	8" Round	Air Balance	Unknown	Pass	N/A	None
FSD	12FL-FSD1 North	16" Round	Unknown	Unknown	Pass	N/A	Zone 9
FSD	12FL-FSD2 North	14" Round	Ruskin	Unknown	Pass	N/A	Zone 9
FD	12FL-FD1 South	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD1 South	6" Round	Air Balance	Unknown	Pass	N/A	Zone 11
FD	12FL-FD2 South	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD2 South	13" Round	Air Balance	Unknown	Pass	N/A	Zone 4
FD	12FL-FD3 South	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD3 South	13" Round	Air Balance	Unknown	Pass	N/A	Zone 5
FD	12FL-FD4 South	10X8	Air Balance	Unknown	Pass	N/A	None
FD	12FL-FD5 South	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD5 South	13" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	12FL-FD6 South	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD6 South	6" Round	Air Balance	Unknown	Pass	N/A	None
FD	12FL-FD7 South	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD7 South	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	12FL-FD8 South	10" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD8 South	10" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	12FL-FD9 South	14X8	Air Balance	Unknown	Pass	N/A	None

Inspector: Julie Gue/Dan Tulcewicz/Larry Coreno  
Inspection Dates: 2/13/23,3/9/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	12FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	12FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	12FL-FD1 North	8" Round	Air Balance	Unknown	Pass	N/A	None
FD	12FL-FD2 North	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD2 North	13" Round	Air Balance	Unknown	Pass	N/A	Zone 10
FD	12FL-FD3 North	12" Round	Air Balance	Unknown	Abandoned	Abandoned	Abandoned
FD	12FL-FD4 North	6" Round	Ruskin	IBD2	Pass	N/A	None
FD	12FL-FD5 North	36X14	Ruskin	DIBD 60	Pass	N/A	None
FD	12FL-FD6 North	10X8	Air Balance	Unknown	Pass	N/A	None
FD	12FL-FD8 North	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD8 North	13" Round	Air Balance	Unknown	Pass	N/A	Zone 6
FD	12FL-FD9 North	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD9 North	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	12FL-FD10 North	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	12FL-SD10 North	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	12FL-FD11 North	14X8	Air Balance	Unknown	Pass	N/A	None
FD	12FL-FD13 North	14" Round	Ruskin	DIBD2	Pass	N/A	None
FD	12FL-FD14 North	14" Round	Ruskin	IBD60	Pass	N/A	None

Inspector: Julie Gue/Dan Tulcewicz/Larry Coreno  
Inspection Dates: 2/13/23,3/9/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	13FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	13FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	13FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	13FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	13FL-FD1	12X6	Air Balance	Unknown	Pass	N/A	None
FD	13FL-FD2	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	13FL-SD2	13" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	13FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	13FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	13FL-FD4	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	13FL-SD4	8" Round	Air Balance	Unknown	Pass	N/A	Zone1
FD	13FL-FD5	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	13FL-SD5	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	13FL-FD6	16X6	Air Balance	Unknown	Pass	N/A	None
FD	13FL-FD7	8' Round	Air Balance	Unknown	Pass	N/A	None
SD	13FL-SD7	8' Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	13FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	13FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	13FL-FD9	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	13FL-SD9	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector:

Inspection Dates:

Facility:

Justice Center Court Tower

FD = Fire Damper

SD = Smoke Damper

FSD = Fire/Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	13FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	13FL-FD10	11" Round	Air Balance	Unknown	Pass	Pass	Zone 6
FD	13FL-FD11	14X10	Air Balance	Unknown	Pass	Pass	None
FD	13FL-FD12	13" Round	Air Balance	Unknown	Pass	Pass	None
SD	13FL-SD12	13" Round	Air Balance	Unknown	Pass	Pass	Zone 4
FD	13FL-FD13	8X6	Air Balance	Unknown	Pass	Pass	None
FD	13FL-FD14	20X10	Air Balance	Unknown	Pass	Pass	None
FD	13FL-FD15	8" Round	Air Balance	Unknown	Pass	Pass	None
SD	13FL-SD15	8" Round	Air Balance	Unknown	Pass	Pass	Zone 1
FD	13FL-FD16	13" Round	Air Balance	Unknown	Pass	Pass	None
SD	13FL-SD16	13" Round	Air Balance	Unknown	Pass	Pass	Zone 5
FD	13FL-FD17	13" Round	Air Balance	Unknown	Pass	Pass	None
SD	13FL-SD17	13" Round	Air Balance	Unknown	Pass	Pass	Zone 8
FD	13FL-FD18	13" Round	Air Balance	Unknown	Pass	Pass	None
SD	13FL-SD18	13" Round	Air Balance	Unknown	Pass	Pass	Zone 7
FD	13FL-FD19	8X6	Air Balance	Unknown	Pass	Pass	None
FD	13FL-FD20	20X10	Air Balance	Unknown	Pass	Pass	None
FD	13FL-FD21	8" Round	Air Balance	Unknown	Pass	Pass	None
SD	13FL-SD21	8" Round	Air Balance	Unknown	Pass	Pass	Zone 1
SD	13FL-SD22	8" Round	Air Balance	Unknown	Pass	Pass	Zone 9

Inspector:

Inspection Dates:

Facility:

Justice Center Court Tower

FD = Fire Damper

SD = Smoke Damper

FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	14FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	14FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	14FL-FD1	12X6	Air Balance	Unknown	Pass	N/A	None
FD	14FL-FD2	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD2	13" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	14FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	14FL-FD4	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD4	8" Round	Air Balance	Unknown	Pass	N/A	Zone1
FD	14FL-FD5	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD5	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	14FL-FD6	16X6	Air Balance	Unknown	Pass	N/A	None
FD	14FL-FD7	8' Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD7	8' Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	14FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	14FL-FD9	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD9	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector: J Gue/D Tulcewicz/L Coreno  
Inspection Dates: 2/7/23, 3/2/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	14FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	Zone 6
FD	14FL-FD11	8X16	Air Balance	Unknown	Pass	N/A	None
FD	14FL-FD12	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD12	13" Round	Air Balance	Unknown	Pass	N/A	Zone 4
FD	14FL-FD13	10X6	Air Balance	Unknown	Pass	N/A	None
FD	14FL-FD14	16X10	Air Balance	Unknown	Pass	N/A	None
FD	14FL-FD15	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD15	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	14FL-FD16	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD16	13" Round	Air Balance	Unknown	Pass	N/A	Zone 5
FD	14FL-FD17	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD17	13" Round	Air Balance	Unknown	Pass	N/A	Zone 8
FD	14FL-FD18	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD18	13" Round	Air Balance	Unknown	Pass	N/A	Zone 7
FD	14FL-FD19	8X6	Air Balance	Unknown	Pass	N/A	None
FD	14FL-FD20	20X10	Air Balance	Unknown	Pass	N/A	None
FD	14FL-FD21	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	14FL-SD21	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
SD	14FL-FSD22	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9

Inspector: J Gue/ D Tulcewicz/ L Coreno  
Inspection Dates: 2/7/23, 3/2/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	15FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	15FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	15FL-FD1	12X6	Air Balance	Unknown	Pass	N/A	None
FD	15FL-FD2	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD2	11" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	15FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	15FL-FD4	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD4	8" Round	Air Balance	Unknown	Pass	N/A	Zone1
FD	15FL-FD5	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD5	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	15FL-FD6	16X6	Air Balance	Unknown	Pass	N/A	None
FD	15FL-FD7	8' Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD7	8' Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	15FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	15FL-FD9	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD9	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector: J Gue/ D Tulcewicz/L Coreno  
Inspection Dates: 11/16/23, 2/6/23,3/6/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	15FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	Zone 6
FD	15FL-FD11	14X10	Air Balance	Unknown	Pass	N/A	None
FD	15FL-FD12	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD12	13" Round	Air Balance	Unknown	Pass	N/A	Zone 4
FD	15FL-FD13	10X6	Air Balance	Unknown	Pass	N/A	None
FD	15FL-FD14	16X10	Air Balance	Unknown	Pass	N/A	None
FD	15FL-FD15	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD15	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	15FL-FD16	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD16	13" Round	Air Balance	Unknown	Pass	N/A	Zone 5
FD	15FL-FD17	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD17	13" Round	Air Balance	Unknown	Pass	N/A	Zone9
FD	15FL-FD18	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD18	13" Round	Air Balance	Unknown	Pass	N/A	Zone 8
FD	15FL-FD19	8X6	Air Balance	Unknown	Pass	N/A	None
FD	15FL-FD20	10xX6	Air Balance	Unknown	Pass	N/A	None
FD	15FL-FD21	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	15FL-SD21	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector: J Gue/ D Tulcewicz/ L Coreno  
Inspection Dates: 11/16/22, 2/6/23,3/6/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	16FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	16FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	16FL-FD1	12X6	Air Balance	Unknown	Pass	N/A	None
FD	16FL-FD2	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD2	11" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	16FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	16FL-FD4	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD4	8" Round	Air Balance	Unknown	Pass	N/A	Zone1
FD	16FL-FD5	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD5	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	16FL-FD6	16X6	Air Balance	Unknown	Pass	N/A	None
FD	16FL-FD7	8' Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD7	8' Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	16FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	16FL-FD9	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD9	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector: J Gue, / D Tulcewicz  
Inspection Dates: 11/16/22, 1/19/23, 2/2/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	16FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	Zone 6
FD	16FL-FD11	14X10	Air Balance	Unknown	Pass	N/A	None
FD	16FL-FD12	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD12	13" Round	Air Balance	Unknown	Pass	N/A	Zone 4
FD	16FL-FD13	8X6	Air Balance	Unknown	Pass	N/A	None
FD	16FL-FD14	20X10	Air Balance	Unknown	Pass	N/A	None
FD	16FL-FD15	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD15	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	16FL-FD16	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD16	13" Round	Air Balance	Unknown	Pass	N/A	Zone 5
FD	16FL-FD17	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD17	13" Round	Air Balance	Unknown	Pass	N/A	Zone 8
FD	16FL-FD18	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD18	13" Round	Air Balance	Unknown	Pass	N/A	Zone 7
FD	16FL-FD19	8X6	Air Balance	Unknown	Pass	N/A	None
FD	16FL-FD20	20X10	Air Balance	Unknown	Pass	N/A	None
FD	16FL-FD21	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	16FL-SD21	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
SD	16FL-SD22	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9

Inspector: J Gue/ D Tulcewicz  
Inspection Dates: 11/16/22, 1/19/23, 2/2/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	17FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	17FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	17FL-FD1	12X6	Air Balance	Unknown	Pass	N/A	None
FD	17FL-FD2	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD2	11" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	17FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	17FL-FD4	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD4	8" Round	Air Balance	Unknown	Pass	N/A	Zone1
FD	17FL-FD5	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD5	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	17FL-FD6	16X6	Air Balance	Unknown	Pass	N/A	None
FD	17FL-FD7	8' Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD7	8' Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	17FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	17FL-FD9	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD9	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/15/22, 1/18/23, 2/1/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	17FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	Zone 6
FD	17FL-FD11	14X10	Air Balance	Unknown	Pass	N/A	None
FD	17FL-FD12	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD	13" Round	Air Balance	Unknown	Pass	N/A	Zone 4
FD	17FL-FD13	8X6	Air Balance	Unknown	Pass	N/A	None
FD	17FL-FD14	20X10	Air Balance	Unknown	Pass	N/A	None
FD	17FL-FD15	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD15	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	17FL-FD16	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD16	13" Round	Air Balance	Unknown	Pass	N/A	Zone 5
FD	17FL-FD17	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD17	13" Round	Air Balance	Unknown	Pass	N/A	Zone 8
FD	17FL-FD18	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD18	13" Round	Air Balance	Unknown	Pass	N/A	Zone 7
FD	17FL-FD19	8X6	Air Balance	Unknown	Pass	N/A	None
FD	17FL-FD20	20X10	Air Balance	Unknown	Pass	N/A	None
FD	17FL-FD21	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	17FL-SD21	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FSD	17FL-FSD22	8" Round	Ruskin	Unknown	Pass	N/A	Zone 9

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/15/22, 1/18/23, 2/1/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	18FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	18FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	18FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	18FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	18FL-FD1	12X6	Air Balance	Unknown	Pass	N/A	None
FD	18FL-FD2	11' Round	Air Balance	Unknown	Pass	N/A	None
SD	18FL-SD2	11' Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	18FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	18FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	18FL-FD4	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	18FL-SD4	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	18FL-FD5	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	18FL-SD5	13" Round	Air Balance	Unknown	Pass	N/A	Zone 5
FD	18FL-FD6	16X6	Air Balance	Unknown	Pass	N/A	None
FD	18FL-FD7	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	18FL-SD7	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	18FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	18FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	18FL-FD9	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	18FL-SD9	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/14/22, 1/18/23, 1/31/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	18FL-FD10	11" Round	Air Balance	Uknown	Pass	N/A	None
SD	18FL-SD10	11" Round	Air Balance	Uknown	Pass	N/A	Zone 6
FD	18FL-FD11	14X10	Air Balance	Uknown	Pass	N/A	None
FD	18FL-FD12	13" Round	Air Balance	Uknown	Pass	N/A	None
SD	18FL-SD12	13" Round	Air Balance	Uknown	Pass	N/A	Zone 4
FD	18FL-FD13	8X6	Air Balance	Uknown	Pass	N/A	None
FD	18FL-FD14	20X10	Air Balance	Uknown	Pass	N/A	None
FD	18FL-FD15	8" Round	Air Balance	Uknown	Pass	N/A	None
SD	18FL-SD15	8" Round	Air Balance	Uknown	Pass	N/A	Zone 1
FD	18FL-FD16	13" Round	Air Balance	Uknown	Pass	N/A	None
SD	18FL-SD16	13" Round	Air Balance	Uknown	Pass	N/A	Zone 5
FD	18FL-FD17	13" Round	Air Balance	Uknown	Pass	N/A	None
SD	18FL-SD17	13" Round	Air Balance	Uknown	Pass	N/A	Zone 8
FD	18FL-FD18	13" Round	Air Balance	Uknown	Pass	N/A	None
SD	18FL-SD18	13" Round	Air Balance	Uknown	Pass	N/A	Zone 7
FD	18FL-FD19	8X6	Air Balance	Uknown	Pass	N/A	None
FD	18FL-FD20	20X10	Air Balance	Uknown	Pass	N/A	None
FD	18FL-FD21	8" Round	Air Balance	Uknown	Pass	N/A	None
SD	18FL-SD21	8" Round	Air Balance	Uknown	Pass	N/A	Zone 1
FSD	18FL-FSD22	8" Round	Ruskin	Uknown	Pass	N/A	Zone 9

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/14/22, 1/18/23, 1/31/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	19FL-FD N Rturn	60x12	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD N Rturn	60x12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	19FL-FD N Rturn	60x12	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD N Rturn	60x12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	19FL-FD1	12X6	Air Balance	Unknown	Pass	N/A	None
FD	19FL-FD2	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD2	11" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	19FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	19FL-FD4	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD4	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	19FL-FD5	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD5	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	19FL-FD6	16X6	Air Balance	Unknown	Pass	N/A	None
FD	19FL-FD7	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD7	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	19FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	19FL-FD9	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD9	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/14/22, 1/14/23, 1/30/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	19FL-FD10	12" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD10	12" Round	Air Balance	Unknown	Pass	N/A	Zone 6
FD	19FL-FD11	14X10	Air Balance	Unknown	Pass	N/A	None
FD	19FL-FD12	13" Round	Air Balance	Unknown	Pass	N/A	None
FD	19FL-FD13	8X6	Air Balance	Unknown	Pass	N/A	None
FD	19FL-FD14	20X10	Air Balance	Unknown	Pass	N/A	None
FD	19FL-FD15	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD15	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	19FL-FD16	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD16	13" Round	Air Balance	Unknown	Pass	N/A	Zone 5
FD	19FLFD17	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD17	13" Round	Air Balance	Unknown	Pass	N/A	Zone 8
FD	19FL-FD18	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD18	13" Round	Air Balance	Unknown	Pass	N/A	Zone 7
FD	19FL-FD19	8X6	Air Balance	Unknown	Pass	N/A	None
FD	19FL-FD20	20X10	Air Balance	Unknown	Pass	N/A	None
FD	19FL-FD21	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	19FL-SD21	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
SD	19FL-SD22	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/14/22, 1/17/23, 1/30/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	20FL-FD10	12" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD10	12" Round	Air Balance	Unknown	Pass	N/A	Zone 6
FD	20FL-FD11	14X10	Air Balance	Unknown	Pass	N/A	None
FD	20FL-FD12	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL SD12	13" Round	Air Balance	Unknown	Pass	N/A	None
FD	20FL-FD13	8X6	Air Balance	Unknown	Pass	N/A	None
FD	20FL-FD14	20X10	Air Balance	Unknown	Pass	N/A	None
FD	20FL-FD15	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD15	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	20FL-FD16	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD16	13" Round	Air Balance	Unknown	Pass	N/A	Zone 5
FD	20FLFD17	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD17	13" Round	Air Balance	Unknown	Pass	N/A	Zone 8
FD	20FL-FD18	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD18	13" Round	Air Balance	Unknown	Pass	N/A	Zone 7
FD	20FL-FD19	8X6	Air Balance	Unknown	Pass	N/A	None
FD	20FL-FD20	20X10	Air Balance	Unknown	Pass	N/A	None
FD	20FL-FD21	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD21	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
SD	20FL-SD22	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/10/22, 1/17/23, 1/30/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	20FL-FD N Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD N Return	60X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	20FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	20FL-FD1	12X6	Air Balance	Unknown	Pass	N/A	None
FD	20FL-FD2	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD2	11" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	20FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	20FL-FD4	8' Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD4	8' Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	20FL-FD5	13' Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD5	13' Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	20FL-FD6	16x8	Air Balance	Unknown	Pass	N/A	none
FD	20FL-FD7	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-FD7	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	20FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	20FL-FD9	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	20FL-SD9	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/10/22, 1.17/23, 1/30/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	21FL North Return	60x12	Air Balance	Unknown	Pass	N/A	None
SD	21FL North Return	60x12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	21FL-FD1	12x6	Air Balance	Unknown	Pass	N/A	None
FD	21FL-FD2	11" R	Air Balance	Unknown	Pass	N/A	Changed Fusible Link
SD	21FL-SD2	11" R	Air Balance	Unknown	Pass	N/A	Zone 2
FD	21FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	Changed Fusible Link
SD	21FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	21FL-FD4	8" Round	Air Balance	Unknown	Pass	N/A	Changed Fusible Link
SD	21FLSD4	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	21FL-FD5	13" Round	Air Balance	Unknown	Pass	N/A	Changed Fusible Link
SD	21FL-SD5	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	21FL-FD6	16x6	Air Balance	Unknown	Pass	N/A	None
FD	21FL-FD7	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FLSD7	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	21FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	21FL-FD9	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD9	11" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	21FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD10	11" Round	Air Balance	Unknown	Pass	N/A	Zone 6

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: 11/9/22, 1/9/23, 1/26/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	21FL-FD11	14X10	Air Balance	Unknown	Pass	N/A	None
FD	21FL-FD12	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD12	13" Round	Air Balance	Unknown	Pass	N/A	Zone 4
FD	21FL-FD13	10X6	Air Balance	Unknown	Pass	N/A	None
FD	21FL-FD14	20X10	Air Balance	Unknown	Pass	N/A	None
FD	21FL-FD15	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD15	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	21FL-FD16	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD16	13" Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	21FL-FD17	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD17	13" Round	Air Balance	Unknown	Pass	N/A	Zone 8
FD	21FL-FD18	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD18	13" Round	Air Balance	Unknown	Pass	N/A	Zone 7
FD	21FL-FD19	8X6	Air Balance	Unknown	Pass	N/A	None
FD	21FL-FD20	20X10	Air Balance	Unknown	Pass	N/A	None
FD	21FL-FD21	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD21	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FSD	21FL-FSD22	8" Round	Ruskin	Unknown	Pass	N/A	Zone 5
FD	21FL-FD S Return	60X12	Air Balance	Unknown	Pass	N/A	None
SD	21FL-SD S Return	60X12	Air Balance	Unknown	Pass	N/A	Zone SR

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/9/22, 1/9/23, 1/26/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
	FD	22FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	None
	SD	22FL-SD10	11" Round	Air Balance	Unknown	Pass	N/A	Zone 6
	FD	22FL-FD12	8" Round	Air Balance	Unknown	Pass	N/A	None
	SD	22FL-SD12	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
	FD	22FL-FD13	16x10	Air Balance	Unknown	Pass	N/A	None
	FD	22FL-FD14	8x6	Air Balance	Unknown	Pass	N/A	None
	FD	22FL-FD15	13" Round	Air Balance	Unknown	Pass	N/A	None
	SD	22FL-SD15	13" Round	Air Balance	Unknown	Pass	N/A	Zone 4
	FD	22FL-FD16	13" Round	Air Balance	Unknown	Pass	N/A	None
	SD	22FL-SD16	13" Round	Air Balance	Unknown	Pass	N/A	Zone 5
	FD	22FL-FD17	8" Round	Air Balance	Unknown	Pass	N/A	None
	SD	22FL-SD17	8" Round	Air Balance	Unknown	Pass	N/A	Zone 10
	FD	22FL-FD18	8" Round	Air Balance	Unknown	Pass	N/A	None
	SD	22FL-SD18	8" Round	Air Balance	Unknown	Pass	N/A	Zone 10
	FD	22FL-FD19	16x10	Air Balance	Unknown	Pass	N/A	None
	FD	22FL-FD20	10x6	Air Balance	Unknown	Pass	N/A	None
	FD	22FL-FD21	13" Round	Air Balance	Unknown	Pass	N/A	None
	FD	22FL-FD22	8" Round	Air Balance	Unknown	Pass	N/A	None
	SD	22FL-SD22	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9
	FD	22FL-FD23	8" Round	Air Balance	Unknown	Pass	N/A	None

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/9/22, 1/9/23, 1/25/23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	22FL-FD N Return	60x12	Air Balance	Unknown	Pass	N/A	None
SD	22FL-SD N Return	60x12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	22FL-FD S Return	60x12	Air Balance	Unknown	Pass	N/A	None
SD	22FL-SD S Return	60x12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	22FL-FD1	12x6	Air Balance	Unknown	Pass	N/A	None
FD	22FL-FD2	11" Round	Air Balance	Unknown	Pass	N/A	None
SD	22FL-SD2	11" Round	Air Balance	Unknown	Pass	N/A	Zone 2
FD	22FL-FD3	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	22FL-SD3	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	22FL-FD4	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	22FL-SD4	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	22FL-FD5	13" Round	Air Balance	Unknown	Pass	N/A	None
SD	22FL-SD5	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
FD	22FL-FD6	16x6	Air Balance	Unknown	Pass	N/A	None
FD	22FL-FD7	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	22FL-SD7	8" Round	Air Balance	Unknown	Pass	N/A	Zone 9
FD	22FL-FD8	6" Round	Air Balance	Unknown	Pass	N/A	None
SD	22FL-SD8	6" Round	Air Balance	Unknown	Pass	N/A	Zone 1
FD	22FL-FD9	8" Round	Air Balance	Unknown	Pass	N/A	None
SD	22FL-SD9	8" Round	Air Balance	Unknown	Pass	N/A	Zone 1

Inspector:

Julie Gue/ D Tulcewicz

SA = Supply Air

FD = Fire Damper

Inspection Dates:

11/9/22, 1/16/23, 1/25/23

RA = Return Air

SD = Smoke Damper

Facility:

Justice Center Court Tower

EA = Exhaust Air

FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
787	FD	23FL-FD1	20X10	Air Balance	Unknown	Pass	N/A	None
788	FD	23FL-FD2	12" Round	Air Balance	Unknown	Pass	N/A	None
789	SD	23FL-SD2	12" Round	Air Balance	Unknown	Pass	N/A	Zone 2
790	FD	23FL-FD3	13" Round	Air Balance	Unknown	Pass	N/A	None
791	SD	23FL-SD3	13" Round	Air Balance	Unknown	Pass	N/A	Zone 2
792	FD	23FL-FD5	12x6	Air Balance	Unknown	Pass	N/A	None
793	FD	23FL-FD6	9" Round	Air Balance	Unknown	Pass	N/A	None
794	SD	23FL-SD6	9" Round	Air Balance	Unknown	Pass	N/A	Zone 5
795	FD	23FL-FD10	11" Round	Air Balance	Unknown	Pass	N/A	None
796	SD	23FL-SD10	11" Round	Air Balance	Unknown	Pass	N/A	Zone 6
797	FD	23FL-FD12	13" Round	Air Balance	Unknown	Pass	N/A	None
798	SD	23FL-SD12	13" Round	Air Balance	Unknown	Pass	N/A	Zone 3
799	FD	23FL-FD13	16x10	Air Balance	Unknown	Pass	N/A	None
800	FD	23FL-FD14	8.5x6.5	Ruskin	IBD2	Pass	N/A	None
801	FD	23FL-FD16	13" Round	Air Balance	Unknown	Pass	N/A	None
802	SD	23FL-SD16	13" Round	Air Balance	Unknown	Pass	N/A	Zone 4
803	FD	23FL-FD17	13" Round	Air Balance	Unknown	Pass	N/A	None
804	SD	23FL-SD17	13" Round	Air Balance	Unknown	Pass	N/A	Zone 8
805	FD	23FL-FD18	13" Round	Air Balance	Unknown	Pass	N/A	None
806	SD	23FL-SD18	13" Round	Air Balance	Unknown	Pass	N/A	Zone 7

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/8/22, 1/16/23, 1/25/23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	AC1-RA1	60X28	Air Balance	Unknown	Pass	N/A	None
FD	AC1-S1	16" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC1-S2	10" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC1-S3	12" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC1-S4	20" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC1-S5	24" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC1-S6	23" Round	Ruskin	DIBD20	Pass	N/A	None
FD	AC1-S7	16" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC1-S8	14" Round	Ruskin	DIBD20	Pass	N/A	None
FD	AC1-S9	20" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC1-S10	14" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC1-S11	15" Round	Ruskin	DIBD20	Pass	N/A	None
FD	AC1-S12	14" Round	Ruskin	DIBD20	Pass	N/A	None
FD	AC2-RA1	54X36	Air Balance	Unknown	Pass	N/A	None
FD	AC2-RA2	60x30	Air Balance	Unknown	Pass	N/A	None
FD	AC2-S1	36" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC2-S2	30" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC2-S3	14" Round	Ruskin	DIBD20	Pass	N/A	None
FD	AC2-S4	13" Round	Ruskin	DIBD20	Pass	N/A	None
FD	AC2-S	15" Round	Air Balance	Unknown	Pass	N/A	None

Inspector:

J Gue/ D Tulcewicz

Inspection Dates:

11/11/22, 12/6/23

Facility:

Justice Center Court Tower

FD = Fire Damper

SD = Smoke Damper

FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	AC2-S6	18" Round	Ruskin	DIBD20	Pass	N/A	None
FD	AC2-S7	12" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC2-S8	12" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC3-S1	23" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC6-S1	22" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC13-S1	23" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC14-S1	26" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC14-S2	26" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC14-S3	25" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC14-S4	27" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC14-R	66x66	Air Balance	Unknown	Pass	N/A	None
FD	AC15-RA1	66X66	Air Balance	Unknown	Pass	N/A	None
FD	AC15-S1	27" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC15-S2	25" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC15-S3	23" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC15-S4	13" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC16-S1	23" Round	Air Balance	Unknown	Pass	N/A	None
FD	AC24-RA1	38X38	Ruskin	IBD40	Pass	N/A	None
FD	AC24-S1	18X18	Ruskin	IBD40	Pass	N/A	None
FD	AC24-S2	36X18	Ruskin	IBD40	Pass	N/A	None

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/11/23, 12/6 23, 12/15/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	AC24-S	36X18	Ruskin	DIBD20	Pass	N/A	None
FD	EF1 FD1	45X35	Air Balance	Unknown	Pass	N/A	None
FD	EF1-FD2	18X10	Air Balance	Unknown	Pass	N/A	None
FD	EF-K West	38x36	Air Balance	Unknown	Pass	N/A	None
FD	EF2-K East	34X32	Ruskin	DIBD23	Pass	N/A	None
FD	EF2-5th Floor	24x24	Air Balance	Unknown	Pass	N/A	None
FD	EF2-24th floor	34x36	Air Balance	Unknown	Pass	N/A	None
FD	EF3-5th Floor	20x20	Air Balance	Unknown	Pass	N/A	None
FD	EF3-24th Floor	32X34	Air Balance	Unknown	Pass	N/A	None
FD	EF4-5th Floor	24X24	Air Balance	Unknown	Pass	N/A	None
FD	EF4-24th Floor	26X24	Air Balance	Unknown	Pass	N/A	None
FD	EF5-5TH Floor	24X24	Air Balance	Unknown	Pass	N/A	None
FD	EF5-24th Floor	34x35	Air Balance	Unknown	Pass	N/A	None
FD	Elevator relief 1	48x48	Air Balance	Unknown	Pass	N/A	None
FD	Elevator relief 2	48x48	Air Balance	Unknown	Pass	N/A	None
FD	5th FL NW Stair	48x24	Air Balance	Unknown	Pass	N/A	None
FD	5th FL SW Stair	48x24	Air Balance	Unknown	Pass	N/A	None
FD	5th FL NE Stair	48x24	Air Balance	Unknown	Pass	N/A	None
FD	5th FL SE Stair	48x24	Air Balance	Unknown	Pass	N/A	None
FD	24th NE Stair	48x24	Air Balance	Unknown	Pass	N/A	None
FD	24th NW Stair	48x24	Air Balance	Unknown	Pass	N/A	None

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 11/11/22, 12/6/23, 12/15/23  
Facility: Justice Center Court Tower

FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire/Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	24th SE Stair	48x24	Air Balance	Unknown	Pass	N/A	24FL
FD	24th SW Stair	48x24	Air Balance	Unknown	Pass	N/A	24FL
FD	I1-R1	36x16	Ruskin	IBD40	Pass	N/A	24FL
FD	I1-S1	22x10	Ruskin	IBD40	Pass	N/A	24FL
FD	I2-EX	18x16	Ruskin	IBD40	Pass	N/A	24FL
FD	I2-S1	22x10	Ruskin	IBD40	Pass	N/A	24FL
FD	I2-R1	36x16	Ruskin	IBD40	Pass	N/A	24FL
FD	JE-S1	30x30	Ruskin	IBD2	Pass	N/A	24FL
FD	JE-S2	16x16	Ruskin	IBD40	Pass	N/A	24FL
FD	JE-S3	30x22	Ruskin	IBD2	Pass	N/A	24FL
FD	JE-EX1	38x38	Ruskin	IBD2	Pass	N/A	24FL
FD	JE-TA1	48x30	Air Balance	Unknown	Pass	N/A	24FL
FD	JE-TA2	48x30	Air Balance	Unknown	Pass	N/A	24FL
FD	Kitchen S-Fan1	30x15	Unknown	Unknown	Pass	N/A	5FL
FD	MAU-2 East	30x24	Air Balance	Unknown	Pass	N/A	5FL
FD	MAU-2 West	36x26	Air Balance	Unknown	Pass	N/A	5FL
FD	506 Supply	30x24	Ruskin	IBD20	Pass	N/A	None
FD	506 Return	30x24	Ruskin	IBD20	Pass	N/A	None

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates:  
Facility: Justice Center Court Tower

SA = Supply Air  
 RA = Return Air  
 EA = Exhaust Air  
 FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
825	SD	Galleria 2FL-SD1	14" R	Air Balance	Unknown	Pass	N/A	Zone-4 Repairs
826	SD	Galleria 2FL-SD2	18x9	Air Balance	Unknown	Pass	N/A	Zone G3
827	SD	Galleria 2FL-SD3	22x12	Air Balance	Unknown	Pass	N/A	Zone G3
828	SD	Galleria 2FL-SD4	14" R	Air Balance	Unknown	Pass	N/A	Zone G3
829	SD	Galleria 2FL-SD5	16" R	Air Balance	Unknown	Pass	N/A	Zone G3
830	FD	Galleria 2FL-FD6	10x6	Air Balance	Unknown	Pass	N/A	None
831	SD	Galleria 2FL-SD6	17" R	Air Balance	Unknown	Pass	N/A	Zone G3
832	FD	Galleria 2FL-FD7	8" R	Air Balance	Unknown	Pass	N/A	None
833	FD	Galleria 2FL-FD8	18x9	Air Balance	Unknown	Pass	N/A	Changed Fusible Link
834	FD	Galleria 2FL-FD9	18x14	Air Balance	Unknown	Pass	N/A	None
835	FD	Galleria 2FL-FD10	22x12	Air Balance	Unknown	Pass	N/A	Changed Fusible Link
836	FD	Galleria 2FL-FD11	36x8	Air Balance	Unknown	Pass	N/A	None
837	FD	Galleria 2FL- FD12	14" R	Air Balance	Unknown	Pass	N/A	None
838	FD	Galleria 2FL-FD13	10x6	Air Balance	Unknown	Pass	N/A	None
839	FD	Galleria 2FL-FD N R1	54x12	Air Balance	Unknown	Pass	N/A	None
840	SD	Galleria 2FL-SD N R1	54x12	Air Balance	Unknown	Pass	N/A	Zone GNR
841	FD	Galleria 2FL-FD N R2	54x9	Air Balance	Unknown	Pass	N/A	None
842	SD	Galleria 2FL-SD N R2	54x9	Air Balance	Unknown	Pass	N/A	Zone NR
843	SD	Galleria 2 FL-SD S R	36x12	Air Balance	Unknown	Pass	N/A	Zone GSR
844	FD	Galleria 2 FL-FD S R	36x12	Air Balance	Unknown	Pass	N/A	None

Inspector: Julie Gue/ D Tulcewicz  
Inspection Dates: 21-Feb-23  
Facility: Justice Center Court Tower

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
FD	Galleria 3FL-FD NR	54X12	Air Balance	Unknown	Pass	N/A	None
SD	Galleria 3FL-SD NR	54X12	Air Balance	Unknown	Pass	N/A	Zone NR
FD	Galleria 3FL-FD SR	36X12	Air Balance	Unknown	Pass	N/A	None
SD	Galleria 3FL-SD SR	36X12	Air Balance	Unknown	Pass	N/A	Zone SR
FD	Galleria 3FL-FD1	15" R	Air Balance	Unknown	Pass	N/A	None
SD	Galleria 3FL-SD1	8" R	Air Balance	Unknown	Pass	N/A	None
FD	Galleria 3FL-FD2	44x10	Air Balance	Unknown	Pass	N/A	None
SD	Galleria 3FL-SD2	9" R	Air Balance	Unknown	Pass	N/A	Zone 11
SD	Galleria 3FL-SD3	16X12	Air Balance	Unknown	Pass	N/A	None
FD	Galleria 3FL-FD3	24X14	Air Balance	Unknown	Pass	N/A	None
FD	Galleria 3FL-FD4	10" R	Air Balance	Unknown	Pass	N/A	None
SD	Galleria 3FL-SD4	12X12	Air Balance	Unknown	Pass	N/A	Zone 12.
SD	Galleria 3FL-SD5-	12" R	Air Balance	Unknown	Pass	N/A	None
SD	Galleria 3FL-SD6	14X12	Air Balance	Unknown	Pass	N/A	Zone 6
SD	Galleria 3FL-SD7	12" R	Air Balance	Unknown	Pass	N/A	Zone 6
SD	Galleria 3FL-SD8	12" R	Air Balance	Unknown	Pass	N/A	Zone 5
SD	Galleria 3FL-SD9	10" R	Air Balance	Unknown	Pass	N/A	None

Inspector: Julie Gue/ D Tulcewicz  
Inspection Dates: 22-Feb-23  
Facility: Justice Center Court Tower

SA = Supply Air  
 RA = Return Air  
 EA = Exhaust Air  
 FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire Smoke Damper





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

1FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

North Corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

1FL-FD North Return

### Damper Type

Vertical Fire Damper

### Damper Size

60"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10"x23"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

1FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"x23"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

South Corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

1FL-SD South Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

23"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

1FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

South Corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

1FL-SD1 South

### Damper Type

Vertical Smoke Damper

### Damper Size

14" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

9"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

1FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

1FL-SD2 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

North Corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

1FL-SD3 North

### Damper Type

Vertical Smoke Damper

### Damper Size

11" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

7"x4"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

1FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

1FL-SD4 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

1FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-27

### Facility Location

Justice Center Court Towers

### Damper Location

2FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

2FL FD South Return

### Damper Type

Vertical Fire Damper

### Damper Size

60"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

2nd floor North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL- FD1 North Shaft

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14"x 6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

2nd floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL- FD1 South Shaft

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Second floor shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL FD2 South Shaft

**Damper Type**

Horizontal Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2nd floor shaft south

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL South Shaft FD3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x7"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL South Shaft FD4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2nd floor South Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL South Shaft Return

**Damper Type**

Horizontal Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD North return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

22x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"x10"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

15"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-27

### Facility Location

Justice Center Court Towers

### Damper Location

North Corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

2FL-FD2 North

### Damper Type

Vertical Fire Damper

### Damper Size

12" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Second floor shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD2 North shaft

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD3 North shaft

**Damper Type**

Horizontal Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x9"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-27

### Facility Location

Justice Center Court Towers

### Damper Location

North Corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

2FL-FD4 North

### Damper Type

Vertical Fire Damper

### Damper Size

9" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD4 North shaft

**Damper Type**

Horizontal Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-27

### Facility Location

Justice Center Court Towers

### Damper Location

2FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

2FL-FD4 South

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD5 North shaft

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-27

### Facility Location

Justice Center Court Towers

### Damper Location

2FL North

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

2FL-FD6 North

### Damper Type

Vertical Fire Damper

### Damper Size

10" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-27

### Facility Location

Justice Center Court Towers

### Damper Location

2FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

2FL-FD6 South

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

7" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x7"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

9"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-21

### Facility Location

Justice Center Court Towers

### Damper Location

North shaft

### Inspector Name

Julie Gue

### Damper I.D. #

2FL-SD North Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

22x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-27

### Facility Location

Justice Center Court Towers

### Damper Location

2FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

2FL-SD1 South

### Damper Type

Vertical Smoke Damper

### Damper Size

15"Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6"Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD1 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD2 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12"x9"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-27

### Facility Location

Justice Center Court Towers

### Damper Location

2FL North

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

2FL-SD4 North

### Damper Type

Vertical Smoke Damper

### Damper Size

9" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-27

### Facility Location

Justice Center Court Towers

### Damper Location

2FL North

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

2FL-SD5 North

### Damper Type

Vertical Smoke Damper

### Damper Size

10" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

9"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD6 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD7 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

7" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12"x7"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD7 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

2FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

2FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-FD South Return

### Damper Type

Vertical Fire Damper

### Damper Size

60"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x22"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Ibd

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

10"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-10

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

3FL-FD2 North

### Damper Type

Vertical Fire Damper

### Damper Size

6" round

### Damper Manufacturer

Ruskin

### Damper Model #

Ibd

### Fusible Link Temperature

165 Degrees

### Access Door Size

6x9 Oval

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Grand jury

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Inspection Date:

1/10/23

Inspected By:

Julie Gue

Next Inspect. By:

1/10/24

Reference I.D.#:

3FL-FD3

North

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

FIRE SAFETY DIVISION

NEMI Certified HVAC Fire Life Safety Technicians

MEMBER

NFPA

## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-FD4 South

### Damper Type

Vertical Fire Damper

### Damper Size

12" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-FD5 South

### Damper Type

Vertical Fire Damper

### Damper Size

14"x10"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD8 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-FD9 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL North

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-FD10 North

### Damper Type

Vertical Fire Damper

### Damper Size

12"x10"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD20

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD11 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

34"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

NE Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-FD12 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

26x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Transfer

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL North

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-FD13 North

### Damper Type

Vertical Fire Damper

### Damper Size

30"x18"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD20

### Fusible Link Temperature

165 Degrees

### Access Door Size

Open

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD14 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD15 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL North

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-FD16 North

### Damper Type

Vertical Fire Damper

### Damper Size

12"x10"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD20

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL North

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-FD17 North

### Damper Type

Vertical Fire Damper

### Damper Size

10" Round

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

9"x6" Oval

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD18 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

26"x16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FD19 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

28"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL North

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-FD20 North

### Damper Type

Vertical Fire Damper

### Damper Size

26"x12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

Open

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-FSD1 South

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

16"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

36x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-SD2 South

### Damper Type

Vertical Smoke Damper

### Damper Size

16" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

12" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-SD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Unknown

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

3FL-SD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-28

### Facility Location

Justice Center Court Towers

### Damper Location

3FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

3FL-SD7 South

### Damper Type

Vertical Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-28

**Facility Location**

Justice Center Court Towers

**Damper Location**

3FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

3FL-SD8 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-16

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-FD North Return

### Damper Type

Vertical Fire Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

24x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Kitchen

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Kitchen

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Kitchen

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-16

### Facility Location

Justice Center Court Towers

### Damper Location

Jury room

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-FD4 North

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Jury room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Jury room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-16

### Facility Location

Justice Center Court Towers

### Damper Location

Jury room

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-FD8 North

### Damper Type

Vertical Fire Damper

### Damper Size

24 x15

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-16

### Facility Location

Justice Center Court Towers

### Damper Location

Jury room closet

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-FSD1 South

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

14" Round

### Damper Manufacturer

Ruskin

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

4"x4"

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-16

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-SD North Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

24x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Kitchen

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-SD1 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Kitchen

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-SD2 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-16

### Facility Location

Justice Center Court Towers

### Damper Location

Jury room

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-SD4 North

### Damper Type

Vertical Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Jury room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-SD5 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Jury room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-02

### Facility Location

Justice Center Court Towers

### Damper Location

5th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

5FL N.E Stairwell

### Damper Type

Vertical Fire Damper

### Damper Size

48x24

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

Grille access

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

5FL N.W Stairwell

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

5FL-EF4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

23x23

**Damper Manufacturer**

Ruskin

**Damper Model #**

DIBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

5FL-SE Stairwell

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

S.W Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

5FL-SW Stairwell

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-15

### Facility Location

Justice Center Court Towers

### Damper Location

Open staircase

### Inspector Name

Julie Gue

### Damper I.D. #

6FL-FD North Return

### Damper Type

Vertical Fire Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

Open duct

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

By men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD Return Shaft 2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

66x66

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding area

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD1 Shaft 1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26x28

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

22x22

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft 2

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD1 Shaft 2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

17x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft 3

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD1 Shaft 3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

28" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2 ow

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

13x15

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft 4

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD1 Shaft 4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

36x34

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x19

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD2 Shaft 1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

23" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x21

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft 2

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD2 Shaft 2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

29" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

17x19

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft 3

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD2 Shaft 3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

66x66

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

17x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD3 Shaft 1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

22" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x20

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft 3

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD3 Shaft 3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

lbd2ow

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

22x13

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft 4

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD3 Shaft 4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

lbd2ow

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft 4

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD4 Shaft 4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26x26

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft 1

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD4 Shaft 1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

25" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20W

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 59

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Copy room

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD5 Shaft 1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Shaft4

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD5 Shaft 4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

22" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11"x18"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-15

### Facility Location

Justice Center Court Towers

### Damper Location

Open staircase

### Inspector Name

Julie Gue

### Damper I.D. #

6FL-FSD1 North

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

10" Round

### Damper Manufacturer

Ruskin

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

5x3

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FSD1 South

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x9 oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-FSD2 South

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-15

### Facility Location

Justice Center Court Towers

### Damper Location

Open staircase

### Inspector Name

Julie Gue

### Damper I.D. #

6FL-SD North Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

Open duct

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding area

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD1 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD2 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 59

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Copy RM

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD5 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Women room

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD6 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD7 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

6FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Open staircase

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 10

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-14

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

7FL-FD2 South

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Across from RM 43

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Typing pool

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 43

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Open staircase

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-FSD1 South

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x4 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Open staircase

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-14

### Facility Location

Justice Center Court Towers

### Damper Location

RM 10

### Inspector Name

Julie Gue

### Damper I.D. #

7FL-SD South Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

Open

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD2 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD4 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11 Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

19" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 43

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Typing pool

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD7 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Open staircase

**Inspector Name**

Julie Gue

**Damper I.D. #**

7FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

By RM 51

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Property room

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM83

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-14

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

8FL-FD1 South

### Damper Type

Vertical Fire Damper

### Damper Size

16x10

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

14x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-14

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

8FL-FD6 South

### Damper Type

Vertical Fire Damper

### Damper Size

20x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

18x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Property room

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD8 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FD9 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM74

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FSD1 North

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

3x3

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FSD1 South

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x6 oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM79

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-FSD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-15

### Facility Location

Justice Center Court Towers

### Damper Location

Property room

### Inspector Name

Julie Gue

### Damper I.D. #

8FL-FSD2 South

### Damper Type

Vertical Fire Damper

### Damper Size

14" Round

### Damper Manufacturer

Ruskin

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

9x6 Oval

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-14

### Facility Location

Justice Center Court Towers

### Damper Location

RN51

### Inspector Name

Julie Gue

### Damper I.D. #

8FL-SD North Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

24x24

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Property room

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

16x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM83

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD2 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD4 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD5 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-14

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

8FL-SD6 North

### Damper Type

Vertical Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD7 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Property room

**Inspector Name**

Julie Gue

**Damper I.D. #**

8FL-SD8 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 63

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD North return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

20x20

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 64

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Kitchenette

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 58

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Across RM58

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Coffee bar

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Hall closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 73

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FSD1 North

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x4 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FSD1 South

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x4 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-FSD2 North

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x4 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 63

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

20x20

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-13

### Facility Location

Justice Center Court Towers

### Damper Location

RM 64

### Inspector Name

Julie Gue

### Damper I.D. #

9FL-SD South Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

14x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Kitchenette

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD2 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

7" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD4 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD5 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Across Rm 58

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Across RM 58

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD6 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Found closed.  
Has been opened .


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Hall closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD7 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 73

**Inspector Name**

Julie Gue

**Damper I.D. #**

9FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

4"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Dispute resolution

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Dispute resolution

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Dispute resolution

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-09

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

10FL-FD2 South

### Damper Type

Vertical Fire Damper

### Damper Size

14" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-09

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

10FL-FD3 South

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM23

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM25

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 77

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

West of RM77

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM28

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FD8 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-FSD1 South

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

fSd50

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD2 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD5 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-25

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM23

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 25

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD6 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 77

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD7 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

West of RM 77

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 28

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-SD8 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Dispute resolution

**Inspector Name**

Julie Gue

**Damper I.D. #**

10FL-South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x12

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-01

### Facility Location

Justice Center Court Towers

### Damper Location

Common pleas lobby

### Inspector Name

Julie Gue

### Damper I.D. #

11FL- FD South Return

### Damper Type

Vertical Fire Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

14x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

Common pleas lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL- SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

14"x14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

Common pleas lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

26x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-01

### Facility Location

Justice Center Court Towers

### Damper Location

Common pleas lobby

### Inspector Name

Julie Gue

### Damper I.D. #

11FL-FD1 North

### Damper Type

Vertical Fire Damper

### Damper Size

6" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

8"x5"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

Storage by 92a

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM77

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

Common pleas lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD8 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD9 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM #77

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-FD9 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

9"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

Common pleas lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

26x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

Common pleas lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

11x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD5 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD6 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD7 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-02-02

**Facility Location**  
Justice Center Court Towers

**Damper Location**  
RM 77

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
11FL-SD7 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
10x10

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

Common pleas lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD8 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

11x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

11FL-SD9 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-02

### Facility Location

Justice Center Court Towers

### Damper Location

11th South #77

### Inspector Name

Julie Gue

### Damper I.D. #

11FL-SD9 South

### Damper Type

Vertical Smoke Damper

### Damper Size

9"Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6"Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Court lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Court lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Court lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Court lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-09

### Facility Location

Justice Center Court Towers

### Damper Location

12FL Womens Restroom South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

12FL-FD2 South

### Damper Type

Vertical Fire Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

9" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

12FL Men's Restroom South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

12FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-20

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

12FL-FD4 South

### Damper Type

Vertical Fire Damper

### Damper Size

10x8

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

8x8

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

36"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

DIBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-20

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

12FL-FD6 North

### Damper Type

Vertical Fire Damper

### Damper Size

10x8

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

8x8

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-20

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

12FL-FD8 North

### Damper Type

Vertical Fire Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD8 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD9 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD9 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

14"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD10 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-08

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

12FL-FD11 North

### Damper Type

Vertical Fire Damper

### Damper Size

14"x8"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

8"x8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD13 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

DIBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD14 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Found closed/ reopened


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FD15 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-FSD2 North

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Court lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Court lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24"x14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

Court lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD1 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-09

### Facility Location

Justice Center Court Towers

### Damper Location

12FL Women's Restroom

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

12FL-SD2 South

### Damper Type

Vertical Smoke Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

9" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

12FL Men's Restroom

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

12FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD6 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD7 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-13

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD8 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD9 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

12FL-SD10 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

36"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

36"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-07

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

13FL-FD2

### Damper Type

Vertical Fire Damper

### Damper Size

11" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-07

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

13FL-FD3

### Damper Type

Vertical Fire Damper

### Damper Size

6" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

8"x5"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-08

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

13FL-FD6

### Damper Type

Vertical Fire Damper

### Damper Size

16"x 6"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-08

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

13FL-FD7

### Damper Type

Vertical Fire Damper

### Damper Size

8"Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7"Round

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

6"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench A

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

14"X10"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding A

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

10"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

13FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD-15

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

13FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding B

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding D

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD20

**Damper Type**

Vertical Fire Damper

**Damper Size**

20"x10"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FD21

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

13FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-FSD22

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

36"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

13FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

36"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-07

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

13FL-SD4

### Damper Type

Vertical Smoke Damper

### Damper Size

8"Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6"Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

,8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

13FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

13FL South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-07

### Facility Location

Justice Center Court Towers

### Damper Location

13FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

13FL-SD15

### Damper Type

Vertical Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-07

### Facility Location

Justice Center Court Towers

### Damper Location

13FL South

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

13FL-SD16

### Damper Type

Vertical Smoke Damper

### Damper Size

13"Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

9"Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

13FL North

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

13FL-SD21

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-02

### Facility Location

Justice Center Court Towers

### Damper Location

South Shaft

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

14 FL-SD South Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

24"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

14FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-02

### Facility Location

Justice Center Court Towers

### Damper Location

South Shaft

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

14FL-FD South Return

### Damper Type

Vertical Fire Damper

### Damper Size

60"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-07

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

14FL-FD1

### Damper Type

Vertical Fire Damper

### Damper Size

12"x6"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10"x10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-07

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

14FL-FD7

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

6"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

14FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"x16"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-06

### Facility Location

Justice Center Court Towers

### Damper Location

Bench A

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

14FL-FD12

### Damper Type

Vertical Fire Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-06

### Facility Location

Justice Center Court Towers

### Damper Location

Holding cell

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

14FL-FD13

### Damper Type

Vertical Fire Damper

### Damper Size

10"x6"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-06

### Facility Location

Justice Center Court Towers

### Damper Location

Holding cell C

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

14FL-FD14

### Damper Type

Vertical Fire Damper

### Damper Size

16"x10"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-02

### Facility Location

Justice Center Court Towers

### Damper Location

Bench C

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

14FL-FD15

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-02

### Facility Location

Justice Center Court Towers

### Damper Location

Bailiff B

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

14FL-FD18

### Damper Type

Vertical Fire Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding cell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

14FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-06

### Facility Location

Justice Center Court Towers

### Damper Location

Holding cell

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

14FL-FD20

### Damper Type

Vertical Fire Damper

### Damper Size

20"x10"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-02

### Facility Location

Justice Center Court Towers

### Damper Location

Bench D

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

14FL-FD21

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

14FL-FSD22

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSDR25

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

14FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-07

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

14FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench A

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

14FL-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

14FL-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

14FL-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

14FL-SD21

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

22x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-06

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

15FL-FD1

### Damper Type

Vertical Fire Damper

### Damper Size

18"x10"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

16"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-06

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

15FL-FD9

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench A

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

14"x10"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding A

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding C

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding B

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding D

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-FD20

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-FD21

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-FD22

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-FD23

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-06

### Facility Location

Justice Center Court Towers

### Damper Location

North Shaft

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

15FL-SD North Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

22"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

JCI is aware 15 FL panel is down all smokes will be closed

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Panel down

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Panel down


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Panel down

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Panel down

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Panel down

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Panel down


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Panel down JCI will repair

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

15FL-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-SD21

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-SD22

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

15FL-SD23

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-02

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

16FL-FD1

### Damper Type

Vertical Fire Damper

### Damper Size

12"x6"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10"x10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-02

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

16FL-FD2

### Damper Type

Vertical Fire Damper

### Damper Size

11"Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

9"Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-02

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

16FL-FD9

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding A

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding C

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding B

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding D

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-FD20

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-19

### Facility Location

Justice Center Court Towers

### Damper Location

South Shaft

### Inspector Name

Julie Gue

### Damper I.D. #

16FL-FSD22

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" round

### Damper Manufacturer

Ruskin

### Damper Model #

FSDR25

### Fusible Link Temperature

165 Degrees

### Access Door Size

4x6 oval

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Advanced Air

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

13" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

16FL-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-01

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

17FL-FD3

### Damper Type

Vertical Fire Damper

### Damper Size

6" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

8"x5"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-01

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

17FL-FD4

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-01

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

17FL-FD8

### Damper Type

Vertical Fire Damper

### Damper Size

6" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

8"x5"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench A

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding A

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding C

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Advanced Air

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD15

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding B

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-11-15

### Facility Location

Justice Center Court Towers

### Damper Location

Holding D

### Inspector Name

Julie Gue

### Damper I.D. #

17FL-FD20

### Damper Type

Vertical Fire Damper

### Damper Size

20x10

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-FD21

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-18

### Facility Location

Justice Center Court Towers

### Damper Location

South Shaft

### Inspector Name

Julie Gue

### Damper I.D. #

17FL-FSD22

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Ruskin

### Damper Model #

FSDR25

### Fusible Link Temperature

165 Degrees

### Access Door Size

4x6

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-18

### Facility Location

Justice Center Court Towers

### Damper Location

South Shaft

### Inspector Name

Julie Gue

### Damper I.D. #

17FL-SD South Return

### Damper Type

Vertical Smoke Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

24x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-01

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

17FL-SD3

### Damper Type

Vertical Smoke Damper

### Damper Size

6" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

8"x5"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

17FL-SD21

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-31

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

18FL-FD6

### Damper Type

Vertical Fire Damper

### Damper Size

16"x6"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench A

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding A

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding C

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-18

### Facility Location

Justice Center Court Towers

### Damper Location

Bench C

### Inspector Name

Julie Gue

### Damper I.D. #

18FL-FD15

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-11-14

### Facility Location

Justice Center Court Towers

### Damper Location

Conference C

### Inspector Name

Julie Gue

### Damper I.D. #

C

### Damper Type

Vertical Fire Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

9" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding B

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding D

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD20

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FD21

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-FSD22

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSDR25

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

South

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-31

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

18FL-SD7

### Damper Type

Vertical Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

7" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-31

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

18FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-11-14

### Facility Location

Justice Center Court Towers

### Damper Location

Bailiff B

### Inspector Name

Julie Gue

### Damper I.D. #

18FL-SD18

### Damper Type

Vertical Smoke Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7" Round

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

18FL-SD21

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Advanced Air

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-30

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

19FL-FD1

### Damper Type

Vertical Fire Damper

### Damper Size

12x6

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

6"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-30

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

19FL-FD7

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

6"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"X5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-30

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

19FL-FD9

### Damper Type

Vertical Fire Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-30

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

19FL-FD10

### Damper Type

Vertical Fire Damper

### Damper Size

11" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench A

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding C

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD15

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding B

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding D

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD20

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FD21

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6". Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-FSD 22

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSDR25

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4x6 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

5"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-18

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-14

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

19FL-SD21

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

20"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-30

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

20FL-FD5

### Damper Type

Vertical Fire Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-30

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

20FL-FD10

### Damper Type

Vertical Fire Damper

### Damper Size

11" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench A

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding A

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding C

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD15

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7' Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding B

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding D

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD20

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-FD21

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-17

### Facility Location

Justice Center Court Towers

### Damper Location

South Shaft

### Inspector Name

Julie Gue

### Damper I.D. #

20FL-FSD22

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Ruskin

### Damper Model #

Fsdr25

### Fusible Link Temperature

165 Degrees

### Access Door Size

4x6

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

20"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-30

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-11-11

### Facility Location

Justice Center Court Towers

### Damper Location

Bailiff A

### Inspector Name

Julie Gue

### Damper I.D. #

20FL-SD12

### Damper Type

Vertical Smoke Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

9" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-10

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-11-10

### Facility Location

Justice Center Court Towers

### Damper Location

Bailiff B

### Inspector Name

Julie Gue

### Damper I.D. #

20FL-SD18

### Damper Type

Vertical Smoke Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-17

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

20FL-SD21

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24X14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

20x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

20x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round OD

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench A

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding A

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding C

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD15

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding B

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding D

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD20

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-FD21

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-16

### Facility Location

Justice Center Court Towers

### Damper Location

South Shaft

### Inspector Name

Julie Gue

### Damper I.D. #

21FL-FSD22

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Ruskin

### Damper Model #

FSDR25

### Fusible Link Temperature

N/A

### Access Door Size

4x6

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

20x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-26

### Facility Location

Justice Center Court Towers

### Damper Location

South corridor

### Inspector Name

Julie Gue

### Damper I.D. #

21FL-SD4

### Damper Type

Vertical Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

20x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-26

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

21FL-SD21

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-16

### Facility Location

Justice Center Court Towers

### Damper Location

North shaft

### Inspector Name

Julie Gue

### Damper I.D. #

22FL-FD North Return

### Damper Type

Vertical Fire Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

24x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**







## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-24

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-24

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-24

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-24

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding C

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding A

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD15

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding B

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD19

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding D

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD20

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD21

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD22

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-FD23

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD South Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-24

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-24

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-24

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-24

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-24

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-11-09

### Facility Location

Justice Center Court Towers

### Damper Location

Bailiff A

### Inspector Name

Julie Gue

### Damper I.D. #

22FL-SD12

### Damper Type

Vertical Smoke Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench C

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bench D

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD21

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

22FL-SD22

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-16

### Facility Location

Justice Center Court Towers

### Damper Location

23rd Floor

### Inspector Name

Julie Gue

### Damper I.D. #

23FL-FD North Return

### Damper Type

Vertical Fire Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

24x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-25

**Facility Location**

Justice Center Court Towers

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-25

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-25

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-25

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-25

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

23FL-FD6

### Damper Type

Vertical Fire Damper

### Damper Size

11" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-25

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

11" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding C

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Holding A

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

8.5x6.5

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD17

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD18

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-11-08

### Facility Location

Justice Center Court Towers

### Damper Location

Holding B

### Inspector Name

Julie Gue

### Damper I.D. #

23FL-FD19

### Damper Type

Vertical Fire Damper

### Damper Size

8x6

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7x7

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-11-08

### Facility Location

Justice Center Court Towers

### Damper Location

Holding D

### Inspector Name

Julie Gue

### Damper I.D. #

23FL-FD20

### Damper Type

Vertical Fire Damper

### Damper Size

2x10

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

South Shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD22

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-FD23

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD North Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

24x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-16

### Facility Location

Justice Center Court Towers

### Damper Location

South Shaft

### Inspector Name

Julie Gue

### Damper I.D. #

23FL-SD South Return

### Damper Type

Vertical Fire Damper

### Damper Size

60x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

24x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-25

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-25

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-25

**Facility Location**

Justice Center Court Towers

**Damper Location**

North corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-01-25

### Facility Location

Justice Center Court Towers

### Damper Location

North corridor

### Inspector Name

Julie Gue

### Damper I.D. #

23FL-SD10

### Damper Type

Vertical Smoke Damper

### Damper Size

11" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

10" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff A

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference C

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Conference D

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-08

**Facility Location**

Justice Center Court Towers

**Damper Location**

Bailiff B

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

South shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD22

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-01-16

**Facility Location**

Justice Center Court Towers

**Damper Location**

North shaft

**Inspector Name**

Julie Gue

**Damper I.D. #**

23FL-SD23

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

24FL- N. E. Stairwell.

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x24

**Damper Manufacturer**

Advanced Air

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Removed the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

24FL NW Stairwell

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

24FL- S.W. Stairwell

**Damper Type**

Vertical Fire Damper

**Damper Size**

48"x24"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Removed the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

24FL-S.E. Stairwell

**Damper Type**

Vertical Fire Damper

**Damper Size**

48"x24"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Removed the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

506-FD Supply

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC1-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

60x28

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC1-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC1-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC1-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC1-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

20" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

13x19

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC1-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

13x19

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-11-11

### Facility Location

Justice Center Court Towers

### Damper Location

Mechanical room

### Inspector Name

Julie Gue

### Damper I.D. #

AC1-S6

### Damper Type

Horizontal Fire Damper

### Damper Size

23" Round

### Damper Manufacturer

Ruskin

### Damper Model #

DIBD20

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x20

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC1-S7

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11x11

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC1-S8

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

DIBD23

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC1-S9

**Damper Type**

Horizontal Fire Damper

**Damper Size**

20" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-05

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC1-S10

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-05

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC1-S11

**Damper Type**

Horizontal Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

DIBD23

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

13x13

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-05

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC1-S12

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

DIBD23

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC2- Return

**Damper Type**

Horizontal Fire Damper

**Damper Size**

60x30

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC2-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

54x36

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC2-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

36" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

19x13

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-11

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC2-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

13x19

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC2-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC2-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC2-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC2-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x11

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-06

### Facility Location

Justice Center Court Towers

### Damper Location

Mechanical room

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AC2-S7

### Damper Type

Horizontal Fire Damper

### Damper Size

12" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

9x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-05

### Facility Location

Justice Center Court Towers

### Damper Location

Mechanical room

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AC3-S1

### Damper Type

Horizontal Fire Damper

### Damper Size

23" Round

### Damper Manufacturer

Ruskin

### Damper Model #

DIBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

18x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-06

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC6-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

22" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC13-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

23" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x21

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC14-Return

**Damper Type**

Horizontal Fire Damper

**Damper Size**

66x66

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC14-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

19x19

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC14-S2

**Damper Type**

Vertical Fire Damper

**Damper Size**

26" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

21x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC14-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

25" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x20

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC14-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

27" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

20x22

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC15-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

66x66

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC15-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

27" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18"x20"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC15-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

25" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18"x20"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC15-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

23" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC15-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

AC16-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

23" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

17x19

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC24-R1

**Damper Type**

Vertical Fire Damper

**Damper Size**

38x38

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD40

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Removed the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-15

### Facility Location

Justice Center Court Towers

### Damper Location

24th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AC24-S1

### Damper Type

Vertical Fire Damper

### Damper Size

18"x18"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD40

### Fusible Link Temperature

165 Degrees

### Access Door Size

Removed the grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor room.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AC24-S2

**Damper Type**

Vertical Fire Damper

**Damper Size**

36"x18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD40

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Removed the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-15

### Facility Location

Justice Center Court Towers

### Damper Location

24th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AC24-S3

### Damper Type

Vertical Fire Damper

### Damper Size

36x18

### Damper Manufacturer

Ruskin

### Damper Model #

IBD40

### Fusible Link Temperature

165 Degrees

### Access Door Size

Removed the grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU506 Return

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

EF1-2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-05

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

EF1-FD1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

45x35

**Damper Manufacturer**

Ruskin

**Damper Model #**

DIBD23

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-05

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

EF2 Kitchen East

**Damper Type**

Horizontal Fire Damper

**Damper Size**

34x32

**Damper Manufacturer**

Ruskin

**Damper Model #**

DIBD23

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

EF2-5FL

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

EF3-5FL

**Damper Type**

Horizontal Fire Damper

**Damper Size**

20x20

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

EF3-24

**Damper Type**

Horizontal Fire Damper

**Damper Size**

32x34

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

EF4-24

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

EF5-5FL

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

20x20

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-23

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

EF5-24

**Damper Type**

Horizontal Fire Damper

**Damper Size**

34x34

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

1FL Galleria

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Galleria 1FL-FD Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

36"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

15"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-02

### Facility Location

Justice Center Court Towers

### Damper Location

1FL Galleria

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Galleria 1FL-FD1

### Damper Type

Vertical Fire Damper

### Damper Size

14" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

4"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

1FL Galleria

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Galleria 1FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Fail

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-02

### Facility Location

Justice Center Court Towers

### Damper Location

1FL Galleria

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Galleria 1FL-FD4

### Damper Type

Vertical Fire Damper

### Damper Size

14"x6"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

1FL Galleria

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Galleria 1FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

22"x 8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-02

**Facility Location**

Justice Center Court Towers

**Damper Location**

1FL Galleria

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Galleria 1FL-SD Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

36"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

15"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL FD North Return 2

**Damper Type**

Vertical Fire Damper

**Damper Size**

54x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-20

### Facility Location

Justice Center Court Towers

### Damper Location

Galleria

### Inspector Name

Julie Gue

### Damper I.D. #

Galleria 2FL SD North Return 2

### Damper Type

Vertical Smoke Damper

### Damper Size

54x9

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

16x16

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

17" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x4 oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-FD North Return 1

**Damper Type**

Vertical Fire Damper

**Damper Size**

54x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

36x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

15x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x9

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x9

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

22x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-20

### Facility Location

Justice Center Court Towers

### Damper Location

Galleria

### Inspector Name

Julie Gue

### Damper I.D. #

Galleria 2FL-FD11

### Damper Type

Vertical Fire Damper

### Damper Size

36x8

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

14x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

14" round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-FD13

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-20

### Facility Location

Justice Center Court Towers

### Damper Location

Galleria

### Inspector Name

Julie Gue

### Damper I.D. #

Galleria 2FL-SD North return 1

### Damper Type

Vertical Smoke Damper

### Damper Size

54x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

16"x10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-21

### Facility Location

Justice Center Court Towers

### Damper Location

Galleria corridor

### Inspector Name

Julie Gue

### Damper I.D. #

Galleria 2FL-SD South Return

### Damper Type

Vertical Fire Damper

### Damper Size

36x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

15x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-SD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-21

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18x9

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x9

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-21

### Facility Location

Justice Center Court Towers

### Damper Location

Galleria

### Inspector Name

Julie Gue

### Damper I.D. #

Galleria 2FL-SD3

### Damper Type

Vertical Smoke Damper

### Damper Size

22x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

12x8

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x4 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-20

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 2FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x4 oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-22

### Facility Location

Justice Center Court Towers

### Damper Location

Corridor

### Inspector Name

Julie Gue

### Damper I.D. #

Galleria 3FL-FD North Return

### Damper Type

Vertical Fire Damper

### Damper Size

54x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x8

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-FD South Return

**Damper Type**

Vertical Fire Damper

**Damper Size**

36x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x3

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

44x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Flex access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-SD North Return

**Damper Type**

Vertical Smoke Damper

**Damper Size**

54x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 oval

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7"x7"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-02-22

### Facility Location

Justice Center Court Towers

### Damper Location

Corridor

### Inspector Name

Julie Gue

### Damper I.D. #

Galleria 3FL-SD6

### Damper Type

Vertical Smoke Damper

### Damper Size

14x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

8x8

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x4 oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Galleria corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x4 oval

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-02-22

**Facility Location**

Justice Center Court Towers

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

Galleria 3FL-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

4FL Galleria

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Galleria 4FL-FD North Return 1

**Damper Type**

Vertical Fire Damper

**Damper Size**

54"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

4FL Galleria

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Galleria 4FL-FD North Return 2

### Damper Type

Vertical Fire Damper

### Damper Size

26"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10"x8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

4FL Galleria

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Galleria 4FL-FD1

### Damper Type

Horizontal Fire Damper

### Damper Size

36"x30"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

Open

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

4FL Galleria

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Galleria 4FL-SD North Return 1

### Damper Type

Vertical Smoke Damper

### Damper Size

54"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

14"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

4FL Galleria

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Galleria 4FL-SD North Return 2

### Damper Type

Vertical Smoke Damper

### Damper Size

26"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

10"x8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

4FL Galleria

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Galleria 4FL-SD1

### Damper Type

Vertical Smoke Damper

### Damper Size

12" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

8"x4"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-01

**Facility Location**

Justice Center Court Towers

**Damper Location**

4FL Galleria

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Galleria 4FL-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-03-01

### Facility Location

Justice Center Court Towers

### Damper Location

4FL Galleria

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Galleria 4FL-SD3

### Damper Type

Vertical Smoke Damper

### Damper Size

16" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

8"x4" Oval

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-15

### Facility Location

Justice Center Court Towers

### Damper Location

24th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

H.R.Elev Room Relief 1

### Damper Type

Vertical Fire Damper

### Damper Size

48"x48"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

Thru the Relief Air damper.

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

H.R.Elev Room Relief 2

**Damper Type**

Vertical Fire Damper

**Damper Size**

48"x48"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Thru the Relief Air damper.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

I1-R1

**Damper Type**

Vertical Fire Damper

**Damper Size**

36x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

Ibd40

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

I1-S1

**Damper Type**

Vertical Fire Damper

**Damper Size**

22x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

Ibd40

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-15

### Facility Location

Justice Center Court Towers

### Damper Location

24th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

I2-EX

### Damper Type

Vertical Fire Damper

### Damper Size

18"x16"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD40

### Fusible Link Temperature

165 Degrees

### Access Door Size

Removed the grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-15

**Facility Location**

Justice Center Court Towers

**Damper Location**

Elevator room I-2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

I2-R1

**Damper Type**

Vertical Fire Damper

**Damper Size**

36"x16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD40

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Removed the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-15

### Facility Location

Justice Center Court Towers

### Damper Location

24th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

I2-S1

### Damper Type

Vertical Fire Damper

### Damper Size

22"x10"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

Removed the grille

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

JE Exhaust 1

**Damper Type**

Vertical Fire Damper

**Damper Size**

38x38

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-19

### Facility Location

Justice Center Court Towers

### Damper Location

24th floor

### Inspector Name

Julie Gue

### Damper I.D. #

JE-S1

### Damper Type

Vertical Fire Damper

### Damper Size

30x30

### Damper Manufacturer

Ruskin

### Damper Model #

IBD40

### Fusible Link Temperature

165 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

JE-S2

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

Ibd40

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th Floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

JE-S3

**Damper Type**

Vertical Fire Damper

**Damper Size**

30x22

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD40

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

JE-TA1

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x30

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-19

**Facility Location**

Justice Center Court Towers

**Damper Location**

24th floor

**Inspector Name**

Julie Gue

**Damper I.D. #**

JE-TA2

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x30

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-03-09

**Facility Location**

Justice Center Court Towers

**Damper Location**

5FL Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Kitchen Supply Fan 1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

28"x14"

**Damper Manufacturer**

Unknown

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x18"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-05

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

MAU-2 West

**Damper Type**

Horizontal Fire Damper

**Damper Size**

36x26

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-05

**Facility Location**

Justice Center Court Towers

**Damper Location**

Mechanical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

MUA-2East

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

Dock

**Inspector Name**

Julie Gue

**Damper I.D. #**

P1 -FD EX 4

**Damper Type**

Vertical Fire Damper

**Damper Size**

108x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

P1

**Inspector Name**

Julie Gue

**Damper I.D. #**

P1-FD EX 1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

Dock

**Inspector Name**

Julie Gue

**Damper I.D. #**

P1-FD EX2

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

Dock

**Inspector Name**

Julie Gue

**Damper I.D. #**

P1-FD EX3

**Damper Type**

Vertical Fire Damper

**Damper Size**

120x7

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-12-27

### Facility Location

Justice Center Court Towers

### Damper Location

P1

### Inspector Name

Julie Gue

### Damper I.D. #

P1-FD R1

### Damper Type

Vertical Fire Damper

### Damper Size

70x14

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Was R1xR2


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

Dock

**Inspector Name**

Julie Gue

**Damper I.D. #**

P1-FD R2

**Damper Type**

Vertical Fire Damper

**Damper Size**

70x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

Dock

**Inspector Name**

Julie Gue

**Damper I.D. #**

P1-FD S1

**Damper Type**

Vertical Fire Damper

**Damper Size**

96x30

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12 x 12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

P2

**Inspector Name**

Julie Gue

**Damper I.D. #**

P2-FD S1

**Damper Type**

Vertical Fire Damper

**Damper Size**

26x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-12-27

**Facility Location**

Justice Center Court Towers

**Damper Location**

P2

**Inspector Name**

Julie Gue

**Damper I.D. #**

P2-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD23

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Cuyahoga County  
Justice Center  
Tower Two

1300 Ontario Street  
Cleveland, Ohio 44113

Fire Damper Inspection Report  
May 6, 2022

*Duct Fabricators, Inc.*  
**FIRE SAFETY DIVISION**



Report Date: May 6, 2022

Project: Cuyahoga County  
Justice Center Tower Two

Inspector(s):

- Julianne Gue, Certified Technician
- Dan Tulcewicz, Certified Technician

Inspection and Test Date(s):

- January 14, 2022-March 4, 2022

Duct Fabricators, Inc. "Fire Safety Division" inspected floors one through 24, excluding the fourth floor and Galleria. The dampers were then tested and photographed in the "open" and "closed" positions to confirm that they were functioning as designed. We are in the process of completing punch list items and repairs within the Court Tower.

All of the dampers passed the inspection and functional testing unless otherwise noted.

NOTES: NFPA 80 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers located in patient care facilities are to be inspected and tested every six years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
13	FD	2FL-FD1 North	25x12Oval	Air Balance	Unknown	Pass	Pass	None
14	FD	2FL-FD2 North	54x14	Air Balance	Unknown	Pass	Pass	None
15	FD	2FL-FD3 North	6"R	Air Balance	Unknown	Pass	Pass	Changed Fusible Link
16	FD	2FL-FD4 North	10" R	Ruskin	IBD60	Pass	Pass	None
17	FD	2FL-FD5 North	12x8	Air Balance	Unknown	Pass	Pass	None
18	FD	2FL-FD6 North	16x12	Air Balance	Unknown	Pass	Pass	None
19	FD	2FL-FD7 North	24x12 Oval	Air Balance	Unknown	Pass	Pass	None
20	FD	2FL-FD8 North	8" R	Air Balance	Unknown	Pass	Pass	Changed Fusible Link
21	FD	2FL-FD9 North	10" R	Ruskin	IBD60	Pass	Pass	None
22	FD	2FL-FD10 North	21x12 Oval	Air Balance	Unknown	Pass	Pass	None
23	FD	2FL-FD11 North	18x12 Oval	Air Balance	Unknown	Pass	Pass	Changed Fusible Link
24	FD	2FL-FD12 North	64x14	Air Balance	Unknown	Pass	Pass	None
25	FD	2FL-FD13 North	54x14	Air Balance	Unknown	Pass	Pass	None
26	FD	2FL-FD14 North	60x6	Air Balance	Unknown	Pass	Pass	None
27	FD	2FL-FD15 North	16x10 Oval	Air Balance	Unknown	Pass	Pass	Changed Fusible Link

Inspector: Julie Gue  
Inspection Dates: 2/14/2022-3/4/2022  
Facility: Court Tower 2 Old Police Headquarters

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Cuyahoga County  
Justice Center  
Tower Two

1300 Ontario Street  
Cleveland, Ohio 44113

Fire Damper Inspection Report  
May 6, 2022

*Duct Fabricators, Inc.*  
**FIRE SAFETY DIVISION**





Report Date: May 6, 2022

Project: Cuyahoga County  
Justice Center Tower Two

Inspector(s):

- Julianne Gue, Certified Technician
- Dan Tulcewicz, Certified Technician

Inspection and Test Date(s):

- January 14, 2022-March 4, 2022

Duct Fabricators, Inc. "Fire Safety Division" inspected floors one through 24, excluding the fourth floor and Galleria. The dampers were then tested and photographed in the "open" and "closed" positions to confirm that they were functioning as designed. We are in the process of completing punch list items and repairs within the Court Tower.

All of the dampers passed the inspection and functional testing unless otherwise noted.

NOTES: NFPA 80 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers located in patient care facilities are to be inspected and tested every six years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
13	FD	2FL-FD1 North	25x12Oval	Air Balance	Unknown	Pass	Pass	None
14	FD	2FL-FD2 North	54x14	Air Balance	Unknown	Pass	Pass	None
15	FD	2FL-FD3 North	6"R	Air Balance	Unknown	Pass	Pass	Changed Fusible Link
16	FD	2FL-FD4 North	10" R	Ruskin	IBD60	Pass	Pass	None
17	FD	2FL-FD5 North	12x8	Air Balance	Unknown	Pass	Pass	None
18	FD	2FL-FD6 North	16x12	Air Balance	Unknown	Pass	Pass	None
19	FD	2FL-FD7 North	24x12 Oval	Air Balance	Unknown	Pass	Pass	None
20	FD	2FL-FD8 North	8" R	Air Balance	Unknown	Pass	Pass	Changed Fusible Link
21	FD	2FL-FD9 North	10" R	Ruskin	IBD60	Pass	Pass	None
22	FD	2FL-FD10 North	21x12 Oval	Air Balance	Unknown	Pass	Pass	None
23	FD	2FL-FD11 North	18x12 Oval	Air Balance	Unknown	Pass	Pass	Changed Fusible Link
24	FD	2FL-FD12 North	64x14	Air Balance	Unknown	Pass	Pass	None
25	FD	2FL-FD13 North	54x14	Air Balance	Unknown	Pass	Pass	None
26	FD	2FL-FD14 North	60x6	Air Balance	Unknown	Pass	Pass	None
27	FD	2FL-FD15 North	16x10 Oval	Air Balance	Unknown	Pass	Pass	Changed Fusible Link

Inspector: Julie Gue  
Inspection Dates: 2/14/2022-3/4/2022  
Facility: Court Tower 2 Old Police Headquarters

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
57	FD	4FL-FD1 South	16x10 Oval	Air Balance	Unknown	Pass	Pass	None
58	FD	4FL-FD2 South	28x12	Air Balance	Unknown	Pass	Pass	None
59	FD	4FL-FD3 South	24x18	Ruskin	IBD60	Pass	Pass	None
60	FD	4FL-FD4 South	18x12	Air Balance	Unknown	Pass	Pass	None
61	FD	4FL-FD5 South	50x10	Air Balance	Unknown	Pass	Pass	None
62	FD	4FL-FD6 South	16x11	Air Balance	Unknown	Pass	Pass	None
63	FD	4FL-FD7 South	30x14	Air Balance	Unknown	Pass	Pass	None
64	FD	4FL-FD8 South	12x8 Oval	Air Balance	Unknown	Pass	Pass	None
65	FD	4FL-FD9 South	28x12 Oval	Air Balance	Unknown	Pass	Pass	None
66	FD	4FL-FD10 South	28x12 Oval	Air Balance	Unknown	Pass	Pass	Installed larger access door
67	FD	4FL-FD11 South	48x24	Air Balance	Unknown	Pass	Pass	None
68	FD	4FL-FD12 South	34x12	Air Balance	Unknown	Pass	Pass	Installed larger access door
69	FD	4FL-FD13 South	20x14	Ruskin	IBD60	Pass	Pass	None

Inspector: Julie Gue  
Inspection Dates: 2/14/2022-3/01/2022  
Facility: Court Tower 2 Old Police Headquarters

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
38	FD	4FL-FD1 North	36x12	Air Balance	Unknown	Pass	Pass	None
39	FD	4FL-FD2 North	28x12	Air Balance	Unknown	Pass	Pass	Changed Fusible Link
40	FD	4FL-FD3 North	24x18	Ruskin	IBD60	Pass	Pass	None
41	FD	4FL-FD4 North	12x8	Air Balance	Unknown	Pass	Pass	None
42	FD	4FL-FD 5 North	22x10	Air Balance	Unknown	Pass	Pass	None
43	FD	4FL-FD6 North	6" R	Air Balance	Unknown	Pass	Pass	None
44	FD	4FL-FD7 North	14x6	Air Balance	Unknown	Pass	Pass	None
45	FD	4FL-FD8 North	72x12	Air Balance	Unknown	Pass	Pass	None
46	FD	4FL-FD9 North	60x6	Air Balance	Unknown	Pass	Pass	None
47	FD	4FL-FD10 North	8" R	Air Balance	Unknown	Pass	Pass	None
48	FD	4FL-FD11 North	60x6	Air Balance	Unknown	Pass	Pass	None
49	FD	4FL-FD12 North	12" R	Ruskin	IBD60	Pass	Pass	None
50	FD	4FL-FD13 North	64x14	Air Balance	Unknown	Pass	Pass	None
51	FD	4FL-FD14 North	56x14	Air Balance	Unknown	Pass	Pass	None
52	FD	4FL-FD15 North	10x6	Air Balance	Unknown	Pass	Pass	None
53	FD	4FL-FD16 North	10x8 Oval	Air Balance	Unknown	Pass	Pass	None
54	FD	4FL-FD17 North	6x6	Air Balance	Unknown	Pass	Pass	None
55	FD	4FL-FD18 North	18x12 Oval	Air Balance	Unknown	Pass	Pass	None
56	FD	4FL-FD19 North	28x12	Air Balance	Unknown	Pass	Pass	Installed larger access

Inspector: Julie Gue  
Inspection Dates: 2/14/2022-3/01/2022  
Facility: Court Tower 2 Old Police Headquarters

SA = Supply Air  
 RA = Return Air  
 EA = Exhaust Air  
 FD = Fire Damper  
 SD = Smoke Damper  
 FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-14

**Facility Location**

Old Police Dept Building

**Damper Location**

Break room

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-14

**Facility Location**

Old Police Dept Building

**Damper Location**

Labs lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-14

**Facility Location**

Old Police Dept Building

**Damper Location**

Labs lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

6x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-14

**Facility Location**

Old Police Dept Building

**Damper Location**

Labs lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-02-14

### Facility Location

Old Police Dept Building

### Damper Location

Labs lobby

### Inspector Name

Julie Gue

### Damper I.D. #

1FL-FD6

### Damper Type

Vertical Fire Damper

### Damper Size

19" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12" Round

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-03-04

### Facility Location

Old Police Dept Building

### Damper Location

Museum office

### Inspector Name

Julie Gue

### Damper I.D. #

1FL-FD7 m

### Damper Type

Vertical Fire Damper

### Damper Size

20x8

### Damper Manufacturer

Ruskin

### Damper Model #

IBD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

16x16

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

A Carpenter stud screw was found screwed into damper track


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label







Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-03-04

### Facility Location

Old Police Dept Building

### Damper Location

Museum office

### Inspector Name

Julie Gue

### Damper I.D. #

1FD-FD8

### Damper Type

Vertical Fire Damper

### Damper Size

20x12

### Damper Manufacturer

Ruskin

### Damper Model #

IBD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Dowl was found Propping damper open and link broke when it was touched. New link installed

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-03-04

**Facility Location**

Old Police Dept Building

**Damper Location**

Museum storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-03-04

**Facility Location**

Old Police Dept Building

**Damper Location**

Museum office

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Changed link


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-03-04

**Facility Location**

Old Police Dept Building

**Damper Location**

Museum

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x16

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-03-04

**Facility Location**

Old Police Dept Building

**Damper Location**

Museum

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

36x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

North East corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

25x12 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 1 31 22	Reference I.D.# 2FL-FD1
Inspected By: GUE	NORTH
Next Inspect. By: 1 31 24	

Duct Fabricators, Inc. **FIRE SAFETY DIVISION**  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-28

**Facility Location**

Old Police Dept Building

**Damper Location**

RM 206

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-01-31

### Facility Location

Old Police Dept Building

### Damper Location

NE corridor

### Inspector Name

Julie Gue

### Damper I.D. #

2FL-FD2 North

### Damper Type

Vertical Fire Damper

### Damper Size

50x14

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

14x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: 1-31-22	Reference I.D.# 2FL-FD2
Inspected By: GUE	NORTH
Next Inspect. By: 1-31-24(M)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-28

**Facility Location**

Old Police Dept Building

**Damper Location**

SE Corner of hallway

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-01-31

**Facility Location**  
Old Police Dept Building

**Damper Location**  
NW corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
2FL-FD3 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
7x4


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
Changed link

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: 1-31-22	Reference I.D.# 2FL-FD3
Inspected By: GUE	NORTH
Next Inspect. By: 1-31-24(M)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-28

**Facility Location**

Old Police Dept Building

**Damper Location**

RM 222

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x11 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Women's toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x5 oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 1/31/22	Reference I.D.#: 2FL-FD4
Inspected By: GUE	North
Next Inspect. By: 1/31/24(N)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Southeast corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Women's toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 1-31-22	Reference I.D.#: 2FL-FD5
Inspected By: GUE	NORTH
Next Inspect. By: 1-31-24	
Duct Fabricators, Inc. FIRE SAFETY DIVISION NFPA	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-28

**Facility Location**

Old Police Dept Building

**Damper Location**

Waiting room

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Women's toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-01-28

### Facility Location

Old Police Dept Building

### Damper Location

East elevator lobby

### Inspector Name

Julie Gue

### Damper I.D. #

2FL-FD6 South

### Damper Type

Vertical Fire Damper

### Damper Size

60x6

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

16x16

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

FIRE DAMPER	
Inspection Date: 1-28-22	Reference I.D.# 2FL-FD6
Inspected By: GUE	South
Next Inspect. By: 1-28-24(M)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

NW corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

25x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 1-31-22	Reference I.D.# 2FL-FD7
Inspected By: GUE	NORTH
Next Inspect. By: 1-31-24(y)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

NW corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

25x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Label Mismarked North

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 1-31-22	Reference I.D.# 2FL-FD7
Inspected By: GUE	NORTH
Next Inspect. By: 1-31-24(y)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Room 254

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Changed link


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

South hallway

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD8 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

36x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 1-31-22	Reference I.D.#: 2FL-FD8 South
Inspected By: Gue	
Next Inspect. By: 1-31-24 (M)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Room 253

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD9 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x5 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE**  
**DAMPER**

Inspection Date: 1-31-22  
 Inspected By: Gue  
 Next Inspect. By: 1-31-24(X)

Reference I.D. #:  
 2FL-FD9  
 NORTH

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
 NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Room 249

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD10 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

21x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-09

**Facility Location**

Old Police Dept Building

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD10 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Carpenter removed trim  
Very dirty

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

NE closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD11 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Changed link


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-01-31

### Facility Location

Old Police Dept Building

### Damper Location

Room 230

### Inspector Name

Julie Gue

### Damper I.D. #

2FL-FD12 North

### Damper Type

Vertical Fire Damper

### Damper Size

64x14

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

Open duct

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Room 228

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD13 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

50x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

Room 227

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD14 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11x11

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 2-1-22	Reference I.D.# 2FL-FD14
Inspected By: GUE	NORTH
Next Inspect. By: 2-1-24(M)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

RM 225

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD15 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Changed link

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

West waiting room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4 FL-FD14 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

56x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

West corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

36x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

SE corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10 oval

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

West corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Changed link


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

SE corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: <u>2-1-22</u>	Reference I.D. # <u>4FL-FD2</u>
Inspected By: <u>GUE</u>	<u>South</u>
Next Inspect. By: <u>2-1-24</u>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

NW corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-02-01

**Facility Location**  
Old Police Dept Building

**Damper Location**  
SE corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
4FL-FD3 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
24x18

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD60


**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
14x14

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 2-1-22	Reference ID # 4FL-FD3
Inspected By: GUE	South
Next Inspect. By: 2-1-24(v)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
216-391-2400 F 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

Women's toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-02-01

**Facility Location**  
Old Police Dept Building

**Damper Location**  
SE Infront of stairwell A

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
4FL-FD4 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
18x12

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12x12

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: 2-1-22	Reference I.D.#: 4FL-FD4
Inspected By: Gue	South
Next Inspect. By: 2-1-24(N)	

Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-02-02

### Facility Location

Old Police Dept Building

### Damper Location

Women's toilet

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-FD5 North

### Damper Type

Vertical Fire Damper

### Damper Size

22x10

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

11x9

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

50x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x9

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

Women's toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

SW corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

NE corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

SW corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

30x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

NE corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

72x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

Waiting room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD8 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

File room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD9 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: <u>2-2-22</u>	Reference I.D.#: <u>4FL-FD9</u>
Inspected By: <u>GVE</u>	<u>NORTH</u>
Next Inspect. By: <u>2-2-24</u>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

Waiting room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD9 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-02-02

**Facility Location**  
Old Police Dept Building

**Damper Location**  
File room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
4FL-FD10 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
6" Round


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>2-2-22</b>	Reference I.D.#: <b>4FL-FD10</b>
Inspected By: <b>Gue</b>	<b>NORTH</b>
Next Inspect. By: <b>2-2-24(M)</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-08

**Facility Location**

Old Police Dept Building

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD10 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Installed larger access door

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

File room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD11 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD12 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Files

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD12 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

34x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Installed larger access

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD13 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

64x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Files

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD13 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-09

**Facility Location**

Old Police Dept Building

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD14 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Carpenter needed dirty

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD15 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-08

**Facility Location**

Old Police Dept Building

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD16 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x8 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Cleaning closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD17 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

6x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

5x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-02-07

### Facility Location

Old Police Dept Building

### Damper Location

Cleaning closet

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-FD18 North

### Damper Type

Vertical Fire Damper

### Damper Size

18x12 Oval

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

6" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

FIRE DAMPER	
Inspection Date: 2-7-22	Reference I.D.# 4FL-FD18
Inspected By: JG	North
Next Inspect. By: 2-7-24	

Duct Fabricators, Inc. FIRE SAFETY DIVISION MEMBER  
883 Addison Rd. Cleveland, Ohio NEMI Certified HVAC Fire Life Safety Technicians NFPA

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-02-08

### Facility Location

Old Police Dept Building

### Damper Location

East corridor

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-FD19 North

### Damper Type

Vertical Fire Damper

### Damper Size

28x12 Oval

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

14x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Installed larger access.

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: 2-8-22	Reference I.D.# 4FL-FD19
Inspected By: GUE	NORTH
Next Inspect. By: 2-8-24	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
57	FD	4FL-FD1 South	16x10 Oval	Air Balance	Unknown	Pass	Pass	None
58	FD	4FL-FD2 South	28x12	Air Balance	Unknown	Pass	Pass	None
59	FD	4FL-FD3 South	24x18	Ruskin	IBD60	Pass	Pass	None
60	FD	4FL-FD4 South	18x12	Air Balance	Unknown	Pass	Pass	None
61	FD	4FL-FD5 South	50x10	Air Balance	Unknown	Pass	Pass	None
62	FD	4FL-FD6 South	16x11	Air Balance	Unknown	Pass	Pass	None
63	FD	4FL-FD7 South	30x14	Air Balance	Unknown	Pass	Pass	None
64	FD	4FL-FD8 South	12x8 Oval	Air Balance	Unknown	Pass	Pass	None
65	FD	4FL-FD9 South	28x12 Oval	Air Balance	Unknown	Pass	Pass	None
66	FD	4FL-FD10 South	28x12 Oval	Air Balance	Unknown	Pass	Pass	Installed larger access door
67	FD	4FL-FD11 South	48x24	Air Balance	Unknown	Pass	Pass	None
68	FD	4FL-FD12 South	34x12	Air Balance	Unknown	Pass	Pass	Installed larger access door
69	FD	4FL-FD13 South	20x14	Ruskin	IBD60	Pass	Pass	None

Inspector: Julie Gue  
Inspection Dates: 2/14/2022-3/01/2022  
Facility: Court Tower 2 Old Police Headquarters

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
38	FD	4FL-FD1 North	36x12	Air Balance	Unknown	Pass	Pass	None
39	FD	4FL-FD2 North	28x12	Air Balance	Unknown	Pass	Pass	Changed Fusible Link
40	FD	4FL-FD3 North	24x18	Ruskin	IBD60	Pass	Pass	None
41	FD	4FL-FD4 North	12x8	Air Balance	Unknown	Pass	Pass	None
42	FD	4FL-FD 5 North	22x10	Air Balance	Unknown	Pass	Pass	None
43	FD	4FL-FD6 North	6" R	Air Balance	Unknown	Pass	Pass	None
44	FD	4FL-FD7 North	14x6	Air Balance	Unknown	Pass	Pass	None
45	FD	4FL-FD8 North	72x12	Air Balance	Unknown	Pass	Pass	None
46	FD	4FL-FD9 North	60x6	Air Balance	Unknown	Pass	Pass	None
47	FD	4FL-FD10 North	8" R	Air Balance	Unknown	Pass	Pass	None
48	FD	4FL-FD11 North	60x6	Air Balance	Unknown	Pass	Pass	None
49	FD	4FL-FD12 North	12" R	Ruskin	IBD60	Pass	Pass	None
50	FD	4FL-FD13 North	64x14	Air Balance	Unknown	Pass	Pass	None
51	FD	4FL-FD14 North	56x14	Air Balance	Unknown	Pass	Pass	None
52	FD	4FL-FD15 North	10x6	Air Balance	Unknown	Pass	Pass	None
53	FD	4FL-FD16 North	10x8 Oval	Air Balance	Unknown	Pass	Pass	None
54	FD	4FL-FD17 North	6x6	Air Balance	Unknown	Pass	Pass	None
55	FD	4FL-FD18 North	18x12 Oval	Air Balance	Unknown	Pass	Pass	None
56	FD	4FL-FD19 North	28x12	Air Balance	Unknown	Pass	Pass	Installed larger access

Inspector: Julie Gue  
Inspection Dates: 2/14/2022-3/01/2022  
Facility: Court Tower 2 Old Police Headquarters

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-14

**Facility Location**

Old Police Dept Building

**Damper Location**

Break room

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-14

**Facility Location**

Old Police Dept Building

**Damper Location**

Labs lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-14

**Facility Location**

Old Police Dept Building

**Damper Location**

Labs lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

6x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-14

**Facility Location**

Old Police Dept Building

**Damper Location**

Labs lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-02-14

### Facility Location

Old Police Dept Building

### Damper Location

Labs lobby

### Inspector Name

Julie Gue

### Damper I.D. #

1FL-FD6

### Damper Type

Vertical Fire Damper

### Damper Size

19" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12" Round

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-03-04

### Facility Location

Old Police Dept Building

### Damper Location

Museum office

### Inspector Name

Julie Gue

### Damper I.D. #

1FL-FD7 m

### Damper Type

Vertical Fire Damper

### Damper Size

20x8

### Damper Manufacturer

Ruskin

### Damper Model #

IBD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

16x16

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

A Carpenter stud screw was found screwed into damper track


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label







## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-03-04

**Facility Location**

Old Police Dept Building

**Damper Location**

Museum office

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FD-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Dowl was found Propping damper open and link broke when it was touched. New link installed

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-03-04

**Facility Location**

Old Police Dept Building

**Damper Location**

Museum storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-03-04

**Facility Location**

Old Police Dept Building

**Damper Location**

Museum office

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Changed link


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-03-04

**Facility Location**

Old Police Dept Building

**Damper Location**

Museum

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD11

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x16

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-03-04

**Facility Location**

Old Police Dept Building

**Damper Location**

Museum

**Inspector Name**

Julie Gue

**Damper I.D. #**

1FL-FD12

**Damper Type**

Vertical Fire Damper

**Damper Size**

36x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

North East corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

25x12 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 1 31 22	Reference I.D.# 2FL-FD1
Inspected By: GUE	NORTH
Next Inspect. By: 1 31 24	

Duct Fabricators, Inc. **FIRE SAFETY DIVISION**  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-28

**Facility Location**

Old Police Dept Building

**Damper Location**

RM 206

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

NE corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

50x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-28

**Facility Location**

Old Police Dept Building

**Damper Location**

SE Corner of hallway

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-01-31

**Facility Location**  
Old Police Dept Building

**Damper Location**  
NW corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
2FL-FD3 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
7x4


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
Changed link

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: 1-31-22	Reference I.D.# 2FL-FD3
Inspected By: GUE	NORTH
Next Inspect. By: 1-31-24(M)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-28

**Facility Location**

Old Police Dept Building

**Damper Location**

RM 222

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x11 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 1-28-22	Reference I.D.#: 2FL-FD3 South
Inspected By: GUE	
Next Inspect. By: 1-28-24(N)	

Duct Fabricators, Inc. **FIRE SAFETY DIVISION** MEMBER **NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-01-31

**Facility Location**  
Old Police Dept Building

**Damper Location**  
Women's toilet

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
2FL-FD4 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD60

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
9x5 oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**FIRE DAMPER**

Inspection Date: 1/31/22	Reference I.D.#: 2FL-FD4 North
Inspected By: GUE	
Next Inspect. By: 1/31/24(N)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Southeast corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 1-31-22	Reference I.D. #: 2FL-FD4
Inspected By: GUE	South
Next Inspect. By: 1-31-24 (Y)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Women's toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 1-31-22	Reference I.D.#: 2FL-FD5
Inspected By: GUE	NORTH
Next Inspect. By: 1-31-24	

Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio  
FIRE SAFETY DIVISION NEMI Certified HVAC Fire Life Safety Technicians NFPA

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-28

**Facility Location**

Old Police Dept Building

**Damper Location**

Waiting room

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 1-28-22	Reference I.D.#: 2FL-FD5
Inspected By: Gue	South
Next Inspect. By: 1-28-24	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Women's toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-01-28

### Facility Location

Old Police Dept Building

### Damper Location

East elevator lobby

### Inspector Name

Julie Gue

### Damper I.D. #

2FL-FD6 South

### Damper Type

Vertical Fire Damper

### Damper Size

60x6

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

16x16

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

FIRE DAMPER	
Inspection Date: 1-28-22	Reference I.D.# 2FL-FD6
Inspected By: CUE	South
Next Inspect. By: 1-28-24(C)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

NW corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

25x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 1-31-22	Reference I.D.# 2FL-FD7
Inspected By: GUE	NORTH
Next Inspect. By: 1-31-24(Y)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

NW corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

25x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Label Mismarked North

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 1-31-22	Reference I.D.# 2FL-FD7
Inspected By: GUE	NORTH
Next Inspect. By: 1-31-24(y)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-01-31

**Facility Location**  
Old Police Dept Building

**Damper Location**  
Room 254

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
2FL-FD8 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
6" Round


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
Changed link

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: 1 31 22	Reference I.D.# 2FL-FD8
Inspected By: GUE	
Next Inspect. By: 1 31 24(V)	NORTH

Duct Fabricators, Inc. **FIRE SAFETY DIVISION**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-01-31

### Facility Location

Old Police Dept Building

### Damper Location

South hallway

### Inspector Name

Julie Gue

### Damper I.D. #

2FL-FD8 South

### Damper Type

Vertical Fire Damper

### Damper Size

36x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: 1-31-22	Reference I.D.#: 2FL-FD8
Inspected By: Gue	South
Next Inspect. By: 1-31-24 (M)	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small><b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER NFPA</small>	

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-01-31

### Facility Location

Old Police Dept Building

### Damper Location

Room 253

### Inspector Name

Julie Gue

### Damper I.D. #

2FL-FD9 North

### Damper Type

Vertical Fire Damper

### Damper Size

10" Round

### Damper Manufacturer

Ruskin

### Damper Model #

IBD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

9x5 Oval

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <u>1-31-22</u>	Reference I.D. #: <u>2FL-FD9</u> <u>NORTH</u>
Inspected By: <u>Gue</u>	
Next Inspect. By: <u>1-31-24(Y)</u>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Room 249

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD10 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

21x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-09

**Facility Location**

Old Police Dept Building

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD10 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Carpenter removed trim  
Very dirty

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

NE closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD11 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Changed link


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-01-31

### Facility Location

Old Police Dept Building

### Damper Location

Room 230

### Inspector Name

Julie Gue

### Damper I.D. #

2FL-FD12 North

### Damper Type

Vertical Fire Damper

### Damper Size

64x14

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

Open duct

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-01-31

**Facility Location**

Old Police Dept Building

**Damper Location**

Room 228

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD13 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

50x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

Room 227

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD14 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11x11

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 2-1-22	Reference I.D.# 2FL-FD14
Inspected By: GUE	NORTH
Next Inspect. By: 2-1-24(M)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

RM 225

**Inspector Name**

Julie Gue

**Damper I.D. #**

2FL-FD15 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Changed link

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

West waiting room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4 FL-FD14 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

56x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

West corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

36x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

SE corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10 oval

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

West corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

11" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Changed link


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

SE corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

NW corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-02-01

**Facility Location**  
Old Police Dept Building

**Damper Location**  
SE corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
4FL-FD3 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
24x18

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD60


**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
14x14

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 2-1-22	Reference ID # 4FL-FD3
Inspected By: GUE	South
Next Inspect. By: 2-1-24(v)	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
216-391-2400 F 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

Women's toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-02-01

**Facility Location**  
Old Police Dept Building

**Damper Location**  
SE Infront of stairwell A

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
4FL-FD4 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
18x12

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12x12

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 2-1-22	Reference I.D.#: 4FL-FD4
Inspected By: Gue	South
Next Inspect. By: 2-1-24(N)	

Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-02-02

### Facility Location

Old Police Dept Building

### Damper Location

Women's toilet

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-FD5 North

### Damper Type

Vertical Fire Damper

### Damper Size

22x10

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

11x9

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

50x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x9

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

Women's toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

SW corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

NE corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-02-01

**Facility Location**  
Old Police Dept Building

**Damper Location**  
SW corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
4FL-FD7 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
30x14

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
16x16

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

NE corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

72x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

Waiting room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD8 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

File room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD9 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: <u>2-2-22</u>	Reference I.D.#: <u>4FL-FD9</u>
Inspected By: <u>GVE</u>	<u>NORTH</u>
Next Inspect. By: <u>2-2-24</u>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-01

**Facility Location**

Old Police Dept Building

**Damper Location**

Waiting room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD9 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-02-02

**Facility Location**  
Old Police Dept Building

**Damper Location**  
File room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
4FL-FD10 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
6" Round


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>2-2-22</b>	Reference I.D.#: <b>4FL-FD10</b>
Inspected By: <b>Gue</b>	<b>NORTH</b>
Next Inspect. By: <b>2-2-24(M)</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-02-08

### Facility Location

Old Police Dept Building

### Damper Location

Corridor

### Inspector Name

Julie Gue

### Damper I.D. #

4FL-FD10 South

### Damper Type

Vertical Fire Damper

### Damper Size

28x12

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

14x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Installed larger access door


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

File room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD11 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-02

**Facility Location**

Old Police Dept Building

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD12 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Files

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD12 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

34x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Installed larger access

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD13 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

64x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Files

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD13 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-09

**Facility Location**

Old Police Dept Building

**Damper Location**

South corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD14 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x24

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Carpenter needed dirty

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD15 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-08

**Facility Location**

Old Police Dept Building

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD16 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x8 oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Cleaning closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD17 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

6x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

5x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-07

**Facility Location**

Old Police Dept Building

**Damper Location**

Cleaning closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD18 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-02-08

**Facility Location**

Old Police Dept Building

**Damper Location**

East corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

4FL-FD19 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x12 Oval

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Installed larger access.

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

