

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
123	FSD	AHU T01-R	120x60	Ruskin	14x14	FSD60	Pass	Pass	10th Floor Penthouse
124	FD	AHU T01-R2	50x50	Greenheck	16x16	DFDTT210	Pass	Pass	10th Floor Penthouse
125	SD	AHU T01-R2	50X50	Ruskin	16X16	SD60	Pass	Pass	10th Floor Penthouse
126	FSD	AHU T01-S	78X60	Ruskin	20X20	FSD60	Pass	Pass	10th Floor Penthouse
127	FSD	AHU T02-R	120X60	Ruskin	14X14	FSD60	Pass	Pass	10th Floor Penthouse
128	FSD	AHU T02-S	78X60	Ruskin	14X14	FSD60	Pass	Pass	10th Floor Penthouse
129	FD	AHU-001-R	64X17	Ruskin	Man DR	IBD2	Pass	Pass	129
130	FD	AHU-001-S	40X20	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
131	FD	AHU-002-R	84X25	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
132	FD	AHU-002-S	48X22	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
133	FD	AHU-004-R	73X18	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
134	FD	AHU-004-S	48X22	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
135	FD	AHU-005-R	54X17	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
136	FD	AHU-005-S	40X22	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: July 18, August 7, 10 ,11 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
140	FD	AHU-008-R	48X26	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
141	FD	AHU-008-S	24X24	Ruskin	12X12	IBD2	Pass	Pass	Penthouse 5
124	FD	AHU-009-R	58X18	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
143	FD	AHU-009-S	26X26	Ruskin	BELOW	IBD2	Pass	Pass	Penthouse 5
144	FD	AHU-010-R	58X16	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
145	FD	AHU-010-S	25X25	Ruskin	BELOW	IBD2	Pass	Pass	Penthouse 5
146	FD	AHU-011-R	67X18	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
147	FD	AHU-011-S	44X22	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
148	FD	AHU-012-R	67X15	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
149	FD	AHU-012-S	67X15	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August10 and11, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU T02-S

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

78" x 60"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-07

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse

### Inspector Name

Julie Gue

### Damper I.D. #

AHU TO1-R

### Damper Type

Horizontal Fire / Smoke Damper

### Damper Size

120" x 60"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

14" x 14"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
AHU T02-R

**Damper Type**  
Horizontal Fire / Smoke Damper

**Damper Size**  
120" x 60"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
14" x 14"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU001-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

40"x20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU002-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

83.5"x23.25"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU002-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

48"x22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-X1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

# FIRE DAMPER

Inspection Date:  
**7-14-23**  
Inspected By:  
**TULCEWICZ**  
Next Inspect. By:  
**7-14-25**

Reference I.D.#  
**AHUI02-EX1**

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P. 216-351-2400 F. 216-351-2492

**FIRE SAFETY DIVISION**  
NFPA Certified HVAC Fire Life Safety Technicians





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU004-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

73"x18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU004-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

48"x22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU005-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

63"x20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU005-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

40"x22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU008-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

48" x 26"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU-008-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU009-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

58" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-11

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU010-R

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
58" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
Screen

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU011-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

67" x 18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU011-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

44" x 22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU012-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

67" x 15"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU012-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

38" x 19"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1	FD	AHU101-EX	10X8	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
2	FD	AHU101-R1	23X11	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
3	FD	AHU101-R2	13X11	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
4	FD	AHU101-R3	12X8	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
5	FD	AHU101-R4	16X16	Ruskin	16X16	IBD2	Pass	N/A	Penthouse 1
6	FD	AHU101-R5	8X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
7	FD	AHU101-R6	9X9	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
8	FD	AHU101-S1	13X23	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
9	FD	AHU101-S2	15X15	Ruskin	8x8	IBD2	Pass	N/A	Penthouse 1
10	FD	AHU101-S3	15X13	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
11	FD	AHU101-S4	16X14	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
12	FD	AHU101-S5	17X15	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
13	FD	AHU101-S6	18X16	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
14	FD	AHU101-S7	13X23	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
15	FD	AHU101-S8	13X17	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1

Inspector: Julie Gue / Dan Tulcewicz/Larry Coreno

Inspection Dates: 13-Jul-23

Facility: Juvenile Justice Center

SA = Supply Air

RA = Return Air

EA = Exhaust Air

FD = Fire Damper

SD = Smoke Damper

FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Picture of Damper in Open Position**



**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-EX1

**Picture of Damper in Closed Position**



**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Picture of Damper I.D. Label**



**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R1

**Damper Type**

Vertical Fire Damper

**Damper Size**

23" x 11 "

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R2

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" x 11"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-13

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU101-R3

### Damper Type

Horizontal Fire Damper

### Damper Size

12 "x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

8" x 8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-13

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU101-R6

### Damper Type

Vertical Fire Damper

### Damper Size

10" x 10"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

8" x 8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S2

**Damper Type**

Vertical Fire Damper

**Damper Size**

16" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S3

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S4

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-13

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU101-S5

### Damper Type

Vertical Fire Damper

### Damper Size

18"x16"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

10"x10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S7

**Damper Type**

Vertical Fire Damper

**Damper Size**

24"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S8

**Damper Type**

Vertical Fire Damper

**Damper Size**

24"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
16	FD	AHU102-EX	8X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
17	FD	AHU102-R1	12X12	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
18	FD	AHU102-R2	13X19	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
19	FD	AHU102-R3	8X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
20	FD	AHU102-R4	18X12	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
21	FD	AHU102-S1	13X23	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
22	FD	AHU102-S2	13X17	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
23	FD	AHU102-S3	13X11	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
24	FD	AHU102-S4	10X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
25	FD	AHU102-S5	15X17	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
26	FD	AHU102-S6	17X15	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1

Inspector: Julie Gue / Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 14-Jul  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R1

**Damper Type**

Vertical Fire Damper

**Damper Size**

9x9

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R2

**Damper Type**

Vertical Fire Damper

**Damper Size**

13x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-14-23</b>	Reference I.D. #: <b>AHU102-R2</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>7-14-25</b>	
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
MEMBER <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S1

**Damper Type**

Vertical Fire Damper

**Damper Size**

14.5"x22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S2

**Damper Type**

Vertical Fire Damper

**Damper Size**

14.5"x18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-14

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU102-S3

### Damper Type

Vertical Fire Damper

### Damper Size

13x11

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

10x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-14

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU102-S4

### Damper Type

Horizontal Fire Damper

### Damper Size

10"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S5

**Damper Type**

Vertical Fire Damper

**Damper Size**

15"x17"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S6

**Damper Type**

Vertical Fire Damper

**Damper Size**

17"x15"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
27	FD	AHU201-R1	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
28	FD	AHU201-R2	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
29	FD	AHU201-R3	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
30	FD	AHU201-R4	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
31	FD	AHU201-R5	24X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
32	FD	AHU201-R6	16X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
33	FD	AHU201-S1	25.5X16.5	Ruskin	24X24	IBD2	Pass	N/A	Penthouse 2
34	FD	AHU201-S2	16X14	Ruskin	12x12	IBD2	Pass	N/A	Penthouse 2
35	FD	AHU201-S3	16X12	Ruskin	12X12	IBD2	Pass	N/A	Penthouse 2
36	FD	AHU201-S4	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 2
37	FD	AHU201-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 2
38	FD	AHU201-S6	10X10	Ruskin	8x8	IBD2	Pass	N/A	Penthouse 2

Inspector: Julie Gue / Tulcewicz/ Larry Coreno  
Inspection Dates: 17-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-17

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU201-R1

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-17

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU201-R4

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
8"x8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-17

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #2

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU201-R5

### Damper Type

Horizontal Fire Damper

### Damper Size

24"x12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

25.5"x16.5"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-17

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU201-S6

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
10"x10"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
8"x8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
39	FD	AHU202-R1	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
40	FD	AHU202-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
41	FD	AHU202-R3	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
42	FD	AHU202-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
43	FD	AHU202-R5	18X14	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
44	FD	AHU202-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
45	FD	AHU202-S1	16X12	Ruskin	12x12	IBD2	Pass	Pass	Penthouse 2
46	FD	AHU202-S2	14X14	Ruskin	12x12	IBD2	Pass	Pass	Penthouse 2
47	FD	AHU202-S3	18X14	Ruskin	8x8	IBD2	Pass	Pass	Penthouse 2
48	FD	AHU202-S4	18X7	Ruskin	6x6	IBD2	Pass	Pass	Penthouse 2
49	FD	AHU202-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	Penthouse 2
50	FD	AHU202-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	Penthouse 2

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 17-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
RA = Return Air      SD = Smoke Damper  
EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-17

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #2

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU202-R1

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"


### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-17-23</b>	Reference I.D.#: <b>AHU202-R1</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>7-17-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b>	
<small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER</small>	
<b>NFPA</b>	



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-17

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #2

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU202-R2

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-17-23</b>	Reference I.D. #
Inspected By: <b>TULCEWICZ</b>	<b>AHU202-R2</b>
Next Inspect. By: <b>7-17-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
	
<small>NEMI Certified HVAC Fire Life Safety Technicians</small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-17

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU202-R4

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-17-23</b>	Reference I.D. #: <b>AHU202-R4</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>7-17-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small><b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-17

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #2

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU202-R5

### Damper Type

Horizontal Fire Damper

### Damper Size

18"x14"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-17

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU202-R6

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU202-S1

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU202-S2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
14"x14"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
51	FD	AHU301-R1	12X12	Ruskin	24x24	IBD2	Pass	Pass	None
52	FD	AHU301-R2	12X12	Ruskin	24x24	IBD2	Pass	Pass	None
53	FD	AHU301-R3	8X8	Ruskin	24x24	IBD2	Pass	Pass	None
54	FD	AHU301-R4	8X8	Ruskin	24x24	IBD2	Pass	Pass	None
55	FD	AHU301-R5	24X12	Ruskin	24x24	IBD2	Pass	Pass	None
56	FD	AHU301-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	None
57	FD	AHU301-S1	26X14	Ruskin	12x12	IBD2	Pass	Pass	None
58	FD	AHU301-S2	16X14	Ruskin	12x12	IBD2	Pass	Pass	None
59	FD	AHU301-S3	16X12	Ruskin	10X10	IBD2	Pass	Pass	None
60	FD	AHU301-S4	18X7	Ruskin	6x6	IBD2	Pass	Pass	None
61	FD	AHU301-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	None
62	FD	AHU301-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	None

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 7-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-20

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #3

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU301-R3

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>7-20-23</b>	Reference I.D.#
Inspected By: <b>TULCEWICZ</b>	<b>AHU301-R3</b>
Next Inspect. By: <b>7-20-25</b>	
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE**  
**DAMPER**

Inspection Date: <b>7-20-23</b>	Reference I.D.#: <b>AHU301-R5</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>7-20-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE**  
**DAMPER**

Inspection Date: <b>7-20-23</b>	Reference I.D.#: <b>AHU301-S5</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>7-20-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
63	FD	AHU302-R1	8X8	Ruskin	24x24	IBD2	Pass	Pass	
64	FD	AHU302-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	
65	FD	AHU302-R3	12X12	Ruskin	24x24	IBD2	Pass	Pass	
66	FD	AHU302-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	
67	FD	AHU302-R5	18X14	Ruskin	24x24	IBD2	Pass	Pass	
68	FD	AHU302-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	
69	FD	AHU302-S1	14X14	Ruskin	10X10	IBD2	Pass	Pass	
70	FD	AHU302-S2	16X12	Ruskin	12x12	IBD2	Pass	Pass	
71	FD	AHU302-S3	18X14	Ruskin	8x8	IBD2	Pass	Pass	
72	FD	AHU302-S4	18X7	Ruskin	8X8	IBD2	Pass	Pass	
73	FD	AHU302-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	
74	FD	AHU302-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 19-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-19-23</b>	Reference I.D. #: <b>AHU302-R3</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>7-19-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small><b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: <b>7-19-23</b>	Reference I.D.#:
Inspected By: <b>Tulcewicz</b>	<b>AHU302-S1</b>
Next Inspect. By: <b>7-19-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #3

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU302-S2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-19-23</b>	Reference I.D.#:
Inspected By: <b>Tulcewicz</b>	<b>AHU302-S2</b>
Next Inspect. By: <b>7-19-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small><b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 7-19-23	Reference I.D. #
Inspected By: TULCEWICZ	AHU302-S5
Next Inspect. By: 7-19-25	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-19

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #3

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU302-S6

### Damper Type

Horizontal Fire Damper

### Damper Size

10"x10"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

8"x8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>7-19-23</b>	Reference I.D. #: <b>AHU302-S6</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect By: <b>7-19-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
75	FD	AHU401-R1	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
76	FD	AHU401-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
77	FD	AHU401-R3	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
78	FD	AHU401-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
79	FD	AHU401-R5	24X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
80	FD	AHU401-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
81	FD	AHU401-S1	10X10	Ruskin	6X6	IBD2	Pass	Pass	Penthouse 4
82	FD	AHU401-S2	18X7	Ruskin	6X6	IBD2	Pass	Pass	Penthouse 4
83	FD	AHU401-S3	18X7	Ruskin	10X10	IBD2	Pass	Pass	Penthouse 4
84	FD	AHU401-S4	16X12	Ruskin	10X10	IBD2	Pass	Pass	Penthouse 4
85	FD	AHU401-S5	16X14	Ruskin	12X12	IBD2	Pass	Pass	Penthouse 4
86	FD	AHU401-S6	26X14	Ruskin	12X12	IBD2	Pass	Pass	Penthouse 4

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 7-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-21

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU401-R2

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-21-23</b>	Reference I.D. #: <b>AHU401-R2</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>7-21-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER</small> <b>NFPA</b>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-21

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU401-R3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: <b>7-21-23</b>	Reference I.D. #: <b>AHU401-R4</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>7-21-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-20

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU401-S2

### Damper Type

Horizontal Fire Damper

### Damper Size

18"x7"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-20

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU401-S3

### Damper Type

Horizontal Fire Damper

### Damper Size

18"x7"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

10"x10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
87	FD	AHU402-R1	8X8	Ruskin	24x24	IBD2	Pass	Pass	
88	FD	AHU402-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	
89	FD	AHU402-R3	12X12	Ruskin	24x24	IBD2	Pass	Pass	
90	FD	AHU402-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	
91	FD	AHU402-R5	18X14	Ruskin	24x24	IBD2	Pass	Pass	
92	FD	AHU402-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	
93	FD	AHU402-S1	14X14	Ruskin	12x12	IBD2	Pass	Pass	
94	FD	AHU402-S2	16X12	Ruskin	12x12	IBD2	Pass	Pass	
95	FD	AHU402-S3	18X14	Ruskin	12X12	IBD2	Pass	Pass	
96	FD	AHU402-S4	18X7	Ruskin	6x6	IBD2	Pass	Pass	
97	FD	AHU402-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	
98	FD	AHU402-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 21-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air     SD = Smoke Damper  
 EA = Exhaust Air     FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 7-21-23	Reference I.D. #: AHU-402
Inspected By: Tulcewicz	R1
Next Inspect. By: 7-21-25	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-21

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU402-R2

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: 7-21-23	Reference I.D.#:
Inspected By: Tulcewicz	AHU-402
Next Inspect. By: 7-21-25	R2
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
MEMBER <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-21

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-R3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-R4

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-21

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-R6

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-S1

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
14"x14"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-S2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-S5

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
18"x7"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6"x6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-24-23</b>	Reference I.D.#:
Inspected By: <b>Tulcewicz</b>	<b>AHU-402</b>
Next Inspect. By: <b>7-24-25</b>	<b>S5</b>
Duct Fabricators, Inc. <b>FIRE SAFETY DIVISION</b> MEMBER 883 Addison Rd. Cleveland, Ohio NEMI Certified HVAC Fire Life Safety Technicians <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
99	FD	AHU501-R1	24X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
100	FD	AHU501-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
101	FD	AHU501-R3	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
102	FD	AHU501-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
103	FD	AHU501-R5	16X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
104	FD	AHU501-R6	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
105	FD	AHU501-S1	24X14	Ruskin	12x12	IBD2	Pass	Pass	Penthouse 5
106	FD	AHU501-S2	16X14	Ruskin	12x12	IBD2	Pass	Pass	Penthouse 5
107	FD	AHU501-S3	16X14	Ruskin	12X12	IBD2	Pass	Pass	Penthouse 5
108	FD	AHU501-S4	18X7	Ruskin	6x6	IBD2	Pass	Pass	Penthouse 5
109	FD	AHU501-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	Penthouse 5
110	FD	AHU501-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	Penthouse 5

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 24-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU501-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU501-R2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
8"x8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**FIRE DAMPER**

Inspection Date: 7-24-23  
Inspected By: TULCEWICZ  
Next Inspect. By: 7-24-25

Reference I.D.#: AHU501-R2

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-24

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #5

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU501-R3

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

6"x6"


### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>7-24-23</b>	Reference I.D. #
Inspected By: <b>TULCEWICZ</b>	<b>AHU501-R3</b>
Next Inspect. By: <b>7-24-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	<small>MEMBER <b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians <b>NFPA</b></small>

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-24

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #5

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU501-R4

### Damper Type

Horizontal Fire Damper

### Damper Size

12"x12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"


### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU501-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU501-R6

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>7-24-23</b>	Reference I.D.#
Inspected By: <b>TULCEWICZ</b>	<b>AHU501-R6</b>
Next Inspect. By: <b>7-24-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	<small>MEMBER <b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians <b>NFPA</b></small>

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU501-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-10

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #5

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU501-S2

### Damper Type

Horizontal Fire Damper

### Damper Size

16" x 14"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"


### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>8-10-23</b>	Reference I.D.#: <b>AHU501-S2</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>8-10-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU501-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU501-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU501-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center



**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU501-S6

**Picture of Damper in Closed Position**

**Damper Type**  
Horizontal Fire Damper



**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Picture of Damper I.D. Label**

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
111	FD	AHU502-R1	12X12	Ruskin	24x24	IBD2	Pass	Pass	
112	FD	AHU502-R2	12X12	Ruskin	24x24	IBD2	Pass	Pass	
113	FD	AHU502-R3	8X8	Ruskin	24x24	IBD2	Pass	Pass	
114	FD	AHU502-R4	8X8	Ruskin	24x24	IBD2	Pass	Pass	
115	FD	AHU502-R5	16X12	Ruskin	24x24	IBD2	Pass	Pass	
116	FD	AHU502-R6	18X14	Ruskin	24x24	IBD2	Pass	Pass	
117	FD	AHU502-S1	12X12	Ruskin	12x12	IBD2	Pass	Pass	
118	FD	AHU502-S2	16X12	Ruskin	12x12	IBD2	Pass	Pass	
119	FD	AHU502-S3	18X14	Ruskin	8x8	IBD2	Pass	Pass	
120	FD	AHU502-S4	18X7	Ruskin	12X12	IBD2	Pass	Pass	
121	FD	AHU502-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	
122	FD	AHU502-S6	10X10	Ruskin	6X6	IBD2	Pass	Pass	

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno

Inspection Dates: 10-Aug-23

Facility: Juvenile Justice Center

SA = Supply Air

RA = Return Air

EA = Exhaust Air

FD = Fire Damper

SD = Smoke Damper

FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24" x 24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-R2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24" x 24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>8-10-23</b>	Reference I.D. #: <b>AHU502-R2</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>8-10-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER FOR  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center



**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-R3

**Picture of Damper in Closed Position**

**Damper Type**  
Horizontal Fire Damper



**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Picture of Damper I.D. Label**

**Access Door Size**  
24" x 24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>8-10-23</b>	Reference I.D.# <b>AHU502-R3</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>8-10-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd., Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small>MEMBER <b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-10

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #5

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU502-R4

### Damper Type

Horizontal Fire Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24" x 24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>8-10-23</b>	Reference I.D.#
Inspected By: <b>TULCEWICZ</b>	<b>AHU502-</b>
Next Inspect By: <b>8-10-25</b>	<b>R4</b>
Duct Fabricators, Inc. <b>FIRE SAFETY DIVISION</b> MEMBER 883 Addison Rd. Cleveland, Ohio NEMI Certified HVAC Fire Life Safety Technicians <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-R5

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24" x 24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center



**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-R6

**Picture of Damper in Closed Position**

**Damper Type**  
Horizontal Fire Damper



**Damper Size**  
18" x 14"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2


**Fusible Link Temperature**  
212 Degrees

**Picture of Damper I.D. Label**

**Access Door Size**  
24" x 24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-S1

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
14" x 14"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-S2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

C

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

78" x 60"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD1630

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

20" x 20"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Basement

**Inspector Name**

Julie Gue

**Damper I.D. #**

Basement FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

35" x 15.5"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-07

### Facility Location

Juvenile Justice Center

### Damper Location

Basement

### Inspector Name

Julie Gue

### Damper I.D. #

Basement FD2

### Damper Type

Vertical Fire Damper

### Damper Size

10" Round

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Screen

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Basement

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
Basement FD3

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
32" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
10" x 10"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
170	SD	IM121-SD12	18X12	Greenheck	12X12	SMD201	Pass	Pass	Transportation
171	SD	IM121-SD13	12X8	Ruskin	6X6	SD50	Pass	Pass	Prints Room
172	SD	IM121-SD14	12X10	Ruskin	6X6	SD50	Pass	Pass	Prints Room
173	SD	IM121-SD15	36X30	Greenheck	Screen	SMD201	Pass	Pass	None

Inspector: Julie Gue / Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 4 and 28, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
203	FSD	IM131-FSD1	12X10	Greenheck	8x8	FSD311	Pass	Pass	Employee restroom
204	SD	IM131-SD1	10X8	Greenheck	8x8	SMD301	Pass	Pass	Mediation
205	SD	IM131-SD2	26X6	Greenheck	Open	SMD301	Pass	Pass	Mediation
206	FD	IM132-FD1	24X12	Ruskin	10x10	IBD2	Pass	Pass	Vestibule
207	FSD	IM132-FSD1	12X20	Ruskin	6x6	FSD60	Pass	Pass	West Mechanical Room
208	FSD	IM132-FSD2	30X12	Ruskin	6x6	FSD60	Pass	Pass	West Mechanical Room
209	FSD	IM132-FSD3	30X12	Ruskin	6x6	FSD60	Pass	Pass	East Mechanical Room
210	FSD	IM132-FSD4	12X20	Ruskin	6x6	FSD60	Pass	Pass	East Mechanical Room
211	FSD	IM132-FSD5	8X8	Ruskin	Grille	FSD60	Pass	Pass	Custodial Closet
212	FSD	IM132-FSD6	50X24	Ruskin	10x10	FSD60	Pass	Pass	Main Corridor
213	FSD	IM132-FSD7	60X24	Ruskin	Screen	FSD60	Pass	Pass	Main Corridor
214	FSD	IM132-FSD8	60X30	Ruskin	14x14	FSD60	Pass	Pass	Training Room
215	FSD	IM132-FSD9	60X24	Ruskin	16x16	FSD60	Pass	Pass	Training Room
216	FSD	IM133-FSD1	10" Round	Greenheck	9x6 Oval	FSDR511	Pass	Pass	
217	FSD	IM133-FSD2	12X10	Greenheck	6x6	FSD311	Pass	Pass	RM 3106
218	SD	IM133-SD1	8" Round	Greenheck	9x6 Oval	SMD201	Pass	Pass	RM 3206
219	SD	IM133-SD2	10x10	Greenheck	8x8	SMD201	Pass	Pass	RM 3206
220	SD	IM133-SD3	8x10	Greenheck	8x8	SMD201	Pass	Pass	RM 3206
221	SD	IM133-SD4	36x16	Greenheck	Open	SMD301	Pass	Pass	RM #3207

Inspector: Julie Gue /Dan Tulcewicz /Larry Coreno  
Inspection Dates: August 3, 2023, September 18 and 19, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
222	SD	IM133-SD5	26X6	Greenheck	Open	SMD301	Pass	Pass	RM #3209
223	SD	IM133-SD6	6" Round	Greenheck	8x8	SMDR301	Pass	Pass	RM # 3109
224	SD	IM133-SD7	12X10	Greenheck	6x6	SMD301	Pass	Pass	RM # 3106
225	SD	IM133-SD8	26X8	Greenheck	Open	SMD301	Pass	Pass	RM # 3106

Inspector: Julie Gue, Larry Coreno  
Inspection Dates: August 3, September 18 and 19, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
225	FSD	IM141-FSD1	8X8	Greenheck	8X8	FSD211	Pass	Pass	Women's Restroom
226	SD	IM141-SD1	14" Round	Greenheck	9X6 Oval	SMD501	Pass	Pass	Main corridor
227	SD	IM141-SD2	26X6	Greenheck	Open	SMD301	Pass	Pass	Main corridor
228	SD	IM141-SD3	26X6	Greenheck	Open	SMD301	Pass	Pass	Women's Restroom
229	SD	IM141-SD4	8" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM #4812
230	SD	IM141-SD5	8" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM #4812
231	SD	IM141-SD6	6" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM #4812
232	SD	IM141-SD7	10" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM# 4805
233	SD	IM141-SD8	10" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM# 4805
234	SD	IM141-SD9	15X16	Greenheck	12X12	SMD301	Pass	Pass	RM# 4805
235	SD	IM141-SD10	14" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	Main corridor
236	SD	IM141-SD11	14" Round	Greenheck	3X3	SMDR301	Pass	Pass	Main corridor
237	SD	IM141-SD12	8" Round	Greenheck	9" x 6" Oval	SMDR301	Pass	Pass	RM #4612
238	SD	IM141-SD13	10" x 8"	Greenheck	8' x 8"	SMD211	Pass	Pass	RM #4611
239	SD	IM141-SD14	26" x 12"	Greenheck	5" x 5"	SMD211	Pass	Pass	RM #4611
240	SD	IM141-SD15	8" x 10"	Greenheck	8" x 8"	SMD211	Pass	Pass	RM #4611
241	SD	IM141-SD16	10" Round	Greenheck	9" x 6" Oval	SMDR211	Pass	Pass	RM #4611
242	FSD	IM142-FSD1	12X20	Ruskin	6X6	FSD60	Pass	Pass	Electrical room
243	FSD	IM142-FSD2	30X12	Ruskin	6X6	FSD60	Pass	Pass	Electrical room
244	FSD	IM142-FSD3	30X12	Ruskin	6X6	FSD60	Pass	Pass	Electrical room
245	FSD	IM142-FSD4	12X20	Ruskin	6X6	FSD60	Pass	Pass	Electrical room
246	FSD	IM142-FSD5	8X8	Ruskin	Grille	FSD60	Pass	Pass	Custodial closet
247	FSD	IM142-FSD6	20X10	Greenheck	6X6	FSD211	Pass	Pass	RM#4503
248	FSD	IM142-FSD7	14X10	Greenheck	6X6	FSD211	Pass	Pass	RM#4308
249	FSD	IM142-FSD8	60X20	Ruskin	60X24	FSD60	Pass	Pass	Main corridor

Inspector: Julie Gue, Larry Coreno  
Inspection Dates: August 3 and 30, October 4 and 5, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	FD/SD/FSD	I.D.#	Size	Manufacturer	A/D	Model	Visual	Functional	Comments
250	FSD	IM142-FSD9	48X24	Ruskin	12X12	FSD60	Pass	Pass	Main corridor
251	FSD	IM142-FSD10	54X24	Ruskin	12X12	FSD60	Pass	Pass	Main corridor
252	FSD	IM142-FSD11	60X24	Ruskin	12X12	FSD60	Pass	Pass	Main corridor
253	SD	IM142-SD1	10X10	Greenheck	8X8	SMD301	Pass	Pass	RM #4610
254	SD	IM142-SD2	26" x 6"	Greenheck	Open	SMD301	Pass	Pass	Corridor
255	SD	IM142-SD3	26" x 6"	Greenheck	Open	SMD301	Pass	Pass	RM #4404
256	FSD	IM143-FSD1	12X10	Greenheck	8x8	FSD211	Pass	Pass	RM #4107
257	FSD	IM143-SD1	10X12	Greenheck	8X8	SMD301	Pass	Pass	RM #4406
258	FSD	IM143-SD2	10" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM #4405

Inspector: Julie Gue/ Larry Coreno  
Inspection Dates: October 3 and 4, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
259	FSD	IM151-FSD1	10X8	Greenheck	8X7	FSD211	Pass	Pass	None
260	SD	IM151-SD1	12X10	Greenheck	8X8	SMD201	Pass	Pass	RM #5146
261	FD	IM152-FD1	24X12	Ruskin	12X12	IBD2	Pass	Pass	Elevator Lobby
262	FD	IM152-FD2	18X18	Greenheck	Screen	DFD150	Pass	Pass	RM #5150
263	FD	IM152-FD3	18X18	Greenheck	Screen	DFD150	Pass	Pass	RM #5150
264	FSD	IM152-FSD1	12X20	Ruskin	6X6	FSD60	Pass	Pass	West Mechanical Rm
265	FSD	IM152-FSD2	30X12	Ruskin	6X6	FSD60	Pass	Pass	West Mechanical Rm
266	FSD	IM152-FSD3	30X12	Ruskin	6X6	FSD60	Pass	Pass	East Mechanical Rm
267	FSD	IM152-FSD4	12X20	Ruskin	6X6	FSD60	Pass	Pass	East Mechanical Rm
268	FSD	IM152-FSD5	16X10	Ruskin	12X12	FSD60	Pass	Pass	Elevator Lobby
269	FSD	IM152-FSD6	8X8	Ruskin	Grille	FSD60	Pass	Pass	Custodial Closet
270	FSD	IM152-FSD7	48X24	Ruskin	14X14	FSD60	Pass	Pass	None
271	FSD	IM152-FSD8	60X30	Ruskin	12X12	FSD60	Pass	Pass	None
272	FSD	IM152-FSD9	60X30	Ruskin	Screen	FSD60	Pass	Pass	Main Corridor
273	FSD	IM152-FSD10	48X24	Ruskin	10X10	FSD60	Pass	Pass	None
274	FSD	IM152-FSD11	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
275	FSD	IM152-FSD12	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
276	FSD	IM153-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	None

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 2 and 16,  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
277	FSD	IM161-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	West sitting area
278	FSD	IM162-FSD1	12X20	Ruskin	6X6	FSD60	Pass	Pass	West Mechanical rm
279	FSD	IM162-FSD2	30X12	Ruskin	6X6	FSD60	Pass	Pass	West Mechanical rm
280	FSD	IM162-FSD3	30X12	Ruskin	6X6	FSD60	Pass	Pass	East Mechanical Rm
281	FSD	IM162-FSD4	12X20	Ruskin	6X6	FSD60	Pass	Pass	East Mechanical Rm
282	FSD	IM162-FSD5	48X24	Ruskin	14X14	FSD60	Pass	Pass	Main Corridor
283	FSD	IM162-FSD6	60X24	Ruskin	16X16	FSD60	Pass	Pass	Main Corridor
284	FSD	IM162-FSD7	48X24	Ruskin	12X12	FSD60	Pass	Pass	Main Corridor
285	FSD	IM162-FSD8	60x24	Ruskin	Screen	FSD60	Pass	Pass	Main Corridor
286	FSD	IM162-FSD9	14X8	Greenheck	12X12	FSD211	Pass	Pass	Woman's Room
287	FSD	IM162-FSD10	14X8	Greenheck	12X12	FSD211	Pass	Pass	Men's Room
288	FSD	IM162-FSD11	8X8	Ruskin	Grille	FSD60	Pass	Pass	Custodial Closet
289	FSD	IM162-FSD12	16X10	Ruskin	12X12	FSD60	Pass	Pass	Elevator Lobby
290	FSD	IM163-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	East Sitting Area

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 2 & 28, October 13, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
291	FSD	IM171-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	None
292	FD	IM172-FD1	24X12	Ruskin	10X10	IBD2	Pass	Pass	None
293	FSD	IM172-FSD1	12X20	Ruskin	6X6	FSD60	Pass	Pass	None
294	FSD	IM172-FSD2	30X12	Ruskin	6X6	FSD60	Pass	Pass	None
295	FSD	IM172-FSD3	30X12	Ruskin	6X6	FSD60	Pass	Pass	None
296	FSD	IM172-FSD4	12X20	Ruskin	6X6	FSD60	Pass	Pass	None
297	FSD	IM172-FSD5	8X8	Ruskin	Grille	FSD60	Pass	Pass	None
298	FSD	IM172-FSD6	16X10	Ruskin	12X12	FSD60	Pass	Pass	None
299	FSD	IM172-FSD7	60X24	Ruskin	14X14	FSD60	Pass	Pass	None
300	FSD	IM172-FSD8	48X24	Ruskin	14X14	FSD60	Pass	Pass	None
301	FSD	IM172-FSD9	48X24	Ruskin	10X10	FSD60	Pass	Pass	None
302	FSD	IM172-FSD10	60X24	Ruskin	12X12	FSD60	Pass	Pass	None
303	FSD	IM172-FSD11	14X8	Greenheck	12X12	FSD211	Pass	Pass	None
304	FSD	IM172-FSD12	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
305	FSD	IM173-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	None

Inspector: Julie Gue / Dan Tulcewicz / Larry Coreno  
Inspection Dates: August 24, 2023 & October 13, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
305	FSD	IM181-FSD1	12X8	Greenheck	12x12	FSD211	Pass	Pass	None
306	FSD	IM182-FSD1	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
307	FSD	IM182-FSD2	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
308	FSD	IM182-FSD3	24X12	Greenheck	8X8	FSD211	Pass	Pass	None
309	FSD	IM182-FSD4	8X8	Ruskin	Grille	FSD60	Pass	Pass	None
310	FSD	IM182-FSD5	60X24	Ruskin	16X16	FSD60	Pass	Pass	Main Corridor
311	FSD	IM182-FSD6	48X24	Ruskin	14X14	FSD60	Pass	Pass	Main Corridor
312	FSD	IM182-FSD7	12X20	Ruskin	6X6	FSD60	Pass	Pass	Electrical closet
313	FSD	IM182-FSD8	30X12	Ruskin	6X6	FSD60	Pass	Pass	Electrical closet
314	FSD	IM182-FSD9	12X20	Ruskin	6X6	FSD60	Pass	Pass	Electrical closet
315	FSD	IM182-FSD10	30X12	Ruskin	6X6	FSD60	Pass	Pass	Electrical closet
316	FSD	IM182-FSD11	54X24	Ruskin	14X14	FSD60	Pass	Pass	Main Corridor
317	FSD	IM182-FSD12	60X24	Ruskin	14X14	FSD60	Pass	Pass	Main Corridor
318	FSD	IM183-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	None

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 2 & October 12, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
319	FSD	IM191-FSD1	22X14	Greenheck	12X12	FSD211	Pass	Pass	None
320	FD	IM192-FD1	24x12	Ruskin	10X10	IBD2	Pass	Pass	Elevator lobby
321	FSD	IM192-FSD1	84X12	Ruskin	Screen Access	FSD60	Pass	Pass	Main Corridor
322	FSD	IM192-FSD2	8X8	Ruskin	Grille Access	FSD60	Pass	Pass	Storage
323	FSD	IM192-FSD3	36X10	Greenheck	8X8	FSD211	Paass	Pass	Womans rm
324	FSD	IM192-FSD4	36X10	Greenheck	10X10	FSD211	Paass	Pass	Mens room
325	FSD	IM192-FSD5	16X10	Ruskin	16X10	FSD211	Paass	Pass	Vestibule
326	SD	IM192-SD1	28X6	Greenheck	26X8	SMD201	Pass	Pass	Copy RM
327	SD	IM192-SD2	8" Round	Greenheck	9X6 Oval	SMDR501	Pass	Pass	Copy RM
328	FSD	IM193-FSD1	16X24	Greenheck	12X12	FSD211	Pass	Pass	Mens room

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: October 12 & 15, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
150	FD	IM121-FD1	8X8	Ruskin	8X8	IBD2	Pass	Pass	Room 209
151	FD	IM121-FD2	32X14	Ruskin	12X12	IBD2	Pass	Pass	Room 209
152	FD	IM121-FD3	30X18	Ruskin	12X12	IBD2	Pass	Pass	Room 209
153	FD	IM121-FD4	16X18	Ruskin	12X12	IBD2	Pass	Pass	Building Maintenance
154	FD	IM121-FD5	30X17	Ruskin	12X12	IBD2	Pass	Pass	Building Maintenance
155	FD	IM121-FD6	24X17	Ruskin	12X12	IBD2	Pass	Pass	Building Maintenance
156	FSD	IM121-FSD1	60X30	Ruskin	16x16	FSD60	Pass	Pass	None
157	FSD	IM121-FSD2	48X24	Ruskin	16x16	FSD60	Pass	Pass	RM #2826
158	FSD	IM121-FSD3	40X24	Ruskin	16X16	FSD60	Pass	Pass	Transportation
159	SD	IM121-SD1	24X12	Greenheck	10X10	SMD201	Pass	Pass	RM #2806
160	SD	IM121-SD2	14X12	Greenheck	10X10	SMD201	Pass	Pass	RM #2806
161	SD	IM121-SD3	14X12	Greenheck	12X12	SMD201	Pass	Pass	RM #2826
162	SD	IM121-SD4	10X8	Greenheck	6X6	SMD201	Pass	Pass	RM #2826
163	SD	IM121-SD5	24X12	Greenheck	12X12	SMD201	Pass	Pass	General Storage
164	SD	IM121-SD6	26X12	Greenheck	12X12	SMD201	Pass	Pass	General Storage
165	SD	IM121-SD7	18X12	Greenheck	8X8	SMD201	Pass	Pass	General Storage
166	SD	IM121-SD8	42X16	Greenheck	OPEN	SMD201	Pass	Pass	General Storage
167	SD	IM121-SD9	26X10	Greenheck	12X12	SMD201	Pass	Pass	General Storage
168	SD	IM121-SD10	26X6	Greenheck	OPEN	SMD201	Pass	Pass	Transportation
169	SD	IM121-SD11	8X8	Greenheck	9X6 Oval	SMD201	Pass	Pass	Transportation

Inspector: Julie Gue, Dan Tulcewicz, Larry Coreno

Inspection Dates: August 4 and 28, 2023

Facility: Juvenile Justice Center

SA = Supply Air

RA = Return Air

EA = Exhaust Air

FD = Fire Damper

SD = Smoke Damper

FSD = Fire Smoke Damper




## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center



**Damper Location**  
RM 209

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-FD1

**Picture of Damper in Closed Position**

**Damper Type**  
Horizontal Fire Damper



**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Picture of Damper I.D. Label**

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 209

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-FD2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
32" x 14"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>8/3/23</b>	Reference I.D. # <b>IM121</b>
Inspected By: <b>GW</b>	<b>FD2</b>
Next Inspect. By: <b>8/4/25</b>	

Duct Fabricators, Inc. **FIRE SAFETY DIVISION**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 209

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-FD3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
30" x 18"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Bldg Maintenance Office

**Inspector Name**

Larry Coreno

**Damper I.D. #**

IM121-FD5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30" x 17"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Bldg Maintenance Office

**Inspector Name**

Larry Coreno

**Damper I.D. #**

IM121-FD6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24" x 17"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Furniture storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Furniture storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

42" x 16"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Transportation office

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMF201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Transportation office

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-SD12

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
18" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" x 12"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Print Room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-SD13

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Print Room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-SD14

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 10"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
174	FD	IM122-FD1	9.25x9.25	Ruskin	8x8	IBD2	Pass	Pass	RM208
175	FD	IM122-FD2	36x16	Ruskin	16x16	IBD2	Pass	Pass	RM208
176	FD	IM122-FD3	24x16	Ruskin	16x16	IBD2	Pass	Pass	RM208
177	FD	IM122-FD4	36x16	Ruskin	16x16	IBD2	Pass	Pass	RM208
178	FD	IM122-FD5	24x16	Ruskin	16x16	IBD2	Pass	Pass	RM208
179	FD	IM122-FD6	10x10	Ruskin	8x8	IBD2	Pass	Pass	RM208
180	FD	IM122-FD7	96x30	Ruskin	16X16	IBD2	Pass	Pass	RM208
181	FSD	IM122-FSD1	60X30	Ruskin	16X16	IBD2	Pass	Pass	Main Corridor
182	FSD	IM122-FSD2	60X40	Ruskin	16X16	FSD60	Pass	Pass	Main Corridor
183	FSD	IM122-FSD3	60X30	Ruskin	16X16	FSD60	Pass	Pass	Rm 2402
184	FSD	IM122-FSD4	8X8	Ruskin	Grille	FSD60	Pass	Pass	Janitors Closet
185	FSD	IM122-FSD5	50X22	Greenheck	14X14	FSD311	Pass	Pass	Janitors Closet
186	FSD	IM122-FSD6	20X16	Ruskin	8X8	FSD60	Pass	Pass	None

Inspector: Julie Gue / Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 4 and 28, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
RA = Return Air      SD = Smoke Damper  
EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

9.25" x 9.25"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD2

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
36" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
24" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD4

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
36" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD6

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**FIRE DAMPER**

Inspection Date: 8/4/23  
Inspected By: Gw  
Next Inspect. By: 8/4/25

Reference I.D.#: IM122  
FD6

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD7

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
96" x 30"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16" - 3 doors

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 40"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2402

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-16

### Facility Location

Juvenile Justice Center

### Damper Location

Janitors closet .

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM122-FSD4

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-16

### Facility Location

Juvenile Justice Center

### Damper Location

Janitors closet .

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM122-FSD4

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
187	SD	IM123-SD1	14X12	Greenheck	10x10	SMD201	Pass	Pass	IT
188	SD	IM123-SD2	14X12	Greenheck	Open	SMD201	Pass	Pass	IT
189	SD	IM123-SD3	16" Round	Greenheck	9x6 Oval	SMDR201	Pass	Pass	IT
190	SD	IM123-SD4	10x12	Greenheck	8x8	SMD201	Pass	Pass	IT Storage
191	SD	IM123-SD5	14x12	Greenheck	Open	SMD201	Pass	Pass	IT Storage
192	SD	IM123-SD6	16x10	Greenheck	6x6	SMD201	Pass	Pass	IT Corridor
193	SD	IM123-SD7	8" Round	Greenheck	6x6	SMDR201	Pass	Pass	IT Corridor
194	SD	IM123-SD8	8" Round	Greenheck	Flex	SMDR201	Pass	Pass	IT Corridor
195	SD	IM123-SD9	12x12	Greenheck	Open	SMD201	Pass	Pass	Files
196	SD	IM123-SD10	16x12	Greenheck	Open	SMD201	Pass	Pass	Files
197	SD	IM123-SD11	12x12	Greenheck	Open	SMD201	Pass	Pass	RM 2110
198	SD	IM123-SD12	10" Round	Greenheck	6x6	SMDR201	Pass	Pass	RM 2110
199	SD	IM123-SD13	14X12	Greenheck	12x12	SMD201	Pass	Pass	RM 2110
200	SD	IM123-SD14	8" Round	Greenheck	6x6	SMDR201	Pass	Pass	RM 2110
201	SD	IM123-SD15	14" Round	Greenheck	6x9 Oval	SMDR201	Pass	Pass	Mail Room
202	SD	IM123-SD16	10x10	Greenheck	6x6	SMD201	Pass	Pass	Mail Room

Inspector: Julie Gue /Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 7-Sep-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Area

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Area

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

IT Area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SNDR201

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Storage

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD4

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Storage

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD5

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
24" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD6

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
16" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE DAMPER**

Inspection Date: **9 7 23** Reference I.D. #: **IM 123**

Inspected By: **GUE** **506**

Duct Fabricators, Inc. **FIRE SAFETY DIVISION**  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492 NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD7

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD8

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Flex

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Files

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD9

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Files Area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 2110

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD11

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 2110

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD12

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2110

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD13

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 2110

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD14

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"


**"Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Mail room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD15

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" oval


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE DAMPER**

Inspection Date: 9 7 23 Reference ID #: IM 123  
Inspected By: Gue SD 15

Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492  
**FIRE SAFETY DIVISION** NEMI Certified HVAC Fire Life Safety Technicians  
MEMBER **NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Mail Room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD16

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>SMOKE DAMPER</b>	
Inspection Date:	Reference I.D.#:
9 7 23	IM 123
Inspected By:	SD 16
GUE	
Duct Fabricators, Inc. 83 Addison Rd. Cleveland, Ohio 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM131-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD311

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Office

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM131-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM3810

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM131-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

By Stairwell #6

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM132-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
West Mechanical Room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM132-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
12" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

West Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

East Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

East Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-16

### Facility Location

Juvenile Justice Center

### Damper Location

Janitors closet.

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM132-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE/SMOKE DAMPER</b>	
Inspection Date: <b>8-16-23</b>	Reference I.D.#: <b>IM132-</b>
Inspected By: <b>Tulcewicz</b>	<b>FSD5</b>
Next Inspect. By: <b>8-16-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small>NEMI Certified HVAC Fire Life Safety Technicians</small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

50" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-28

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM132-FSD7

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Screen

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training Room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

60" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 3106

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD311

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 3206

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM133-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 3206

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM133-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 3206

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

36" x 16"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 3209

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SND301

**Fusible Link Temperature**

N/A

**Access Door Size**

Open


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 3109

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM133-SD6

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD301

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE DAMPER**

Inspection Date: <b>9-19-23</b>	Reference I.D. # <b>IM133 SD6</b>
Inspected By: <b>GUE</b>	

Duct Fabricators, Inc. **FIRE SAFETY DIVISION** MEMBER **NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Corridor by cubes

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Outside of 3106

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

28" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-04

### Facility Location

Juvenile Justice Center

### Damper Location

Women's room

### Inspector Name

Julie Gue

### Damper I.D. #

IM141-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Greenheck

### Damper Model #

FSD211

### Fusible Link Temperature

212 Degrees

### Access Door Size

8" x 8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE/SMOKE DAMPER</b>	
Inspection Date: <i>10-4-23</i>	Reference I.D.#: <b>IM141</b>
Inspected By: <i>Gue</i>	<b>FSD1</b>
Next Inspect. By: <i>10-4-25</i>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Main Corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR501

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Across from woman's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4812

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD4

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR301

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM4812

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD5

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR301


**Fusible Link Temperature**  
N/A

**Access Door Size**  
9x6 Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4812

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
South of RM 4805

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD7

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR301

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
9" x 6" oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

South of RM 4805

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15" x 16"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Main corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD10

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR301


**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>SMOKE DAMPER</b>	
Inspection Date: 10-4-23	Reference I.D.#: IM141 5010
Inspected By: Gue	
Next Inspect. By: 10-4-25	
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
MEMBER <b>NFPA</b>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD11

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

3" x 3"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4611

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD13

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
211


**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4611

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD14

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
26" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD211

**Fusible Link Temperature**  
N/A

**Access Door Size**  
5" x 5"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 4611

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD211

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4611

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD16

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
211

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
West mechanical room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM142-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
12" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

West mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-03

### Facility Location

Juvenile Justice Center

### Damper Location

East mechanical room

### Inspector Name

Julie Gue

### Damper I.D. #

IM142-FSD3

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

30" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

6" x 6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

Janitors' closet.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM142-FSD5

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4503

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM142-FSD6

**Damper Type**  
Horizontal Fire / Smoke Damper

**Damper Size**  
20" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
FSD211

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4308

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-30

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM142-FSD8

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 20"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-30

### Facility Location

Juvenile Justice Center

### Damper Location

Main Corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM142-FSD10

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

54" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

N/A

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4610

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM142-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
211

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

211

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4404

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SD3

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4612

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM142-SD12

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
211

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4107

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM143-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4405

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM143-SD1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD301

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4405

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM143-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR-301

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-13

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Women's room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM151-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
FSD211

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
8" x 7"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-13

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 5146

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM151-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM #5150

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

18" x 18"

**Damper Manufacturer**

Greenheck

**Damper Model #**

DFD150

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM #5150

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

18" x 18"

**Damper Manufacturer**

Greenheck

**Damper Model #**

DFD150

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-02

### Facility Location

Juvenile Justice Center

### Damper Location

West mechanical room

### Inspector Name

Julie Gue

### Damper I.D. #

IM152-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

12" x 20"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

6x6

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

West mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical Room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-16

### Facility Location

Juvenile Justice Center

### Damper Location

Elevator Lobby

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM152-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

16" x 10"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE/SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>8-16-23</b>	Reference I.D. #: <b>IM152-</b>
Inspected By: <b>Tulcewicz</b>	<b>FSD5</b>
Next Inspect. By: <b>8-16-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

Janitor's closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

West sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 8"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

East sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM153-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

West sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM161-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-02

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
West mechanical room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM162-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
12" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East Mechanical Room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD5

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-28

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM162-FSD6

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

16" x 16"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD8

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-13

### Facility Location

Juvenile Justice Center

### Damper Location

Men's room

### Inspector Name

Julie Gue

### Damper I.D. #

IM162-FSD10

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

14" x 8"

### Damper Manufacturer

Greenheck

### Damper Model #

FSD211

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-15

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Janitors closet.

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
IM162-FSD11

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Ruskin


**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
Grille

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator Lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Est sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM163-FSD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM171-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator Lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM172-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-02

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
West mechanical room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM172-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
12" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6x6

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-15

### Facility Location

Juvenile Justice Center

### Damper Location

Janitors' closet.

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM172-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Has been cleaned.  
Unable to remove  
All of the grim.

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label







Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-15

### Facility Location

Juvenile Justice Center

### Damper Location

Elevator Lobby

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM172-FSD6

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

16" x 10"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD8

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-23

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM172-FSD10

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Judges' elevator

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM173-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

West sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM181-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182 FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator Lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM182-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-15

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Janitors closet

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
IM182-FSD4

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
Grille

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-24

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM182-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

16" x 16"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-24

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM182-FSD6

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

14" x 14"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD8

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

West mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12"x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

West mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD10

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

54" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-12

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Sitting area

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM183-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
12" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
FSD211


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12" x 12"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Restroom

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM191-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

22" x 14"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator Lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM192-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD1

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

84" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Janitors closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM192-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

36" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

36" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-15

### Picture of Damper in Open Position



### Facility Location

Juvenile Justice Center

### Damper Location

Elevator Lobby

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM192-FSD5

### Picture of Damper in Closed Position



### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

16" x 10"

### Damper Manufacturer

Ruskin


### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Picture of Damper I.D. Label



### Access Door Size

10" x 10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Copy

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-SD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

28" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

26" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

South of copy room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR501

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-12

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Restroom

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM193-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
16" x 24"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
FSD211


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
123	FSD	AHU T01-R	120x60	Ruskin	14x14	FSD60	Pass	Pass	10th Floor Penthouse
124	FD	AHU T01-R2	50x50	Greenheck	16x16	DFDTT210	Pass	Pass	10th Floor Penthouse
125	SD	AHU T01-R2	50X50	Ruskin	16X16	SD60	Pass	Pass	10th Floor Penthouse
126	FSD	AHU T01-S	78X60	Ruskin	20X20	FSD60	Pass	Pass	10th Floor Penthouse
127	FSD	AHU T02-R	120X60	Ruskin	14X14	FSD60	Pass	Pass	10th Floor Penthouse
128	FSD	AHU T02-S	78X60	Ruskin	14X14	FSD60	Pass	Pass	10th Floor Penthouse
129	FD	AHU-001-R	64X17	Ruskin	Man DR	IBD2	Pass	Pass	129
130	FD	AHU-001-S	40X20	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
131	FD	AHU-002-R	84X25	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
132	FD	AHU-002-S	48X22	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
133	FD	AHU-004-R	73X18	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
134	FD	AHU-004-S	48X22	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
135	FD	AHU-005-R	54X17	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2
136	FD	AHU-005-S	40X22	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 2

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: July 18, August 7, 10 ,11 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
140	FD	AHU-008-R	48X26	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
141	FD	AHU-008-S	24X24	Ruskin	12X12	IBD2	Pass	Pass	Penthouse 5
124	FD	AHU-009-R	58X18	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
143	FD	AHU-009-S	26X26	Ruskin	BELOW	IBD2	Pass	Pass	Penthouse 5
144	FD	AHU-010-R	58X16	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
145	FD	AHU-010-S	25X25	Ruskin	BELOW	IBD2	Pass	Pass	Penthouse 5
146	FD	AHU-011-R	67X18	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
147	FD	AHU-011-S	44X22	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
148	FD	AHU-012-R	67X15	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
149	FD	AHU-012-S	67X15	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August10 and11, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU T02-S

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

78" x 60"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-07

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse

### Inspector Name

Julie Gue

### Damper I.D. #

AHU TO1-R

### Damper Type

Horizontal Fire / Smoke Damper

### Damper Size

120" x 60"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

14" x 14"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
AHU T02-R

**Damper Type**  
Horizontal Fire / Smoke Damper

**Damper Size**  
120" x 60"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
14" x 14"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU001-S

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
40"x20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
Remove the screen.

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU002-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

83.5"x23.25"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU002-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

48"x22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-X1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

# FIRE DAMPER

Inspection Date:  
**7-14-23**  
Inspected By:  
**TULCEWICZ**  
Next Inspect. By:  
**7-14-25**

Reference I.D.#  
**AH4102-EX1**

Duct Fabricators, Inc.  
8831 Addison Rd., Cleveland, Ohio  
P. 216-351-2400 F. 216-351-2492

**FIRE SAFETY DIVISION**  
NFPA Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU004-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

73"x18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU004-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

48"x22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU005-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

63"x20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU005-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

40"x22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Remove the screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU008-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

48" x 26"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU-008-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU009-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

58" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU010-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

58" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU011-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

67" x 18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU011-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

44" x 22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU012-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

67" x 15"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU012-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

38" x 19"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1	FD	AHU101-EX	10X8	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
2	FD	AHU101-R1	23X11	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
3	FD	AHU101-R2	13X11	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
4	FD	AHU101-R3	12X8	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
5	FD	AHU101-R4	16X16	Ruskin	16X16	IBD2	Pass	N/A	Penthouse 1
6	FD	AHU101-R5	8X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
7	FD	AHU101-R6	9X9	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
8	FD	AHU101-S1	13X23	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
9	FD	AHU101-S2	15X15	Ruskin	8x8	IBD2	Pass	N/A	Penthouse 1
10	FD	AHU101-S3	15X13	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
11	FD	AHU101-S4	16X14	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
12	FD	AHU101-S5	17X15	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
13	FD	AHU101-S6	18X16	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
14	FD	AHU101-S7	13X23	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
15	FD	AHU101-S8	13X17	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1

Inspector: Julie Gue / Dan Tulcewicz/Larry Coreno  
Inspection Dates: 13-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
RA = Return Air      SD = Smoke Damper  
EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Picture of Damper in Open Position**



**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-EX1

**Picture of Damper in Closed Position**



**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Picture of Damper I.D. Label**



**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R1

**Damper Type**

Vertical Fire Damper

**Damper Size**

23" x 11 "

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R2

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" x 11"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12 "x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-13

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU101-R6

### Damper Type

Vertical Fire Damper

### Damper Size

10" x 10"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

8" x 8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S2

**Damper Type**

Vertical Fire Damper

**Damper Size**

16" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S3

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S4

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-13

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU101-S5

### Damper Type

Vertical Fire Damper

### Damper Size

18"x16"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

10"x10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S7

**Damper Type**

Vertical Fire Damper

**Damper Size**

24"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S8

**Damper Type**

Vertical Fire Damper

**Damper Size**

24"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
16	FD	AHU102-EX	8X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
17	FD	AHU102-R1	12X12	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
18	FD	AHU102-R2	13X19	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
19	FD	AHU102-R3	8X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
20	FD	AHU102-R4	18X12	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
21	FD	AHU102-S1	13X23	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
22	FD	AHU102-S2	13X17	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
23	FD	AHU102-S3	13X11	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
24	FD	AHU102-S4	10X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
25	FD	AHU102-S5	15X17	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
26	FD	AHU102-S6	17X15	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1

Inspector: Julie Gue / Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 14-Jul  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-14

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #1

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU102-R1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
9x9

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
8x8

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R2

**Damper Type**

Vertical Fire Damper

**Damper Size**

13x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-14-23</b>	Reference I.D. #: <b>AHU102-R2</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>7-14-25</b>	
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
MEMBER <b>NFPA</b>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S1

**Damper Type**

Vertical Fire Damper

**Damper Size**

14.5"x22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S2

**Damper Type**

Vertical Fire Damper

**Damper Size**

14.5"x18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-14

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU102-S3

### Damper Type

Vertical Fire Damper

### Damper Size

13x11

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

10x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-14

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU102-S4

### Damper Type

Horizontal Fire Damper

### Damper Size

10"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>7-14-23</b>	Reference I.D.#: <b>AHU102-S4</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>7-14-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small><b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S5

**Damper Type**

Vertical Fire Damper

**Damper Size**

15"x17"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S6

**Damper Type**

Vertical Fire Damper

**Damper Size**

17"x15"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
27	FD	AHU201-R1	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
28	FD	AHU201-R2	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
29	FD	AHU201-R3	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
30	FD	AHU201-R4	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
31	FD	AHU201-R5	24X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
32	FD	AHU201-R6	16X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
33	FD	AHU201-S1	25.5X16.5	Ruskin	24X24	IBD2	Pass	N/A	Penthouse 2
34	FD	AHU201-S2	16X14	Ruskin	12x12	IBD2	Pass	N/A	Penthouse 2
35	FD	AHU201-S3	16X12	Ruskin	12X12	IBD2	Pass	N/A	Penthouse 2
36	FD	AHU201-S4	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 2
37	FD	AHU201-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 2
38	FD	AHU201-S6	10X10	Ruskin	8x8	IBD2	Pass	N/A	Penthouse 2

Inspector: Julie Gue / Tulcewicz/ Larry Coreno  
Inspection Dates: 17-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-17

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU201-R4

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
8"x8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-17

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #2

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU201-R5

### Damper Type

Horizontal Fire Damper

### Damper Size

24"x12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

25.5"x16.5"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-17

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU201-S2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x14"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 7-17-23  
Inspected By: Tulcewicz  
Next Inspect. By: 7-17-25

Reference I.D. #: AHU201-S2

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-17

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU201-S6

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
10"x10"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
8"x8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
39	FD	AHU202-R1	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
40	FD	AHU202-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
41	FD	AHU202-R3	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
42	FD	AHU202-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
43	FD	AHU202-R5	18X14	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
44	FD	AHU202-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 2
45	FD	AHU202-S1	16X12	Ruskin	12x12	IBD2	Pass	Pass	Penthouse 2
46	FD	AHU202-S2	14X14	Ruskin	12x12	IBD2	Pass	Pass	Penthouse 2
47	FD	AHU202-S3	18X14	Ruskin	8x8	IBD2	Pass	Pass	Penthouse 2
48	FD	AHU202-S4	18X7	Ruskin	6x6	IBD2	Pass	Pass	Penthouse 2
49	FD	AHU202-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	Penthouse 2
50	FD	AHU202-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	Penthouse 2

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 17-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
RA = Return Air      SD = Smoke Damper  
EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-17

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #2

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU202-R2

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-17-23</b>	Reference I.D. #
Inspected By: <b>TULCEWICZ</b>	<b>AHU202-R2</b>
Next Inspect. By: <b>7-17-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
	
<small>NEMI Certified HVAC Fire Life Safety Technicians</small>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-17

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #2

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU202-R5

### Damper Type

Horizontal Fire Damper

### Damper Size

18"x14"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-17

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU202-R6

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
51	FD	AHU301-R1	12X12	Ruskin	24x24	IBD2	Pass	Pass	None
52	FD	AHU301-R2	12X12	Ruskin	24x24	IBD2	Pass	Pass	None
53	FD	AHU301-R3	8X8	Ruskin	24x24	IBD2	Pass	Pass	None
54	FD	AHU301-R4	8X8	Ruskin	24x24	IBD2	Pass	Pass	None
55	FD	AHU301-R5	24X12	Ruskin	24x24	IBD2	Pass	Pass	None
56	FD	AHU301-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	None
57	FD	AHU301-S1	26X14	Ruskin	12x12	IBD2	Pass	Pass	None
58	FD	AHU301-S2	16X14	Ruskin	12x12	IBD2	Pass	Pass	None
59	FD	AHU301-S3	16X12	Ruskin	10X10	IBD2	Pass	Pass	None
60	FD	AHU301-S4	18X7	Ruskin	6x6	IBD2	Pass	Pass	None
61	FD	AHU301-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	None
62	FD	AHU301-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	None

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 7-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
RA = Return Air      SD = Smoke Damper  
EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-20

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #3

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU301-R1

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-20

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #3

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU301-R3

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-20

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #3

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU301-R4

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
8"x8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-20

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center



**Damper Location**  
Penthouse #3

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU301-R6

**Picture of Damper in Closed Position**

**Damper Type**  
Horizontal Fire Damper



**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Picture of Damper I.D. Label**

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-20-23</b>	Reference I.D. #: <b>AHU301-R6</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>7-20-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b>	
<small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER</small>	
<b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-20-23</b>	Reference I.D.#:
Inspected By: <b>TULCEWICZ</b>	<b>AHU301-S5</b>
Next Inspect. By: <b>7-20-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
<small>MEMBER</small> <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
63	FD	AHU302-R1	8X8	Ruskin	24x24	IBD2	Pass	Pass	
64	FD	AHU302-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	
65	FD	AHU302-R3	12X12	Ruskin	24x24	IBD2	Pass	Pass	
66	FD	AHU302-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	
67	FD	AHU302-R5	18X14	Ruskin	24x24	IBD2	Pass	Pass	
68	FD	AHU302-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	
69	FD	AHU302-S1	14X14	Ruskin	10X10	IBD2	Pass	Pass	
70	FD	AHU302-S2	16X12	Ruskin	12x12	IBD2	Pass	Pass	
71	FD	AHU302-S3	18X14	Ruskin	8x8	IBD2	Pass	Pass	
72	FD	AHU302-S4	18X7	Ruskin	8X8	IBD2	Pass	Pass	
73	FD	AHU302-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	
74	FD	AHU302-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 19-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: <b>7-19-23</b>	Reference I.D. #
Inspected By: <b>Tulcewicz</b>	<b>AHU302-R2</b>
Next Inspect. By: <b>7-19-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: <b>7-19-23</b>	Reference I.D.#:
Inspected By: <b>Tulcewicz</b>	<b>AHU302-S1</b>
Next Inspect. By: <b>7-19-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #3

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU302-S2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-19

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #3

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU302-S6

### Damper Type

Horizontal Fire Damper

### Damper Size

10"x10"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

8"x8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>7-19-23</b>	Reference I.D. #: <b>AHU302-S6</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect By: <b>7-19-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
75	FD	AHU401-R1	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
76	FD	AHU401-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
77	FD	AHU401-R3	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
78	FD	AHU401-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
79	FD	AHU401-R5	24X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
80	FD	AHU401-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 4
81	FD	AHU401-S1	10X10	Ruskin	6X6	IBD2	Pass	Pass	Penthouse 4
82	FD	AHU401-S2	18X7	Ruskin	6X6	IBD2	Pass	Pass	Penthouse 4
83	FD	AHU401-S3	18X7	Ruskin	10X10	IBD2	Pass	Pass	Penthouse 4
84	FD	AHU401-S4	16X12	Ruskin	10X10	IBD2	Pass	Pass	Penthouse 4
85	FD	AHU401-S5	16X14	Ruskin	12X12	IBD2	Pass	Pass	Penthouse 4
86	FD	AHU401-S6	26X14	Ruskin	12X12	IBD2	Pass	Pass	Penthouse 4

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 7-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-21

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU401-R2

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-21-23</b>	Reference I.D. #: <b>AHU401-R2</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>7-21-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER</small> <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-21

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU401-R3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-21

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU401-R4

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-21-23</b>	Reference I.D. #: <b>AHU401-R4</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>7-21-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-20

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU401-S2

### Damper Type

Horizontal Fire Damper

### Damper Size

18"x7"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-20

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU401-S3

### Damper Type

Horizontal Fire Damper

### Damper Size

18"x7"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

10"x10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: <b>7-20-23</b>	Reference I.D.#: <b>AHU401-S4</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>7-20-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU401-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
87	FD	AHU402-R1	8X8	Ruskin	24x24	IBD2	Pass	Pass	
88	FD	AHU402-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	
89	FD	AHU402-R3	12X12	Ruskin	24x24	IBD2	Pass	Pass	
90	FD	AHU402-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	
91	FD	AHU402-R5	18X14	Ruskin	24x24	IBD2	Pass	Pass	
92	FD	AHU402-R6	16X12	Ruskin	24x24	IBD2	Pass	Pass	
93	FD	AHU402-S1	14X14	Ruskin	12x12	IBD2	Pass	Pass	
94	FD	AHU402-S2	16X12	Ruskin	12x12	IBD2	Pass	Pass	
95	FD	AHU402-S3	18X14	Ruskin	12X12	IBD2	Pass	Pass	
96	FD	AHU402-S4	18X7	Ruskin	6x6	IBD2	Pass	Pass	
97	FD	AHU402-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	
98	FD	AHU402-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 21-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: 7-21-23	Reference I.D. #: AHU-402
Inspected By: Tulcewicz	R1
Next Inspect. By: 7-21-25	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-21

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU402-R2

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-21

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-R3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-R4

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-21

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-21

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-R6

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-S1

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
14"x14"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-S2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #4

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU402-S5

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
18"x7"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6"x6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-24-23</b>	Reference I.D.#:
Inspected By: <b>Tulcewicz</b>	<b>AHU-402</b>
Next Inspect. By: <b>7-24-25</b>	<b>S5</b>
Duct Fabricators, Inc. <b>FIRE SAFETY DIVISION</b> MEMBER 883 Addison Rd. Cleveland, Ohio NEMI Certified HVAC Fire Life Safety Technicians <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU402-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10"x10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
99	FD	AHU501-R1	24X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
100	FD	AHU501-R2	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
101	FD	AHU501-R3	8X8	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
102	FD	AHU501-R4	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
103	FD	AHU501-R5	16X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
104	FD	AHU501-R6	12X12	Ruskin	24x24	IBD2	Pass	Pass	Penthouse 5
105	FD	AHU501-S1	24X14	Ruskin	12x12	IBD2	Pass	Pass	Penthouse 5
106	FD	AHU501-S2	16X14	Ruskin	12x12	IBD2	Pass	Pass	Penthouse 5
107	FD	AHU501-S3	16X14	Ruskin	12X12	IBD2	Pass	Pass	Penthouse 5
108	FD	AHU501-S4	18X7	Ruskin	6x6	IBD2	Pass	Pass	Penthouse 5
109	FD	AHU501-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	Penthouse 5
110	FD	AHU501-S6	10X10	Ruskin	8x8	IBD2	Pass	Pass	Penthouse 5

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 24-Jul-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-07-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU501-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24"x24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU501-R2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
8"x8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-24

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #5

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU501-R3

### Damper Type

Horizontal Fire Damper

### Damper Size

8"x8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

6"x6"


### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>7-24-23</b>	Reference I.D.#
Inspected By: <b>TULCEWICZ</b>	<b>AHU501-R3</b>
Next Inspect. By: <b>7-24-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	<small>MEMBER <b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians <b>NFPA</b></small>

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-07-24

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #5

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU501-R4

### Damper Type

Horizontal Fire Damper

### Damper Size

12"x12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24"x24"


### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU501-R5

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>7-24-23</b>	Reference I.D. #: <b>AHU501-R5</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>7-24-25</b>	
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
MEMBER <b>NFPA</b>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-07-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU501-R6

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12"x12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24"x24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>7-24-23</b>	Reference I.D.#
Inspected By: <b>TULCEWICZ</b>	<b>AHU501-R6</b>
Next Inspect. By: <b>7-24-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	<small>MEMBER <b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians <b>NFPA</b></small>

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU501-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-10

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #5

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU501-S2

### Damper Type

Horizontal Fire Damper

### Damper Size

16" x 14"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"


### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>8-10-23</b>	Reference I.D.#: <b>AHU501-S2</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>8-10-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
<small>MEMBER</small> <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU501-S3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16" x 14"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU501-S4

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
18" x 7"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU501-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center



**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU501-S6

**Picture of Damper in Closed Position**

**Damper Type**  
Horizontal Fire Damper



**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Picture of Damper I.D. Label**

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
111	FD	AHU502-R1	12X12	Ruskin	24x24	IBD2	Pass	Pass	
112	FD	AHU502-R2	12X12	Ruskin	24x24	IBD2	Pass	Pass	
113	FD	AHU502-R3	8X8	Ruskin	24x24	IBD2	Pass	Pass	
114	FD	AHU502-R4	8X8	Ruskin	24x24	IBD2	Pass	Pass	
115	FD	AHU502-R5	16X12	Ruskin	24x24	IBD2	Pass	Pass	
116	FD	AHU502-R6	18X14	Ruskin	24x24	IBD2	Pass	Pass	
117	FD	AHU502-S1	12X12	Ruskin	12x12	IBD2	Pass	Pass	
118	FD	AHU502-S2	16X12	Ruskin	12x12	IBD2	Pass	Pass	
119	FD	AHU502-S3	18X14	Ruskin	8x8	IBD2	Pass	Pass	
120	FD	AHU502-S4	18X7	Ruskin	12X12	IBD2	Pass	Pass	
121	FD	AHU502-S5	18X7	Ruskin	6x6	IBD2	Pass	Pass	
122	FD	AHU502-S6	10X10	Ruskin	6X6	IBD2	Pass	Pass	

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno

Inspection Dates: 10-Aug-23

Facility: Juvenile Justice Center

SA = Supply Air

RA = Return Air

EA = Exhaust Air

FD = Fire Damper

SD = Smoke Damper

FSD = Fire Smoke Damper



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24" x 24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-R2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
12" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24" x 24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>8-10-23</b>	Reference I.D. #: <b>AHU502-R2</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>8-10-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER FOR  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-R3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24" x 24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: <b>8-10-23</b>	Reference I.D.# <b>AHU502-R3</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>8-10-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd., Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-10

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #5

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU502-R4

### Damper Type

Horizontal Fire Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24" x 24"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None



### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>8-10-23</b>	Reference I.D. #
Inspected By: <b>TULCEWICZ</b>	<b>AHU502-</b>
Next Inspect By: <b>8-10-25</b>	<b>R4</b>
Duct Fabricators, Inc.  	
883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492 NEMI Certified HVAC Fire Life Safety Technicians	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-R5

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
24" x 24"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**FIRE DAMPER**

Inspection Date: <b>B-10-23</b>	Reference I.D.#: <b>AHU502-R5</b>
Inspected By: <b>Tulcewicz</b>	
Next Inspect. By: <b>B-10-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24" x 24"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-10

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #5

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU502-S1

### Damper Type

Horizontal Fire Damper

### Damper Size

14" x 14"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
AHU502-S2

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
16" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18" x 7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU502-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
c

**Damper Type**  
Horizontal Fire / Smoke Damper

**Damper Size**  
78" x 60"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD1630

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
20" x 20"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Basement

**Inspector Name**

Julie Gue

**Damper I.D. #**

Basement FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

35" x 15.5"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-07

### Facility Location

Juvenile Justice Center

### Damper Location

Basement

### Inspector Name

Julie Gue

### Damper I.D. #

Basement FD2

### Damper Type

Vertical Fire Damper

### Damper Size

10" Round

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Screen

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Basement

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
Basement FD3

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
32" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
10" x 10"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
150	FD	IM121-FD1	8X8	Ruskin	8X8	IBD2	Pass	Pass	Room 209
151	FD	IM121-FD2	32X14	Ruskin	12X12	IBD2	Pass	Pass	Room 209
152	FD	IM121-FD3	30X18	Ruskin	12X12	IBD2	Pass	Pass	Room 209
153	FD	IM121-FD4	16X18	Ruskin	12X12	IBD2	Pass	Pass	Building Maintenance
154	FD	IM121-FD5	30X17	Ruskin	12X12	IBD2	Pass	Pass	Building Maintenance
155	FD	IM121-FD6	24X17	Ruskin	12X12	IBD2	Pass	Pass	Building Maintenance
156	FSD	IM121-FSD1	60X30	Ruskin	16x16	FSD60	Pass	Pass	None
157	FSD	IM121-FSD2	48X24	Ruskin	16x16	FSD60	Pass	Pass	RM #2826
158	FSD	IM121-FSD3	40X24	Ruskin	16X16	FSD60	Pass	Pass	Transportation
159	SD	IM121-SD1	24X12	Greenheck	10X10	SMD201	Pass	Pass	RM #2806
160	SD	IM121-SD2	14X12	Greenheck	10X10	SMD201	Pass	Pass	RM #2806
161	SD	IM121-SD3	14X12	Greenheck	12X12	SMD201	Pass	Pass	RM #2826
162	SD	IM121-SD4	10X8	Greenheck	6X6	SMD201	Pass	Pass	RM #2826
163	SD	IM121-SD5	24X12	Greenheck	12X12	SMD201	Pass	Pass	General Storage
164	SD	IM121-SD6	26X12	Greenheck	12X12	SMD201	Pass	Pass	General Storage
165	SD	IM121-SD7	18X12	Greenheck	8X8	SMD201	Pass	Pass	General Storage
166	SD	IM121-SD8	42X16	Greenheck	OPEN	SMD201	Pass	Pass	General Storage
167	SD	IM121-SD9	26X10	Greenheck	12X12	SMD201	Pass	Pass	General Storage
168	SD	IM121-SD10	26X6	Greenheck	OPEN	SMD201	Pass	Pass	Transportation
169	SD	IM121-SD11	8X8	Greenheck	9X6 Oval	SMD201	Pass	Pass	Transportation

Inspector: Julie Gue, Dan Tulcewicz, Larry Coreno

Inspection Dates: August 4 and 28, 2023

Facility: Juvenile Justice Center

SA = Supply Air

RA = Return Air

EA = Exhaust Air

FD = Fire Damper

SD = Smoke Damper

FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
170	SD	IM121-SD12	18X12	Greenheck	12X12	SMD201	Pass	Pass	Transportation
171	SD	IM121-SD13	12X8	Ruskin	6X6	SD50	Pass	Pass	Prints Room
172	SD	IM121-SD14	12X10	Ruskin	6X6	SD50	Pass	Pass	Prints Room
173	SD	IM121-SD15	36X30	Greenheck	Screen	SMD201	Pass	Pass	None

Inspector: Julie Gue / Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 4 and 28, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
RA = Return Air      SD = Smoke Damper  
EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
203	FSD	IM131-FSD1	12X10	Greenheck	8x8	FSD311	Pass	Pass	Employee restroom
204	SD	IM131-SD1	10X8	Greenheck	8x8	SMD301	Pass	Pass	Mediation
205	SD	IM131-SD2	26X6	Greenheck	Open	SMD301	Pass	Pass	Mediation
206	FD	IM132-FD1	24X12	Ruskin	10x10	IBD2	Pass	Pass	Vestibule
207	FSD	IM132-FSD1	12X20	Ruskin	6x6	FSD60	Pass	Pass	West Mechanical Room
208	FSD	IM132-FSD2	30X12	Ruskin	6x6	FSD60	Pass	Pass	West Mechanical Room
209	FSD	IM132-FSD3	30X12	Ruskin	6x6	FSD60	Pass	Pass	East Mechanical Room
210	FSD	IM132-FSD4	12X20	Ruskin	6x6	FSD60	Pass	Pass	East Mechanical Room
211	FSD	IM132-FSD5	8X8	Ruskin	Grille	FSD60	Pass	Pass	Custodial Closet
212	FSD	IM132-FSD6	50X24	Ruskin	10x10	FSD60	Pass	Pass	Main Corridor
213	FSD	IM132-FSD7	60X24	Ruskin	Screen	FSD60	Pass	Pass	Main Corridor
214	FSD	IM132-FSD8	60X30	Ruskin	14x14	FSD60	Pass	Pass	Training Room
215	FSD	IM132-FSD9	60X24	Ruskin	16x16	FSD60	Pass	Pass	Training Room
216	FSD	IM133-FSD1	10" Round	Greenheck	9x6 Oval	FSDR511	Pass	Pass	
217	FSD	IM133-FSD2	12X10	Greenheck	6x6	FSD311	Pass	Pass	RM 3106
218	SD	IM133-SD1	8" Round	Greenheck	9x6 Oval	SMD201	Pass	Pass	RM 3206
219	SD	IM133-SD2	10x10	Greenheck	8x8	SMD201	Pass	Pass	RM 3206
220	SD	IM133-SD3	8x10	Greenheck	8x8	SMD201	Pass	Pass	RM 3206
221	SD	IM133-SD4	36x16	Greenheck	Open	SMD301	Pass	Pass	RM #3207

Inspector: Julie Gue /Dan Tulcewicz /Larry Coreno  
Inspection Dates: August 3, 2023, September 18 and 19, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
222	SD	IM133-SD5	26X6	Greenheck	Open	SMD301	Pass	Pass	RM #3209
223	SD	IM133-SD6	6" Round	Greenheck	8x8	SMDR301	Pass	Pass	RM # 3109
224	SD	IM133-SD7	12X10	Greenheck	6x6	SMD301	Pass	Pass	RM # 3106
225	SD	IM133-SD8	26X8	Greenheck	Open	SMD301	Pass	Pass	RM # 3106

Inspector: Julie Gue, Larry Coreno  
Inspection Dates: August 3, September 18 and 19, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
225	FSD	IM141-FSD1	8X8	Greenheck	8X8	FSD211	Pass	Pass	Women's Restroom
226	SD	IM141-SD1	14" Round	Greenheck	9X6 Oval	SMD501	Pass	Pass	Main corridor
227	SD	IM141-SD2	26X6	Greenheck	Open	SMD301	Pass	Pass	Main corridor
228	SD	IM141-SD3	26X6	Greenheck	Open	SMD301	Pass	Pass	Women's Restroom
229	SD	IM141-SD4	8" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM #4812
230	SD	IM141-SD5	8" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM #4812
231	SD	IM141-SD6	6" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM #4812
232	SD	IM141-SD7	10" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM# 4805
233	SD	IM141-SD8	10" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM# 4805
234	SD	IM141-SD9	15X16	Greenheck	12X12	SMD301	Pass	Pass	RM# 4805
235	SD	IM141-SD10	14" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	Main corridor
236	SD	IM141-SD11	14" Round	Greenheck	3X3	SMDR301	Pass	Pass	Main corridor
237	SD	IM141-SD12	8" Round	Greenheck	9" x 6" Oval	SMDR301	Pass	Pass	RM #4612
238	SD	IM141-SD13	10" x 8"	Greenheck	8' x 8"	SMD211	Pass	Pass	RM #4611
239	SD	IM141-SD14	26" x 12"	Greenheck	5" x 5"	SMD211	Pass	Pass	RM #4611
240	SD	IM141-SD15	8" x 10"	Greenheck	8" x 8"	SMD211	Pass	Pass	RM #4611
241	SD	IM141-SD16	10" Round	Greenheck	9" x 6" Oval	SMDR211	Pass	Pass	RM #4611
242	FSD	IM142-FSD1	12X20	Ruskin	6X6	FSD60	Pass	Pass	Electrical room
243	FSD	IM142-FSD2	30X12	Ruskin	6X6	FSD60	Pass	Pass	Electrical room
244	FSD	IM142-FSD3	30X12	Ruskin	6X6	FSD60	Pass	Pass	Electrical room
245	FSD	IM142-FSD4	12X20	Ruskin	6X6	FSD60	Pass	Pass	Electrical room
246	FSD	IM142-FSD5	8X8	Ruskin	Grille	FSD60	Pass	Pass	Custodial closet
247	FSD	IM142-FSD6	20X10	Greenheck	6X6	FSD211	Pass	Pass	RM#4503
248	FSD	IM142-FSD7	14X10	Greenheck	6X6	FSD211	Pass	Pass	RM#4308
249	FSD	IM142-FSD8	60X20	Ruskin	60X24	FSD60	Pass	Pass	Main corridor

Inspector:

Julie Gue, Larry Coreno

Inspection Dates:

August 3 and 30, October 4 and 5, 2023

Facility:

Juvenile Justice Center

SA = Supply Air

FD = Fire Damper

RA = Return Air

SD = Smoke Damper

EA = Exhaust Air

FSD = Fire Smoke Damper

*Duct Fabricators, Inc.*  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
250	FSD	IM142-FSD9	48X24	Ruskin	12X12	FSD60	Pass	Pass	Main corridor
251	FSD	IM142-FSD10	54X24	Ruskin	12X12	FSD60	Pass	Pass	Main corridor
252	FSD	IM142-FSD11	60X24	Ruskin	12X12	FSD60	Pass	Pass	Main corridor
253	SD	IM142-SD1	10X10	Greenheck	8X8	SMD301	Pass	Pass	RM #4610
254	SD	IM142-SD2	26" x 6"	Greenheck	Open	SMD301	Pass	Pass	Corridor
255	SD	IM142-SD3	26" x 6"	Greenheck	Open	SMD301	Pass	Pass	RM #4404
256	FSD	IM143-FSD1	12X10	Greenheck	8x8	FSD211	Pass	Pass	RM #4107
257	FSD	IM143-SD1	10X12	Greenheck	8X8	SMD301	Pass	Pass	RM #4406
258	FSD	IM143-SD2	10" Round	Greenheck	9X6 Oval	SMDR301	Pass	Pass	RM #4405

Inspector: Julie Gue/ Larry Coreno  
Inspection Dates: October 3 and 4, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
259	FSD	IM151-FSD1	10X8	Greenheck	8X7	FSD211	Pass	Pass	None
260	SD	IM151-SD1	12X10	Greenheck	8X8	SMD201	Pass	Pass	RM #5146
261	FD	IM152-FD1	24X12	Ruskin	12X12	IBD2	Pass	Pass	Elevator Lobby
262	FD	IM152-FD2	18X18	Greenheck	Screen	DFD150	Pass	Pass	RM #5150
263	FD	IM152-FD3	18X18	Greenheck	Screen	DFD150	Pass	Pass	RM #5150
264	FSD	IM152-FSD1	12X20	Ruskin	6X6	FSD60	Pass	Pass	West Mechanical Rm
265	FSD	IM152-FSD2	30X12	Ruskin	6X6	FSD60	Pass	Pass	West Mechanical Rm
266	FSD	IM152-FSD3	30X12	Ruskin	6X6	FSD60	Pass	Pass	East Mechanical Rm
267	FSD	IM152-FSD4	12X20	Ruskin	6X6	FSD60	Pass	Pass	East Mechanical Rm
268	FSD	IM152-FSD5	16X10	Ruskin	12X12	FSD60	Pass	Pass	Elevator Lobby
269	FSD	IM152-FSD6	8X8	Ruskin	Grille	FSD60	Pass	Pass	Custodial Closet
270	FSD	IM152-FSD7	48X24	Ruskin	14X14	FSD60	Pass	Pass	None
271	FSD	IM152-FSD8	60X30	Ruskin	12X12	FSD60	Pass	Pass	None
272	FSD	IM152-FSD9	60X30	Ruskin	Screen	FSD60	Pass	Pass	Main Corridor
273	FSD	IM152-FSD10	48X24	Ruskin	10X10	FSD60	Pass	Pass	None
274	FSD	IM152-FSD11	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
275	FSD	IM152-FSD12	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
276	FSD	IM153-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	None

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 2 and 16,  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
277	FSD	IM161-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	West sitting area
278	FSD	IM162-FSD1	12X20	Ruskin	6X6	FSD60	Pass	Pass	West Mechanical rm
279	FSD	IM162-FSD2	30X12	Ruskin	6X6	FSD60	Pass	Pass	West Mechanical rm
280	FSD	IM162-FSD3	30X12	Ruskin	6X6	FSD60	Pass	Pass	East Mechanical Rm
281	FSD	IM162-FSD4	12X20	Ruskin	6X6	FSD60	Pass	Pass	East Mechanical Rm
282	FSD	IM162-FSD5	48X24	Ruskin	14X14	FSD60	Pass	Pass	Main Corridor
283	FSD	IM162-FSD6	60X24	Ruskin	16X16	FSD60	Pass	Pass	Main Corridor
284	FSD	IM162-FSD7	48X24	Ruskin	12X12	FSD60	Pass	Pass	Main Corridor
285	FSD	IM162-FSD8	60x24	Ruskin	Screen	FSD60	Pass	Pass	Main Corridor
286	FSD	IM162-FSD9	14X8	Greenheck	12X12	FSD211	Pass	Pass	Woman's Room
287	FSD	IM162-FSD10	14X8	Greenheck	12X12	FSD211	Pass	Pass	Men's Room
288	FSD	IM162-FSD11	8X8	Ruskin	Grille	FSD60	Pass	Pass	Custodial Closet
289	FSD	IM162-FSD12	16X10	Ruskin	12X12	FSD60	Pass	Pass	Elevator Lobby
290	FSD	IM163-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	East Sitting Area

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 2 & 28, October 13, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
291	FSD	IM171-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	None
292	FD	IM172-FD1	24X12	Ruskin	10X10	IBD2	Pass	Pass	None
293	FSD	IM172-FSD1	12X20	Ruskin	6X6	FSD60	Pass	Pass	None
294	FSD	IM172-FSD2	30X12	Ruskin	6X6	FSD60	Pass	Pass	None
295	FSD	IM172-FSD3	30X12	Ruskin	6X6	FSD60	Pass	Pass	None
296	FSD	IM172-FSD4	12X20	Ruskin	6X6	FSD60	Pass	Pass	None
297	FSD	IM172-FSD5	8X8	Ruskin	Grille	FSD60	Pass	Pass	None
298	FSD	IM172-FSD6	16X10	Ruskin	12X12	FSD60	Pass	Pass	None
299	FSD	IM172-FSD7	60X24	Ruskin	14X14	FSD60	Pass	Pass	None
300	FSD	IM172-FSD8	48X24	Ruskin	14X14	FSD60	Pass	Pass	None
301	FSD	IM172-FSD9	48X24	Ruskin	10X10	FSD60	Pass	Pass	None
302	FSD	IM172-FSD10	60X24	Ruskin	12X12	FSD60	Pass	Pass	None
303	FSD	IM172-FSD11	14X8	Greenheck	12X12	FSD211	Pass	Pass	None
304	FSD	IM172-FSD12	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
305	FSD	IM173-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	None

Inspector: Julie Gue / Dan Tulcewicz / Larry Coreno  
Inspection Dates: August 24, 2023 & October 13, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
305	FSD	IM181-FSD1	12X8	Greenheck	12x12	FSD211	Pass	Pass	None
306	FSD	IM182-FSD1	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
307	FSD	IM182-FSD2	14X8	Greenheck	8X8	FSD211	Pass	Pass	None
308	FSD	IM182-FSD3	24X12	Greenheck	8X8	FSD211	Pass	Pass	None
309	FSD	IM182-FSD4	8X8	Ruskin	Grille	FSD60	Pass	Pass	None
310	FSD	IM182-FSD5	60X24	Ruskin	16X16	FSD60	Pass	Pass	Main Corridor
311	FSD	IM182-FSD6	48X24	Ruskin	14X14	FSD60	Pass	Pass	Main Corridor
312	FSD	IM182-FSD7	12X20	Ruskin	6X6	FSD60	Pass	Pass	Electrical closet
313	FSD	IM182-FSD8	30X12	Ruskin	6X6	FSD60	Pass	Pass	Electrical closet
314	FSD	IM182-FSD9	12X20	Ruskin	6X6	FSD60	Pass	Pass	Electrical closet
315	FSD	IM182-FSD10	30X12	Ruskin	6X6	FSD60	Pass	Pass	Electrical closet
316	FSD	IM182-FSD11	54X24	Ruskin	14X14	FSD60	Pass	Pass	Main Corridor
317	FSD	IM182-FSD12	60X24	Ruskin	14X14	FSD60	Pass	Pass	Main Corridor
318	FSD	IM183-FSD1	12X8	Greenheck	12X12	FSD211	Pass	Pass	None

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 2 & October 12, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
319	FSD	IM191-FSD1	22X14	Greenheck	12X12	FSD211	Pass	Pass	None
320	FD	IM192-FD1	24x12	Ruskin	10X10	IBD2	Pass	Pass	Elevator lobby
321	FSD	IM192-FSD1	84X12	Ruskin	Screen Access	FSD60	Pass	Pass	Main Corridor
322	FSD	IM192-FSD2	8X8	Ruskin	Grille Access	FSD60	Pass	Pass	Storage
323	FSD	IM192-FSD3	36X10	Greenheck	8X8	FSD211	Paass	Pass	Womans rm
324	FSD	IM192-FSD4	36X10	Greenheck	10X10	FSD211	Paass	Pass	Mens room
325	FSD	IM192-FSD5	16X10	Ruskin	16X10	FSD211	Paass	Pass	Vestibule
326	SD	IM192-SD1	28X6	Greenheck	26X8	SMD201	Pass	Pass	Copy RM
327	SD	IM192-SD2	8" Round	Greenheck	9X6 Oval	SMDR501	Pass	Pass	Copy RM
328	FSD	IM193-FSD1	16X24	Greenheck	12X12	FSD211	Pass	Pass	Mens room

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: October 12 & 15, 2023  
Facility: Juvenile Justice Center


SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center



**Damper Location**  
RM 209

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-FD1

**Picture of Damper in Closed Position**

**Damper Type**  
Horizontal Fire Damper



**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Picture of Damper I.D. Label**

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 209

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-FD2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

32" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 209

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-FD3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30" x 18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Bldg Maintenance Office

**Inspector Name**

Larry Coreno

**Damper I.D. #**

IM121-FD5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30" x 17"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Bldg Maintenance Office

**Inspector Name**

Larry Coreno

**Damper I.D. #**

IM121-FD6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24" x 17"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Furniture storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Furniture storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

42" x 16"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

General storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Transportation office

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMF201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Transportation office

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-SD12

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
18" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" x 12"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Print Room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-SD13

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Print Room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM121-SD14

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 10"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
174	FD	IM122-FD1	9.25x9.25	Ruskin	8x8	IBD2	Pass	Pass	RM208
175	FD	IM122-FD2	36x16	Ruskin	16x16	IBD2	Pass	Pass	RM208
176	FD	IM122-FD3	24x16	Ruskin	16x16	IBD2	Pass	Pass	RM208
177	FD	IM122-FD4	36x16	Ruskin	16x16	IBD2	Pass	Pass	RM208
178	FD	IM122-FD5	24x16	Ruskin	16x16	IBD2	Pass	Pass	RM208
179	FD	IM122-FD6	10x10	Ruskin	8x8	IBD2	Pass	Pass	RM208
180	FD	IM122-FD7	96x30	Ruskin	16X16	IBD2	Pass	Pass	RM208
181	FSD	IM122-FSD1	60X30	Ruskin	16X16	IBD2	Pass	Pass	Main Corridor
182	FSD	IM122-FSD2	60X40	Ruskin	16X16	FSD60	Pass	Pass	Main Corridor
183	FSD	IM122-FSD3	60X30	Ruskin	16X16	FSD60	Pass	Pass	Rm 2402
184	FSD	IM122-FSD4	8X8	Ruskin	Grille	FSD60	Pass	Pass	Janitors Closet
185	FSD	IM122-FSD5	50X22	Greenheck	14X14	FSD311	Pass	Pass	Janitors Closet
186	FSD	IM122-FSD6	20X16	Ruskin	8X8	FSD60	Pass	Pass	None

Inspector: Julie Gue / Dan Tulcewicz/ Larry Coreno  
Inspection Dates: August 4 and 28, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-04

### Facility Location

Juvenile Justice Center

### Damper Location

RM 208

### Inspector Name

Julie Gue

### Damper I.D. #

IM122-FD1

### Damper Type

Horizontal Fire Damper

### Damper Size

9.25" x 9.25"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

8" x 8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD2

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
36" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
24" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD4

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
36" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD5

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
24" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 208

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM122-FD6

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**FIRE**  
**DAMPER**

Inspection Date: 8/4/23	Reference I.D.#: IM122
Inspected By: Gw	FD6
Next Inspect. By: 8/4/25	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

96" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16" - 3 doors

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 40"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2402

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-16

### Facility Location

Juvenile Justice Center

### Damper Location

Janitors closet .

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM122-FSD4

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-16

### Facility Location

Juvenile Justice Center

### Damper Location

Janitors closet .

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM122-FSD4

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
187	SD	IM123-SD1	14X12	Greenheck	10x10	SMD201	Pass	Pass	IT
188	SD	IM123-SD2	14X12	Greenheck	Open	SMD201	Pass	Pass	IT
189	SD	IM123-SD3	16" Round	Greenheck	9x6 Oval	SMDR201	Pass	Pass	IT
190	SD	IM123-SD4	10x12	Greenheck	8x8	SMD201	Pass	Pass	IT Storage
191	SD	IM123-SD5	14x12	Greenheck	Open	SMD201	Pass	Pass	IT Storage
192	SD	IM123-SD6	16x10	Greenheck	6x6	SMD201	Pass	Pass	IT Corridor
193	SD	IM123-SD7	8" Round	Greenheck	6x6	SMDR201	Pass	Pass	IT Corridor
194	SD	IM123-SD8	8" Round	Greenheck	Flex	SMDR201	Pass	Pass	IT Corridor
195	SD	IM123-SD9	12x12	Greenheck	Open	SMD201	Pass	Pass	Files
196	SD	IM123-SD10	16x12	Greenheck	Open	SMD201	Pass	Pass	Files
197	SD	IM123-SD11	12x12	Greenheck	Open	SMD201	Pass	Pass	RM 2110
198	SD	IM123-SD12	10" Round	Greenheck	6x6	SMDR201	Pass	Pass	RM 2110
199	SD	IM123-SD13	14X12	Greenheck	12x12	SMD201	Pass	Pass	RM 2110
200	SD	IM123-SD14	8" Round	Greenheck	6x6	SMDR201	Pass	Pass	RM 2110
201	SD	IM123-SD15	14" Round	Greenheck	6x9 Oval	SMDR201	Pass	Pass	Mail Room
202	SD	IM123-SD16	10x10	Greenheck	6x6	SMD201	Pass	Pass	Mail Room

Inspector: Julie Gue /Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 7-Sep-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Area

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Area

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

IT Area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SNDR201

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Storage

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD4

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Storage

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD5

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
24" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD6

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
16" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD7

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
IT Corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD8

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Flex

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Files

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD9

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Files Area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" x 12"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 2110

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD11

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 2110

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD12

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-09-07

### Facility Location

Juvenile Justice Center

### Damper Location

RM 2110

### Inspector Name

Julie Gue

### Damper I.D. #

IM123-SD13

### Damper Type

Vertical Smoke Damper

### Damper Size

14" x 12"

### Damper Manufacturer

Greenheck

### Damper Model #

SMD201

### Fusible Link Temperature

N/A

### Access Door Size

12" x 12"


### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 2110

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD14

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"


**"Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>SMOKE DAMPER</b>	
Inspection Date: <b>9 7 23</b>	Reference I.D.# <b>IM123</b>
Inspected By: <b>Gue</b>	<b>5014</b>
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small>NEMI Certified HVAC Fire Life Safety Technicians</small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Mail room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD15

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" oval


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE DAMPER**

Inspection Date: 9 7 23 Reference I.D. #: IM 123  
Inspected By: Gue SD 15

Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492  
**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Mail Room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM123-SD16

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>SMOKE DAMPER</b>	
Inspection Date:	Reference I.D.#:
9 7 23	IM 123
Inspected By:	SD 16
GUE	
Duct Fabricators, Inc. 83 Addison Rd. Cleveland, Ohio 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM131-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD311

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Office

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM131-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM3810

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM131-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

By Stairwell #6

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM132-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

West Mechanical Room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

West Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
East Mechanical room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM132-FSD3

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
30" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

East Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-16

### Facility Location

Juvenile Justice Center

### Damper Location

Janitors closet.

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM132-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE/SMOKE DAMPER</b>	
Inspection Date: <b>8-16-23</b>	Reference I.D.#: <b>IM132-</b>
Inspected By: <b>Tulcewicz</b>	<b>FSD5</b>
Next Inspect. By: <b>8-16-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small>NEMI Certified HVAC Fire Life Safety Technicians</small>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

50" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-28

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM132-FSD7

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Screen

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-30

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center



**Damper Location**  
Training Room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM132-FSD8

**Picture of Damper in Closed Position**

**Damper Type**  
Vertical Fire Damper



**Damper Size**  
60" x 30"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Picture of Damper I.D. Label**

**Access Door Size**  
14" x 14"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 3106

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM133-FSD2

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
12" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
FSD311

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 3206

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM133-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 3206

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM133-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201


**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 3206

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

36" x 16"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 3209

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM133-SD5

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
26" x 6"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SND301

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 3109

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM133-SD6

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD301

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>SMOKE DAMPER</b>	
Inspection Date: <b>9-19-23</b>	Reference I.D. # <b>IM133 SD6</b>
Inspected By: <b>GUE</b>	

Duct Fabricators, Inc. **FIRE SAFETY DIVISION** MEMBER **NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Corridor by cubes

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Outside of 3106

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

28" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-04

### Facility Location

Juvenile Justice Center

### Damper Location

Women's room

### Inspector Name

Julie Gue

### Damper I.D. #

IM141-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Greenheck

### Damper Model #

FSD211

### Fusible Link Temperature

212 Degrees

### Access Door Size

8" x 8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE/SMOKE DAMPER</b>	
Inspection Date: <i>10-4-23</i>	Reference I.D.#: <b>IM141</b>
Inspected By: <i>Gue</i>	<b>FSD1</b>
Next Inspect. By: <i>10-4-25</i>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR501

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Across from woman's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4812

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM4812

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 Oval


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4812

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

South of RM 4805

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" x 6" oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

South of RM 4805

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15" x 16"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Main corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD10

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMDR301


**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE DAMPER**

Inspection Date: 10-4-23	Reference I.D.#: IM141 5010
Inspected By: Gue	
Next Inspect. By: 10-4-25	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD11

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

3" x 3"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4611

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD13

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
211


**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4611

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD14

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
26" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD211

**Fusible Link Temperature**  
N/A

**Access Door Size**  
5" x 5"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Justice Center Court Towers

**Damper Location**

RM 4611

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM141-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD211

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4611

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM141-SD16

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
211

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
West mechanical room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM142-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
12" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

West mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

Janitors' closet.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM142-FSD5

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4503

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM142-FSD6

**Damper Type**  
Horizontal Fire / Smoke Damper

**Damper Size**  
20" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
FSD211

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4308

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-30

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM142-FSD8

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 20"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD10

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

54" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4610

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM142-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
211

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

211

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4404

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM142-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SD3

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4612

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM142-SD12

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
211

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4107

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM143-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 4405

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM143-SD1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10" x 12"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD301

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 4405

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM143-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR-301

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-13

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Women's room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM151-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
FSD211

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
8" x 7"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-13

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 5146

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM151-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 10"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SMD201

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM #5150

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

18" x 18"

**Damper Manufacturer**

Greenheck

**Damper Model #**

DFD150

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM #5150

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

18" x 18"

**Damper Manufacturer**

Greenheck

**Damper Model #**

DFD150

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-02

### Facility Location

Juvenile Justice Center

### Damper Location

West mechanical room

### Inspector Name

Julie Gue

### Damper I.D. #

IM152-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

12" x 20"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

6x6

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

West mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical Room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-16

### Facility Location

Juvenile Justice Center

### Damper Location

Elevator Lobby

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM152-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

16" x 10"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE/SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>8-16-23</b>	Reference I.D. #: <b>IM152-</b>
Inspected By: <b>Tulcewicz</b>	<b>FSD5</b>
Next Inspect. By: <b>8-16-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-16

**Facility Location**

Juvenile Justice Center

**Damper Location**

Janitor's closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

West sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 8"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM152-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

East sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM153-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

West sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM161-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-02

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
West mechanical room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM162-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
12" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East Mechanical Room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD5

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-28

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM162-FSD6

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

16" x 16"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD8

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM162-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-13

### Facility Location

Juvenile Justice Center

### Damper Location

Men's room

### Inspector Name

Julie Gue

### Damper I.D. #

IM162-FSD10

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

14" x 8"

### Damper Manufacturer

Greenheck

### Damper Model #

FSD211

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-15

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Janitors closet.

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
IM162-FSD11

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Ruskin


**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
Grille

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator Lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Est sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM163-FSD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM171-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator Lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM172-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-02

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
West mechanical room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
IM172-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
12" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6x6

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-15

### Facility Location

Juvenile Justice Center

### Damper Location

Janitors' closet.

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM172-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Has been cleaned.  
Unable to remove  
All of the grim.

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-15

### Facility Location

Juvenile Justice Center

### Damper Location

Elevator Lobby

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM172-FSD6

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

16" x 10"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD8

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-23

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM172-FSD10

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Judges' elevator

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM173-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

West sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM181-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182 FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator Lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM182-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Janitors closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM182-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-24

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM182-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

16" x 16"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD8

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-02

### Facility Location

Juvenile Justice Center

### Damper Location

West mechanical room

### Inspector Name

Julie Gue

### Damper I.D. #

IM182-FSD9

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

12"x 20"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

6" x 6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-02

**Facility Location**

Juvenile Justice Center

**Damper Location**

West mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD10

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

54" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Sitting area

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM183-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Restroom

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM191-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

22" x 14"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Elevator Lobby

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM192-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD1

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

84" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-15

**Facility Location**

Juvenile Justice Center

**Damper Location**

Janitors closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM192-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

36" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

36" x 10"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-15

### Picture of Damper in Open Position



### Facility Location

Juvenile Justice Center

### Damper Location

Elevator Lobby

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM192-FSD5

### Picture of Damper in Closed Position



### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

16" x 10"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Picture of Damper I.D. Label



### Access Door Size

10" x 10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Copy

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-SD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

28" x 6"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

26" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

South of copy room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR501

**Fusible Link Temperature**

N/A

**Access Door Size**

9" x 6" Oval


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Restroom

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM193-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16" x 24"

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
329	FD	M201-FD1	24"X 8"	Ruskin	5 X4"	IBD2	Pass	Pass	Room #945
330	FD	M201-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	Room #945
331	FSD	M201-FSD1	10"X 8"	Ruskin	8"X 8"	FSD60	Pass	Pass	Room #907
332	FSD	M201-FSD2	10"X 8"	Ruskin	4"X 4"	FSD60	Pass	Pass	Dry Storage
333	FSD	M201-FSD3	10"X 10"	Ruskin	8"X 8"	FSD60	Pass	Pass	Room #943
334	SD	M201-SD1	10" Round	Ruskin	5"X 5"	SDR25	Pass	Pass	Room #907
335	SD	M201-SD2	30"X 17"	Ruskin	12"X 12"	SD50	Pass	Pass	Room #907
336	SD	M201-SD3	24"X 17"	Ruskin	12"X 12"	SD50	Pass	Pass	Room #907
337	SD	M201-SD4	6" Round	Ruskin	5"X 5"	SDR25	Pass	Pass	Room #907
338	SD	M201-SD5	16"X 8"	Ruskin	12"X 12"	SD50	Pass	Pass	Room #907
339	SD	M201-SD6	10"X 6"	Ruskin	8"X 8"	SD50	Pass	Pass	Room #907
340	SD	M201-SD7	8" Round	Ruskin	4"X 4"	SD50	Pass	Pass	Room #911
341	SD	M201-SD8	12"X 6"	Ruskin	8"X 8"	SD50	Pass	Pass	Room #913
342	SD	M201-SD9	10"X 6"	Ruskin	10"X 6"	SD50	Pass	Pass	Room #913
343	SD	M201-SD10	14"X 14"	Ruskin	4"X 4"	SD50	Pass	Pass	Bulk Storage
344	SD	M201-SD11	18"X 12"	Ruskin	12"X 12"	SD50	Pass	Pass	Room #943
345	SD	M201-SD12	12"X 6"	Ruskin	6"X 6"	SD50	Pass	Pass	Central Mechanical
346	SD	M201-SD13	10" Round	Ruskin	3"X 2"	SDR25	Pass	Pass	Room #929

Inspector: Julie Gue / Larry Coreno  
Inspection Dates: 23-Aug-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-31

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Elevator Room S945

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M201-FD1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
24" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
5" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage RM 907

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-19

### Facility Location

Juvenile Justice Center

### Damper Location

Bulk Storage

### Inspector Name

Larry Coreno

### Damper I.D. #

M201-FSD2

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

10" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

4" x 4"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE/SMOKE DAMPER</b>	
Inspection Date: <b>10/19/23</b>	Reference I.D.#: <b>M201</b>
Inspected By: <b>Coreno</b>	<b>FSD2</b>
Next Inspect. By: <b>10/19/25</b>	

Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION** NEMI Certified HVAC Fire Life Safety Technicians

MEMBER NFPA

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage RM

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 907

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
5" x 5"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Storage 907

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
30" x 17"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 907

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD3

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
24" x 17"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**SMOKE**  
**DAMPER**

Inspection Date: **8 23 23**  
Inspected By: **GUE**

Reference I.D.#: **M201**  
**SD3**

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 907

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD4

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
5" x 5"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 907

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD5

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
16" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD 50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>SMOKE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>8 23 23</b>	Reference ID #: <b>M201</b>
Inspected By: <b>GUE</b>	<b>SD5</b>
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
907 Office

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD6

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 6"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE**  
**DAMPER**

Inspection Date: 8 23 23 Reference I.D.#: M201  
Inspected By: GUE SD6

Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492  
**FIRE SAFETY DIVISION** NEMI Certified HVAC Fire Life Safety Technicians  
MEMBER **NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Bulk Storage

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M201-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage RM

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD11

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
347	FSD	M202-FSD1	48"X 22"	Ruskin	12"X 12"	FSD60	Pass	Pass	Dinning Hall
348	FSD	M202-FSD2	50"X 12"	Ruskin	12"X 12"	FSD60	Pass	Pass	Dinning Hall
349	FSD	M202-FSD3	10"X 7"	Ruskin	8"X 8"	FSD60	Pass	Pass	Intake
350	SD	M202-SD1	8"X 8"	Ruskin	6"X 6"	SD50	Pass	Pass	Dinning Hall
351	SD	M202-SD2	14"X 8"	Ruskin	4"X 4"	SD50	Pass	Pass	Kitchen
352	SD	M202-SD3	10" Round	Ruskin	4"X 4"	SDR25	Pass	Pass	Kinchen Storage
353	SD	M202-SD4	6" Round	Ruskin	4"X 4"	SDR25	Pass	Pass	Kinchen Storage
354	SD	M202-SD5	8" Round	Ruskin	4"X 4"	SDR25	Pass	Pass	Kitchen
355	SD	M202-SD6	12"X 6"	Ruskin	6"X 6"	SD50	Pass	Pass	Population Files
356	SD	M202-SD7	8" Round	Ruskin	4"X 4"	SDR25	Pass	Pass	Intake
357	SD	M202-SD8	12"X 8"	Ruskin	8"X 8"	SD50	Pass	Pass	Supervisor Office
358	SD	M202-SD9	10"X 10"	Ruskin	8"X 8"	SD50	Pass	Pass	Intake
359	SD	M202-SD10	16"X 12"	Ruskin	8"X 8"	SD50	Pass	Pass	Intake

Inspector: Julie Gue/Larry Coreno  
Inspection Dates: 24-Aug-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-24

### Facility Location

Juvenile Justice Center

### Damper Location

Dining hall

### Inspector Name

Julie Gue

### Damper I.D. #

M202-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48" x 22"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Dining hall

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

50" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Property room

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M202-FSD3

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
10" x 7"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-24

### Facility Location

Juvenile Justice Center

### Damper Location

Dry Storage

### Inspector Name

Julie Gue

### Damper I.D. #

M202-SD1

### Damper Type

Vertical Smoke Damper

### Damper Size

8" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

SD50

### Fusible Link Temperature

N/A

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date:	Reference I.D. #:
<b>8 24 23</b>	<b>M 202</b>
Inspected By:	<b>SDL</b>
<b>GUE</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	<small>MEMBER <b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians <b>NFPA</b></small>

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Dry Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Dry Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Kitchen

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Population files

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Intake

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M202-SD7

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Intake supervisor office

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Property room

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Intake

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M202-SD10

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
16" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
359	FD	M203-FD1	10"X 10"	Ruskin	8"X 8"	IBD2	Pass	Pass	Medical Waiting Room
360	FD	M203-FD2	10"X 8"	Ruskin	4"X 4"	IBD2	Pass	Pass	Medical Waiting Room
361	FD	M203-FD3	12"X 6"	Ruskin	10"X 10"	IBD2	Pass	Pass	Pharmacy
362	FD	M203-FD4	30"x18"	Ruskin	16"x16"	IBD2	Pass	Pass	Small Gym
363	FD	M203-FD5	32"x14"	Ruskin	16"x16"	IBD2	Pass	Pass	Small Gym
364	FD	M203-FD6	10"x10"	Ruskin	8"x8"	IBD2	Pass	Pass	Small Gym
365	FD	M203-FD7	10"x8"	Ruskin	10"x10"	IBD2	Pass	Pass	Small Gym
366	FD	M203-FD8	22"x22"	Ruskin	16"x16"	IBD2	Pass	Pass	Small Gym
367	FSD	M203-FSD1	60x30	Ruskin	16"x16"	FSD60	Pass	Pass	Small Gym

Inspector:

Julie Gue/ Larry Coreno

SA = Supply Air

FD = Fire Damper

Inspection Dates:

August 28 and October 18, 2023

RA = Return Air

SD = Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
368	SD	M203-SD1	6" Round	Ruskin	SDR25	Pass	Pass	Medical Corridor
369	SD	M203-SD2	6" Round	Ruskin	SDR25	Pass	Pass	Medical Corridor
370	SD	M203-SD3	8x10	Ruskin	SD60	Pass	Pass	Medical Waiting
371	SD	M203-SD4	8x6	Ruskin	SD50	Pass	Pass	Medical
372	SD	M203-SD5	12x10	Ruskin	SD50	Pass	Pass	Medical Office
373	SD	M203-SD6	8x8	Ruskin	SD50	Pass	Pass	Medical
374	SD	M203-SD7	30x18	Ruskin	SD50	Pass	Pass	Medical
375	SD	M203-SD8	10x8	Ruskin	SD50	Pass	Pass	Pharmacy
376	SD	M203-SD9	24X16	Ruskin	SD50	Pass	Pass	Pharmacy
377	SD	M203-SD10	24x16	Ruskin	SD50	Pass	Pass	Medical
378	SD	M203-SD11	6" Round	Ruskin	SDR25	Pass	Pass	Medical Files
379	SD	M203-SD12	8" Round	Ruskin	SDR25	Pass	Pass	Medical Files
380	SD	M203-SD13	6x6	Greenheck	SM201	Pass	Pass	Gym Storage
381	SD	M203-SD14	6x6	Greenheck	SM201	Pass	Pass	Gym Storage
382	SD	M203-SD15	6x6	Greenheck	SM201	Pass	Pass	Gym Storage
383	SD	M203-SD16	6x6	Greenheck	SM201	Pass	Pass	Gym Storage
384	SD	M203-SD17	10" Round	Ruskin	SDR25	Pass	Pass	Domestic Clerk Office
385	SD	M203-SD18	8"x12"	Greenheck	SM201	Pass	Pass	Corridor to Domestic Clinic

Inspector: Julie Gue / Larry Coreno  
Inspection Dates: August 28 and October 18, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Small Gym Storage

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M203- SD16

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Screen

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>10/18/23</b>	Reference I.D. #: <b>M203</b>
Inspected By: <b>Coreno</b>	<b>SD16</b>
Next Inspect. By: <b>10/18/25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical waiting

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical waiting

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Pharmacy

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

30" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

30" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8'

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-18

### Facility Location

Juvenile Justice Center

### Damper Location

Small Gym

### Inspector Name

Larry Coreno

### Damper I.D. #

M203-FD8

### Damper Type

Vertical Fire Damper

### Damper Size

23" x 23"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

16" x 16"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

64" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16" x 16'

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-29

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Medical corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M203-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4x4


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date:	Reference I.D.#
8 29 23	M 203
Inspected By:	SD2
GUE	
Duct Fabricators, Inc. <b>FIRE SAFETY DIVISION</b> MEMBER <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical waiting

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Pharmacy corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Fail


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Pharmacy corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

30' x 18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Pharmacy

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M203-SD8

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-29

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Medical files

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M203-SD11

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-29

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Medical files

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M203-SD12

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym Storage

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-SD13

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym Storage

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-SD14

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Small Gym Storage

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M203-SD15

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Small Gym Storage

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M203-SD16

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Admin Files

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.1-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Elbow

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Admin Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.1-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Admin Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.1-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Custodial Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M204.2 FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-30

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Visitation

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M204.2-FD1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10x10

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
8x8

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Ankle Monitor Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

9" x 6" Oval


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Ankle monitor room

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Ankle Monitor Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

20" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-30

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Visitation

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M204.2-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation Lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
401	FSD	M204.1-FSD1	24"X 12"	Ruskin	Remove Duct	FSD60	Pass	Pass	File Room
402	SD	M204.1.SD1	8' Round	Ruskin	4"X 4"	SD50	Pass	Pass	Time Clock
403	SD	M204.1-SD2	10" Round	Ruskin	4"X 4"	SD50	Pass	Pass	File Room
404	FD	M204.2-FD1	10"X 10"	Ruskin	8"X 8"	IBD2	Pass	Pass	Visitation
405	FD	M204.2-FD2	28"X 14"	Ruskin	10"X 10"	IBD2	Pass	Pass	Recycling 437
406	FD	M204.2-FD3	8" Round	Ruskin	6" X 9" OVAL	IBD2	Pass	Pass	Room 317
407	FD	M204.2-FD4	28"X 10"	Ruskin	12"X 12"	IBD2	Pass	Pass	Room 317
408	FD	M204.2-FD5	20"X 10"	Ruskin	12"X 12"	IBD2	Pass	Pass	Room 317
409	FD	M204.2-FD6	24"x12"	Ruskin	12"X 12"	IBD2	Pass	Pass	Visitation Lobby
410	FSD	M204.2-FSD1	30"x30"	Ruskin	12"X 12"	FSD60	Pass	Pass	Custodial Closet
411	SD	M204.2-SD1	6" Round	Ruskin	4 X 4	SDR 25	Pass	Pass	Professional visit
412	SD	M204.2-SD2	8" Round	Ruskin	3"X 3"	SDR25	Pass	Pass	None
413	SD	M204.2-SD3	24"X 6"	Ruskin	Transfer	SD50	Pass	Pass	None
414	SD	M204.2-SD4	6 X 6	Ruskin	6 X 6	SD50	Pass	Pass	None
415	SD	M204.2-SD5	30"X 18"	Ruskin	12"X 12"	SD50	Pass	Pass	Room 322
416	SD	M204.2-SD6	38"X 18"	Ruskin	12"X 12"	SD50	Pass	Pass	Room 322

Inspector: Julie Gue / Larry Coreno  
Inspection Dates: October 14 17 and 28 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
417	FD	M205-FD1	14 X 12	Ruskin	Open	IBD2	Pass	Pass	Exit corridor
418	FD	M205-FD2	8" Round	Ruskin	Remove pipe	IBD2	Pass	Pass	Exit corridor
419	SD	M205-SD1	8 X 10	Ruskin	2 X 2	SD50	Pass	Pass	Training storage
420	SD	M205-SD2	6" Round	Ruskin	10" Round	SDR525	Pass	Pass	Training storage
421	SD	M205-SD3	24X6	Ruskin	3X3	SD50	Pass	Pass	Training storage
422	SD	M205-SD4	8" Round	Ruskin	4x4	SD50	Pass	Pass	RM120
423	SD	M205-SD5	8" Round	Ruskin	4x4	SD50	Pass	Pass	RM120
424	SD	M205-SD6	12 X 8	Ruskin	6x6	SD50	Pass	Pass	RM 126
425	SD	M205-SD7	24 X 6	Ruskin	Open	SD50	Pass	Pass	RM 126
426	SD	M206-FSD1	24X6	Ruskin	Open	FSD60	Pass	Pass	Education storage/mislabeled as SD previously
427	SD	M206-SD1	8" Round	Ruskin	4X4	SDR25	Pass	Pass	Education secretary
428	SD	M206-SD2	6" Round	Ruskin	4X4	SDR25	Pass	Pass	Education secretary
429	SD	M207SD1	8" Round	Ruskin	4X4	SD50	Pass	Pass	Storage room (M207-FSD1)
430	SD	M207-FSD1	48X24	Ruskin	12X12	FSD60	Pass	Pass	Storage room (M207-SD2)
431	SD	M207-FSD2	26X22	Ruskin	Screen	FSD60	Pass	Pass	Storage room (M207-SD3)

Inspector: Larry Coreno  
Inspection Dates: September 18&19, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
A532 Exit

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M205-FD1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
14" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

A532 Exit corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Elbow

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training Room Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Training Room Storage

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M205-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25


**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training Room Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM E120

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

E120 storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

5" x 5"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM E126

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M205-SD6

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM E126

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM E110

**Inspector Name**

Julie Gue

**Damper I.D. #**

M206-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

24" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

E109 Education liaison

**Inspector Name**

Julie Gue

**Damper I.D. #**

M206-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM E109

**Inspector Name**

Julie Gue

**Damper I.D. #**

M206-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-04

### Facility Location

Juvenile Justice Center

### Damper Location

Big Gym Storage RM

### Inspector Name

Larry Coreno

### Damper I.D. #

M207-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Big Gym Storage RM

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M207-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

26" x 22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Big Gym Storage RM

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M207-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

MUA-001

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30" x 18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

MAU-002

**Damper Type**

Horizontal Fire Damper

**Damper Size**

34" x 26"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

18" x 18"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
MUA-004

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
36 " x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE**  
**DAMPER**

Inspection Date: <b>8-10-23</b>	Reference I.D. #: <b>MUA-004</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>8-10-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
432	FD	PH-FD1	36"X 16"	Ruskin	Grille	IBD2	Pass	Pass	None
433	FD	PH-FD2	24"X 20"	Ruskin	Grille	IBD2	Pass	Pass	None
434	FD	PH-FD3	42"X 42"	Ruskin	16"X 16"	IBD2	Pass	Pass	None
435	FSD	PH-FSD1	30"X 30"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
436	FSD	PH-FSD2	30"X 30"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
437	FSD	PH-FSD3	38"X 24"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
438	FSD	PH-FSD4	60"X 18"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
439	FSD	PH-FSD5	38"X 24"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
440	FD	Basement-FD1	35x25.5	Ruskin	12X12	IBD2	Pass	N/A	None
441	FD	Basement-FD2	10" Round	Ruskin	Screen	IBD2	Pass	N/A	None
442	FD	Basement-FD3	32X20	Ruskin	10x10	IBD2	Pass	N/A	None

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 7-Aug-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH- FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-07

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse

### Inspector Name

Julie Gue

### Damper I.D. #

PH-FD 1

### Damper Type

Vertical Fire Damper

### Damper Size

36" x 16"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
PH-FD3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
42" x 42"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
PH-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
30" x 30"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
14" x 14"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
PH-FSD3

**Damper Type**  
Horizontal Fire / Smoke Damper

**Damper Size**  
38" x 24"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
14" x 14'


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FSD5

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

38" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
443	FD	STR5-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
444	FD	STR5-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
445	FD	STR5-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
446	FD	STR5-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
447	FD	STR5-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
448	FD	STR6-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
449	FD	STR6-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
450	FD	STR6-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
451	FD	STR6-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
452	FD	STR6-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
453	FD	STR7-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
454	FD	STR7-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
455	FD	STR7-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
456	FD	STR7-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
457	FD	STR7-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None

Inspector: Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 14-Aug-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

7th Floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell #5 FD-2

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

3rd Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #5 FD-4

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell#5 9th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #5 FD-1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

5<sup>th</sup> Floor.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #5 FD-3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

1st floor.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #5 FD-5

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

9th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell#6 FD-1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

7th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell#6 FD-2

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

5th Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell#6 FD-3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>8-14-23</b>	Reference I.D.#: <b>STAIRWELL#6</b>
Inspected By: <b>TULCEWICZ</b>	<b>FD-3</b>
Next Inspect. By: <b>8-14-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

3rd floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell#6 FD-4

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

1st floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell#6 FD-5

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

1st floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell #7 FD-1

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille.

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

3rd Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #7 FD-2

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: <b>8-14-23</b>	Reference I.D. #: <b>Stairwell #7</b>
Inspected By: <b>Tulcewicz</b>	<b>FD-2</b>
Next Inspect. By: <b>8-14-25</b>	
Duct Fabricators, Inc. <b>FIRE SAFETY DIVISION</b>	
883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492 NEMI Certified HVAC Fire Life Safety Technicians	

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #7 FD-3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

7th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell #7 FD-4

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille.

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

9th Floor.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #7 FD-5

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper level

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

16" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

18" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT1-FD3

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Level

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Level

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Level

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT1-FD7

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
14" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Level

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

18" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-27

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

Unit1-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-27

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier

**Inspector Name**

Larry Coreno

**Damper I.D. #**

Unit1-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

17" x 15"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: <b>10/27/23</b>	Reference I.D.#: <b>Unit 1-FD10</b>
Inspected By: <b>Coreno</b>	
Next Inspect. By: <b>10/27/25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-27

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
Unit1-FD11

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
17" x 15"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-27

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
Unit1-FD12

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
17" x 15"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>10/27/23</b>	Reference I.D.#: <b>Unit1-FD12</b>
Inspected By: <b>Coreno</b>	
Next Inspect. By: <b>10/27/25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
<small>MEMBER NFPA</small>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-27

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier

**Inspector Name**

Larry Coreno

**Damper I.D. #**

Unit1-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

17" x 15"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-27

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
Unit1-FD15

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
13" x 9"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
10" x 10"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-27

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

1DS1

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
UNIT2

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT2-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" x 6"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50


**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**SMOKE**  
**DAMPER**

Inspection Date: 10-3-23 Reference I.D.#: unit2-501  
Inspected By: Coreno

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

2DS1

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT2-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

3D01

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT3-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Housing Unit 3

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT3-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6x6

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6x6

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Housing Unit4

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT4-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>SMOKE DAMPER</b>	
Inspection Date: <b>10-3-23</b>	Reference I.D.# <b>Unit 4- SD1</b>
Inspected By: <b>Coreno</b>	
Next Inspect. By: <b>10-3-25</b>	
Duct Fabricators, Inc. <b>FIRE SAFETY DIVISION</b> 	
883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492 NEMI Certified HVAC Fire Life Safety Technicians	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Housing UNIT4

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT4-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE DAMPER**

Inspection Date:	Reference I.D. #
10-3-23	unit4-SD2
Inspected By:	
Coreno	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
House 5SD1

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT5-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" x 6"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

5D01

**Inspector Name**

Larry Coreno

**Damper I.D. #**

Unit5-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

5D50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
458	FD	Unut1-FD1	16X14	Ruskin	10x10	IBD2	Pass	Pass	Second Tier
459	FD	Unit1-FD2	16X10	Ruskin	10x10	IBD2	Pass	Pass	Second Tier
460	FD	Unit1-FD3	10X8	Ruskin	8X8	IBD2	Pass	Pass	Second Tier
461	FD	Unit1-FD4	12X6	Ruskin	10X10	IBD2	Pass	Pass	Second Tier
462	FD	Unit1-FD5	12X8	Ruskin	4X8	IBD2	Pass	Pass	Second Tier
463	FD	Unit1-FD6	10X10	Ruskin	10X10	IBD2	Pass	Pass	Second Tier
464	FD	Unit1-FD7	14X16	Ruskin	12X12	IBD2	Pass	Pass	Second Tier
465	FD	Unit1-FD8	18X16	Ruskin	12X12	IBD2	Pass	Pass	Second Tier
466	FD	Unit1-FD9	8x8	Ruskin	4x4	IBD2	Pass	Pass	Second Tier needed on house side. Electrician needed to remove lights for access
467	FD	Unit1-FD10	17x15	Ruskin	8x8	IBD2	Pass	Pass	
468	FD	Unit1-FD11	17x15	Ruskin	12x12	IBD2	Pass	Pass	
469	FD	Unit1-FD12	17x15	Ruskin	12x12	IBD2	Pass	Pass	
470	FD	Unit1-FD13	17x15	Ruskin	10x10	IBD2	Pass	Pass	
471	FD	Unit1-FD14	17x15	Ruskin	10x10	IBD2	Pass	Pass	
472	FD	Unit1-FD15	13x9	Ruskin	10x10	IBD2	Pass	Pass	
473	FD	Unit1-FD16	8x8	Ruskin	4x4	IBD2	Pass	Pass	
474	FSD	Unit1-FSD1	6X6	Ruskin	6X6	FSD60	Pass	Pass	
475	FSD	Unit1-FSD2	6X6	Ruskin	6X6	FSD60	Pass	Pass	Storage Room
476	SD	Unit2- SD1	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
477	SD	Unit2- SD2	6X6	Ruskin	6X6	SD50	Pass	Pass	Managers Office

Inspector: Larry Coreno  
Inspection Dates: October 3 & 27, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
478	SD	Unit3-SD1	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
479	SD	Unit3-SD2	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
480	SD	Unit4-SD1	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
481	SD	Unit4-SD2	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
482	SD	Unit5-SD1	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
483	SD	Unit5-SD2	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room

Inspector: Larry Coreno  
Inspection Dates: October 3 & 5, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
329	FD	M201-FD1	24"X 8"	Ruskin	5 X4"	IBD2	Pass	Pass	Room #945
330	FD	M201-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	Room #945
331	FSD	M201-FSD1	10"X 8"	Ruskin	8"X 8"	FSD60	Pass	Pass	Room #907
332	FSD	M201-FSD2	10"X 8"	Ruskin	4"X 4"	FSD60	Pass	Pass	Dry Storage
333	FSD	M201-FSD3	10"X 10"	Ruskin	8"X 8"	FSD60	Pass	Pass	Room #943
334	SD	M201-SD1	10" Round	Ruskin	5"X 5"	SDR25	Pass	Pass	Room #907
335	SD	M201-SD2	30"X 17"	Ruskin	12"X 12"	SD50	Pass	Pass	Room #907
336	SD	M201-SD3	24"X 17"	Ruskin	12"X 12"	SD50	Pass	Pass	Room #907
337	SD	M201-SD4	6" Round	Ruskin	5"X 5"	SDR25	Pass	Pass	Room #907
338	SD	M201-SD5	16"X 8"	Ruskin	12"X 12"	SD50	Pass	Pass	Room #907
339	SD	M201-SD6	10"X 6"	Ruskin	8"X 8"	SD50	Pass	Pass	Room #907
340	SD	M201-SD7	8" Round	Ruskin	4"X 4"	SD50	Pass	Pass	Room #911
341	SD	M201-SD8	12"X 6"	Ruskin	8"X 8"	SD50	Pass	Pass	Room #913
342	SD	M201-SD9	10"X 6"	Ruskin	10"X 6"	SD50	Pass	Pass	Room #913
343	SD	M201-SD10	14"X 14"	Ruskin	4"X 4"	SD50	Pass	Pass	Bulk Storage
344	SD	M201-SD11	18"X 12"	Ruskin	12"X 12"	SD50	Pass	Pass	Room #943
345	SD	M201-SD12	12"X 6"	Ruskin	6"X 6"	SD50	Pass	Pass	Central Mechanical
346	SD	M201-SD13	10" Round	Ruskin	3"X 2"	SDR25	Pass	Pass	Room #929

Inspector: Julie Gue / Larry Coreno  
Inspection Dates: 23-Aug-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-31

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Elevator Room S945

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M201-FD1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
24" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
5" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-23

### Facility Location

Juvenile Justice Center

### Damper Location

Storage RM 907

### Inspector Name

Julie Gue

### Damper I.D. #

M201-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

10" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

8" x 8"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>FIRE/SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: 8-23-23	Reference I.D.# M201
Inspected By: Gue	FSD1
Next Inspect. By: 8-23-23	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	<small>NEMI Certified HVAC Fire Life Safety Technicians</small>

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-19

### Facility Location

Juvenile Justice Center

### Damper Location

Bulk Storage

### Inspector Name

Larry Coreno

### Damper I.D. #

M201-FSD2

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

10" x 8"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

4" x 4"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage RM

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 907

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
5" x 5"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-23

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage 907

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

30" x 17"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 907

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD3

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
24" x 17"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" x 12"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 907

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD4

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
5" x 5"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 907

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD5

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
16" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD 50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
907 Office

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD6

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 6"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE**  
**DAMPER**

Inspection Date: 8 23 23 Reference I.D.#: M201  
Inspected By: GUE SD6

Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492  
**FIRE SAFETY DIVISION** NEMI Certified HVAC Fire Life Safety Technicians  
MEMBER **NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Bulk Storage

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M201-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-23

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Storage RM

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M201-SD11

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
18" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
347	FSD	M202-FSD1	48"X 22"	Ruskin	12"X 12"	FSD60	Pass	Pass	Dinning Hall
348	FSD	M202-FSD2	50"X 12"	Ruskin	12"X 12"	FSD60	Pass	Pass	Dinning Hall
349	FSD	M202-FSD3	10"X 7"	Ruskin	8"X 8"	FSD60	Pass	Pass	Intake
350	SD	M202-SD1	8"X 8"	Ruskin	6"X 6"	SD50	Pass	Pass	Dinning Hall
351	SD	M202-SD2	14"X 8"	Ruskin	4"X 4"	SD50	Pass	Pass	Kitchen
352	SD	M202-SD3	10" Round	Ruskin	4"X 4"	SDR25	Pass	Pass	Kinchen Storage
353	SD	M202-SD4	6" Round	Ruskin	4"X 4"	SDR25	Pass	Pass	Kinchen Storage
354	SD	M202-SD5	8" Round	Ruskin	4"X 4"	SDR25	Pass	Pass	Kitchen
355	SD	M202-SD6	12"X 6"	Ruskin	6"X 6"	SD50	Pass	Pass	Population Files
356	SD	M202-SD7	8" Round	Ruskin	4"X 4"	SDR25	Pass	Pass	Intake
357	SD	M202-SD8	12"X 8"	Ruskin	8"X 8"	SD50	Pass	Pass	Supervisor Office
358	SD	M202-SD9	10"X 10"	Ruskin	8"X 8"	SD50	Pass	Pass	Intake
359	SD	M202-SD10	16"X 12"	Ruskin	8"X 8"	SD50	Pass	Pass	Intake

Inspector: Julie Gue/Larry Coreno  
Inspection Dates: 24-Aug-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-24

### Facility Location

Juvenile Justice Center

### Damper Location

Dining hall

### Inspector Name

Julie Gue

### Damper I.D. #

M202-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48" x 22"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Dining hall

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

50" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Property room

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10" x 7"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Dry Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Dry Storage

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M202-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Grille

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-24

**Facility Location**

Juvenile Justice Center

**Damper Location**

Dry Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-24

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Kitchen

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M202-SD5

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Population files

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Intake

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M202-SD7

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Intake supervisor office

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Property room

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Intake

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M202-SD10

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
16" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
359	FD	M203-FD1	10"X 10"	Ruskin	8"X 8"	IBD2	Pass	Pass	Medical Waiting Room
360	FD	M203-FD2	10"X 8"	Ruskin	4"X 4"	IBD2	Pass	Pass	Medical Waiting Room
361	FD	M203-FD3	12"X 6"	Ruskin	10"X 10"	IBD2	Pass	Pass	Pharmacy
362	FD	M203-FD4	30"x18"	Ruskin	16"x16"	IBD2	Pass	Pass	Small Gym
363	FD	M203-FD5	32"x14"	Ruskin	16"x16"	IBD2	Pass	Pass	Small Gym
364	FD	M203-FD6	10"x10"	Ruskin	8"x8"	IBD2	Pass	Pass	Small Gym
365	FD	M203-FD7	10"x8"	Ruskin	10"x10"	IBD2	Pass	Pass	Small Gym
366	FD	M203-FD8	22"x22"	Ruskin	16"x16"	IBD2	Pass	Pass	Small Gym
367	FSD	M203-FSD1	60x30	Ruskin	16"x16"	FSD60	Pass	Pass	Small Gym

Inspector:

Julie Gue/ Larry Coreno

SA = Supply Air

FD = Fire Damper

Inspection Dates:

August 28 and October 18, 2023

RA = Return Air

SD = Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
368	SD	M203-SD1	6" Round	Ruskin	SDR25	Pass	Pass	Medical Corridor
369	SD	M203-SD2	6" Round	Ruskin	SDR25	Pass	Pass	Medical Corridor
370	SD	M203-SD3	8x10	Ruskin	SD60	Pass	Pass	Medical Waiting
371	SD	M203-SD4	8x6	Ruskin	SD50	Pass	Pass	Medical
372	SD	M203-SD5	12x10	Ruskin	SD50	Pass	Pass	Medical Office
373	SD	M203-SD6	8x8	Ruskin	SD50	Pass	Pass	Medical
374	SD	M203-SD7	30x18	Ruskin	SD50	Pass	Pass	Medical
375	SD	M203-SD8	10x8	Ruskin	SD50	Pass	Pass	Pharmacy
376	SD	M203-SD9	24X16	Ruskin	SD50	Pass	Pass	Pharmacy
377	SD	M203-SD10	24x16	Ruskin	SD50	Pass	Pass	Medical
378	SD	M203-SD11	6" Round	Ruskin	SDR25	Pass	Pass	Medical Files
379	SD	M203-SD12	8" Round	Ruskin	SDR25	Pass	Pass	Medical Files
380	SD	M203-SD13	6x6	Greenheck	SM201	Pass	Pass	Gym Storage
381	SD	M203-SD14	6x6	Greenheck	SM201	Pass	Pass	Gym Storage
382	SD	M203-SD15	6x6	Greenheck	SM201	Pass	Pass	Gym Storage
383	SD	M203-SD16	6x6	Greenheck	SM201	Pass	Pass	Gym Storage
384	SD	M203-SD17	10" Round	Ruskin	SDR25	Pass	Pass	Domestic Clerk Office
385	SD	M203-SD18	8"x12"	Greenheck	SM201	Pass	Pass	Corridor to Domestic Clinic

Inspector: Julie Gue / Larry Coreno  
Inspection Dates: August 28 and October 18, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym Storage

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203- SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical waiting

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical waiting

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Pharmacy

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M203-FD3

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
12" x 6"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
10" x 10"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-18

### Facility Location

Juvenile Justice Center

### Damper Location

Small Gym

### Inspector Name

Larry Coreno

### Damper I.D. #

M203-FD4

### Damper Type

Vertical Fire Damper

### Damper Size

30" x 20"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

16" x 16"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

30" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16" x 16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Small Gym

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M203-FD6

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
8" x 8'

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-18

### Facility Location

Juvenile Justice Center

### Damper Location

Small Gym

### Inspector Name

Larry Coreno

### Damper I.D. #

M203-FD8

### Damper Type

Vertical Fire Damper

### Damper Size

23" x 23"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

16" x 16"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

64" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16" x 16'

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-29

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Medical corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M203-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4x4


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date:	Reference I.D.#
8 29 23	M 203
Inspected By:	SD2
GUE	
Duct Fabricators, Inc. <b>FIRE SAFETY DIVISION</b> MEMBER <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical waiting

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Pharmacy corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Fail


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Pharmacy corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

30' x 18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Pharmacy

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M203-SD8

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-29

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-29

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Medical files

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M203-SD11

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-29

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Medical files

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M203-SD12

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Small Gym Storage

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M203-SD13

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Screen

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

Small Gym Storage

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M203-SD14

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Greenheck

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Small Gym Storage

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M203-SD15

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Small Gym Storage

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M203-SD16

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" x 8"

**Damper Manufacturer**  
Greenheck

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Admin Files

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.1-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Elbow

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Admin Corridor

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M204.1-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Admin Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.1-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Custodial Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M204.2 FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

N/A

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-30

**Picture of Damper in Open Position**

**Facility Location**  
Juvenile Justice Center



**Damper Location**  
Visitation

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M204.2-FD1

**Picture of Damper in Closed Position**

**Damper Type**  
Vertical Fire Damper



**Damper Size**  
10x10

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Picture of Damper I.D. Label**

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
8x8

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-30

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Ankle Monitor Storage

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M204.2-FD3

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
9" x 6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Ankle monitor room

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Ankle Monitor Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

20" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-30

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Visitation

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M204.2-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-30

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Visitation

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M204.2-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4x4

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-30

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation Lobby

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
401	FSD	M204.1-FSD1	24"X 12"	Ruskin	Remove Duct	FSD60	Pass	Pass	File Room
402	SD	M204.1.SD1	8' Round	Ruskin	4"X 4"	SD50	Pass	Pass	Time Clock
403	SD	M204.1-SD2	10" Round	Ruskin	4"X 4"	SD50	Pass	Pass	File Room
404	FD	M204.2-FD1	10"X 10"	Ruskin	8"X 8"	IBD2	Pass	Pass	Visitation
405	FD	M204.2-FD2	28"X 14"	Ruskin	10"X 10"	IBD2	Pass	Pass	Recycling 437
406	FD	M204.2-FD3	8" Round	Ruskin	6" X 9" OVAL	IBD2	Pass	Pass	Room 317
407	FD	M204.2-FD4	28"X 10"	Ruskin	12"X 12"	IBD2	Pass	Pass	Room 317
408	FD	M204.2-FD5	20"X 10"	Ruskin	12"X 12"	IBD2	Pass	Pass	Room 317
409	FD	M204.2-FD6	24"x12"	Ruskin	12"X 12"	IBD2	Pass	Pass	Visitation Lobby
410	FSD	M204.2-FSD1	30"x30"	Ruskin	12"X 12"	FSD60	Pass	Pass	Custodial Closet
411	SD	M204.2-SD1	6" Round	Ruskin	4 X 4	SDR 25	Pass	Pass	Professional visit
412	SD	M204.2-SD2	8" Round	Ruskin	3"X 3"	SDR25	Pass	Pass	None
413	SD	M204.2-SD3	24"X 6"	Ruskin	Transfer	SD50	Pass	Pass	None
414	SD	M204.2-SD4	6 X 6	Ruskin	6 X 6	SD50	Pass	Pass	None
415	SD	M204.2-SD5	30"X 18"	Ruskin	12"X 12"	SD50	Pass	Pass	Room 322
416	SD	M204.2-SD6	38"X 18"	Ruskin	12"X 12"	SD50	Pass	Pass	Room 322

Inspector: Julie Gue / Larry Coreno  
Inspection Dates: October 14 17 and 28 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
417	FD	M205-FD1	14 X 12	Ruskin	Open	IBD2	Pass	Pass	Exit corridor
418	FD	M205-FD2	8" Round	Ruskin	Remove pipe	IBD2	Pass	Pass	Exit corridor
419	SD	M205-SD1	8 X 10	Ruskin	2 X 2	SD50	Pass	Pass	Training storage
420	SD	M205-SD2	6" Round	Ruskin	10" Round	SDR525	Pass	Pass	Training storage
421	SD	M205-SD3	24X6	Ruskin	3X3	SD50	Pass	Pass	Training storage
422	SD	M205-SD4	8" Round	Ruskin	4x4	SD50	Pass	Pass	RM120
423	SD	M205-SD5	8" Round	Ruskin	4x4	SD50	Pass	Pass	RM120
424	SD	M205-SD6	12 X 8	Ruskin	6x6	SD50	Pass	Pass	RM 126
425	SD	M205-SD7	24 X 6	Ruskin	Open	SD50	Pass	Pass	RM 126
426	SD	M206-FSD1	24X6	Ruskin	Open	FSD60	Pass	Pass	Education storage/mislabeled as SD previously
427	SD	M206-SD1	8" Round	Ruskin	4X4	SDR25	Pass	Pass	Education secretary
428	SD	M206-SD2	6" Round	Ruskin	4X4	SDR25	Pass	Pass	Education secretary
429	SD	M207SD1	8" Round	Ruskin	4X4	SD50	Pass	Pass	Storage room (M207-FSD1)
430	SD	M207-FSD1	48X24	Ruskin	12X12	FSD60	Pass	Pass	Storage room (M207-SD2)
431	SD	M207-FSD2	26X22	Ruskin	Screen	FSD60	Pass	Pass	Storage room (M207-SD3)

Inspector: Larry Coreno  
Inspection Dates: September 18&19, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
A532 Exit

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M205-FD1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
14" x 12"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2


**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

A532 Exit corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Elbow

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training Room Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" x 10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-19

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Training Room Storage

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M205-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SDR25


**Fusible Link Temperature**  
N/A

**Access Door Size**  
9" x 6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training Room Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM E120

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

E120 storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

5" x 5"


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-09-18

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM E126

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M205-SD6

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM E126

**Inspector Name**

Julie Gue

**Damper I.D. #**

M205-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM E110

**Inspector Name**

Julie Gue

**Damper I.D. #**

M206-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

24" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

E109 Education liaison

**Inspector Name**

Julie Gue

**Damper I.D. #**

M206-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-09-18

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM E109

**Inspector Name**

Julie Gue

**Damper I.D. #**

M206-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4" x 4"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-10-04

### Facility Location

Juvenile Justice Center

### Damper Location

Big Gym Storage RM

### Inspector Name

Larry Coreno

### Damper I.D. #

M207-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48" x 24"

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

12" x 12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Big Gym Storage RM

**Inspector Name**

Larry Coreno

**Damper I.D. #**

M207-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

26" x 22"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE/SMOKE  
DAMPER**

Inspection Date: <b>10-4-23</b>	Reference I.D.#: <b>M207-FSD 2</b>
Inspected By: <b>Coreno</b>	
Next Inspect. By: <b>10-4-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-04

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Big Gym Storage RM

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
M207-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4" x 4"


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

MUA-001

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30" x 18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #5

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

MAU-002

**Damper Type**

Horizontal Fire Damper

**Damper Size**

34" x 26"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

18" x 18"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-10

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse #5

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
MUA-004

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
36" x 20"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>8-10-23</b>	Reference I.D. #: <b>MUA-004</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>8-10-25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small>MEMBER <b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
432	FD	PH-FD1	36"X 16"	Ruskin	Grille	IBD2	Pass	Pass	None
433	FD	PH-FD2	24"X 20"	Ruskin	Grille	IBD2	Pass	Pass	None
434	FD	PH-FD3	42"X 42"	Ruskin	16"X 16"	IBD2	Pass	Pass	None
435	FSD	PH-FSD1	30"X 30"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
436	FSD	PH-FSD2	30"X 30"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
437	FSD	PH-FSD3	38"X 24"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
438	FSD	PH-FSD4	60"X 18"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
439	FSD	PH-FSD5	38"X 24"	Ruskin	14"X 14"	FSD60	Pass	Pass	None
440	FD	Basement-FD1	35x25.5	Ruskin	12X12	IBD2	Pass	N/A	None
441	FD	Basement-FD2	10" Round	Ruskin	Screen	IBD2	Pass	N/A	None
442	FD	Basement-FD3	32X20	Ruskin	10x10	IBD2	Pass	N/A	None

Inspector: Julie Gue/ Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 7-Aug-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH- FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30" x 30"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-07

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse

### Inspector Name

Julie Gue

### Damper I.D. #

PH-FD 1

### Damper Type

Vertical Fire Damper

### Damper Size

36" x 16"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 20"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
PH-FD3

**Damper Type**  
Horizontal Fire Damper

**Damper Size**  
42" x 42"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
16" x 16"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
PH-FSD1

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
30" x 30"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
14" x 14"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-08-07

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Penthouse

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
PH-FSD3

**Damper Type**  
Horizontal Fire / Smoke Damper

**Damper Size**  
38" x 24"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
FSD60

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
14" x 14'


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label







## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60" x 18"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FSD5

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

38" x 24"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14" x 14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
443	FD	STR5-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
444	FD	STR5-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
445	FD	STR5-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
446	FD	STR5-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
447	FD	STR5-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
448	FD	STR6-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
449	FD	STR6-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
450	FD	STR6-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
451	FD	STR6-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
452	FD	STR6-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
453	FD	STR7-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
454	FD	STR7-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
455	FD	STR7-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
456	FD	STR7-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None
457	FD	STR7-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	Pass	None

Inspector: Dan Tulcewicz/ Larry Coreno  
Inspection Dates: 14-Aug-23  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

7th Floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell #5 FD-2

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>8-14-23</b>	Reference I.D.# <b>Stairwell #5 FD-2</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>8-14-25</b>	
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

3rd Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #5 FD-4

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell#5 9th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #5 FD-1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

5<sup>th</sup> Floor.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #5 FD-3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

1st floor.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #5 FD-5

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

1st floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell #7 FD-1

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille.

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

3rd Floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell #7 FD-2

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille.

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>8-14-23</b>	Reference I.D. #: <b>Stairwell #7</b>
Inspected By: <b>Tulcewicz</b>	<b>FD-2</b>
Next Inspect. By: <b>8-14-25</b>	

Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #7 FD-3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

7th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell #7 FD-4

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille.

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

9th Floor.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell #7 FD-5

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

1st floor.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell#5 FD-5

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

9th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell#6 FD-1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

7th floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell#6 FD-2

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

5th Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell#6 FD-3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Remove the grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE DAMPER**

Inspection Date: <b>8-14-23</b>	Reference I.D.#: <b>STAIRWELL#6</b>
Inspected By: <b>TULCEWICZ</b>	<b>FD-3</b>
Next Inspect. By: <b>8-14-25</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-08-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

3rd floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell#6 FD-4

**Damper Type**

Vertical Fire Damper

**Damper Size**

24" x 12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2023-08-14

### Facility Location

Juvenile Justice Center

### Damper Location

1st floor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

Stairwell#6 FD-5

### Damper Type

Vertical Fire Damper

### Damper Size

24" x 12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper level

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

16" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

18" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT1-FD3

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10" x 8"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
8" x 8"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Level

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Level

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" x 14"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Level

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT1-FD6

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
10" x 10"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
10" x 10"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-05

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT1-FD7

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
14" x 16"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Level

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

18" x 16"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" x 12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-27

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

Unit1-FD9

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-27

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier

**Inspector Name**

Larry Coreno

**Damper I.D. #**

Unit1-FD10

**Damper Type**

Vertical Fire Damper

**Damper Size**

17" x 15"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8" x 8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: <b>10/27/23</b>	Reference I.D.#: <b>Unit 1-FD10</b>
Inspected By: <b>Coreno</b>	
Next Inspect. By: <b>10/27/25</b>	
Duct Fabricators, Inc. <b>FIRE SAFETY DIVISION</b> MEMBER 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492 NEMI Certified HVAC Fire Life Safety Technicians <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-27

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
Unit1-FD11

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
17" x 15"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-27

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
Unit1-FD12

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
17" x 15"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" x 12"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>10/27/23</b>	Reference I.D. #: <b>Unit1-FD12</b>
Inspected By: <b>Coreno</b>	
Next Inspect. By: <b>10/27/25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER NFPA</small>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-27

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier

**Inspector Name**

Larry Coreno

**Damper I.D. #**

Unit1-FD14

**Damper Type**

Vertical Fire Damper

**Damper Size**

17" x 15"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" x 10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-27

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Upper Tier

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
Unit1-FD15

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
13" x 9"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
10" x 10"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-27

**Facility Location**

Juvenile Justice Center

**Damper Location**

Upper Tier Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" x 8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4" x 4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

1DS1

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT1-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
UNIT2

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT2-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" x 6"

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50


**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" x 6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**SMOKE**  
**DAMPER**

Inspection Date: 10-3-23 Reference I.D.#: unit2-501  
Inspected By: Coreno

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

3D01

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT3-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-10-03

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Housing Unit 3

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
UNIT3-SD2

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6x6

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6x6

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE DAMPER**

Inspection Date: <b>10-3-23</b>	Reference I.D. #: <b>Unit 3-SD2</b>
Inspected By: <b>Coreno</b>	
Next Inspect. By: <b>10-3-2025</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Housing Unit4

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT4-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>SMOKE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>10-3-23</b>	Reference I.D.# <b>Unit 4- SD1</b>
Inspected By: <b>Coreno</b>	
Next Inspect. By: <b>10-3-25</b>	
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
<b>NFPA</b>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Housing UNIT4

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT4-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE DAMPER**

Inspection Date:	Reference I.D. #
10-3-23	unit4-SD2
Inspected By:	
Coreno	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

House 5SD1

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT5-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

5D01

**Inspector Name**

Larry Coreno

**Damper I.D. #**

Unit5-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

5D50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

2DS1

**Inspector Name**

Larry Coreno

**Damper I.D. #**

UNIT2-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" x 6"

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6" x 6"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
458	FD	Unut1-FD1	16X14	Ruskin	10x10	IBD2	Pass	Pass	Second Tier
459	FD	Unit1-FD2	16X10	Ruskin	10x10	IBD2	Pass	Pass	Second Tier
460	FD	Unit1-FD3	10X8	Ruskin	8X8	IBD2	Pass	Pass	Second Tier
461	FD	Unit1-FD4	12X6	Ruskin	10X10	IBD2	Pass	Pass	Second Tier
462	FD	Unit1-FD5	12X8	Ruskin	4X8	IBD2	Pass	Pass	Second Tier
463	FD	Unit1-FD6	10X10	Ruskin	10X10	IBD2	Pass	Pass	Second Tier
464	FD	Unit1-FD7	14X16	Ruskin	12X12	IBD2	Pass	Pass	Second Tier
465	FD	Unit1-FD8	18X16	Ruskin	12X12	IBD2	Pass	Pass	Second Tier
466	FD	Unit1-FD9	8x8	Ruskin	4x4	IBD2	Pass	Pass	Second Tier needed on house side. Electrician needed to remove lights for access
467	FD	Unit1-FD10	17x15	Ruskin	8x8	IBD2	Pass	Pass	
468	FD	Unit1-FD11	17x15	Ruskin	12x12	IBD2	Pass	Pass	
469	FD	Unit1-FD12	17x15	Ruskin	12x12	IBD2	Pass	Pass	
470	FD	Unit1-FD13	17x15	Ruskin	10x10	IBD2	Pass	Pass	
471	FD	Unit1-FD14	17x15	Ruskin	10x10	IBD2	Pass	Pass	
472	FD	Unit1-FD15	13x9	Ruskin	10x10	IBD2	Pass	Pass	
473	FD	Unit1-FD16	8x8	Ruskin	4x4	IBD2	Pass	Pass	
474	FSD	Unit1-FSD1	6X6	Ruskin	6X6	FSD60	Pass	Pass	
475	FSD	Unit1-FSD2	6X6	Ruskin	6X6	FSD60	Pass	Pass	Storage Room
476	SD	Unit2- SD1	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
477	SD	Unit2- SD2	6X6	Ruskin	6X6	SD50	Pass	Pass	Managers Office

Inspector: Larry Coreno  
Inspection Dates: October 3 & 27, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
478	SD	Unit3-SD1	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
479	SD	Unit3-SD2	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
480	SD	Unit4-SD1	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
481	SD	Unit4-SD2	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
482	SD	Unit5-SD1	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room
483	SD	Unit5-SD2	6X6	Ruskin	6X6	SD50	Pass	Pass	Storage Room

Inspector: Larry Coreno  
Inspection Dates: October 3 & 5, 2023  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-01

**Facility Location**

Juvenile Justice Center

**Damper Location**

House #1 Second tier

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit1 -FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU T01-R

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

102x60

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-20

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse

### Inspector Name

Julie Gue

### Damper I.D. #

AHU T01-S

### Damper Type

Horizontal Fire / Smoke Damper

### Damper Size

78x60

### Damper Manufacturer

Ruskin

### Damper Model #

FS1630

### Fusible Link Temperature

212 Degrees

### Access Door Size

24x24

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU T01-SD R2

**Damper Type**

Horizontal Smoke Damper

**Damper Size**

50x50

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD60

**Fusible Link Temperature**

N/A

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU T02-R

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

102x60

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU T02-S

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

78x60

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU001-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

64x17

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Open thru screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU-001-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

40x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU002-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

84x25

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Open thru screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU002-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

48x22

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU004-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

73x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU004-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

48x22

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Open thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU005-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

54x17

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Open thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU005-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

40x22

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU008-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

48x26

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU008-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU009-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

58x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Man door

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU010-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

58x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Man door

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU011-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

67x15

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Man door

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU011-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

44x22

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Man door

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU012-R

**Damper Type**

Horizontal Fire Damper

**Damper Size**

67x15

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Man door

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU012-S

**Damper Type**

Horizontal Fire Damper

**Damper Size**

38x19

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Man door

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-EX1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R1

**Damper Type**

Vertical Fire Damper

**Damper Size**

23x11

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R2

**Damper Type**

Vertical Fire Damper

**Damper Size**

13x11

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-03

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU101-R5

### Damper Type

Horizontal Fire Damper

### Damper Size

8x8

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

6x6

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-R6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

9x9

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S1

**Damper Type**

Vertical Fire Damper

**Damper Size**

17x15

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S2

**Damper Type**

Vertical Fire Damper

**Damper Size**

15x15

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S3

**Damper Type**

Vertical Fire Damper

**Damper Size**

15x13

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S4

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S5

**Damper Type**

Vertical Fire Damper

**Damper Size**

17x15

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S7

**Damper Type**

Vertical Fire Damper

**Damper Size**

13x23

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU101-S8

**Damper Type**

Vertical Fire Damper

**Damper Size**

13x17

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-03

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU102-EX1

### Damper Type

Horizontal Fire Damper

### Damper Size

8x8

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

6x6

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R1

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-R4

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S1

**Damper Type**

Vertical Fire Damper

**Damper Size**

13x23

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S2

**Damper Type**

Vertical Fire Damper

**Damper Size**

13x17

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S3

**Damper Type**

Vertical Fire Damper

**Damper Size**

13x11

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU102-S5

**Damper Type**

Vertical Fire Damper

**Damper Size**

15x17

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-03

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU102-S6

### Damper Type

Vertical Fire Damper

### Damper Size

17x15

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

10x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

AHU-201

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-04

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #2

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU201-R6

### Damper Type

Horizontal Fire Damper

### Damper Size

16x12

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

24x24

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

25.5x16.25

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU201-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-03

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU202-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-04

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #3

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU301-S4

### Damper Type

Horizontal Fire Damper

### Damper Size

18x7

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

6x6

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU301-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-04

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse #3

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

AHU302-R2

### Damper Type

Horizontal Fire Damper

### Damper Size

8x8

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24x24

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-04

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse #3

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

AHU302-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

lbd2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU401-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

26x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

lbd2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-R5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x14

**Damper Manufacturer**

Unknown

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

14x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

lbd2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH4

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU402-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-R4

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-05

### Facility Location

Juvenile Justice Center

### Damper Location

PH5

### Inspector Name

Julie Gue

### Damper I.D. #

AHU501-R5

### Damper Type

Horizontal Fire Damper

### Damper Size

16x12

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

165 Degrees

### Access Door Size

24x24

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-05

### Facility Location

Juvenile Justice Center

### Damper Location

PH5

### Inspector Name

Julie Gue

### Damper I.D. #

AHU501-S3

### Damper Type

Horizontal Fire Damper

### Damper Size

16x14

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU501-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-R1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-R3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-R4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-05

### Facility Location

Juvenile Justice Center

### Damper Location

PH5

### Inspector Name

Julie Gue

### Damper I.D. #

AHU502-R5

### Damper Type

Horizontal Fire Damper

### Damper Size

16x12

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

24x24

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-R6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

24x24

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-S1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-S2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-S3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-S4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-S5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHU502-S6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

AHUT01-FD R2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

50x50

**Damper Manufacturer**

Greenheck

**Damper Model #**

DFD TT210

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Basement

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Basement FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

35x25.5

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Basement elevator area

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Basement FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Bird screen end cap

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Basement elevator area

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Basement FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

30x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 209

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-FD1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

8x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM209

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-FD2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

32x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM209

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-FD3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Building Maintenance

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM121-FD4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

16x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Building Maintenance office

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM121-FD5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30x17

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Maintenance office

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM121-FD6

**Damper Type**

Horizontal Fire Damper

**Damper Size**

23.75x16.75

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Transportation office

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM121-FSD3

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

24x40

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2806

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2806

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2826

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

42x16

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Transportation

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x6

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Transportation

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD11

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x8 w/end cap

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR201

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Transportation

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Central Services

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM121-SD13

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Central Services

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM121-SD14

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM121-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

36x30

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD1

**Damper Type**

Horizontal Fire Damper

**Damper Size**

9.5x7.5

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD2

**Damper Type**

Horizontal Fire Damper

**Damper Size**

36x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD4

**Damper Type**

Horizontal Fire Damper

**Damper Size**

36x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD 2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

24x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 208

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

96x32

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD 2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x30

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x40

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

IT Reception

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x30

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Custodial closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM122-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Custodial closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD5

**Damper Type**

Horizontal Fire Damper

**Damper Size**

50x22

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD311

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Vestibule

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM122-FSD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

IT corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Outside of 2408

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Outside of RM 2408

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SDM201

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 Oval


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2408

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

IT corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open duct


**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

IT office corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2407

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR201

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

IT office

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

RM 2412

**Fusible Link Temperature**

N/A

**Access Door Size**

Removed flex

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Files room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

File room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

IM123-SD10

**Fusible Link Temperature**

N/A

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2110

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD11

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2110

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR201

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2110

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD13

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 2110

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD14

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR201

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Mail room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR201

**Fusible Link Temperature**

N/A

**Access Door Size**

6x9 Oval

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-13

**Facility Location**

Juvenile Justice Center

**Damper Location**

Mail room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM123-SD16

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

SDR201

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Employee restroom west

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM131-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD311

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Mediation

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM131-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Mediation

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM131-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x6

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

Thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Vestibule

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM132-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Electrical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Label mismarked

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Electrical closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM132-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x12

**Damper Manufacturer**

Unknown

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Electrical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM132-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSF60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Electrical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM132-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-12

### Facility Location

Juvenile Justice Center

### Damper Location

Custodial closet

### Inspector Name

Julie Gue

### Damper I.D. #

IM132-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8x8

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

Grille

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

Mislabeled #4  
Report correct  
Is #5


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-11

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM132-FSD6

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

50x24

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

10x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM132-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Office 3106

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD311

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-12

### Facility Location

Juvenile Justice Center

### Damper Location

Training room

### Inspector Name

Julie Gue

### Damper I.D. #

IM132-FSD9

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60X24

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

16x16

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-11

### Facility Location

Juvenile Justice Center

### Damper Location

Room #3206

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM133-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

10" Round

### Damper Manufacturer

Greenheck

### Damper Model #

FSDR511

### Fusible Link Temperature

165 Degrees

### Access Door Size

9x6

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-12

### Facility Location

Juvenile Justice Center

### Damper Location

Corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM133-FSD2

### Damper Type

Vertical Smoke Damper

### Damper Size

26x6

### Damper Manufacturer

Greenheck

### Damper Model #

SMD301

### Fusible Link Temperature

N/A

### Access Door Size

Open duct

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #3206

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM133-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

250 Degrees

**Access Door Size**

9x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**


None



Interior Picture of Damper



Picture of Damper I.D. Label



**Exterior Picture of Damper**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #3206

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM133-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

250 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #3206

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM133-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

250 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #3207

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM133-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

36x16

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

250 Degrees

**Access Door Size**

Open thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x6

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open duct

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 3109

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR201

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-12

**Facility Location**

Juvenile Justice Center

**Damper Location**

East corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM133-SD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-10

### Facility Location

Juvenile Justice Center

### Damper Location

4th floor women's restroom

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM141-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8x8

### Damper Manufacturer

Greenheck

### Damper Model #

FSD211

### Fusible Link Temperature

165 Degrees

### Access Door Size

8x8

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141--SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD501

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x6

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

Open thru the screen

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

4th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x6

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

Open thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #4812

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #4812

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #4812

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9"x6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #4805

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #4805

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6 Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #4805

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15x16

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

4th floor corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9"x6" Oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM141-SD11

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

3x3

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Custodial closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM142-FSD5

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #4503

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM142-FSD6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

20x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM142-FSD8

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-11

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM142-FSD9

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48x24

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM142-FSD10

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

54x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM142-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Office #4610

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM142-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD301

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-11

### Facility Location

Juvenile Justice Center

### Damper Location

#4405

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM143-SD1

### Damper Type

Vertical Smoke Damper

### Damper Size

10x12

### Damper Manufacturer

Greenheck

### Damper Model #

SMD301

### Fusible Link Temperature

N/A

### Access Door Size

8x8

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

Label mismarked.


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-11

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #4405

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM143-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR301

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's restroom

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM151-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM #5146

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM151-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main elevator

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x18

**Damper Manufacturer**

Greenheck

**Damper Model #**

DFD150

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open Thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x18

**Damper Manufacturer**

Greenheck

**Damper Model #**

DFD150

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Thru the screen

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Electrical closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Electrical closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Equipment room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-07

### Facility Location

Juvenile Justice Center

### Damper Location

Equipment room

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM152-FSD4

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

12x20

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

6x6

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-07

### Facility Location

Justice Center Court Towers

### Damper Location

Main elevator

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM152-FSD5

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

16x10

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-07

### Facility Location

Juvenile Justice Center

### Damper Location

Utility closet

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM152-FSD6

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8x8

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

Thru the grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-10

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD8

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x30

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Label mismarked 9  
When it is actually 8


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x30

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-10

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM152-FSD10

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48x24

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

10x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's restroom

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's restroom

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM152-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-07

### Facility Location

Juvenile Justice Center

### Damper Location

Judges' elevator

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM153-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

12x8

### Damper Manufacturer

Greenheck

### Damper Model #

FSD211

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

West elevator 6th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM161-FSD1

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

12x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

6th floor electrical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

6th floor electrical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-07

### Facility Location

Juvenile Justice Center

### Damper Location

6th floor electrical room

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM162-FSD3

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

30x12

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

6x6

### Pass / Fail / Abandoned

Pass


### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

6th floor electrical room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

6th floor corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD5

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

6th floor Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Cut in new 12x12 access door


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

6th floor corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD8

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Thru the screen

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-07

### Facility Location

Juvenile Justice Center

### Damper Location

6th floor women's restroom

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM162-FSD9

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

14x8

### Damper Manufacturer

Greenheck

### Damper Model #

FSD211

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

6th floor men's restroom

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD10

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-07

### Facility Location

Juvenile Justice Center

### Damper Location

6th floor utilities closet

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

IM162-FSD11

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

8x8

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

Thru the grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main elevator 6th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM162-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-07

**Facility Location**

Juvenile Justice Center

**Damper Location**

Judges elevator

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

IM163-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

West judges elevator

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM171-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Vestibule

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Custodial closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD5

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Vestibule

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD8

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-06

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM172-FSD9

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48x24

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

10x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-06

### Facility Location

Juvenile Justice Center

### Damper Location

Main corridor

### Inspector Name

Julie Gue

### Damper I.D. #

IM172-FSD10

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

60x24

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Abandoned


### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Woman's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM172-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Judge's elevators

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM173-FSD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

West waiting room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM181-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

14x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD11

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Vestibule

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

24x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Custodial closet

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD5

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD6

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

48x36

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD7

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

East mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD8

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

West mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD9

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

West mechanical room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD10

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD11

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

54x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Main corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM182-FSD12

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

60x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Judges elevator

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM183-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

12x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Toilet

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM191-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

22x14

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Vestibule

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Unknown

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Women's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD3

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

36x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD4

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

36x10

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Vestibule

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-FSD5

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

16x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Copy room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

West of the copy room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM192-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMDR501

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x6 oval

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Men's room

**Inspector Name**

Julie Gue

**Damper I.D. #**

IM193-FSD1

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

16x24

**Damper Manufacturer**

Greenheck

**Damper Model #**

FSD211

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-06

**Facility Location**

Juvenile Justice Center

**Damper Location**

Corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

IN192-FSD1

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

84x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



*Duct Fabricators, Inc.*  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
40	FD	AHU102-EX	8X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
41	FD	AHU102-R1	12X12	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
42	FD	AHU102-R2	13X19	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
43	FD	AHU102-R3	8X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
44	FD	AHU102-R4	18X12	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
45	FD	AHU102-S1	13X23	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
46	FD	AHU102-S2	13X17	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
47	FD	AHU102-S3	13X11	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
48	FD	AHU102-S4	10X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
49	FD	AHU102-S5	15X17	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
50	FD	AHU102-S6	17X15	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1

Inspector: Julie Gue / Dan Tulcewicz  
Inspection Dates: 3-Oct  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
135	FD	AHU502-R1	12X12	Ruskin	24x24	IBD2	Pass	N/A	
136	FD	AHU502-R2	12X12	Ruskin	24x24	IBD2	Pass	N/A	
137	FD	AHU502-R3	8X8	Ruskin	24x24	IBD2	Pass	N/A	
138	FD	AHU502-R4	8X8	Ruskin	24x24	IBD2	Pass	N/A	
139	FD	AHU502-R5	16X12	Ruskin	24x24	IBD2	Pass	N/A	
140	FD	AHU502-R6	18X14	Ruskin	24x24	IBD2	Pass	N/A	
141	FD	AHU502-S1	12X12	Ruskin	12x12	IBD2	Pass	N/A	
142	FD	AHU502-S2	16X12	Ruskin	12x12	IBD2	Pass	N/A	
143	FD	AHU502-S3	18X14	Ruskin	8x8	IBD2	Pass	N/A	
144	FD	AHU502-S4	18X7	Ruskin	12X12	IBD2	Pass	N/A	
145	FD	AHU502-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	
146	FD	AHU502-S6	10X10	Ruskin	6X6	IBD2	Pass	N/A	

Inspector: Julie Gue

Inspection Dates:

Facility: Juvenile Justice Center

SA = Supply Air

RA = Return Air

EA = Exhaust Air

FD = Fire Damper

SD = Smoke Damper

FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
75	FD	AHU301-R1	12X12	Ruskin	24x24	IBD2	Pass	N/A	None
76	FD	AHU301-R2	12X12	Ruskin	24x24	IBD2	Pass	N/A	None
77	FD	AHU301-R3	8X8	Ruskin	24x24	IBD2	Pass	N/A	None
78	FD	AHU301-R4	8X8	Ruskin	24x24	IBD2	Pass	N/A	None
79	FD	AHU301-R5	24X12	Ruskin	24x24	IBD2	Pass	N/A	None
80	FD	AHU301-R6	16X12	Ruskin	24x24	IBD2	Pass	N/A	None
81	FD	AHU301-S1	26X14	Ruskin	12x12	IBD2	Pass	N/A	None
82	FD	AHU301-S2	16X14	Ruskin	12x12	IBD2	Pass	N/A	None
83	FD	AHU301-S3	16X12	Ruskin	10X10	IBD2	Pass	N/A	None
84	FD	AHU301-S4	18X7	Ruskin	6x6	IBD2	Pass	N/A	None
85	FD	AHU301-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	None
86	FD	AHU301-S6	10X10	Ruskin	8x8	IBD2	Pass	N/A	None

Inspector: Julie Gue

Inspection Dates:

Facility: Juvenile Justice Center

SA = Supply Air

RA = Return Air

EA = Exhaust Air

FD = Fire Damper

SD = Smoke Damper

FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
99	FD	AHU401-R1	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 4
100	FD	AHU401-R2	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 4
101	FD	AHU401-R3	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 4
102	FD	AHU401-R4	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 4
103	FD	AHU401-R5	24X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 4
104	FD	AHU401-R6	16X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 4
105	FD	AHU401-S1	10X10	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 4
106	FD	AHU401-S2	18X7	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 4
107	FD	AHU401-S3	18X7	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 4
108	FD	AHU401-S4	16X12	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 4
109	FD	AHU401-S5	16X14	Ruskin	12X12	IBD2	Pass	N/A	Penthouse 4
110	FD	AHU401-S6	26X14	Ruskin	12X12	IBD2	Pass	N/A	Penthouse 4

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: 5-Oct-22  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
111	FD	AHU402-R1	8X8	Ruskin	24x24	IBD2	Pass	N/A	
112	FD	AHU402-R2	8X8	Ruskin	24x24	IBD2	Pass	N/A	
113	FD	AHU402-R3	12X12	Ruskin	24x24	IBD2	Pass	N/A	
114	FD	AHU402-R4	12X12	Ruskin	24x24	IBD2	Pass	N/A	
115	FD	AHU402-R5	18X14	Ruskin	24x24	IBD2	Pass	N/A	
116	FD	AHU402-R6	16X12	Ruskin	24x24	IBD2	Pass	N/A	
117	FD	AHU402-S1	14X14	Ruskin	12x12	IBD2	Pass	N/A	
118	FD	AHU402-S2	16X12	Ruskin	12x12	IBD2	Pass	N/A	
119	FD	AHU402-S3	18X14	Ruskin	12X12	IBD2	Pass	N/A	
120	FD	AHU402-S4	18X7	Ruskin	6x6	IBD2	Pass	N/A	
121	FD	AHU402-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	
122	FD	AHU402-S6	10X10	Ruskin	8x8	IBD2	Pass	N/A	

Inspector: Julie Gue

Inspection Dates:

Facility: Juvenile Justice Center

SA = Supply Air

RA = Return Air

EA = Exhaust Air

FD = Fire Damper

SD = Smoke Damper

FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
289	FSD	IM181-FSD1	12X8	Greenheck	12x12	FSD211	Pass	N/A	None
290	FSD	IM182-FSD1	14X8	Greenheck	8X8	FSD211	Pass	N/A	None
291	FSD	IM182-FSD2	14X8	Greenheck	8X8	FSD211	Pass	N/A	None
292	FSD	IM182-FSD3	24X12	Greenheck	8X8	FSD211	Pass	N/A	None
293	FSD	IM182-FSD4	8X8	Ruskin	Grille	FSD60	Pass	N/A	None
294	FSD	IM182-FSD5	60X24	Ruskin	16X16	FSD60	Pass	N/A	Main Corridor
295	FSD	IM182-FSD6	48X24	Ruskin	14X14	FSD60	Pass	N/A	Main Corridor
296	FSD	IM182-FSD7	12X20	Ruskin	6X6	FSD60	Pass	N/A	Electrical closet
297	FSD	IM182-FSD8	30X12	Ruskin	6X6	FSD60	Pass	N/A	Electrical closet
298	FSD	IM182-FSD9	12X20	Ruskin	6X6	FSD60	Pass	N/A	Electrical closet
299	FSD	IM182-FSD10	30X12	Ruskin	6X6	FSD60	Pass	N/A	Electrical closet
300	FSD	IM182-FSD11	54X24	Ruskin	14X14	FSD60	Pass	N/A	Main Corridor
301	FSD	IM182-FSD12	60X24	Ruskin	14X14	FSD60	Pass	N/A	Main Corridor
302	FSD	IM183-FSD1	12X8	Greenheck	12X12	FSD211	Pass	N/A	None

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: 6-Oct-22  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
63	FD	AHU202-R1	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
64	FD	AHU202-R2	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
65	FD	AHU202-R3	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
66	FD	AHU202-R4	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
67	FD	AHU202-R5	18X14	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
68	FD	AHU202-R6	16X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
69	FD	AHU202-S1	16X12	Ruskin	12x12	IBD2	Pass	N/A	Penthouse 2
70	FD	AHU202-S2	14X14	Ruskin	12x12	IBD2	Pass	N/A	Penthouse 2
71	FD	AHU202-S3	18X14	Ruskin	8x8	IBD2	Pass	N/A	Penthouse 2
72	FD	AHU202-S4	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 2
73	FD	AHU202-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 2
74	FD	AHU202-S6	10X10	Ruskin	8x8	IBD2	Pass	N/A	Penthouse 2

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: 4-Oct-22  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
RA = Return Air      SD = Smoke Damper  
EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
87	FD	AHU302-R1	8X8	Ruskin	24x24	IBD2	Pass	N/A	
88	FD	AHU302-R2	8X8	Ruskin	24x24	IBD2	Pass	N/A	
89	FD	AHU302-R3	12X12	Ruskin	24x24	IBD2	Pass	N/A	
90	FD	AHU302-R4	12X12	Ruskin	24x24	IBD2	Pass	N/A	
91	FD	AHU302-R5	18X14	Ruskin	24x24	IBD2	Pass	N/A	
92	FD	AHU302-R6	16X12	Ruskin	24x24	IBD2	Pass	N/A	
93	FD	AHU302-S1	14X14	Ruskin	10X10	IBD2	Pass	N/A	
94	FD	AHU302-S2	16X12	Ruskin	12x12	IBD2	Pass	N/A	
95	FD	AHU302-S3	18X14	Ruskin	8x8	IBD2	Pass	N/A	
96	FD	AHU302-S4	18X7	Ruskin	8X8	IBD2	Pass	N/A	
97	FD	AHU302-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	
98	FD	AHU302-S6	10X10	Ruskin	8x8	IBD2	Pass	N/A	

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: October 4,2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
123	FD	AHU501-R	24X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 5
124	FD	AHU501-R	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 5
125	FD	AHU501-R	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 5
126	FD	AHU501-R	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 5
127	FD	AHU501-R	16X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 5
128	FD	AHU501-R	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 5
129	FD	AHU501-S1	24X14	Ruskin	12x12	IBD2	Pass	N/A	Penthouse 5
130	FD	AHU501-S2	16X14	Ruskin	12x12	IBD2	Pass	N/A	Penthouse 5
131	FD	AHU501-S3	16X14	Ruskin	12X12	IBD2	Pass	N/A	Penthouse 5
132	FD	AHU501-S4	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 5
133	FD	AHU501-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 5
134	FD	AHU501-S6	10X10	Ruskin	8x8	IBD2	Pass	N/A	Penthouse 5

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: 5-Oct-22  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
242	FSD	IM151-FSD1	10X8	Greenheck	8X7	FSD211	Pass	N/A	None
243	SD	IM151-SD1	12X10	Greenheck	8X8	SMD201	Pass	N/A	RM #5146
244	FD	IM152-FD1	24X12	Ruskin	12X12	IBD2	Pass	N/A	None
245	FD	IM152-FD2	18X18	Greenheck	Screen	DFD150	Pass	N/A	None
246	FD	IM152-FD3	18X18	Greenheck	Screen	DFD150	Pass	N/A	None
247	FSD	IM152-FSD1	12X20	Ruskin	6X6	FSD60	Pass	N/A	None
248	FSD	IM152-FSD2	30X12	Ruskin	6X6	FSD60	Pass	N/A	None
249	FSD	IM152-FSD3	30X12	Ruskin	6X6	FSD60	Pass	N/A	None
250	FSD	IM152-FSD4	12X20	Ruskin	6X6	FSD60	Pass	N/A	None
251	FSD	IM152-FSD5	16X10	Ruskin	12X12	FSD60	Pass	N/A	None
252	FSD	IM152-FSD6	8X8	Ruskin	Grille	FSD60	Pass	N/A	None
253	FSD	IM152-FSD7	48X24	Ruskin	14X14	FSD60	Pass	N/A	None
254	FSD	IM152-FSD8	60X30	Ruskin	12X12	FSD60	Pass	N/A	None
255	FSD	IM152-FSD9	60X30	Ruskin	Screen	FSD60	Pass	N/A	None
256	FSD	IM152-FSD10	48X24	Ruskin	10X10	FSD60	Pass	N/A	None
257	FSD	IM152-FSD11	14X8	Greenheck	8X8	FSD211	Pass	N/A	None
258	FSD	IM152-FSD12	14X8	Greenheck	8X8	FSD211	Pass	N/A	None
259	FSD	IM153-FSD1	12X8	Greenheck	12X12	FSD211	Pass	N/A	None

Inspector: Julie Gue Dan Tulcewicz  
Inspection Dates: October 7 and 10 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
260	FSD	IM161-FSD1	12X8	Greenheck	12X12	FSD211	Pass	N/A	None
261	FSD	IM162-FSD1	12X20	Ruskin	6X6	FSD60	Pass	N/A	None
262	FSD	IM162-FSD2	30X12	Ruskin	6X6	FSD60	Pass	N/A	None
263	FSD	IM162-FSD3	30X12	Ruskin	6X6	FSD60	Pass	N/A	None
264	FSD	IM162-FSD4	12X20	Ruskin	6X6	FSD60	Pass	N/A	None
265	FSD	IM162-FSD5	48X24	Ruskin	14X14	FSD60	Pass	N/A	None
266	FSD	IM162-FSD6	60X24	Ruskin	16X16	FSD60	Pass	N/A	None
267	FSD	IM162-FSD7	48X24	Ruskin	12X12	FSD60	Pass	N/A	Installed access/previous access blocked
268	FSD	IM162-FSD8	60x24	Ruskin	Screen	FSD60	Pass	N/A	None
269	FSD	IM162-FSD9	14X8	Greenheck	12X12	FSD211	Pass	N/A	None
270	FSD	IM162-FSD10	14X8	Greenheck	12X12	FSD211	Pass	N/A	None
271	FSD	IM162-FSD11	8X8	Ruskin	Grille	FSD60	Pass	N/A	None
272	FSD	IM162-FSD12	16X10	Ruskin	12X12	FSD60	Pass	N/A	None
273	FSD	IM163-FSD1	12X8	Greenheck	12X12	FSD211	Pass	N/A	None

Inspector: Julie Gue Dan Tulcewicz  
Inspection Dates: October 7 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
274	FSD	IM171-FSD1	12X8	Greenheck	12X12	FSD211	Pass	N/A	None
275	FD	IM172-FD1	24X12	Ruskin	10X10	IBD2	Pass	N/A	None
276	FSD	IM172-FSD1	12X20	Ruskin	6X6	FSD60	Pass	N/A	None
277	FSD	IM172-FSD2	30X12	Ruskin	6X6	FSD60	Pass	N/A	None
278	FSD	IM172-FSD3	30X12	Ruskin	6X6	FSD60	Pass	N/A	None
279	FSD	IM172-FSD4	12X20	Ruskin	6X6	FSD60	Pass	N/A	None
280	FSD	IM172-FSD5	8X8	Ruskin	Grille	FSD60	Pass	N/A	None
281	FSD	IM172-FSD6	16X10	Ruskin	12X12	FSD60	Pass	N/A	None
282	FSD	IM172-FSD7	60X24	Ruskin	14X14	FSD60	Pass	N/A	None
283	FSD	IM172-FSD8	48X24	Ruskin	14X14	FSD60	Pass	N/A	None
284	FSD	IM172-FSD9	48X24	Ruskin	10X10	FSD60	Pass	N/A	None
285	FSD	IM172-FSD10	60X24	Ruskin	12X12	FSD60	Pass	N/A	None
286	FSD	IM172-FSD11	14X8	Greenheck	12X12	FSD211	Pass	N/A	None
287	FSD	IM172-FSD12	14X8	Greenheck	8X8	FSD211	Pass	N/A	None
288	FSD	IM173-FSD1	12X8	Greenheck	12X12	FSD211	Pass	N/A	None

Inspector: Julie Gue Dan Tulcewicz  
Inspection Dates: October 6 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper





Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F: 216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
167	SD	IM121-SD12	18X12	Greenheck	12X12	SMD201	Pass	N/A	None
168	SD	IM121-SD13	12X8	Ruskin	6X6	SD50	Pass	N/A	None
169	SD	IM121-SD14	12X10	Ruskin	6X6	SD50	Pass	N/A	None
170	SD	IM121-SD15	36X30	Greenheck	Screen	SMD201	Pass	N/A	None
171	FSD	IM122-FSD1	60X30	Ruskin	16X16	FSD60	Pass	N/A	None
172	FSD	IM122-FSD2	60X40	Ruskin	16X16	FSD60	Pass	N/A	None
173	FSD	IM122-FSD3	60X30	Ruskin	16X16	FSD60	Pass	N/A	None
174	FSD	IM122-FSD4	8X8	Ruskin	Grille	FSD60	Pass	N/A	None
175	FSD	IM122-FSD5	50X22	Greenheck	14X14	FSD311	Pass	N/A	None
176	FSD	IM122-FSD6	20X16	Ruskin	8X8	FSD60	Pass	N/A	None

Inspector: Julie Gue / Dan Tulcewicz  
Inspection Dates: October 11, 12 and 13 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
408	FD	Unut1-FD1	16X14	Ruskin	10x10	IBD2	Pass	N/A	Second Tier
409	FD	Unit1-FD2	16X10	Ruskin	10x10	IBD2	Pass	N/A	Second Tier
410	FD	Unit1-FD3	10X8	Ruskin	8X8	IBD2	Pass	N/A	Second Tier
411	FD	Unit1-FD4	12X6	Ruskin	10X10	IBD2	Pass	N/A	Second Tier
412	FD	Unit1-FD5	12X8	Ruskin	4X8	IBD2	Pass	N/A	Second Tier
413	FD	Unit1-FD6	10X10	Ruskin	10X10	IBD2	Pass	N/A	Second Tier
414	FD	Unit1-FD7	14X16	Ruskin	12X12	IBD2	Pass	N/A	Second Tier
415	FD	Unit1-FD8	18X16	Ruskin	12X12	IBD2	Pass	N/A	Second Tier
416	FD	Unit1-FD9							Second Tier needed on house side. Electrician needed to remove lights for access
417	FD	Unit1-FD10							
418	FD	Unit1-FD11							
419	FD	Unit1-FD12							
420	FD	Unit1-FD13							
421	FD	Unit1-FD14							
422	FD	Unit1-FD15							
423	FD	Unit1-FD16							
424	FSD	Unit1-FSD1	6X6	Ruskin	6X6	FSD60	Pass	N/A	
425	FSD	Unit1-FSD2	6X6	Ruskin	6X6	FSD60	Pass	N/A	Storage Room
426	SD	Unit2- SD1	6X6	Ruskin	6X6	SD50	Pass	N/A	Storage Room
427	SD	Unit2- SD2	6X6	Ruskin	6X6	SD50	Pass	N/A	Managers Office

Inspector: Julie Gue / Dan Tulcewicz  
Inspection Dates: October 28 and November 1 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
428	SD	Unit3-SD1	6X6	Ruskin	6X6	SD50	Pass	N/A	Storage Room
429	SD	Unit3-SD2	6X6	Ruskin	6X6	SD50	Pass	N/A	Storage Room
430	SD	Unit4-SD1	6X6	Ruskin	6X6	SD50	Pass	N/A	Storage Room
431	SD	Unit4-SD2	6X6	Ruskin	6X6	SD50	Pass	N/A	Storage Room
432	SD	Unit5-SD1	6X6	Ruskin	6X6	SD50	Pass	N/A	Storage Room
433	SD	Unit5-SD2	6X6	Ruskin	6X6	SD50	Pass	N/A	Storage Room

Inspector: Julie Gue / Dan Tulcewicz  
Inspection Dates: October 28 and November 1 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
176	SD	IM123-SD1	14X12	Greenheck	10x10	SMD201	Pass	N/A	None
177	SD	IM123-SD2	14X12	Greenheck	Open	SMD201	Pass	N/A	None
178	SD	IM123-SD3	16" Round	Greenheck	9x6 Oval	SMDR201	Pass	N/A	None
179	SD	IM123-SD4	10x12	Greenheck	8x8	SMD201	Pass	N/A	None
180	SD	IM123-SD5	14x12	Greenheck	Open	SMD201	Pass	N/A	None
181	SD	IM123-SD6	16x10	Greenheck	6x6	SMD201	Pass	N/A	None
182	SD	IM123-SD7	8" Round	Greenheck	6x6	SMDR201	Pass	N/A	None
183	SD	IM123-SD8	8" Round	Greenheck	Flex	SMDR201	Pass	N/A	None
184	SD	IM123-SD9	12x12	Greenheck	Open	SMD201	Pass	N/A	None
185	SD	IM123-SD10	16x12	Greenheck	Open	SMD201	Pass	N/A	None
186	SD	IM123-SD11	12x12	Greenheck	Open	SMD201	Pass	N/A	None
187	SD	IM123-SD12	10" Round	Greenheck	6x6	SMDR201	Pass	N/A	None
188	SD	IM123-SD13	14X12	Greenheck	12x12	SMD201	Pass	N/A	None
189	SD	IM123-SD14	8" Round	Greenheck	6x6	SMDR201	Pass	N/A	None
190	SD	IM123-SD15	14" Round	Greenheck	6x9 Oval	SMDR201	Pass	N/A	None
191	SD	IM123-SD16	10x10	Greenheck	6x6	SMD201	Pass	N/A	None

Inspector: Julie Gue Dan Tulcewicz  
Inspection Dates: October 11 12 and 13 of 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
147	FD	IM121-FD1	8X8	Ruskin	8X8	IBD2	Pass	N/A	None
148	FD	IM121-FD2	32X14	Ruskin	12X12	IBD2	Pass	N/A	None
149	FD	IM121-FD3	30X18	Ruskin	12X12	IBD2	Pass	N/A	None
150	FD	IM121-FD4	16X18	Ruskin	12X12	IBD2	Pass	N/A	None
151	FD	IM121-FD5	30X17	Ruskin	12X12	IBD2	Pass	N/A	None
152	FD	IM121-FD6	24X17	Ruskin	12X12	IBD2	Pass	N/A	None
153	FSD	IM121-FSD1	60X30	Ruskin	16x16	FSD60	Pass	N/A	None
154	FSD	IM121-FSD2	48X24	Ruskin	16x16	FSD60	Pass	N/A	RM #2826
155	FSD	IM121-FSD3	40X24	Ruskin	16X16	FSD60	Pass	N/A	Transportation
156	SD	IM121-SD1	24X12	Greenheck	10X10	SMD201	Pass	N/A	RM #2806
157	SD	IM121-SD2	14X12	Greenheck	10X10	SMD201	Pass	N/A	RM #2806
158	SD	IM121-SD3	14X12	Greenheck	12X12	SMD201	Pass	N/A	RM #2826
159	SD	IM121-SD4	10X8	Greenheck	6X6	SMD201	Pass	N/A	RM #2826
160	SD	IM121-SD5	24X12	Greenheck	12X12	SMD201	Pass	N/A	None
161	SD	IM121-SD6	26X12	Greenheck	12X12	SMD201	Pass	N/A	None
162	SD	IM121-SD7	18X12	Greenheck	8X8	SMD201	Pass	N/A	None
163	SD	IM121-SD8	42X16	Greenheck	OPEN	SMD201	Pass	N/A	None
164	SD	IM121-SD9	26X10	Greenheck	12X12	SMD201	Pass	N/A	None
165	SD	IM121-SD10	26X6	Greenheck	OPEN	SMD201	Pass	N/A	None
166	SD	IM121-SD11	8X8	Greenheck	9X6 Oval	SMD201	Pass	N/A	None

Inspector: Julie Gue Dan Tulcewicz  
Inspection Dates: October 11,12, and 13 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
191	FSD	IM131-FSD1	12X10	Greenheck	8x8	FSD311	Pass	N/A	Employee restroom
192	SD	IM131-SD1	10X8	Greenheck	8x8	SMD301	Pass	N/A	Mediation
193	SD	IM131-SD2	26X6	Greenheck	Open	SMD301	Pass	N/A	Mediation
194	FD	IM132-FD1	24X12	Ruskin	10x10	IBD2	Pass	N/A	Vestibule
195	FSD	IM132-FSD1	12X20	Ruskin	6x6	FSD60	Pass	N/A	None
196	FSD	IM132-FSD2	30X12	Ruskin	6x6	FSD60	Pass	N/A	None
197	FSD	IM132-FSD3	30X12	Ruskin	6x6	FSD60	Pass	N/A	None
198	FSD	IM132-FSD4	12X20	Ruskin	6x6	FSD60	Pass	N/A	None
199	FSD	IM132-FSD5	8X8	Ruskin	Grille	FSD60	Pass	N/A	None
200	FSD	IM132-FSD6	50X24	Ruskin	10x10	FSD60	Pass	N/A	None
201	FSD	IM132-FSD7	60X24	Ruskin	Screen	FSD60	Pass	N/A	None
202	FSD	IM132-FSD8	60X30	Ruskin	14x14	FSD60	Pass	N/A	None
203	FSD	IM132-FSD9	60X24	Ruskin	16x16	FSD60	Pass	N/A	None
204	FSD	IM133-FSD1	10" Round	Greenheck	9x6 Oval	FSDR511	Pass	N/A	None
205	FSD	IM133-FSD2	12X10	Greenheck	6x6	FSD311	Pass	N/A	None
206	SD	IM133-SD1	8" Round	Greenheck	9x6 Oval	SMD201	Pass	N/A	None
207	SD	IM133-SD2	10x10	Greenheck	8x8	SMD201	Pass	N/A	None
208	SD	IM133-SD3	8x10	Greenheck	8x8	SMD201	Pass	N/A	None
209	SD	IM133-SD4	36x16	Greenheck	Open	SMD301	Pass	N/A	RM #3207

Inspector: Julie Gue Dan Tulcewicz  
Inspection Dates: October 11 and 12 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
214	FSD	IM141-FSD1	8X8	Greenheck	8X8	FSD211	Pass	N/A	Women's Restroom
215	SD	IM141-SD1	14" Round	Greenheck	9X6 Oval	SMD501	Pass	N/A	Main corridor
216	SD	IM141-SD2	26X6	Greenheck	Open	SMD301	Pass	N/A	Main corridor
217	SD	IM141-SD3	26X6	Greenheck	Open	SMD301	Pass	N/A	Women's Restroom
218	SD	IM141-SD4	8" Round	Greenheck	9X6 Oval	SMDR301	Pass	N/A	RM #4812
219	SD	IM141-SD5	8" Round	Greenheck	9X6 Oval	SMDR301	Pass	N/A	RM #4812
220	SD	IM141-SD6	6" Round	Greenheck	9X6 Oval	SMDR301	Pass	N/A	RM #4812
221	SD	IM141-SD7	10" Round	Greenheck	9X6 Oval	SMDR301	Pass	N/A	RM# 4805
222	SD	IM141-SD8	10" Round	Greenheck	9X6 Oval	SMDR301	Pass	N/A	RM# 4805
223	SD	IM141-SD9	15X16	Greenheck	12X12	SMD301	Pass	N/A	RM# 4805
224	SD	IM141-SD10	14" Round	Greenheck	9X6 Oval	SMDR301	Pass	N/A	Main corridor
225	SD	IM141-SD11	14" Round	Greenheck	3X3	SMDR301	Pass	N/A	Main corridor
226	FSD	IM142-FSD1	12X20	Ruskin	6X6	FSD60	Pass	N/A	Electrical room
227	FSD	IM142-FSD2	30X12	Ruskin	6X6	FSD60	Pass	N/A	Electrical room
228	FSD	IM142-FSD3	30X12	Ruskin	6X6	FSD60	Pass	N/A	Electrical room
229	FSD	IM142-FSD4	12X20	Ruskin	6X6	FSD60	Pass	N/A	Electrical room
230	FSD	IM142-FSD5	8X8	Ruskin	Grille	FSD60	Pass	N/A	Custodial closet
231	FSD	IM142-FSD6	20X10	Greenheck	6X6	FSD211	Pass	N/A	RM#4503
232	FSD	IM142-FSD7	14X10	Greenheck	6X6	FSD211	Pass	N/A	RM#4308
233	FSD	IM142-FSD8	60X20	Ruskin	60X24	FSD60	Pass	N/A	Main corridor

Inspector: Julie Gue Dan Tulcewicz  
Inspection Dates: October 10 and 11 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
235	FSD	IM142-FSD9	48X24	Ruskin	12X12	FSD60	Pass	N/A	Main corridor
236	FSD	IM142-FSD10	54X24	Ruskin	12X12	FSD60	Pass	N/A	Main corridor
237	FSD	IM142-FSD11	60X24	Ruskin	12X12	FSD60	Pass	N/A	Main corridor
238	SD	IM142-SD1	10X10	Greenheck	8X8	SMD301	Pass	N/A	RM #4610
239	FSD	IM143-FSD1	12X10	Greenheck	8x8	FSD211	Pass	N/A	RM #4107
240	FSD	IM143-SD1	10X12	Greenheck	8X8	SMD301	Pass	N/A	RM #4406
241	FSD	IM143-SD2	10" Round	Greenheck	9X6 Oval	SMDR301	Pass	N/A	RM #4405

Inspector: Julie Gue Dan Tulcewicz  
Inspection Dates: October 10 and 11 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
303	FD	M201-FD1	24"X 8"	Ruskin	5 X4"	IBD2	Pass	N/A	Room #945
304	FD	M201-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	Room #945
305	FSD	M201-FSD1	10"X 8"	Ruskin	8"X 8"	FSD60	Pass	N/A	Room #907
306	FSD	M201-FSD2	10"X 8"	Ruskin	4"X 4"	FSD60	Pass	N/A	Dry Storage
307	FSD	M201-FSD3	10"X 10"	Ruskin	8"X 8"	FSD60	Pass	N/A	Room #943
308	SD	M201-SD1	10" Round	Ruskin	5"X 5"	SDR25	Pass	N/A	Room #907
309	SD	M201-SD2	30"X 17"	Ruskin	12"X 12"	SD50	Pass	N/A	Room #907
310	SD	M201-SD3	24"X 17"	Ruskin	12"X 12"	SD50	Pass	N/A	Room #907
311	SD	M201-SD4	6" Round	Ruskin	5"X 5"	SDR25	Pass	N/A	Room #907
312	SD	M201-SD5	16"X 8"	Ruskin	12"X 12"	SD50	Pass	N/A	Room #907
313	SD	M201-SD6	10"X 6"	Ruskin	8"X 8"	SD50	Pass	N/A	Room #907
314	SD	M201-SD7	8" Round	Ruskin	4"X 4"	SD50	Pass	N/A	Room #911
315	SD	M201-SD8	12"X 6"	Ruskin	8"X 8"	SD50	Pass	N/A	Room #913
316	SD	M201-SD9	10"X 6"	Ruskin	10"X 6"	SD50	Pass	N/A	Room #913
317	SD	M201-SD10	14"X 14"	Ruskin	4"X 4"	SD50	Pass	N/A	Bulk Storage
318	SD	M201-SD11	18"X 12"	Ruskin	12"X 12"	SD50	Pass	N/A	Room #943
319	SD	M201-SD12	12"X 6"	Ruskin	6"X 6"	SD50	Pass	N/A	Central Mechanical
320	SD	M201-SD13	10" Round	Ruskin	3"X 2"	SDR25	Pass	N/A	Room #929

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: October 14,19 and 20 of 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
320	FSD	M202-FSD1	48"X 22"	Ruskin	12"X 12"	FSD60	Pass	N/A	Dinning Hall
321	FSD	M202-FSD2	50"X 12"	Ruskin	12"X 12"	FSD60	Pass	N/A	Dinning Hall
322	FSD	M202-FSD3	10"X 7"	Ruskin	8"X 8"	FSD60	Pass	N/A	Intake
323	SD	M202-SD1	8"X 8"	Ruskin	6"X 6"	SD50	Pass	N/A	Dinning Hall
324	SD	M202-SD2	14"X 8"	Ruskin	4"X 4"	SD50	Pass	N/A	Kitchen
325	SD	M202-SD3	10" Round	Ruskin	4"X 4"	SDR25	Pass	N/A	Kinchen Storage
326	SD	M202-SD4	6" Round	Ruskin	4"X 4"	SDR25	Pass	N/A	Kinchen Storage
327	SD	M202-SD5	8" Round	Ruskin	4"X 4"	SDR25	Pass	N/A	Kitchen
328	SD	M202-SD6	12"X 6"	Ruskin	6"X 6"	SD50	Pass	N/A	Intake
329	SD	M202-SD7	8" Round	Ruskin	4"X 4"	SDR25	Pass	N/A	Intake
330	SD	M202-SD8	12"X 8"	Ruskin	8"X 8"	SD50	Pass	N/A	Intake
331	SD	M202-SD9	10"X 10"	Ruskin	8"X 8"	SD50	Pass	N/A	Intake
332	SD	M202-SD10	16"X 12"	Ruskin	8"X 8"	SD50	Pass	N/A	Intake

Inspector: Julie Gue/Dan Tulcewicz  
Inspection Dates: 19-Oct-22  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
333	FD	M203-FD1	10"X 10"	Ruskin	8"X 8"	IBD2	Pass	N/A	Medical Waiting Room
334	FD	M203-FD2	10"X 8"	Ruskin	4"X 4"	IBD2	Pass	N/A	Medical Waiting Room
335	FD	M203-FD3	12"X 6"	Ruskin	10"X 10"	IBD2	Pass	N/A	Pharmacy
336	SD	M203-SD1	6" Round	Ruskin	4"X 4"	SD50	Pass	N/A	Medical Corridor
337	SD	M203-SD2	6" Round	Ruskin	4"X 4"	SD50	Pass	N/A	Medical Corridor
338	SD	M203-SD3	10"X 8"	Ruskin	4"X 4"	SD50	Pass	N/A	Medical Waiting Room
339	SD	M203-SD4	8"X 6"	Ruskin	4"X 4"	SD50	Pass	N/A	Medical
340	SD	M203-SD5	12"X 10"	Ruskin	8"X 8"	SD50	Pass	N/A	Medical Office
341	SD	M203-SD6	8"X 8"	Ruskin	4"X 4"	SD50	Pass	N/A	Medical
342	SD	M203-SD7	30"X 18"	Ruskin	12"X 12'	SD50	Pass	N/A	Pharmacy
343	SD	M203-SD8	10"X 8"	Ruskin	8"X 8"	SD50	Pass	N/A	Pharmacy
344	SD	M203-SD9	24"X 16"	Ruskin	12"X 12"	SD50	Pass	N/A	Medical
345	SD	M203-SD10	24"X 16"	Ruskin	12"X 12"	SD50	Pass	N/A	Medical
346	SD	M203-SD11	6" Round	Ruskin	4"X 4"	SDR25	Pass	N/A	Medical Files
347	SD	M203-SD12	8" Round	Ruskin	4"X 4"	SDR25	Pass	N/A	Medical
348	SD	M203-SD13	8"X 8"	Greenheck	4"X 4"	SMD201	Pass	N/A	Gym Storage
349	SD	M203-SD14	8"X 8"	Greenheck	4"X 4"	SMD201	Pass	N/A	Gym Storage
350	SD	M201-SD15	8"X 8"	Greenheck	4"X 4"	SMD201	Pass	N/A	Gym Storage
351	SD	M203-SD16	8"X 8"	Greenheck	Screen	SMD201	Pass	N/A	Gym Storage
352	SD	M203-SD17	10" Round	Ruskin	9"x 6" Oval	SDR25	Pass	N/A	Domestic Clinic
353	SD	M203-SD18	8"X 12"	Greenheck	10"X 10"	SM201	Pass	N/A	Clerk's Office

Inspector:

Julie Gue/ Dan Tulcewicz

SA = Supply Air

FD = Fire Damper

Inspection Dates:

October 14, 17 and 20 of 2022

RA = Return Air

SD = Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
354	FSD	M204.1-FSD1	24"X 12"	Ruskin	Remove Duct	FSD60	Pass	N/A	File Room
355	SD	M204.1.SD1	8' Round	Ruskin	4"X 4"	SD50	Pass	N/A	Time Clock
356	SD	M204.1-SD2	10" Round	Ruskin	4"X 4"	SD50	Pass	N/A	File Room
357	FD	M204.2-FD1	10"X 10"	Ruskin	8"X 8"	IBD2	Pass	N/A	Visitation
358	FD	M204.2-FD2	28"X 14"	Ruskin	10"X 10"	IBD2	Pass	N/A	Recycling 437
359	FD	M204.2-FD3	8" Round	Ruskin	6" X 9" OVAL	IBD2	Pass	N/A	Room 317
360	FD	M204.2-FD4	28"X 10"	Ruskin	12"X 12"	IBD2	Pass	N/A	Room 317
361	FD	M204.2-FD5	20"X 10"	Ruskin	12"X 12"	IBD2	Pass	N/A	Room 317
362	SD	M204.2-SD1	6" Round	Ruskin	4 X 4	SDR 25	Pass	N/A	Profesional visit
363	SD	M204.2-SD2	8" Round	Ruskin	3"X 3"	SDR25	Pass	N/A	None
364	SD	M204.2-SD3	24"X 6"	Ruskin	Transfer	SD50	Pass	N/A	None
365	SD	M204.2-SD4	6 X 6	Ruskin	6 X 6	SD50	Pass	N/A	None
366	SD	M204.2-SD5	30"X 18"	Ruskin	12"X 12"	SD50	Pass	N/A	Room 322
367	SD	M204.2-SD6	38"X 18"	Ruskin	12"X 12"	SD50	Pass	N/A	Room 322

Inspector: Julie Gue / Dan Tulcewicz  
Inspection Dates: October 14 17 and 28 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
368	FD	M205-FD1	14 X 12	Ruskin					
369	FD	M205-FD2	8" Round	Ruskin	Remove pipe	IBD2	Pass	N/A	Admin
370	SD	M205-SD1	8 X 10	Ruskin	2 X 2	SD50	Pass	N/A	Training storage
371	SD	M205-SD2	6" Round	Ruskin	10" Round	SDR525	Pass	N/A	Training storage
372	SD	M205-SD3	24X6	Ruskin	3X3	SD50	Pass	N/A	Training storage
373	SD	M205-SD4		Ruskin					
374	SD	M205-SD6	12 X 8	Ruskin					Need access to classroom
375	SD	M205-SD7	24 X 6	Ruskin					Need access to classroom
376	SD	M206-FSD1	24X6	Ruskin	Open	FSD60	Pass	Pass	Education storage/mislabeled as SD previously
377	SD	M206-SD1	8" Round	Ruskin	4X4	SDR25	Pass	N/A	Education secretary
378	SD	M206-SD2	6" Round	Ruskin	4X4	SDR25	Pass	N/A	Education secretary
379	SD	M207SD1	8" Round	Ruskin	4X4	SD50	Pass	N/A	Storage room (M207-FSD1)
380	SD	M207-FSD1	48X24	Ruskin	12X12	FSD60	Pass	N/A	Storage room (M207-SD2)
381	SD	M207-FSD2	26X22	Ruskin	Screen	FSD60	Pass	N/A	Storage room (M207-SD3)

Inspector: Julie Gue / Dan Tulcewicz  
Inspection Dates: October 14,17 and 31 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
111	FD	AHU402-R1	8X8	Ruskin	24x24	IBD2	Pass	N/A	
112	FD	AHU402-R2	8X8	Ruskin	24x24	IBD2	Pass	N/A	
113	FD	AHU402-R3	12X12	Ruskin	24x24	IBD2	Pass	N/A	
114	FD	AHU402-R4	12X12	Ruskin	24x24	IBD2	Pass	N/A	
115	FD	AHU402-R5	18X14	Ruskin	24x24	IBD2	Pass	N/A	
116	FD	AHU402-R6	16X12	Ruskin	24x24	IBD2	Pass	N/A	
117	FD	AHU402-S1	14X14	Ruskin	12x12	IBD2	Pass	N/A	
118	FD	AHU402-S2	16X12	Ruskin	12x12	IBD2	Pass	N/A	
119	FD	AHU402-S3	18X14	Ruskin	12X12	IBD2	Pass	N/A	
120	FD	AHU402-S4	18X7	Ruskin	6x6	IBD2	Pass	N/A	
121	FD	AHU402-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	
122	FD	AHU402-S6	10X10	Ruskin	8x8	IBD2	Pass	N/A	

Inspector: Julie Gue

Inspection Dates:

Facility: Juvenile Justice Center

SA = Supply Air

RA = Return Air

EA = Exhaust Air

FD = Fire Damper

SD = Smoke Damper

FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
382	FD	STR5-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
383	FD	STR5-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
384	FD	STR5-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
385	FD	STR5-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
386	FD	STR5-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
387	FD	STR6-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
388	FD	STR6-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
389	FD	STR6-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
390	FD	STR6-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
391	FD	STR6-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
392	FD	STR7-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
393	FD	STR7-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
394	FD	STR7-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
395	FD	STR7-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
396	FD	STR7-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: 31-Oct-22  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
397	FD	PH-FD1	36"X 16"	Ruskin	Grille	IBD2	Pass	N/A	None
398	FD	PH-FD2	24"X 20"	Ruskin	Grille	IBD2	Pass	N/A	None
399	FD	PH-FD3	42"X 42"	Ruskin	16"X 16"	IBD2	Pass	N/A	None
400	FSD	PH-FSD1	30"X 30"	Ruskin	14"X 14"	FSD60	Pass	N/A	None
401	FSD	PH-FSD2	30"X 30"	Ruskin	14"X 14"	FSD60	Pass	N/A	None
402	FSD	PH-FSD3	38"X 24"	Ruskin	14"X 14"	FSD60	Pass	N/A	None
403	FSD	PH-FSD4	60"X 18"	Ruskin	14"X 14"	FSD60	Pass	N/A	None
404	FSD	PH-FSD5	38"X 24"	Ruskin	14"X 14"	FSD60	Pass	N/A	None
405	FD	Basement-FD1	35x25.5	Ruskin	12X12	IBD2	Pass	N/A	None
406	FD	Basement-FD2	10" Round	Ruskin	Screen	IBD2	Pass	N/A	None
407	FD	Basement-FD3	32X20	Ruskin	10x10	IBD2	Pass	N/A	None

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: October 20 and 28 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1	FSD	AHU T01-R	120x60	Ruskin	14x14	FSD60	Pass	N/A	10th Floor Penthouse
2	FD	AHU T01-R2	50x50	Greenheck	16x16	DFDTT210	Pass	N/A	10th Floor Penthouse
3	SD	AHU T01-R2	50X50	Ruskin	16X16	SD60	Pass	N/A	10th Floor Penthouse
4	FSD	AHU T01-S	78X60	Ruskin	20X20	FSD60	Pass	N/A	10th Floor Penthouse
5	FSD	AHU T02-R	120X60	Ruskin	14X14	FSD60	Pass	N/A	10th Floor Penthouse
6	FSD	AHU T02-S	78X60	Ruskin	14X14	FSD60	Pass	N/A	10th Floor Penthouse
7	FD	AHU-001-R	64X17	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 2
8	FD	AHU-001-S	40X20	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 2
9	FD	AHU-002-R	84X25	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 2
10	FD	AHU-002-S	48X22	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 2
11	FD	AHU-004-R	73X18	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 2
12	FD	AHU-004-S	48X22	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 2
13	FD	AHU-005-R	54X17	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 2
14	FD	AHU-005-S	40X22	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 2

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: October 3, 4 and 20, 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
15	FD	AHU-008-R	48X26	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 5
16	FD	AHU-008-S	24X24	Ruskin	12X12	IBD2	Pass	N/A	Penthouse 5
17	FD	AHU-009-R	58X18	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 5
18	FD	AHU-009-S	26X26	Ruskin	BELOW	IBD2	Pass	N/A	Penthouse 5
19	FD	AHU-010-R	58X16	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 5
20	FD	AHU-010-S	25X25	Ruskin	BELOW	IBD2	Pass	N/A	Penthouse 5
21	FD	AHU-011-R	67X18	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 5
22	FD	AHU-011-S	44X22	Ruskin	Man DR	IBD2	Pass	N/A	Penthouse 5
23	FD	AHU-012-R	67X15	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5
24	FD	AHU-012-S	67X15	Ruskin	Man DR	IBD2	Pass	Pass	Penthouse 5

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: October 5th and 31st 2022  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.  
 883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper  
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
382	FD	STR5-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
383	FD	STR5-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
384	FD	STR5-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
385	FD	STR5-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
386	FD	STR5-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
387	FD	STR6-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
388	FD	STR6-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
389	FD	STR6-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
390	FD	STR6-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
391	FD	STR6-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
392	FD	STR7-FD1	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
393	FD	STR7-FD2	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
394	FD	STR7-FD3	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
395	FD	STR7-FD4	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None
396	FD	STR7-FD5	24"X 12"	Ruskin	Grille	IBD2	Pass	N/A	None

Inspector: Julie Gue/ Dan Tulcewicz  
Inspection Dates: 31-Oct-22  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
25	FD	AHU101-EX	10X8	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
26	FD	AHU101-R1	23X11	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
27	FD	AHU101-R2	13X11	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
28	FD	AHU101-R3	12X8	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
29	FD	AHU101-R4	16X16	Ruskin	16X16	IBD2	Pass	N/A	Penthouse 1
30	FD	AHU101-R5	8X8	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
31	FD	AHU101-R6	9X9	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
32	FD	AHU101-S1	13X23	Ruskin	8X8	IBD2	Pass	N/A	Penthouse 1
33	FD	AHU101-S2	15X15	Ruskin	8x8	IBD2	Pass	N/A	Penthouse 1
34	FD	AHU101-S3	15X13	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
35	FD	AHU101-S4	16X14	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
36	FD	AHU101-S5	17X15	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
37	FD	AHU101-S6	18X16	Ruskin	10X10	IBD2	Pass	N/A	Penthouse 1
38	FD	AHU101-S7	13X23	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1
39	FD	AHU101-S8	13X17	Ruskin	6X6	IBD2	Pass	N/A	Penthouse 1

Inspector: Julie Gue / Dan Tulcewicz  
Inspection Dates: 3-Oct-22  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
 P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



Fire / Smoke / Fire & Smoke Damper  
 Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>A/D</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
51	FD	AHU201-R1	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
52	FD	AHU201-R2	12X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
53	FD	AHU201-R3	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
54	FD	AHU201-R4	8X8	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
55	FD	AHU201-R5	24X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
56	FD	AHU201-R6	16X12	Ruskin	24x24	IBD2	Pass	N/A	Penthouse 2
57	FD	AHU201-S1	25.5X16.5	Ruskin	24X24	IBD2	Pass	N/A	Penthouse 2
58	FD	AHU201-S2	16X14	Ruskin	12x12	IBD2	Pass	N/A	Penthouse 2
59	FD	AHU201-S3	16X12	Ruskin	12X12	IBD2	Pass	N/A	Penthouse 2
60	FD	AHU201-S4	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 2
61	FD	AHU201-S5	18X7	Ruskin	6x6	IBD2	Pass	N/A	Penthouse 2
62	FD	AHU201-S6	10X10	Ruskin	8x8	IBD2	Pass	N/A	Penthouse 2

Inspector: Julie Gue / Tulcewicz  
Inspection Dates: 4-Oct-22  
Facility: Juvenile Justice Center

SA = Supply Air      FD = Fire Damper  
 RA = Return Air      SD = Smoke Damper  
 EA = Exhaust Air      FSD = Fire Smoke Damper

## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM #S945

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M201-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24"x8"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

5"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-14

### Facility Location

Juvenile Justice Center

### Damper Location

RM #S945

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

M201-FD2

### Damper Type

Vertical Fire Damper

### Damper Size

24"x12"

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

Take off grille

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM907

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-FSD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Dry storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #943

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M201-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Has a switch

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM907

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

5x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM907

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

30x17

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM907

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x17

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 907

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

5x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 907

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM907

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM911

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM913

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD8

**Damper Type**

Horizontal Fire Damper

**Damper Size**

12x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM913

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Bulk storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M201-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #943

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M201-SD11

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Has a switch


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-14

### Facility Location

Juvenile Justice Center

### Damper Location

Central Mechanical

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

M201-SD12

### Damper Type

Vertical Smoke Damper

### Damper Size

12x6

### Damper Manufacturer

Ruskin

### Damper Model #

SD50

### Fusible Link Temperature

N/A

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Has a switch


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Groundskeeper #S929

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M201-SD13

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

3"x2"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-19

### Facility Location

Juvenile Justice Center

### Damper Location

Dinning hall

### Inspector Name

Julie Gue

### Damper I.D. #

M202-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48x22

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Label is mismarked.  
Damper is M202-FSD1

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-19

### Facility Location

Juvenile Justice Center

### Damper Location

Dinning hall

### Inspector Name

Julie Gue

### Damper I.D. #

M202-FSD2

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

50x12

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Intake

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10x7

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Dinning hall

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Kitchen storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Kitchen

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Kitchen storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR 25

**Fusible Link Temperature**

N/A

**Access Door Size**

6"X 6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Label mismarked as SD2  
Damper is SD3


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Kitchen storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Kitchen

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Intake

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Intake

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Intake

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Intake

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-19

**Facility Location**

Juvenile Justice Center

**Damper Location**

Intake

**Inspector Name**

Julie Gue

**Damper I.D. #**

M202-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical waiting

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical waiting

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Pharmacy

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-28

### Facility Location

Juvenile Justice Center

### Damper Location

Small Gym

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

M203-FD4

### Damper Type

Vertical Fire Damper

### Damper Size

8x8

### Damper Manufacturer

Ruskin

### Damper Model #

IBD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

8x8

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Label mis marked  
Correct label is  
M203-FD4


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Room #209 Small Gym

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M203-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

30x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

4x13

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Label incorrect

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical corridor

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical waiting

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD60

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD6

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Pharmacy

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD7

**Damper Type**

Vertical Smoke Damper

**Damper Size**

30x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Pharmacy

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD8

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD9

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD10

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical file

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD11

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Medical

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD12

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Gym storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD13

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-17

### Facility Location

Juvenile Justice Center

### Damper Location

Gym storage

### Inspector Name

Julie Gue

### Damper I.D. #

M203-SD14

### Damper Type

Vertical Smoke Damper

### Damper Size

8x8

### Damper Manufacturer

Greenheck

### Damper Model #

SMD201

### Fusible Link Temperature

N/A

### Access Door Size

4x4

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Gym storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD15

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Gym storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M203-SD16

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Greenheck

**Damper Model #**

SMD201

**Fusible Link Temperature**

N/A

**Access Door Size**

Screen access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Diagnostic clinic

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M203-SD17

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10"Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR

**Fusible Link Temperature**

N/A

**Access Door Size**

9x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

No switch PL3A-CRT27


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

ID103 Clerks office

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M203-SD18

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x12

**Damper Manufacturer**

Greenheck

**Damper Model #**

SM201

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

M7-120 No Switch


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-14

### Facility Location

Juvenile Justice Center

### Damper Location

File Room

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

M204.1-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

24x12

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

165 Degrees

### Access Door Size

Removed square to round fitting

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-14

### Facility Location

Juvenile Justice Center

### Damper Location

Time clock

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

M204.1-SD1

### Damper Type

Vertical Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Ruskin

### Damper Model #

SD50

### Fusible Link Temperature

N/A

### Access Door Size

4x4

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

File room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M204.1-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Has a switch


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Recycling 437

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-10-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
RM 317

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
M204.2-FD3

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
8" round

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
IBD2

**Fusible Link Temperature**  
212 Degrees

**Access Door Size**  
6x9 oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 317

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 317

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Professional visit

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

2x3

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Visitation

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

Pass through

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

RM 322

**Inspector Name**

Julie Gue

**Damper I.D. #**

M204.2-SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

30x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

HD

**Inspector Name**

Julie Gue

**Damper I.D. #**

204.2-SD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

38x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Administration

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M205-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Administration

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M205-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

10"x10"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Removed pipe

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training Storage

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M205-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

2"x2"

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

Has a switch


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training storage closet

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M205-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDRS25

**Fusible Link Temperature**

N/A

**Access Door Size**

Remove insulated flex

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-14

**Facility Location**

Juvenile Justice Center

**Damper Location**

Training Storage

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

M205-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

3"x3"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Has a switch


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Education storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

M206-FSD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

N/A

**Access Door Size**

Pass through

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Education secretary

**Inspector Name**

Julie Gue

**Damper I.D. #**

M206-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Education secretary

**Inspector Name**

Julie Gue

**Damper I.D. #**

M206-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SDR25

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-17

### Facility Location

Juvenile Justice Center

### Damper Location

Storage room

### Inspector Name

Julie Gue

### Damper I.D. #

M207-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

48x24

### Damper Manufacturer

Ruskin

### Damper Model #

FSD50

### Fusible Link Temperature

212 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

M207-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

26xx22

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Screen access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-17

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage room

**Inspector Name**

Julie Gue

**Damper I.D. #**

M207-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

Damper is smoke only


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

MAU001

**Damper Type**

Horizontal Fire Damper

**Damper Size**

30x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

MAU002

**Damper Type**

Horizontal Fire Damper

**Damper Size**

34x26

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-05

**Facility Location**

Juvenile Justice Center

**Damper Location**

PH5

**Inspector Name**

Julie Gue

**Damper I.D. #**

MAU004

**Damper Type**

Horizontal Fire Damper

**Damper Size**

36x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

36x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x20

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Grille access

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FD3

**Damper Type**

Horizontal Fire Damper

**Damper Size**

42x42

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

16x16

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-20

### Facility Location

Juvenile Justice Center

### Damper Location

Penthouse

### Inspector Name

Julie Gue

### Damper I.D. #

PH-FSD1

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

30x30

### Damper Manufacturer

Ruskin

### Damper Model #

FSD60

### Fusible Link Temperature

212 Degrees

### Access Door Size

14x14

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FSD2

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

30x30

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FSD3

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

38x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FSD4

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

60x18

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

14x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-20

**Facility Location**

Juvenile Justice Center

**Damper Location**

Penthouse

**Inspector Name**

Julie Gue

**Damper I.D. #**

PH-FSD5

**Damper Type**

Horizontal Fire / Smoke Damper

**Damper Size**

38x24

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

1x14

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 5- 9th Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 5 FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 5 -3rd Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 5 -FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 5 -5th Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 5 FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 5-7th Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 5 FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 5-2nd Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 5 FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell #6 9th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 6 FD-1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell #6

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 6 FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell #6 5th floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 6 FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell #6 3rdFloor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 6 FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell #6 1st Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 6 FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 7- 7thFloor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 7 FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 7 9th Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 7 FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 7-2nd Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 7-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

Stairwell 7FD1

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 7-3rd Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 7-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-31

**Facility Location**

Juvenile Justice Center

**Damper Location**

Stairwell 7-5th Floor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

Stairwell 7-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

24x12

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

Thru the grille

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-01

**Facility Location**

Juvenile Justice Center

**Damper Location**

Second tier

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 1- FD7

**Damper Type**

Vertical Fire Damper

**Damper Size**

14x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

Ibd

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-01

**Facility Location**

Juvenile Justice Center

**Damper Location**

Second tier

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 1-FD1

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x14

**Damper Manufacturer**

Ruskin

**Damper Model #**

lbd2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-01

**Facility Location**

Juvenile Justice Center

**Damper Location**

Second tier

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 1-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

16x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

lbd2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-01

**Facility Location**

Juvenile Justice Center

**Damper Location**

House#1 Second tier

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 1-FD6

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x10

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-01

**Facility Location**

Juvenile Justice Center

**Damper Location**

Second tier

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 1-FD8

**Damper Type**

Vertical Fire Damper

**Damper Size**

18x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 1-SD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

6x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

FSD60

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Manager office

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 1-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

Sd5

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2022-10-28

**Facility Location**  
Juvenile Justice Center

**Damper Location**  
Storage

**Inspector Name**  
Julie Gue

**Damper I.D. #**  
Unit 2-SD1

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6x6

**Damper Manufacturer**  
Ruskin

**Damper Model #**  
SD50


**Fusible Link Temperature**  
N/A

**Access Door Size**  
6x6

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE DAMPER**

Inspection Date: 10-28-22  
Inspected By: Gue  
Next Inspect. By: 10-28-24

Reference I.D.#  
unit 2  
SD1

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 3-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 3-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 4-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Manager office

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 4-SD2

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-10-28

**Facility Location**

Juvenile Justice Center

**Damper Location**

Storage

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit 5-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

SD50

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2022-10-31

### Facility Location

Juvenile Justice Center

### Damper Location

Intake room#723

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

010-S

### Damper Type

Horizontal Fire Damper

### Damper Size

30x26

### Damper Manufacturer

Ruskin

### Damper Model #

IBD2

### Fusible Link Temperature

212 Degrees

### Access Door Size

18x18

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Exterior Picture of Damper



### Interior Picture of Damper



### Picture of Damper I.D. Label





## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-01

**Facility Location**

Juvenile Justice Center

**Damper Location**

House #1 second tier

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit1-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x6

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**



## VISUAL CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2022-11-01

**Facility Location**

Juvenile Justice Center

**Damper Location**

House#1 Second tier

**Inspector Name**

Julie Gue

**Damper I.D. #**

Unit1-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD2

**Fusible Link Temperature**

212 Degrees

**Access Door Size**

4x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Exterior Picture of Damper**



**Interior Picture of Damper**



**Picture of Damper I.D. Label**

