

Duct Fabricators, Inc.
 883 Addison Rd. Cleveland, Ohio
 P: 216-391-2400 F:216-391-2492



Fire / Smoke / Fire & Smoke Damper
Composite Inspection Report

	<u>FD/SD/FSD</u>	<u>I.D.#</u>	<u>Size</u>	<u>Manufacturer</u>	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								

Inspector: Dan Tulcewicz
Inspection Dates: 9/15/2022
Facility: Men's Shelter

SA = Supply Air FD = Fire Damper
 RA = Return Air SD = Smoke Damper
 EA = Exhaust Air FSD = Fire Smoke Damper

Cuyahoga County Men's Homeless Shelter

2100 Lakeside Ave
Cleveland Ohio 44115

Visual Inspections
Fire/Smoke Damper Inspection Report

Duct Fabricators, Inc.

FIRE SAFETY DIVISION



Report Date: September 15, 2022

Project: Cuyahoga County
Men's Shelter

Inspector(s):
Julianne Gue, Certified Technician
Dan Tucewicz, Certified Technician

Inspection and Test Date(s):

September 15, 2022

Duct Fabricators, Inc. "Fire Safety Division" inspected the Two (2) fire dampers noted on the following sheets for proper installation. The dampers were then tested and photographed in the "open" and "closed" positions to confirm that they were functioning as designed.

All of the dampers passed the inspection and functional testing.

NOTES: NFPA 80 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers located in patient care facilities are to be inspected and tested every six years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2022-09-15

Facility Location

Men's Homeless Shelter

Damper Location

Mechanical room

Inspector Name

Julie Gue

Damper I.D. #

MS-FD1

Damper Type

Vertical Fire Damper

Damper Size

48x18

Damper Manufacturer

Ruskin

Damper Model #

IBD2

Fusible Link Temperature

165 Degrees

Access Door Size

16x16

Pass / Fail / Abandoned

Pass

Comments / Corrections

None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection
2022-09-15

Facility Location
Men's Homeless Shelter

Damper Location
Mechanical

Inspector Name
Julie Gue

Damper I.D. #
MS-FD2

Damper Type
Vertical Fire Damper

Damper Size
32x18

Damper Manufacturer
Ruskin

Damper Model #
IBD2

Fusible Link Temperature
165 Degrees

Access Door Size
16x16

Pass / Fail / Abandoned
Pass

Comments / Corrections
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

FIRE DAMPER

Inspection Date: 9/15/22	Reference I.D.#: MS-FD2
Inspected By: GUE	
Next Inspect. By: 9/15/24	

Duct Fabricators, Inc.
883 Addison Rd. Cleveland, Ohio
P: 216-391-2400 F: 216-391-2492

FIRE SAFETY DIVISION MEMBER **NFPA**