

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

Bridge to jail 2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

5"x3"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-15

**Facility Location**

Jail 1

**Damper Location**

N.W corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4fL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None



**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <u>5-14-24</u>	Reference I.D.#: <u>4FL-FD2</u>
Inspected By: <u>TULCEWICZ</u>	<u>North</u>
Next Inspect. By: <u>5-14-26</u>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
 	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-15

**Facility Location**

Jail 1

**Damper Location**

Bridge to jail 2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

20"x10"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: 5-15-24	Reference I.D.#
Inspected By: Tulcewicz	4FL-FD2
Next Inspect. By: 5-15-26	South

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-15

**Facility Location**

Jail 1

**Damper Location**

Bridge to jail 2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

15"x10"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

N.W corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

14"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

N.W corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

14"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-15

**Facility Location**

Jail 1

**Damper Location**

Bridge to jail 2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

N.W corridor restroom

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE**  
**DAMPER**

Inspection Date: 5-14-24	Reference I.D.#: 4FL-FD5 North
Inspected By: TULCEWICZ	
Next Inspect. By: 5-14-26	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-15

**Facility Location**  
Jail 1

**Damper Location**  
Bridge to jail 2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
4FL-FD5 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
17" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: 5-15-24	Reference I.D.#:
Inspected By: TULCEWICZ	4FL-FD5
Next Inspect. By: 5-15-26	South
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
MEMBER <b>NFPA</b>	

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-05-14

### Facility Location

Jail 1

### Damper Location

Storage room

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

4FL-FD6 North

### Damper Type

Vertical Fire Damper

### Damper Size

42"x12"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

Open

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: 5-14-24	Reference I.D.#: 4FL-FD6
Inspected By: Tulcewicz	North
Next Inspect. By: 5-14-26	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

Storage room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-15

**Facility Location**

Jail 1

**Damper Location**

F Pod

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

38"x10"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

13"x9"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

Storage room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Replaced link

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE**  
**DAMPER**

Inspection Date: <i>5-14-24</i>	Reference I.D.#:
Inspected By: <i>Tulcewicz</i>	<i>4FL-FD8</i>
Next Inspect. By: <i>5-14-26</i>	<i>North</i>

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-15

**Facility Location**  
Jail 1

**Damper Location**  
F Pod

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
4FL-FD8 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
12" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
9" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
Replaced link.

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: 5-15-24	Reference I.D.#: 4FL-FD 8
Inspected By: TULCEWICZ	South
Next Inspect. By: 5-15-26	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-15

**Facility Location**

Jail 1

**Damper Location**

F Pod

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-FD9 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

34"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-15

**Facility Location**  
Jail 1

**Damper Location**  
Pod 4F

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
4FL-FD11 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: 5-15-24	Reference I.D.#: 4FL-FD11 South
Inspected By: TULCEWICZ	
Next Inspect. By: 5-15-26	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
<small>MEMBER <b>NFPA</b></small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

N.W corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

42"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-14

**Facility Location**  
Jail 1

**Damper Location**  
Bridge to jail 2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
4FL-SD1 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
5"x3"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-14

**Facility Location**  
Jail 1

**Damper Location**  
N.W corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
4FL-SD2 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
9" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>SMOKE DAMPER</b>	
Inspection Date: 5-14-24	Reference I.D. # 4FL-SD2 North
Inspected By: TULCEWICZ	
Next Inspect. By: 5-14-26	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

N.W corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Fail

**Comments / Corrections**

Abandoned


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-15

**Facility Location**  
Jail 1

**Damper Location**  
Bridge to jail 2

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
4FL-SD3 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
15"x10"

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8"x6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-14

**Facility Location**  
Jail 1

**Damper Location**  
N.W corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
4FL-SD4 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14"x6"

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8"x8"

**Pass / Fail / Abandoned**  
Abandoned

**Comments / Corrections**  
Abandoned


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-15

**Facility Location**

Jail 1

**Damper Location**

Bridge to jail 2

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

N.W corridor bathroom

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD5 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

Storage room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

42"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-14

**Facility Location**  
Jail 1

**Damper Location**  
Storage room

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
4FL-SD7 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10"x6"

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8"x6"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-14

**Facility Location**

Jail 1

**Damper Location**

Storage room

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-15

**Facility Location**  
Jail 1

**Damper Location**  
F Pod

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
4FL-SD9 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
34"x12"

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown


**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-16

**Facility Location**

Jail 1

**Damper Location**

Pod 4F

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD-12 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-16

**Facility Location**

Jail 1

**Damper Location**

S.W corridor by release desk

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD14 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

44"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-16

**Facility Location**

Jail 1

**Damper Location**

By release desk

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD15 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

4"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-16

**Facility Location**

Jail 1

**Damper Location**

Vending machine area.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

4FL-SD16 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

44"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-07

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
6FL-FD1 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
Flex

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: <u>5-7-24</u>	Reference I.D.#: <u>6FL-FD1</u>
Inspected By: <u>Coreno</u>	<u>North</u>
Next Inspect. By: <u>5-7-25</u>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

20x16

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

17x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-09

**Facility Location**

Jail 1

**Damper Location**

S.E Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

6FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-FD5 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-09

**Facility Location**

Jail 1

**Damper Location**

S.E Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

6FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE**  
**DAMPER**

Inspection Date: 5-9-24	Reference I.D.#: 6FL-FD5
Inspected By: Tulcewicz	South
Next Inspect. By: 5-9-26	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

32x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-09

**Facility Location**

Jail 1

**Damper Location**

S.E Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

6FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

10x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-09

**Facility Location**

Jail 1

**Damper Location**

S.E corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

6FL-FD7 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

26"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14"x7"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None



**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <u>5-9-24</u>	Reference I.D.#: <u>6FL-FD7</u>
Inspected By: <u>TULCEWICZ</u>	<u>South</u>
Next Inspect. By: <u>5-9-26</u>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>  	



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-09

**Facility Location**

Jail 1

**Damper Location**

S.E Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

6FL-FD11 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-09

**Facility Location**  
Jail 1

**Damper Location**  
S.E Corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
6FL-FD12 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
14"Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12"Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: 5-9-24	Reference I.D.#: 6FL-FD12 South
Inspected By: TULCEWICZ	
Next Inspect. By: 5-9-26	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P. 216-391-2400 F:216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-FD17 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

54x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-FD21 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x12


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**FIRE**  
**DAMPER**

Inspection Date: <i>5-8-24</i>	Reference I.D. #: <i>6FL-FD21</i>
Inspected By: <i>Coreno</i>	<i>5</i>
Next Inspect. By: <i>5-8-26</i>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

Room #616

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-FSD1North

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

20x16

**Damper Manufacturer**

Ruskin

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-09

**Facility Location**  
Jail 1

**Damper Location**  
Room #6A1

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
6FL-FSD2 South

**Damper Type**  
Vertical Fire / Smoke Damper

**Damper Size**  
14"x8"

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
Open


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-09

**Facility Location**  
Jail 1

**Damper Location**  
S.E corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
6FL-SD1 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
16" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
3"x3"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>SMOKE DAMPER</b>	
Inspection Date: <u>5-9-24</u>	Reference I.D.#: <u>6FL-SD1</u>
Inspected By: <u>TULCEWICZ</u>	<u>South</u>
Next Inspect. By: <u>5-9-26</u>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<small><b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

18x18

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-09

**Facility Location**

Jail 1

**Damper Location**

Room #6A1

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

6FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <i>5-9-24</i>	Reference I.D. #: <i>6FL-SD3</i>
Inspected By: <i>Tulcewicz</i>	<i>South</i>
Next Inspect. By: <i>5-9-26</i>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER</small> <b>NFPA</b>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-07

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
6FL-SD4 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
9" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
3x3

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD5 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

3x2

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-09

**Facility Location**  
Jail 1

**Damper Location**  
Room #6A1

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
6FL-SD8 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8"x6" Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-07

**Picture of Damper in Open Position**

**Facility Location**  
Jail 1



**Damper Location**  
North Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
6FL-SD9 North

**Picture of Damper in Closed Position**

**Damper Type**  
Vertical Smoke Damper



**Damper Size**  
14" Round

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown


**Fusible Link Temperature**  
N/A

**Picture of Damper I.D. Label**

**Access Door Size**  
3x2

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-05-09

### Facility Location

Jail 1

### Damper Location

Room #6A1

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

6FL-SD9 South

### Damper Type

Vertical Smoke Damper

### Damper Size

18"x8"

### Damper Manufacturer

Prefco Products

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

Open

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-07

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD10 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-09

**Facility Location**  
Jail 1

**Damper Location**  
S.E corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
6FL-SD11 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b>SMOKE DAMPER</b>	
Inspection Date: <u>5-9-24</u>	Reference I.D.#: <u>6FL-SD11</u>
Inspected By: <u>TULCEWICZ</u>	<u>South</u>
Next Inspect. By: <u>5-9-26</u>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-03

**Facility Location**

Jail 1

**Damper Location**

Corridor Outside E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD12 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

3x2

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-09

**Facility Location**  
Jail 1

**Damper Location**  
S.E corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
6FL-SD12 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>SMOKE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <i>5-9-24</i>	Reference I.D. #: <i>6FL-SD12</i>
Inspected By: <i>Tulcewicz</i>	<i>South</i>
Next Inspect. By: <i>5-9-26</i>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-03

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD13 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-08

**Facility Location**  
Jail 1

**Damper Location**  
South Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
6FL-SD13 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
28x10

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
14x10

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-03

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD14 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD14 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

3x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD15 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x10

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD16 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD16 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

20x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

5x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD17 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD17 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

54x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-03

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD18 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD18 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

38x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-03

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD19 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD19 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

3x3

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-03

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD20 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-08

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD20 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x6

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-06-05

**Facility Location**  
Jail 1

**Damper Location**  
Pod C

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
6FL-SD22 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
20x8

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6x12

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-06-05

**Facility Location**  
Jail 1

**Damper Location**  
Pod C

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
6FL-SD23 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
34x10

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-05

**Facility Location**

Jail 1

**Damper Location**

Pod C

**Inspector Name**

Larry Coreno

**Damper I.D. #**

6FL-SD24 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

20x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-08

**Facility Location**  
Jail 1

**Damper Location**  
South Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
6FL-SD25 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Remove 6" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

6"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Remove the flex.

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-01

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-01

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-01

**Facility Location**  
Jail 1

**Damper Location**  
South Corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
7FL-FD3 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
55"x12"

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
20"x20"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-01

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

13"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: <b>5-1-24</b>	Reference I.D.#: <b>7FL-FD-4</b>
Inspected By: <b>TULCEWICZ</b>	<b>South</b>
Next Inspect. By: <b>5-1-26</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER NFPA</small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-02

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
7FL-FD5 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
17" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" Round.

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>5-2-24</b>	Reference I.D.#: <b>7FL-FD5</b>
Inspected By: <b>Tulcewicz</b>	<b>North</b>
Next Inspect. By: <b>5-2-26</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-01

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-01

**Facility Location**

Jail 1

**Damper Location**

South corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-FD6 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-FD8 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-FD8 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9x9

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-06-06

### Facility Location

Jail 1

### Damper Location

A Pod Corridor

### Inspector Name

Larry Coreno

### Damper I.D. #

7FL-FD11 South

### Damper Type

Vertical Fire Damper

### Damper Size

16" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None



### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b>FIRE DAMPER</b>	
Inspection Date: <b>6-6-24</b>	Reference I.D.#: <b>7FL-FD11</b>
Inspected By: <b>Coreno</b>	<b>South</b>
Next Inspect. By: <b>6-6-26</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
 	

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-06-06

### Facility Location

Jail 1

### Damper Location

A Pod Corridor

### Inspector Name

Larry Coreno

### Damper I.D. #

7FL-FD13 South

### Damper Type

Vertical Fire Damper

### Damper Size

48x11

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12x12

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

A Pod Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-FD14 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

28x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

A Pod Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-FD15 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-05

**Facility Location**

Jail 1

**Damper Location**

H POD

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-FD20 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-05

**Facility Location**

Jail 1

**Damper Location**

H Pod

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-FD21 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

H Pod

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-FD23 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

30x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

H Pod

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-FD24 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-05-02

### Facility Location

Jail 1

### Damper Location

Room #712

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

7FL-FD27 North

### Damper Type

Vertical Fire Damper

### Damper Size

13" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

9" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-01

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD1 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-02

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
7FL-SD2 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12"x8"

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open.

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-01

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

55"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD4 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

54"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-02

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
7FL-SD5 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
16" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
9x6 Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b><u>SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>5-2-24</b>	Reference I.D. #: <b>7FL-SD5</b>
Inspected By: <b>Tulcewicz</b>	<b>North</b>
Next Inspect By: <b>5-2-26</b>	
Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
MEMBER <b>NFPA</b>	



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-01

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

5"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-05-01

### Facility Location

Jail 1

### Damper Location

South Corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

7FL-SD6 South

### Damper Type

Vertical Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6"x4"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label

<b><u>SMOKE</u></b>	
<b><u>DAMPER</u></b>	
Inspection Date: <b>5-1-24</b>	Reference I.D. #: <b>7FL-SD6</b>
Inspected By: <b>TULCEWICZ</b>	<b>South</b>
Next Inspect By: <b>5-1-26</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b>	
<small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER NFPA</small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-01

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD7 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD9 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-01

**Facility Location**  
Jail 1

**Damper Location**  
South Corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
7FL-SD9 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Remove the elbow.

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**SMOKE**  
**DAMPER**

Inspection Date: <b>5-1-24</b>	Reference I.D.#: <b>7FL-SD9</b>
Inspected By: <b>TULCEWICZ</b>	<b>South</b>
Next Inspect. By: <b>5-1-26</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD10 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

28x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-02

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
7FL-SD11 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
16" Round

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4x4

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>SMOKE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>5-2-24</b>	Reference I.D. #: <b>7FL-SD11</b>
Inspected By: <b>Coreno</b>	<b>NORTH</b>
Next Inspect. By: <b>5-2-24</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

A Pod Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD11 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-02

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
7FL-SD12 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
6" Round

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4x4

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

A Pod Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD12 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-02

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
7FL-SD13 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
24x10

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

A Pod Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD13 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48x11

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD14 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

4x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-06-06

**Facility Location**  
Jail 1

**Damper Location**  
A Pod Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
7FL-SD15 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
4x8 Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-02

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
7FL-SD16 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
15" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8x4 Oval

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>SMOKE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: 5-2-24	Reference I.D. #: 7FL-SD16
Inspected By: Coreno	North
Next Inspect. By: 5-2-24	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
<small>MEMBER <b>NFPA</b></small>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

A Pod Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD16 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

5x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule G

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD17 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

20x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

A Pod Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD17 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

28x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-31

**Facility Location**  
Jail 1

**Damper Location**  
Vestibule G

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
7FL-SD18 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
22x12

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
10x10

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD18 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-05

**Facility Location**

Jail 1

**Damper Location**

H Pod

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD19 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

3x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD19 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-05

**Facility Location**

Jail 1

**Damper Location**

H Pod

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD20 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-03

**Facility Location**

Jail 1

**Damper Location**

Vestibule A/B

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD20 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

43x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-06-05

**Facility Location**  
Jail 1

**Damper Location**  
H Pod

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
7FL-SD21 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
48x12

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
12x12

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-03

**Facility Location**

Jail 1

**Damper Location**

Psych Office 7Ab2

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD21 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

5x3

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

H Pod

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD22 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-03

**Facility Location**

Jail 1

**Damper Location**

Vestibule A/B

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD22 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

H Pod

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD23 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

30x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

18x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-06-06

**Facility Location**

Jail 1

**Damper Location**

H Pod

**Inspector Name**

Larry Coreno

**Damper I.D. #**

7FL-SD24 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

Room #712

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7FL-SD27 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9' Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-02

**Facility Location**

Jail 1

**Damper Location**

RM #712

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

7L-FD28 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

50x15

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Need larger access door in ceiling


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

5" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Remove flex

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-29

**Facility Location**

Jail 1

**Damper Location**

South corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-FD3 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

16"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

10"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-FD4 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

26"x11"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7"x5"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

18"x12"

**Damper Manufacturer**

Ruskin

**Damper Model #**

IBD20

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-04-29

### Facility Location

Jail 1

### Damper Location

Room #8J4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

8FL-FD8 South

### Damper Type

Vertical Fire Damper

### Damper Size

10"x16"

### Damper Manufacturer

Prefco Products

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

10"x10"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-30

**Facility Location**

Jail 1

**Damper Location**

Room #8J4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-FD9 South

**Damper Type**

Horizontal Fire Damper

**Damper Size**

18"x14"

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

14"x14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-30

**Facility Location**

Jail 1

**Damper Location**

Room #8J4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-FD10 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

20"x14"

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-29

**Facility Location**  
Jail 1

**Damper Location**  
RM #811

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
8FL-FD21 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
13" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
9" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-29

**Facility Location**

Jail 1

**Damper Location**

South corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-SD1 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

16" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

54"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-25

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
8FL-SD3 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
9" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-29

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-SD4 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

16"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-SD6 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14"x14"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x5"

**Pass / Fail / Abandoned**

Fail

**Comments / Corrections**

Bad Actuator


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-29

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-SD6 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

18"x 18"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x10"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD8 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-04-30

### Facility Location

Jail 1

### Damper Location

South Corridor

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

8FL-SD8 South

### Damper Type

Vertical Smoke Damper

### Damper Size

8" Round

### Damper Manufacturer

Ruskin

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD9 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule A/B

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD9 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

17x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-30

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD10 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

54x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule A/B

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD10 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-30

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD11 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-30

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD12 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-30

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD13 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule G/H

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD14 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

30x11

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD14 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

17x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-05-31

### Facility Location

Jail 1

### Damper Location

8FL-SD15

### Inspector Name

Larry Coreno

### Damper I.D. #

8FL-SD15 North

### Damper Type

Vertical Smoke Damper

### Damper Size

22x8

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

17x10

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-31

**Facility Location**  
Jail 1

**Damper Location**  
Vestibule C/D

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
8FL-SD15 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
26x12

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

North corridor.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-SD16 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

6"x6"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x4"


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

Need to replace 8" Round smoke damper


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD16 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

North corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-SD17 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD17 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD18 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-31

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

8FL-SD19 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-29

**Facility Location**

Jail 1

**Damper Location**

RM #811

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

8FL-SD21 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Fail

**Comments / Corrections**

Bad Actuator


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

Arrainment

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL FD14 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

22"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians

MEMBER



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

Corridor Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-FD1 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

6" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Flex


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-FD1 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9' Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

Corridor Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9" Round


**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

South

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-FD2 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

22"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

13"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

Corridor Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-FD3 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18x12

**Pass / Fail / Abandoned**

Fail

**Comments / Corrections**

No access door in ceiling


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

Arraignment

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12 Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

Arrestment

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-FD5 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

5" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

Main Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

17" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>FIRE DAMPER</b>	
Inspection Date: <b>4-22-24</b>	Reference I.D. #: <b>9FL-FD6 North</b>
Inspected By: <b>TULCEWICZ</b>	
Next Inspect. By: <b>4-22-26</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER NFPA</small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-25

**Facility Location**  
Jail 1

**Damper Location**  
Arrestment

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
9FL-FD6 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
12" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
10" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

Main Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-FD9 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

12x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-04-23

### Facility Location

Jail 1

### Damper Location

Visitation

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

9FL-FD10 North

### Damper Type

Vertical Fire Damper

### Damper Size

30"x8"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

7"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

Visitation

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-FD11 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

48"x12"

**Damper Manufacturer**

Advanced Air

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

17"x14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

arraignment

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-FD13 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

44"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

18"x9"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-23

**Facility Location**  
Jail 1

**Damper Location**  
Visitation

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
9FL-FD14 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
8"x6"

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
8"x5"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>4-23-24</b>	Reference I.D.#: <b>9FL-FD14</b>
Inspected By: <b>TULCEWICZ</b>	<b>North</b>
Next Inspect. By: <b>4-23-26</b>	
Duct Fabricators, Inc. <b>FIRE SAFETY DIVISION</b> <b>NFPA</b> 883 Addison Rd. Cleveland, Ohio NEMI Certified HVAC Fire Life Safety Technicians	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-25

**Facility Location**  
Jail 1

**Damper Location**  
South gym

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
9FL-FD18 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
24"x20"

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
Remove grille.

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-23

**Facility Location**  
Jail 1

**Damper Location**  
Visitation

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
9FL-FD19 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
13" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
10" Round


**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-23

**Facility Location**  
Jail 1

**Damper Location**  
Visitation

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
9FL-FD20 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
5" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
8"x5"

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>4-23-24</b>	Reference I.D. #: <b>9FL-FD20</b>
Inspected By: <b>TULCEWICZ</b>	<b>North</b>
Next Inspect. By: <b>4-23-26</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> NEMI Certified HVAC Fire Life Safety Technicians	
<small>MEMBER <b>NFPA</b></small>	

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-23

**Facility Location**  
Jail 1

**Damper Location**  
Visitation

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
9FL-FD21 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
15" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
10" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

<b><u>FIRE</u></b> <b><u>DAMPER</u></b>	
Inspection Date: <b>4-23-24</b>	Reference I.D.#: <b>9FL-FD21</b>
Inspected By: <b>Tulcewicz</b>	<b>North</b>
Next Inspect. By: <b>4-23-26</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER <b>NFPA</b></small>	



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-04-23

### Facility Location

Jail 1

### Damper Location

RM #9F4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

9FL-FSD1 North

### Damper Type

Vertical Fire / Smoke Damper

### Damper Size

12"x8"

### Damper Manufacturer

Prefco Products

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

Open

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

RM #9F4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

10"x8"

**Damper Manufacturer**

Nailor

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7"x7"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

South Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-SD1 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

9" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-SD2 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

**SMOKE**  
**DAMPER**

Inspection Date: 4/22/24	Reference I.D. #: 9FL-SD2 N
Inspected By: Coreno	
Next Inspect. By: 4/22/26	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio

**FIRE SAFETY DIVISION** MEMBER



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

Corridor Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

18x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-SD4 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-25

**Facility Location**  
Jail 1

**Damper Location**  
Arraignment

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
9FL-SD4 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
15" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
12" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

Arraignment

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-SD5 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

5" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Picture of Damper in Open Position**



**Facility Location**

Jail 1

**Damper Location**

North Corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-SD6 North

**Picture of Damper in Closed Position**



**Damper Type**

Vertical Smoke Damper

**Damper Size**

17"Round

**Damper Manufacturer**

Air Balance


**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Picture of Damper I.D. Label**



**Access Door Size**

12"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-25

**Facility Location**

Jail 1

**Damper Location**

Arraignment

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-SD6 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass


**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-23

**Facility Location**  
Jail 1

**Damper Location**  
South Corridor

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
9FL-SD8 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12"x8"

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-22

**Picture of Damper in Open Position**

**Facility Location**  
Jail 1

**Damper Location**  
North Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
9FL-SD9 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
8" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6x6

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

South Corridor.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-SD9 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

12"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

Visitation

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-SD10 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

28"x11"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

Visitation

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-SD11 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

17"x14"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-25

**Facility Location**  
Jail 1

**Damper Location**  
RM #9A3

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
9FL-SD12 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
12"x8"

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
Paint on blade.  
Damper still works properly.


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-30

**Facility Location**

Jail 1

**Damper Location**

Vestibule F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-SD15 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x5

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-30

**Facility Location**  
Jail 1

**Damper Location**  
Vestibule F

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
9FL-SD16 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
28x12

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

**SMOKE  
DAMPER**

Inspection Date: <b>5-30-24</b>	Reference I.D. #: <b>9FL-SD16</b>
Inspected By: <b>Coreno</b>	<b>N</b>
Next Inspect. By: <b>5-30-26</b>	

Duct Fabricators, Inc.  
883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians

MEMBER  
**NFPA**

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-30

**Facility Location**

Jail 1

**Damper Location**

Vestibule G

**Inspector Name**

Larry Coreno

**Damper I.D. #**

9FL-SD17 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

7x7

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-05-30

**Facility Location**  
Jail 1

**Damper Location**  
G Pod

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
9FL-SD18 North

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
26x12

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
7x7

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-04-23

### Facility Location

Jail 1

### Damper Location

Visitation

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

9FL-SD20 North

### Damper Type

Vertical Smoke Damper

### Damper Size

5" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

6"x6"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-23

**Facility Location**

Jail 1

**Damper Location**

Visitation

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

9FL-SD21 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-12-05

**Facility Location**  
Jail 1

**Damper Location**  
Southwest Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
10FL-FD1 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
15" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-12-04

**Facility Location**

Jail 1

**Damper Location**

Corridor NW

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-FD2 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

5" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

Flex

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-12-05

**Picture of Damper in Open Position**



**Facility Location**

Jail 1

**Damper Location**

Southwest Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-FD2 South

**Picture of Damper in Closed Position**



**Damper Type**

Vertical Fire Damper

**Damper Size**

26x12

**Damper Manufacturer**

Air Balance


**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Picture of Damper I.D. Label**



**Access Door Size**

8x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-12-05

**Facility Location**  
Jail 1

**Damper Location**  
Southwest Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
10FL-FD3 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
60x12

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
16x4

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

South corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

10FL-FD4 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

17" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

7"x6"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-12-04

**Facility Location**  
Jail 1

**Damper Location**  
North Utility Closet

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
10FL-FD5 North

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
13" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
6" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-12-04

**Facility Location**

Jail 1

**Damper Location**

Utility Closet

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-FD6 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

54x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-12-04

**Facility Location**

Jail 1

**Damper Location**

NW Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-FD7 North

**Damper Type**

Vertical Fire Damper

**Damper Size**

26x11

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-12-05

**Facility Location**  
Jail 1

**Damper Location**  
South Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
10FL-FD17 South

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
18x12

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
Open

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-04-30

### Facility Location

Jail 1

### Damper Location

Room #10J4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

10FL-FD18 South

### Damper Type

Vertical Fire Damper

### Damper Size

18"x14"

### Damper Manufacturer

Prefco Products

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-30

**Facility Location**

Jail 1

**Damper Location**

Rm 10J4

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

10FL-FD19 South

**Damper Type**

Vertical Fire Damper

**Damper Size**

10"x14"

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-04-30

### Facility Location

Jail 1

### Damper Location

Rm #10J4

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

10FL-FD20 South

### Damper Type

Vertical Fire Damper

### Damper Size

20"x14"

### Damper Manufacturer

Prefco Products

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

12"x12"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

South corridor

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

10FL-FSD1 South

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

10"x8"

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

8"x8"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-12-04

**Facility Location**

Jail 1

**Damper Location**

NW Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD1 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

13" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

8x8

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-12-05

**Facility Location**

Jail 1

**Damper Location**

Southwest Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD1 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-12-04

**Facility Location**

Jail 1

**Damper Location**

NW Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD3 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

54x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

17x11

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2023-12-05

**Facility Location**

Jail 1

**Damper Location**

Southwest Corridor

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD3 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

16x4

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-12-04

**Facility Location**  
Jail 1

**Damper Location**  
NW Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
10FL-SD8 North

**Damper Type**  
Horizontal Smoke Damper

**Damper Size**  
10x8

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
7x7

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

<b>SMOKE DAMPER</b>	
Inspection Date: <b>12/4/23</b>	Reference I.D. #: <b>10FL - SD8 N</b>
Inspected By: <b>Coreno</b>	
Next Inspect. By: <b>12/4/25</b>	
<small>Duct Fabricators, Inc. 883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F: 216-391-2492</small>	
<b>FIRE SAFETY DIVISION</b> <small>NEMI Certified HVAC Fire Life Safety Technicians</small>	
<small>MEMBER NFPA</small>	



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2023-12-05

**Facility Location**  
Jail 1

**Damper Location**  
Southwest Corridor

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
10FL-SD8 South

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
10x8

**Damper Manufacturer**  
Prefco Products

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
8x8

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-28

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD9 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-29

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD9 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-28

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD10 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-29

**Facility Location**

Jail 1

**Damper Location**

Vestibule C /D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD10 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-28

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD11 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-29

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD11 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-28

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD12 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-29

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD12 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

26x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-28

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD13 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

54x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

10FL-SD13 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

20"x6"

**Pass / Fail / Abandoned**

Fail

**Comments / Corrections**

Not enough air to open


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-28

**Facility Location**

Jail 1

**Damper Location**

Vestibule E/F

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD14 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8x8

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6x6

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-22

**Facility Location**

Jail 1

**Damper Location**

Vestibule C/D

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

10FL-SD14 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

17"x9"

**Pass / Fail / Abandoned**

Fail

**Comments / Corrections**

Bad Actuator


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-29

**Facility Location**

Jail 1

**Damper Location**

Vestibule G/H

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD15 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

30x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-30

**Facility Location**

Jail 1

**Damper Location**

Vestibule A/B

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD15 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22X8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10X10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-29

**Facility Location**

Jail 1

**Damper Location**

Vestibule G/H

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD16 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

22x8

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

10x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-29

**Facility Location**

Jail 1

**Damper Location**

Vestibule A/B

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD16 South

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48X12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-05-29

**Facility Location**

Jail 1

**Damper Location**

H Pod

**Inspector Name**

Larry Coreno

**Damper I.D. #**

10FL-SD17 North

**Damper Type**

Vertical Smoke Damper

**Damper Size**

24x14

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

Open

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

North Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 8FL-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Fail

**Comments / Corrections**

No air to actuator


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-18

**Facility Location**

Jail 1

**Damper Location**

North Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 6FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

26"x8"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-18

**Facility Location**

Jail 1

**Damper Location**

North stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 6FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-18

**Facility Location**

Jail 1

**Damper Location**

North stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 6FL-FSD1

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

18" Round

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-18

**Facility Location**

Jail 1

**Damper Location**

North Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 6FL-FSD3

**Damper Type**

Vertical Fire / Smoke Damper

**Damper Size**

6"x12"

**Damper Manufacturer**

Prefco Products

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

4"x4"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-18

**Facility Location**

Jail 1

**Damper Location**

North stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 6FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

60"x14"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-18

**Facility Location**

Jail 1

**Damper Location**

North Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 6FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

North Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 8FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

48"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12"x12"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

North stairwell.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 8FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

North stairwell.

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 8FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

9"x6" oval

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

North Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

NS 8FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

9" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-03-20

**Facility Location**

Jail 1

**Damper Location**

North Stairwell

**Inspector Name**

Larry Coreno

**Damper I.D. #**

NS 10FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

30x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-03-20

**Facility Location**

Jail 1

**Damper Location**

North Shaft

**Inspector Name**

Larry Coreno

**Damper I.D. #**

NS 10FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-03-20

**Facility Location**  
Jail 1

**Damper Location**  
North Shaft

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
NS 10FL-FD4

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
15" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-03-20

**Facility Location**

Jail 1

**Damper Location**

10FL North Shaft

**Inspector Name**

Larry Coreno

**Damper I.D. #**

NS 10FL-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-03-20

**Facility Location**

Jail 1

**Damper Location**

10FL North Shaft

**Inspector Name**

Larry Coreno

**Damper I.D. #**

NS 10FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-04-17

**Facility Location**  
Jail 1

**Damper Location**  
South Staiwell

**Inspector Name**  
Dan Tulcewicz

**Damper I.D. #**  
SS 8FL-FD1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-04-17

### Facility Location

Jail 1

### Damper Location

South Stairwell

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

SS 8FL-FD2

### Damper Type

Vertical Fire Damper

### Damper Size

30"x10"

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

165 Degrees

### Access Door Size

14"x14"

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

None


### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F:216-391-2492



NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

South Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

SS 8FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

8"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

6"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

South Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

SS 8FL-FD4

**Damper Type**

Vertical Fire Damper

**Damper Size**

48"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

16"x16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**  
NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

South Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

SS 8FL-FD5

**Damper Type**

Vertical Fire Damper

**Damper Size**

15" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio  
P: 216-391-2400 F: 216-391-2492

**FIRE SAFETY DIVISION**

NEMI Certified HVAC Fire Life Safety Technicians



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

### Date of Inspection

2024-04-17

### Facility Location

Jail 1

### Damper Location

South Stairwell

### Inspector Name

Dan Tulcewicz

### Damper I.D. #

SS 8FL-SD1

### Damper Type

Vertical Smoke Damper

### Damper Size

14" Round

### Damper Manufacturer

Air Balance

### Damper Model #

Unknown

### Fusible Link Temperature

N/A

### Access Door Size

12" Round

### Pass / Fail / Abandoned

Pass

### Comments / Corrections

Very low air pressure on actuator

### Picture of Damper in Open Position



### Picture of Damper in Closed Position



### Picture of Damper I.D. Label





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

South Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

SS 8FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

8" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

6" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

South Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

SS 8FL-SD4

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48"x12"

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

16"x16"

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-03-20

**Facility Location**  
Jail 1

**Damper Location**  
South Shaft

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
SS 10FL-FD1

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
12" Round

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-03-20

**Facility Location**

Jail 1

**Damper Location**

South Stairwell

**Inspector Name**

Larry Coreno

**Damper I.D. #**

SS 10FL-FD2

**Damper Type**

Vertical Fire Damper

**Damper Size**

39x10

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

12x12

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-03-20

**Facility Location**

Jail 1

**Damper Location**

South Shaft

**Inspector Name**

Larry Coreno

**Damper I.D. #**

SS 10FL-FD3

**Damper Type**

Vertical Fire Damper

**Damper Size**

48x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

165 Degrees

**Access Door Size**

20x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-03-20

**Facility Location**  
Jail 1

**Damper Location**  
South Shaft

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
SS 10FL-FD4

**Damper Type**  
Vertical Fire Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
165 Degrees

**Access Door Size**  
7x10

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-03-20

**Facility Location**

Jail 1

**Damper Location**

10FL South Shaft

**Inspector Name**

Larry Coreno

**Damper I.D. #**

SS 10FL-SD1

**Damper Type**

Vertical Smoke Damper

**Damper Size**

14" Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12" Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-03-20

**Facility Location**

Jail 1

**Damper Location**

10FL South Shaft

**Inspector Name**

Larry Coreno

**Damper I.D. #**

SS 10FL-SD3

**Damper Type**

Vertical Smoke Damper

**Damper Size**

48x12

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

20x10

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None


**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**





## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**  
2024-03-20

**Facility Location**  
Jail 1

**Damper Location**  
South Shaft

**Inspector Name**  
Larry Coreno

**Damper I.D. #**  
SS 10FL-SD4

**Damper Type**  
Vertical Smoke Damper

**Damper Size**  
14" Round

**Damper Manufacturer**  
Air Balance

**Damper Model #**  
Unknown

**Fusible Link Temperature**  
N/A

**Access Door Size**  
6x6

**Pass / Fail / Abandoned**  
Pass

**Comments / Corrections**  
None


Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label



## CUYAHOGA COUNTY DAMPER INSPECTION REPORT

**Date of Inspection**

2024-04-17

**Facility Location**

Jail 1

**Damper Location**

South Stairwell

**Inspector Name**

Dan Tulcewicz

**Damper I.D. #**

SS-8FL SD5

**Damper Type**

Vertical Smoke Damper

**Damper Size**

15"Round

**Damper Manufacturer**

Air Balance

**Damper Model #**

Unknown

**Fusible Link Temperature**

N/A

**Access Door Size**

12"Round

**Pass / Fail / Abandoned**

Pass

**Comments / Corrections**

None

**Picture of Damper in Open Position**



**Picture of Damper in Closed Position**



**Picture of Damper I.D. Label**

