Cuyahoga County Men's Homeless Shelter

2100 Lakeside Ave Cleveland Ohio 44115

Physical Inspections
Fire/Smoke Damper Inspection Report





883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





Report Date: September 13, 2024

<u>Project</u>: Cuyahoga County

Men's Shelter Addition

Inspector(s):

Dan Tulcewicz, Certified Technician

Inspection and Test Date(s):

July 31, 2024

Duct Fabricators, Inc. "Fire Safety Division" inspected the One (1) fire damper noted on the following sheets for proper installation. The dampers were then tested and photographed in the "open" and "closed" positions to confirm that they were functioning as designed.

All the dampers passed the inspection and functional testing.

NOTES: NFPA 80 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation.

Thereafter, dampers located in patient care facilities are to be inspected and tested every six years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





<u>Fire / Smoke / Fire & Smoke Damper</u> <u>Composite Inspection Report</u>

	FD/SD/FSD	<u>I.D.#</u>	Size	Manufacturer	<u>Model</u>	<u>Visual</u>	<u>Functional</u>	<u>Comments</u>
1	FD	FD-3	8"	Ruskin	DIBD60	Pass	Pass	New Damper - Located in the addition
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								

Inspector:Dan TulcewiczSA = Supply AirFD = Fire DamperInspection Dates:7/31/2024RA = Return AirSD = Smoke Damper

Facility: Men's Shelter EA = Exhaust Air FSD = Fire Smoke Damper

Duct Fabricators, Inc.

883 Addison Rd. Cleveland, Ohio P: 216-391-2400 F:216-391-2492





CUYAHOGA COUNTY DAMPER INSPECTION REPORT

Date of Inspection

2024-07-31

Facility Location

Men's Homeless Shelter

Damper Location

Addition basement

Inspector Name

Dan Tulcewicz

Damper I.D. #

FD-3

Damper Type

Horizontal Fire Damper

Damper Size

8"Round

Damper Manufacturer

Ruskin

Damper Model #

DIBD60

Fusible Link Temperature

165 Degrees

Access Door Size

Remove the grille

Pass / Fail / Abandoned

Pass

Comments / Corrections

None

Picture of Damper in Open Position



Picture of Damper in Closed Position



Picture of Damper I.D. Label

